






| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|-----|---------------------|------------|----------------------|---|
| 119 | GX-B1328/20-3-23112 | 2023年4月18日 | 本次共检绝缘手套6只，6只绝缘手套合格。 |  |
| 120 | GX-B1328/20-3-23113 | 2023年4月18日 | 本次共检绝缘鞋6只，6只绝缘鞋合格。 |  |
| 121 | GX-B1328/20-3-23114 | 2023年4月18日 | 本次共检绝缘杆2套，2套绝缘杆合格。 |  |





| | | | | |
|-----|---------------------------|-------------|--------------------------------------|---|
| 122 | GX-B1328/20-3-23115 | 2023年4月18日 | 本次共检便携式接地和接地短路装置2套，2套便携式接地和接地短路装置合格。 |  |
| 123 | GX-B1328/20-3-23116 | 2023年4月18日 | 本次共检验电器2支，2支验电器合格。 |  |
| 124 | GX-B1352/21-3-23213~23224 | 2023. 4. 20 | 所检项目合格 |  |
| 125 | GX-B1352/21-3-23196~23212 | 2023. 4. 20 | 所检项目合格 |  |





| | | | | |
|-----|---------------------|-------------|------------------------------|---|
| 126 | GX-B1328/20-3-23095 | 2023. 4. 17 | 本次共检绝缘手套34只，34只绝缘手套合格。 |  |
| 127 | GX-B1328/20-3-23096 | 2023. 4. 17 | 本次共检绝缘鞋34只，34只绝缘鞋合格。 |  |
| 128 | GX-B1328/20-3-23097 | 2023. 4. 17 | 本次共检高压验电器10支，10支高压验电器所检项目合格。 |  |
| 129 | GX-B1328/20-3-23098 | 2023. 4. 17 | 本次共检绝缘杆2套，2套绝缘杆所检项目合格。 |  |

| | | | | |
|-----|---------------------------|-------------|--|---|
| 130 | GX-B1328/20-3-23099 | 2023. 4. 17 | 本次共检便携式接地和接地短路装置8套，8套便携式接地和接地短路装置所检项目合格。 |  |
| 131 | GX-B1321/20-3-23766~23774 | 2023. 4. 17 | 本次共检电力电缆9条，9条电力电缆所检项目合格。 |  |
| 132 | GX-B1321/20-3-23775~23779 | 2023. 4. 17 | 本次共检电力电缆5条，5条电力电缆所检项目合格。 |  |
| 133 | GX-B1321/20-3-23780~23786 | 2023. 4. 17 | 本次共检电力电缆7条，7条电力电缆所检项目合格。 |  |


| | | | | |
|-----|---------------------------|-------------|----------------------------|---|
| 134 | GX-B1321/20-3-23787~23791 | 2023. 4. 17 | 本次共检电力电缆5条，5条电力电缆所检项目合格。 |  |
| 135 | GX-B1321/20-3-23792~23804 | 2023. 4. 17 | 本次共检电力电缆13条，13条电力电缆所检项目合格。 |  |
| 136 | GX-B1312/20-3-23261~23264 | 2023. 4. 17 | 本次共检电力变压器4台，4台电力变压器所检项目合格。 |  |
| 137 | GX-B1312/20-3-23265 | 2023. 4. 17 | 所检项目合格。 |  |





| | | | | |
|-----|---------------------------|-------------|----------------------------|---|
| 138 | GX-B1312/20-3-23266~23268 | 2023. 4. 17 | 本次共检电力变压器3台，3电力变压器所检项目合格。 |  |
| 139 | GX-B1312/20-3-23269~23270 | 2023. 4. 17 | 本次共检电力变压器2台，2台电力变压器所检项目合格。 |  |
| 140 | GX-B1312/20-3-23271~23279 | 2023. 4. 17 | 本次共检电力变压器9台，9台电力变压器所检项目合格。 |  |
| 141 | GX-B1312/20-3-23280~23281 | 2023. 4. 17 | 本次共检电力变压器2台，2台电力变压器所检项目合格。 |  |





| | | | | |
|-----|---------------------|-------------|----|---|
| 142 | GX-B1328/20-3-23100 | 2023. 4. 23 | 合格 |  |
| 143 | GX-B1328/20-3-23101 | 2023. 4. 23 | 合格 |  |
| 144 | GX-B1328/20-3-23102 | 2023. 4. 23 | 合格 |  |
| 145 | GX-B1328/20-3-23103 | 2023. 4. 23 | 合格 |  |

| | | | | |
|-----|---------------------|-------------|----|--|
| 146 | GX-B1328/20-3-23104 | 2023. 4. 23 | 合格 |  |
| 147 | GX-B1328/20-3-23105 | 2023. 4. 23 | 合格 |  |
| 148 | GX-B1328/20-3-23106 | 2023. 4. 23 | 合格 |  |
| 149 | GX-B1328/20-3-23107 | 2023. 4. 23 | 合格 |  |

| | | | | |
|-----|---------------------|-------------|----|--|
| 150 | GX-B1328/20-3-23108 | 2023. 4. 23 | 合格 |  |
| 151 | GX-B1328/20-3-23109 | 2023. 4. 23 | 合格 |  |
| 152 | GX-B1328/20-3-23110 | 2023. 4. 23 | 合格 |  |
| 153 | GX-B1328/20-3-23111 | 2023. 4. 23 | 合格 |  |

| | | | | | |
|-----|---------------------|-----------|--------|--|--|
| 154 | GX-B1308/21-3-23005 | 2023/4/26 | 所检项目合格 | |  A worker wearing an orange safety suit and a red helmet is working in a tunnel. The worker is positioned next to some equipment. A yellow timestamp '2023.04.08' is visible in the bottom right corner of the photo. |
| 155 | GX-B1308/21-3-23006 | 2023/4/26 | 所检项目合格 | |  A worker in a dark suit and red helmet is working in a tunnel. The worker is using a tool or equipment. A yellow timestamp '2023.04.08' is visible in the bottom right corner of the photo. |
| 156 | GX-B1308/21-3-23007 | 2023/4/26 | 所检项目合格 | |  A worker in a dark suit and red helmet is working in a tunnel. The worker is using a tool or equipment. A yellow timestamp '2023.04.08' is visible in the bottom right corner of the photo. |
| 157 | GX-B1308/21-3-23008 | 2023/4/26 | 所检项目合格 | |  A worker in a dark suit and red helmet is working in a tunnel. The worker is standing near some equipment. A yellow timestamp '2023.04.08' is visible in the bottom right corner of the photo. |

| | | | | |
|-----|---------------------|-----------|--------|--|
| 158 | GX-B1499/21-3-23061 | 2023/4/26 | 所检项目合格 |  |
| 159 | GX-B1499/21-3-23062 | 2023/4/26 | 所检项目合格 |  |
| 160 | GX-B1499/21-3-23063 | 2023/4/26 | 所检项目合格 |  |
| 161 | GX-B1499/21-3-23064 | 2023/4/26 | 所检项目合格 |  |

| | | | | | |
|-----|---------------------|-----------|--------|--|--|
| 162 | GX-B1499/21-3-23065 | 2023/4/26 | 所检项目合格 |  | |
| 163 | GX-B1499/21-3-23066 | 2023/4/26 | 所检项目合格 |  | |
| 164 | GX-B1499/21-3-23067 | 2023/4/26 | 所检项目合格 |  | |
| 165 | GX-B1499/21-3-23068 | 2023/4/26 | 所检项目合格 |  | |

| | | | | |
|-----|---------------------|-----------|--------|--|
| 166 | GX-B1499/21-3-23069 | 2023/4/26 | 所检项目合格 |  |
| 167 | GX-B1499/21-3-23070 | 2023/4/26 | 所检项目合格 |  |
| 168 | GX-B1499/21-3-23071 | 2023/4/26 | 所检项目合格 |  |
| 169 | GX-B1499/21-3-23072 | 2023/4/26 | 所检项目合格 |  |

| | | | | |
|-----|---------------------|-----------|--------|--|
| 170 | GX-B1499/21-3-23073 | 2023/4/26 | 所检项目合格 |  A photograph showing two workers in blue uniforms and red hard hats inspecting equipment in a tunnel. The date '2023.04.08' is visible in the bottom right corner. |
| 171 | GX-B1499/21-3-23074 | 2023/4/26 | 所检项目合格 |  A photograph of a worker in a blue uniform and red hard hat inspecting a large blue cylindrical machine. The date '2023.04.08' is visible in the bottom right corner. |
| 172 | GX-B1499/21-3-23075 | 2023/4/26 | 所检项目合格 |  A photograph of a worker in a blue uniform and red hard hat inspecting a red machine with a warning sign. The date '2023.04.08' is visible in the bottom right corner. |
| 173 | GX-B1499/21-3-23076 | 2023/4/26 | 所检项目合格 |  A photograph of a worker in a blue uniform and red hard hat inspecting a blue machine. The date '2023.04.08' is visible in the bottom right corner. |

| | | | | |
|-----|---------------------|------------|---|--|
| 174 | GX-B1499/21-3-23077 | 2023/4/26 | 所检项目合格 |  |
| 175 | GX-B1404/20-3-23021 | 2023年4月14日 | 所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。 |  |
| 176 | GX-B1404/20-3-23022 | 2023年4月14日 | 所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。 |  |
| 177 | GX-B1404/20-3-23023 | 2023年4月14日 | 所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。 |  |

| | | | | |
|-----|---------------------|-------------|--|--|
| 178 | GX-B1404/20-3-23024 | 2023年4月14日 | 所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993《电能质量 公用电网谐波》要求。 |  |
| 179 | GX-B1310/21-3-23031 | 2023. 4. 25 | 符合标准要求。 |  |
| 180 | GX-B1310/21-3-23032 | 2023. 4. 26 | 符合标准要求。 |  |
| 181 | GX-B1310/21-3-23033 | 2023. 4. 26 | 符合标准要求。 |  |

| | | | | |
|-----|---------------------|-------------|---------|--|
| 182 | GX-B1427/21-3-23012 | 2023. 4. 25 | 符合标准要求。 |  |
| 183 | GX-B1427/21-3-23013 | 2023. 4. 26 | 符合标准要求。 |  |
| 184 | GX-B1427/21-3-23014 | 2023. 4. 26 | 符合标准要求。 |  |
| 185 | GX-B1428/21-3-23013 | 2023年4月20日 | 无缺陷迹痕显示 |  |

| | | | | |
|-----|---------------------|------------|------------------|--|
| 186 | GX-B1428/21-3-23014 | 2023年4月20日 | 无缺陷迹痕显示 |  |
| 187 | GX-B1310/21-3-23019 | 2023年4月20日 | 符合标准要求 |  |
| 188 | GX-B1310/21-3-23020 | 2023年4月20日 | 符合标准要求 |  |
| 189 | GX-B1310/21-3-23021 | 2023年4月20日 | 未发现超过Φ2mm当量直径的缺陷 |  |

| | | | | |
|-----|---------------------------|-------------|------------------------------------|--|
| 190 | GX-B1310/21-3-23022 | 2023年4月20日 | 未发现超过 $\Phi 2\text{mm}$ 当量直径的缺陷 |  |
| 191 | GX-B1310/21-3-23023 | 2023年4月20日 | 未发现超过 $\Phi 2\text{mm}$ 当量直径的缺陷 |  |
| 192 | GX-B1359/21-3-23061-23070 | 2023. 4. 25 | 本次共检矿用隔爆型照明信号综合保护装置10台, 10台所检项目合格。 |  |