

序号	报告编号	发布日期	结论	影像资料
183	GX-B1321/20-Y-22211	2022年6月17日	合格	
184	GX-B1321/20-Y-22212	2022年6月17日	合格	

185	GX-B1321/20-Y-22213	2022年6月17日	合格	
186	GX-B1321/20-Y-22214~22216	2022年6月17日	合格	



187	GX-B1495/20-Y-22501~22509	2022年6月17日	合格	 A photograph showing a worker in a dark, possibly underground, environment. The worker is wearing a dark jacket and a headlamp. They are kneeling on the floor, operating a piece of equipment that has a white top and a red base. The equipment is illuminated by a bright light source. In the background, there are some red structures and a wall. A yellow timestamp "2022/6/8" is visible in the bottom right corner of the image.
188	GX-B1495/20-Y-22510	2022年6月17日	合格	 A photograph showing a worker in a dark environment, wearing a blue jacket and a red hard hat. The worker is leaning over a piece of equipment, which appears to be a control panel or a piece of machinery. The worker is using a tool or a device to work on the equipment. The scene is dimly lit, with a bright light source illuminating the worker and the equipment. A yellow timestamp "2022/6/8" is visible in the bottom right corner of the image.

189	GX-B1495/20-Y-22511	2022年6月17日	合格	
190	GX-B1495/20-Y-22512~22514	2022年6月17日	合格	

191	GX-B1495/20-Y-22515	2022年6月17日	合格	 <p>2022/6/5</p>
192	GX-B1495/20-Y-22516~22530	2022年6月17日	合格	 <p>2022/6/7</p>

193	GX-B1312/20-Y-22174~22175	2022年6月17日	合格	 <p>A worker wearing a white uniform and a red hard hat is standing in front of a blue cabinet. The cabinet is open, revealing several red fire extinguishers inside. The worker is holding a red tool, possibly a wrench, and appears to be working on one of the extinguishers. A yellow container is visible on the floor in front of the cabinet. The date '2022/6/7' is printed in the bottom right corner of the photo.</p>
194	GX-B1312/20-Y-22176	2022年6月17日	合格	 <p>A worker wearing a white uniform and a red hard hat is working on a red fire extinguisher inside a blue cabinet. The worker is using a yellow tool to work on the extinguisher. The cabinet is open, and the extinguisher is mounted on a shelf. A yellow container is visible on the floor in front of the cabinet. The date '2022/6/7' is printed in the bottom right corner of the photo.</p>

195	GX-B1312/20-Y-22177~22178	2022年6月17日	合格	
196	GX-B1312/20-Y-22179~22181	2022年6月17日	合格	

197	GX-B1312/20-Y-22182	2022年6月17日	合格	 <p>A photograph showing a worker from behind, wearing a red safety helmet and a green work jacket. The worker is positioned in a dark environment, possibly at night, with a very bright light source (likely a work lamp) illuminating the scene. The worker appears to be working on or near some equipment. A date stamp '2022/6/8' is visible in the bottom right corner of the image.</p>
198	GX-B1312/20-Y-22183~22184	2022年6月17日	合格	 <p>A photograph of an industrial interior, possibly a tunnel or a confined space. The lighting is very dim and has a strong orange or red hue, likely from a specific type of work lighting. The scene is somewhat obscured by shadows and dust. A date stamp '2022/6/8' is visible in the bottom right corner of the image.</p>

199	GX-B1312/20-Y-22185~22186	2022年6月17日	合格	
200	GX-B1312/20-Y-22187	2022年6月17日	合格	

201	GX-B1300/20-Y-22006	2022年6月19日	合格	
202	GX-B1539/20-Y-22095	2022年6月20日	合格	

203	GX-B1539/20-Y-22096	2022年6月20日	合格	
204	GX-B1539/20-Y-22097	2022年6月20日	合格	



205	GX-B1539/20-Y-22098	2022年6月20日	合格	
206	GX-B1539/20-Y-22099	2022年6月20日	合格	

207	GX-B1539/20-Y-22100	2022年6月20日	合格	
208	GX-B1539/20-Y-22101	2022年6月20日	合格	

209	GX-B1539/20-Y-22102	2022年6月20日	合格	 <p>A yellow ZL50CN wheel loader is parked on a paved area. Two workers in white uniforms and red hard hats are standing next to it. The loader has 'ZL50CN' and '20' visible on its side. A yellow timestamp '2022/6/2' is in the bottom right corner of the photo.</p>
210	GX-B1539/20-Y-22103	2022年6月20日	合格	 <p>A yellow ZL50CN wheel loader is parked on a paved area. Three workers in white uniforms and red hard hats are standing next to it. The loader has 'ZL50CN' visible on its side. A yellow timestamp '2022/6/2' is in the bottom right corner of the photo.</p>

211	GX-B1539/20-Y-22104	2022年6月20日	合格	 <p>A photograph of a yellow ZL50CN wheel loader parked in an industrial yard. Two workers in safety gear stand in front of the machine. In the background, a blue banner with white Chinese characters reads "管理成为文化 用文". A yellow date stamp "2022/6/2" is visible in the bottom right corner of the photo.</p>
212	GX-B1539/20-Y-22105	2022年6月20日	合格	 <p>A photograph of a yellow ZL50CN wheel loader parked in an industrial yard. Two workers in safety gear stand in front of the machine. In the background, a blue banner with white Chinese characters reads "安全". A yellow date stamp "2022/6/2" is visible in the bottom right corner of the photo.</p>

213	GX-B1539/20-Y-22106	2022年6月21日	合格	
214	GX-B1539/20-Y-22107	2022年6月21日	合格	

215	GX-B1539/20-Y-22118	2022年6月21日	合格	 A yellow wheel loader is parked on a gravel surface. Two workers in safety gear are standing next to it. The background shows a clear blue sky and some distant structures. A yellow date stamp '2022/6/21' is visible in the bottom right corner of the photo.
216	GX-B1539/20-Y-22119	2022年6月21日	合格	 A white wheel loader is parked on a gravel surface. Two workers in safety gear are standing next to it. The background shows a clear blue sky and some distant structures. A yellow date stamp '2022/6/21' is visible in the bottom right corner of the photo.

217	GX-B1539/20-Y-22115	2022年6月21日	合格	
218	GX-B1539/20-Y-22116	2022年6月21日	合格	

219	GX-B1539/20-Y-22117	2022年6月21日	合格	
220	GX-B1539/20-Y-22108	2022年6月21日	合格	

221	GX-B1539/20-Y-22109	2022年6月21日	合格	
222	GX-B1539/20-Y-22110	2022年6月21日	合格	



223	GX-B1423/20-Y-222531	2022年6月21日	合格	
224	GX-B1423/20-Y-222532	2022年6月21日	合格	

225	GX-B1423/20-Y-222533	2022年6月21日	合格	 <p>A yellow TORLY dump truck with the number '3' on its side is parked on a gravel surface. A person in a red hard hat and work clothes stands next to the truck. The date '2022/6/13' is visible in the bottom right corner of the photo.</p>
226	GX-B1423/20-Y-222534	2022年6月21日	合格	 <p>A yellow dump truck with the number '4' on its side is parked on a gravel surface. Two people in work clothes stand in front of the truck. The date '2022/6/13' is visible in the bottom right corner of the photo.</p>

227	GX-B1539/20-Y-22111	2022年6月21日	合格	
228	GX-B1539/20-Y-22112	2022年6月21日	合格	

229	GX-B1539/20-Y-22113	2022年6月21日	合格	
230	GX-B1539/20-Y-22114	2022年6月21日	合格	

231	GX-B1521/20-Y-22195	2022年6月25日	合格	
232	GX-B1521/20-Y-22171	2022. 6. 25	合格	

233	GX-B1521/20-Y-22172	2022. 6. 25	合格	
234	GX-B1521/20-Y-22168	2022年6月25日	合格	

235	GX-B1521/20-Y-22169	2022年6月25日	合格	
236	GX-B1521/20-Y-22170	2022年6月25日	合格	

237	GX-B1521/20-Y-22196	2022年6月25日	合格	
238	GX-B1521/20-Y-22197	2022年6月25日	合格	

239	GX-B1521/20-Y-22198	2022年6月25日	合格	 <p>A red Doosan excavator is shown at a construction site. The excavator is positioned on a dirt and gravel surface, with its arm extended. The background shows a clear blue sky and a bright sun. A yellow timestamp '2022/6/13' is visible in the bottom right corner of the image.</p>
240	GX-B1539/20-Y-22120	2022年6月23日	合格	 <p>A yellow Sdlg wheel loader is shown at a construction site. The loader is positioned on a dirt and gravel surface, with its bucket lowered. The background shows a large pile of gravel and a clear blue sky. A yellow timestamp '2022/6/13' is visible in the bottom right corner of the image.</p>

241	GX-B1539/20-Y-22121	2022年6月23日	合格	
242	GX-B1539/20-Y-22122	2022年6月23日	合格	

243	GX-B1521/20-Y-22179	2022年6月25日	合格	
244	GX-B1521/20-Y-22180	2022年6月25日	合格	

245	GX-B1521/20-Y-22181	2022年6月25日	合格	
246	GX-B1521/20-Y-22182	2022年6月25日	合格	

247	GX-B1521/20-Y-22183	2022年6月25日	合格	
248	GX-B1521/20-Y-22184	2022年6月25日	合格	

249	GX-B1522/20-Y-22042	2022年6月25日	合格	
250	GX-B1522/20-Y-22043	2022年6月25日	合格	

251	GX-B1522/20-Y-22044	2022年6月25日	合格	
252	GX-B1522/20-Y-22045	2022年6月25日	合格	

253	GX-B1423/20-Y-222522	2022年6月25日	合格	
254	GX-B1423/20-Y-222523	2022年6月25日	合格	


255	GX-B1423/20-Y-222524	2022年6月25日	合格	
256	GX-B1423/20-Y-222525	2022年6月25日	合格	

257	GX-B1423/20-Y-222526	2022年6月25日	合格	
258	GX-B1423/20-Y-222527	2022年6月25日	合格	

259	GX-B1423/20-Y-222528	2022年6月25日	合格	
260	GX-B1423/20-Y-222529	2022年6月25日	合格	

261	GX-B1423/20-Y-222530	2022年6月25日	合格	
262	GX-B1521/20-Y-22173	2022. 6. 25	合格	

263	GX-B1521/20-Y-22174	2022. 6. 25	合格	
264	GX-B1521/20-Y-22175	2022. 6. 25	合格	

265	GX-B1521/20-Y-22176	2022. 6. 25	合格	
266	GX-B1521/20-Y-22177	2022. 6. 25	合格	

267	GX-B1521/20-Y-22178	2022. 6. 25	合格	
268	GX-B1521/20-Y-22185	2022年6月25日	合格	

269	GX-B1521/20-Y-22186	2022年6月25日	合格	 A yellow tracked excavator with "SDLG" branding is shown in a construction or quarry setting. The excavator is positioned on a dirt surface, and its bucket is lowered. The background features a clear blue sky and distant hills. A yellow timestamp "2022/6/12" is visible in the bottom right corner of the image.
270	GX-B1521/20-Y-22187	2022年6月25日	合格	 A yellow tracked excavator is shown in a similar construction or quarry setting as in the first image. The excavator is silhouetted against a bright sun, creating a lens flare effect. The background shows a clear sky and distant hills. A yellow timestamp "2022/6/12" is visible in the bottom right corner of the image.

271	GX-B1521/20-Y-22188	2022年6月25日	合格	
272	GX-B1521/20-Y-22189	2022年6月25日	合格	

273	GX-B1521/20-Y-22190	2022年6月25日	合格	
274	GX-B1521/20-Y-22191	2022年6月25日	合格	

275	GX-B1521/20-Y-22192	2022年6月25日	合格	
276	GX-B1521/20-Y-22193	2022年6月25日	合格	

277	GX-B1521/20-Y-22194	2022年6月25日	合格	
-----	---------------------	------------	----	---