

序号	报告编号	发布日期	结论	影像资料
71	GX-B1312 / 20-Z-22096~22097	2022/6/14	所检项目合格	 A worker in a white protective suit and red helmet is working on a piece of equipment inside a confined space. The equipment has a large, vertical, ribbed section. A date stamp '2022 06 22' is visible in the bottom right corner of the image.
72	GX-B1495 / 20-Z-22277~22286	2022/7/12	所检项目合格	 A worker in a grey uniform and red helmet is working on a piece of equipment inside a confined space. The worker is wearing red gloves and is reaching up to adjust or inspect the equipment. A date stamp '2022 06 22' is visible in the bottom right corner of the image.

73	GX-B1495 / 20-Z-22287	2022/7/12	所检项目合格	 <p>2022 06 22</p>	
74	GX-B1322 / 21-Z-22010~22011	2022/7/11	所检项目合格	 <p>2022 06 18</p>	
75	GX-B1451 / 20-Z-22035~22041	2022/7/11	所检项目合格	 <p>2022 06 18</p>	

76	GX-B1451 / 20-Z-22042~22050	2022/7/11	所检项目合格	 A worker wearing a red safety suit and a red helmet is working on a piece of electrical equipment. The equipment has several panels with meters and switches. A wooden chair is visible in the background. The date stamp in the bottom right corner of the photo is 2022.06.18.
77	GX-B1423/20-Z-22081	2022/7/12	合格	 Two workers are standing in front of a blue truck. One worker is wearing a red helmet and a grey shirt, and the other is wearing a grey shirt and dark pants. The truck is parked on a dirt road with green hills in the background. The date stamp in the bottom right corner of the photo is 2022.06.20.
78	GX-B1423/20-Z-22082	2022/7/12	合格	 A worker is sitting in the driver's seat of a blue truck, operating the vehicle. The worker is wearing a grey shirt and dark pants. The truck's interior, including the steering wheel and dashboard, is visible. The date stamp in the bottom right corner of the photo is 2022.06.20.

79	GX-B1423/20-Z-22083	2022/7/12	合格		
80	GX-B1423/20-Z-22078	2022/7/12	合格		
81	GX-B1423/20-Z-22079	2022/7/12	合格		

82	GX-B1423/20-Z-22080	2022/7/12	合格	
83	GX-B1313 / 21-Z-22012	2022/7/12	所检项目合格	
84	GX-B1313 / 21-Z-22013	2022/7/12	所检项目合格	

85	GX-B1423/20-Z-22084	2022/7/12	合格		
86	GX-B1423/20-Z-22085	2022/7/12	合格		
87	GX-B1423/20-Z-22086	2022/7/12	合格		

88	GX-B1423/20-Z-22087	2022/7/12	合格	
89	GX-B1423/20-Z-22088	2022/7/12	合格	
90	GX-B1423/20-Z-22089	2022/7/12	合格	

91	GX-B1423/20-Z-22090	2022/7/12	合格	
92	GX-B1423/20-Z-22091	2022/7/12	合格	
93	GX-B1423/20-Z-22092	2022/7/12	合格	

94	GX-B1423/20-Z-22093	2022/7/12	合格	
95	GX-B1423/20-Z-22094	2022/7/12	合格	
96	GX-B1423/20-Z-22095	2022/7/12	合格	

97	GX-B1499/21-Z-22019	2022/7/12	所检项目合格	
98	GX-B1500/21-Z-22020	2022/7/12	所检项目合格	
99	GX-B1500/21-Z-22021	2022/7/12	所检项目合格	

100	GX-B1500/21-Z-22022	2022/7/12	所检项目合格	
101	GX-B1500/21-Z-22023	2022/7/12	所检项目合格	
102	GX-B1517/20-Z-22007	2022/7/13	所检项目合格。	

103	GX-B1517/20-Z-22008	2022/7/13	所检项目合格。	
104	GX-B1517/20-Z-22009	2022/7/13	所检项目合格。	
105	GX-B1517/20-Z-220010	2022/7/13	所检项目合格。	

106	GX-B1517/20-Z-220011	2022/7/13	所检项目合格。	
107	GX-B1328/20-Z-22036	2022/7/13	所检项目合格。	
108	GX-B1328/20-Z-22037	2022/7/13	所检项目合格。	

109	GX-B1328/20-Z-22038	2022/7/13	所检项目合格。	
110	GX-B1328/20-Z-22039	2022/7/13	所检项目合格。	