

序号	报告编号	发布日期	结论	影像资料
456	GX-B1300/20-Y-22007	2022年7月12日	合格	
457	GX-B1517/20-Y-22004	2022年7月13日	合格	

458	GX-B1517/20-Y-22005	2022年7月13日	合格	 <p>A photograph showing a worker in a dark tunnel environment. The worker is wearing a reflective safety vest and a headlamp. They are standing next to a red piece of machinery, possibly a tunneling machine or a small train car, which has a white circular sign with the number '2' on its side. The scene is dimly lit, with the primary light source being the worker's headlamp and some ambient light from the tunnel. A yellow timestamp '2022/5/26' is visible in the bottom right corner of the image.</p>
459	GX-B1517/20-Y-22006	2022年7月13日	合格	 <p>A photograph showing a worker in a dark tunnel environment. The worker is wearing a reflective safety vest and a headlamp. They are standing next to a piece of machinery, possibly a tunneling machine or a small train car, which has a white circular sign with the number '3' on its side. The scene is dimly lit, with the primary light source being the worker's headlamp and some ambient light from the tunnel. A yellow timestamp '2022/5/26' is visible in the bottom right corner of the image.</p>


460	GX-B1517/20-Y-22007	2022年7月13日	合格	
461	GX-B1308/21-Y-22012	2022年7月13日	合格	

462	GX-B1499/21-Y-22099	2022年7月13日	合格	
463	GX-B1499/21-Y-22100	2022年7月13日	合格	

464	GX-B1499/21-Y-22101	2022年7月13日	合格	
465	GX-B1310/21-Y-22081	2022年7月14日	合格	

466	GX-B1310/21-Y-22082	2022年7月14日	合格	
467	GX-B1427/21-Y-22082	2022年7月14日	合格	

468	GX-B1310/21-Y-22083	2022年7月14日	合格	
469	GX-B1310/21-Y-22084	2022年7月14日	合格	

470	GX-B1310/21-Y-22085	2022年7月14日	合格	
-----	---------------------	------------	----	---

471	GX-B1428/21-Y-22085	2022年7月14日	合格	 <p>A photograph showing a worker in a blue uniform with reflective stripes and a red helmet, working inside a large, dark industrial vessel. The worker is leaning over, and the date '2022/5/26' is visible in yellow text at the bottom right of the image.</p>
472	GX-B1310/21-Y-22086	2022年7月14日	合格	 <p>A photograph showing two workers standing next to a large yellow industrial machine, possibly a conveyor or hopper. One worker is wearing a grey shirt and the other a white shirt. The machine has 'EX' written on it. The date '2022/5/26' is visible in yellow text at the bottom right of the image.</p>

473	GX-B1428/21-Y-22086	2022年7月14日	合格	
474	GX-B1310/21-Y-22087	2022年7月14日	合格	

475	GX-B1310/21-Y-22088	2022年7月14日	合格	
476	GX-B1310/21-Y-22089	2022年7月14日	合格	

477	GX-B1427/21-Y-22089	2022年7月14日	合格	
478	GX-B1310/21-Y-22090	2022年7月14日	合格	

479	GX-B1427/21-Y-22090	2022年7月14日	合格	
480	GX-B1310/21-Y-22091	2022年7月14日	合格	

481	GX-B1427/21-Y-22091	2022年7月14日	合格	 <p>A photograph showing a person in a dark environment, possibly a tunnel or underground setting, using a bright flashlight to inspect a component. The person is wearing a dark jacket and a cap. The flashlight beam is very bright, creating a strong glare. In the bottom right corner of the image, there is a yellow date stamp: 2022/5/25.</p>
482	GX-B1423/20-Y-222786	2022年7月17日	合格	 <p>A photograph showing two workers standing in front of a large truck. The truck is white with a red stripe and has "RKT125" written on the top of the cab. The license plate area has the number "039". One worker is wearing a yellow hard hat and a high-visibility vest, and the other is wearing a red hard hat and a white shirt. They are standing on a dirt surface. In the bottom right corner of the image, there is a yellow date stamp: 2022/7/3.</p>

483	GX-B1423/20-Y-222787	2022年7月17日	合格	
484	GX-B1423/20-Y-222788	2022年7月17日	合格	

485	GX-B1423/20-Y-222789	2022年7月17日	合格	
486	GX-B1423/20-Y-222790	2022年7月17日	合格	

487	GX-B1423/20-Y-222791	2022年7月17日	合格	 A photograph showing a worker from the waist up, seated in the driver's seat of a vehicle. The worker is wearing a white short-sleeved uniform shirt, light-colored trousers, and a pink hard hat. They are looking down at the steering wheel. A yellow date stamp '2022/7/3' is visible in the bottom right corner of the photo.
488	GX-B1423/20-Y-222792	2022年7月17日	合格	 A photograph of a large white truck with a red roof rack, parked on a dirt surface. The truck has '058' on the front bumper and 'HKT125' on the roof rack. Two workers in white uniforms and hard hats are standing in front of the truck. A yellow date stamp '2022/7/3' is visible in the bottom right corner of the photo.


489	GX-B1423/20-Y-222793	2022年7月17日	合格	
490	GX-B1423/20-Y-222794	2022年7月17日	合格	

491	GX-B1423/20-Y-222795	2022年7月17日	合格	
492	GX-B1423/20-Y-222796	2022年7月17日	合格	

493	GX-B1423/20-Y-222797	2022年7月17日	合格	
494	GX-B1423/20-Y-222798	2022年7月17日	合格	

495	GX-B1423/20-Y-222799	2022年7月17日	合格	
496	GX-B1423/20-Y-222800	2022年7月17日	合格	

497	GX-B1423/20-Y-222801	2022年7月17日	合格	
498	GX-B1423/20-Y-222802	2022年7月17日	合格	

499	GX-B1423/20-Y-222803	2022年7月17日	合格	 A photograph showing a worker wearing a pink hard hat, a white long-sleeved shirt, and light-colored pants. The worker is seated in the operator's seat of a piece of heavy machinery, possibly a forklift or a similar vehicle, and is looking down at a device or control panel. The background is slightly blurred, showing the interior of the machine. A yellow timestamp '2022/7/4' is visible in the bottom right corner of the image.
500	GX-B1423/20-Y-222804	2022年7月17日	合格	 A photograph of a large, dark-colored truck, likely a dump truck or a similar heavy-duty vehicle, parked on a dirt road. Several workers wearing hard hats and safety vests are standing near the front of the truck. The background shows a clear blue sky with some clouds and a flat, open landscape. A yellow timestamp '2022/7/4' is visible in the bottom right corner of the image.

501	GX-B1423/20-Y-222805	2022年7月17日	合格	
502	GX-B1423/20-Y-222806	2022年7月17日	合格	

503	GX-B1423/20-Y-222807	2022年7月17日	合格	
504	GX-B1423/20-Y-222808	2022年7月17日	合格	

505	GX-B1423/20-Y-222809	2022年7月17日	合格	 <p>A photograph showing a worker wearing a red hard hat and a grey uniform, seated in the operator's seat of a piece of heavy machinery, possibly a truck or a loader. The worker is looking towards the right side of the frame. A yellow timestamp '2022/7/4' is visible in the bottom right corner of the image.</p>
506	GX-B1423/20-Y-222810	2022年7月17日	合格	 <p>A photograph of a large, dark-colored truck, likely a dump truck or a similar heavy-duty vehicle, parked on a dirt or gravel surface. Two workers in safety gear are standing in front of the truck. The truck has 'HITACHI' visible on its side. A yellow timestamp '2022/7/4' is visible in the bottom right corner of the image.</p>

507	GX-B1423/20-Y-222811	2022年7月17日	合格	
508	GX-B1423/20-Y-222812	2022年7月17日	合格	

509	GX-B1423/20-Y-222813	2022年7月17日	合格	 A photograph showing a worker wearing a red hard hat, a white face mask, and a white uniform. The worker is seated in the driver's seat of a vehicle, holding a handheld electronic device (possibly a tablet or smartphone) and looking at the screen. The background is dark, suggesting an interior or a shaded area. A yellow timestamp "2022/7/5" is visible in the bottom right corner of the image.
510	GX-B1423/20-Y-222814	2022年7月17日	合格	 A photograph of a large, dark-colored truck, likely a dump truck, parked on a dirt road. The truck has "H&T125" written on the top of the cab and "065" on the front bumper. Two workers in safety gear (hard hats and high-visibility vests) are standing in front of the truck. The background shows a clear sky and some distant structures. A yellow timestamp "2022/7/5" is visible in the bottom right corner of the image.

511	GX-B1423/20-Y-222815	2022年7月17日	合格	
512	GX-B1423/20-Y-222816	2022年7月17日	合格	

513	GX-B1423/20-Y-222817	2022年7月17日	合格	
514	GX-B1423/20-Y-222818	2022年7月17日	合格	

515	GX-B1423/20-Y-222819	2022年7月17日	合格	
516	GX-B1423/20-Y-222820	2022年7月17日	合格	

517	GX-B1423/20-Y-222821	2022年7月17日	合格	
518	GX-B1423/20-Y-222822	2022年7月17日	合格	

519	GX-B1423/20-Y-222823	2022年7月17日	合格	
520	GX-B1423/20-Y-222824	2022年7月17日	合格	

521	GX-B1423/20-Y-222825	2022年7月17日	合格	 <p>A photograph of a large yellow HMT125 truck parked in a desert-like environment. Two workers wearing hard hats and safety vests are standing in front of the truck. The truck has 'HMT125' written on its side and '226' on the front. A yellow timestamp '2022/7/6' is visible in the bottom right corner of the image.</p>
522	GX-B1423/20-Y-222826	2022年7月17日	合格	 <p>A photograph showing a worker in a red hard hat and safety gear operating a piece of heavy machinery. The worker is wearing a blue face mask and is focused on the controls. A yellow timestamp '2022/7/6' is visible in the bottom right corner of the image.</p>

523	GX-B1423/20-Y-222827	2022年7月17日	合格	
524	GX-B1423/20-Y-222828	2022年7月17日	合格	

525	GX-B1423/20-Y-222829	2022年7月17日	合格	
526	GX-B1423/20-Y-222830	2022年7月17日	合格	

527	GX-B1423/20-Y-222831	2022年7月17日	合格	
528	GX-B1423/20-Y-222832	2022年7月17日	合格	

529	GX-B1423/20-Y-222833	2022年7月17日	合格	
530	GX-B1423/20-Y-222834	2022年7月17日	合格	

531	GX-B1423/20-Y-222835	2022年7月17日	合格	
532	GX-B1423/20-Y-222836	2022年7月17日	合格	

533	GX-B1423/20-Y-222837	2022年7月17日	合格	
534	GX-B1423/20-Y-222838	2022年7月17日	合格	

535	GX-B1423/20-Y-222839	2022年7月17日	合格	 A photograph showing a worker wearing a red hard hat, a blue face mask, and a white uniform, sitting in the driver's seat of a vehicle. The worker is holding the steering wheel. The date '2022/7/17' is visible in the bottom right corner of the image.
536	GX-B1423/20-Y-222840	2022年7月17日	合格	 A photograph showing three workers in blue uniforms and hard hats standing in front of a large truck. The workers are wearing blue face masks. The date '2022/7/17' is visible in the bottom right corner of the image.

537	GX-B1423/20-Y-222841	2022年7月17日	合格	
538	GX-B1423/20-Y-222842	2022年7月17日	合格	

539	GX-B1423/20-Y-222843	2022年7月17日	合格	
540	GX-B1423/20-Y-222844	2022年7月17日	合格	

541	GX-B1423/20-Y-222845	2022年7月17日	合格	
542	GX-B1423/20-Y-222846	2022年7月17日	合格	

543	GX-B1423/20-Y-222847	2022年7月17日	合格	
544	GX-B1423/20-Y-222848	2022年7月17日	合格	

545	GX-B1423/20-Y-222849	2022年7月17日	合格	
546	GX-B1423/20-Y-222850	2022年7月17日	合格	

547	GX-B1423/20-Y-222851	2022年7月17日	合格	
548	GX-B1423/20-Y-222852	2022年7月17日	合格	


549	GX-B1423/20-Y-222853	2022年7月17日	合格	
550	GX-B1423/20-Y-222854	2022年7月17日	合格	

551	GX-B1423/20-Y-222855	2022年7月17日	合格	
552	GX-B1423/20-Y-222856	2022年7月17日	合格	

553	GX-B1423/20-Y-222857	2022年7月17日	合格	
554	GX-B1423/20-Y-222858	2022年7月17日	合格	

555	GX-B1423/20-Y-222859	2022年7月17日	合格	 A yellow Komatsu WT160 truck with the number 087 on the front. Two workers in safety gear are standing in front of the truck. The date 2022/7/9 is visible in the bottom right corner of the photo.
556	GX-B1423/20-Y-222860	2022年7月17日	合格	 A yellow Komatsu WT160 truck with the number 088 on the front. A worker in safety gear is kneeling in front of the truck. The date 2022/7/9 is visible in the bottom right corner of the photo.

557	GX-B1423/20-Y-222861	2022年7月17日	合格	 A yellow dump truck with the number 089 on the front, parked on a dirt surface. Two workers in safety gear are standing in front of it. The truck has 'WT100F3' written on the top of the dump body. A yellow timestamp '2022/7/9' is visible in the bottom right corner of the photo.
558	GX-B1423/20-Y-222862	2022年7月17日	合格	 A yellow dump truck with the number 090 on the front, parked on a dirt surface. Two workers in safety gear are standing in front of it. The truck has 'WT100F3' written on the top of the dump body. A yellow timestamp '2022/7/9' is visible in the bottom right corner of the photo.

559	GX-B1423/20-Y-222863	2022年7月17日	合格	
560	GX-B1423/20-Y-222864	2022年7月17日	合格	
561	GX-B1423/20-Y-222865	2022年7月17日	合格	

562	GX-B1423/20-Y-222866	2022年7月17日	合格	
563	GX-B1423/20-Y-222867	2022年7月17日	合格	
564	GX-B1423/20-Y-222868	2022年7月17日	合格	

565	GX-B1423/20-Y-222869	2022年7月17日	合格	 <p>A yellow dump truck with the number 23 on its side is parked on a dirt surface. Two workers in high-visibility vests and hard hats stand in front of the truck. A yellow timestamp '2022/7/10' is visible in the bottom right corner of the photo.</p>
566	GX-B1423/20-Y-222870	2022年7月17日	合格	 <p>A yellow dump truck with the number 21 on its side is parked on a dirt surface. Two workers in high-visibility vests and hard hats stand in front of the truck. A yellow timestamp '2022/7/10' is visible in the bottom right corner of the photo.</p>
567	GX-B1423/20-Y-222871	2022年7月17日	合格	 <p>A yellow dump truck with the number 21 on its side is parked on a dirt surface. Two workers in high-visibility vests and hard hats stand in front of the truck. A yellow timestamp '2022/7/10' is visible in the bottom right corner of the photo.</p>

568	GX-B1423/20-Y-222872	2022年7月17日	合格	
569	GX-B1423/20-Y-222873	2022年7月17日	合格	
570	GX-B1423/20-Y-222874	2022年7月17日	合格	

571	GX-B1423/20-Y-222875	2022年7月17日	合格	
572	GX-B1423/20-Y-222876	2022年7月17日	合格	
573	GX-B1423/20-Y-222877	2022年7月17日	合格	

574	GX-B1423/20-Y-222878	2022年7月17日	合格	
575	GX-B1423/20-Y-222879	2022年7月17日	合格	
576	GX-B1423/20-Y-222880	2022年7月17日	合格	

577	GX-B1423/20-Y-222881	2022年7月17日	合格	
578	GX-B1423/20-Y-222882	2022年7月17日	合格	
579	GX-B1423/20-Y-222883	2022年7月17日	合格	

580	GX-B1423/20-Y-222884	2022年7月17日	合格	
581	GX-B1423/20-Y-222885	2022年7月17日	合格	
582	GX-B1423/20-Y-222886	2022年7月17日	合格	

583	GX-B1423/20-Y-222887	2022年7月17日	合格	 A yellow MT860 dump truck is parked on a dirt surface. Two workers wearing hard hats and safety vests are standing in front of the truck. The license plate number 182 is visible on the side of the truck. A yellow timestamp '2022/7/12' is in the bottom right corner.
584	GX-B1423/20-Y-222888	2022年7月17日	合格	 A yellow MT860 dump truck is parked on a dirt surface. Two workers wearing hard hats and safety vests are standing in front of the truck. The license plate number 190 is visible on the side of the truck. A yellow timestamp '2022/7/12' is in the bottom right corner.
585	GX-B1423/20-Y-222889	2022年7月17日	合格	 A yellow MT860 dump truck is parked on a dirt surface. Two workers wearing hard hats and safety vests are standing in front of the truck. The license plate number 181 is visible on the side of the truck. A yellow timestamp '2022/7/12' is in the bottom right corner.

586	GX-B1423/20-Y-222890	2022年7月17日	合格	 <p>A close-up photograph of a worker wearing a red hard hat, a white face mask, and a high-visibility yellow vest, sitting in the driver's seat of a large yellow mining truck. The worker is looking forward, and the truck's steering wheel and dashboard are visible. A yellow timestamp '2022/7/12' is in the bottom right corner.</p>
587	GX-B1423/20-Y-222891	2022年7月17日	合格	 <p>A photograph of a yellow TONLY 163 mining truck parked on a dirt road. Two workers in high-visibility vests and hard hats are standing in front of the truck. The truck has 'TONLY' and '163' written on its side. A yellow timestamp '2022/7/12' is in the bottom right corner.</p>
588	GX-B1423/20-Y-222892	2022年7月17日	合格	 <p>A photograph of a yellow mining truck parked on a dirt road. A worker in a high-visibility vest and hard hat is standing next to the truck. The truck is facing the camera. A yellow timestamp '2022/7/12' is in the bottom right corner.</p>

589	GX-B1423/20-Y-222893	2022年7月17日	合格	
590	GX-B1423/20-Y-222894	2022年7月17日	合格	
591	GX-B1423/20-Y-222895	2022年7月17日	合格	