





序号	报告编号	发布日期	结论	影像资料
1	GX-B1321/20-5-22532-22534	2022-8-1	本次共检电力电缆3条，3条电力电缆所检项目合格。	
2	GX-B1321/20-5-22538	2022. 8. 3	所检项目合格	
3	GX-B1321/20-5-22535~22537	2022. 8. 4	所检项目合格	

4	GX-B1300/20-5-22017	2022/8/3	合格	 A worker wearing a red hard hat and a grey uniform with a logo is operating a green industrial machine. The machine has several bolts and a control panel. The worker is looking down at the machine.
5	GX-B1381/20-5-22024	2022/8/3	合格	 A worker wearing a red hard hat and a black shirt is standing in a tunnel. The worker is holding a device and looking at it. The tunnel has many cables and pipes hanging from the ceiling. The floor is concrete with yellow markings. The date '2022年5月24日' is visible in the bottom right corner of the image. <p data-bbox="1608 1050 1854 1070">2022年5月24日</p>

6	GX-B1358/21-5-22003	2022-8-3	所检项目合格。	 <p>A photograph showing a person in a dark environment, possibly a control room or a confined space, working on a piece of equipment. A sign above the person reads "闲人免进" (No Entry). The date "2022/7/12" is visible in the bottom right corner of the image.</p>
7	GX-B1404/20-5-22030	2022-8-4	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合 GB/T 14549-1993 《电能质量 公用电网谐波》要求。	 <p>A photograph showing a person standing next to a control panel or piece of equipment in a room with green flooring. The person is wearing a black shirt and glasses. The date "2022/7/10" is visible in the bottom right corner of the image.</p>

8	GX-B1404/20-5-22031	2022-8-4	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合 GB/T 14549-1994 《电能质量 公用电网谐波》要求。	
9	GX-B1404/20-5-22032	2022-8-4	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合 GB/T 14549-1995 《电能质量 公用电网谐波》要求。	


10	GX-B1404/20-5-22033	2022-8-4	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合 GB/T 14549-1996 《电能质量 公用电网谐波》要求。	 <p>2022/7/10</p>
11	GX-B1404/20-5-22034	2022-8-4	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合 GB/T 14549-1997 《电能质量 公用电网谐波》要求。	 <p>2022/7/10</p>

12	GX-B1404/20-5-22035	2022-8-4	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合 GB/T 14549-1998 《电能质量 公用电网谐波》要求。	 A photograph showing a person in a black t-shirt and dark pants standing in a control room. They are positioned next to a wooden step ladder and a piece of electrical equipment. The room contains several large white electrical cabinets with various meters and switches. A date stamp '2022/7/11' is visible in the bottom right corner of the photo.
13	GX-B1404/20-5-22036	2022-8-4	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合 GB/T 14549-1999 《电能质量 公用电网谐波》要求。	 A photograph showing a person in a grey short-sleeved shirt and dark pants standing in a control room. They are positioned next to a wooden step ladder and a piece of electrical equipment. The room contains several large white electrical cabinets with various meters and switches. A date stamp '2022/7/11' is visible in the bottom right corner of the photo.

14	GX-B1312/20-5-22450	2022. 8. 4	所检项目合格	
15	GX-B1380/20-5-22007	2022/8/5	所检项目合格。	
16	GX-B1418/22-5-22001	2022/8/5	所检项目合格。	

17	GX-B1424/20-5-22012	2022. 8. 5	合格	 2022-7-17
18	GX-B1424/20-5-22013	2022. 8. 5	合格	 2022-7-17
19	GX-B1424/20-5-22014	2022. 8. 5	合格	 2022-7-17

20	GX-B1424/20-5-22015	2022. 8. 5	合格	 <p>2022-7-17</p>
21	GX-B1424/20-5-22016	2022. 8. 5	合格	 <p>2022-7-17</p>
22	GX-B1310/21-5- 22213	2022/8/3	合格	 <p>2022/7/12</p>
23	GX-B1310/21-5- 22214	2022/8/3	合格	 <p>2022/7/12</p>

24	GX-B1428/21-5- 22030	2022/8/3	合格	
25	GX-B1428/21-5- 22031	2022/8/3	合格	