





序号	报告编号	发布日期	结论	影像资料
222	GX-B1305/21-1-22005	2022/8/26	合格	 A photograph showing the interior of a tunnel. Several workers wearing red safety vests and white hard hats are visible. They are standing on a metal walkway or platform. In the background, there is a large piece of machinery, possibly a conveyor belt or a large fan, with a green cover. The tunnel walls are rough and rocky. A yellow timestamp '2022/7/5' is visible in the bottom right corner of the image.
223	GX-B1305/21-1-22006	2022/8/26	合格	 A photograph showing the interior of a tunnel. A worker in a red safety vest and white hard hat is visible, standing on a metal walkway. The walkway has a metal railing. In the background, there is a large piece of machinery, possibly a conveyor belt or a large fan, with a green cover. The tunnel walls are rough and rocky. A yellow timestamp '2022/7/6' is visible in the bottom right corner of the image.

224	GX-B1520/20-1-22023	2022/8/26	合格	
225	GX-B1520/20-1-22024	2022/8/26	合格	

226	GX-B1520/20-1-22025	2022/8/26	合格	
227	GX-B1520/20-1-22026	2022/8/26	合格	

228	GX-B1520/20-1-22027	2022/8/26	合格	
229	GX-B1520/20-1-22028	2022/8/26	合格	

230	GX-B1520/20-1-22029	2022/8/26	合格	
231	GX-B1520/20-1-22030	2022/8/26	合格	

232	GX-B1520/20-1-22031	2022/8/26	合格	
233	GX-B1520/20-1-22032	2022/8/26	合格	

234	GX-B1451/20-1-22477~22484	2022/8/26	合格	
235	GX-B1322/21-1-22140~22144	2022/8/26	合格	

236	GX-B1332/21-1-22073~22078	2022/8/26	合格	
237	GX-B1423/20-1-22257	2022/8/29	合格	
238	GX-B1423/20-1-22258	2022/8/29	合格	



239	GX-B1423/20-1-22259	2022/8/29	合格	
240	GX-B1423/20-1-22260	2022/8/29	合格	
241	GX-B1423/20-1-22261	2022/8/29	合格	

242	GX-B1423/20-1-22262	2022/8/29	合格	
243	GX-B1423/20-1-22263	2022/8/29	合格	
244	GX-B1423/20-1-22264	2022/8/29	合格	

245	GX-B1423/20-1-22265	2022/8/29	合格	
246	GX-B1423/20-1-22266	2022/8/29	合格	
247	GX-B1423/20-1-22267	2022/8/29	合格	

248	GX-B1423/20-1-22268	2022/8/29	合格	
-----	---------------------	-----------	----	---