

序号	报告编号	发布日期	结论	影像资料
95	GX-B1328/20-4-22167	2022. 9. 21	合格	
96	GX-B1328/20-4-22168	2022. 9. 21	合格	

97	GX-B1328/20-4-22169	2022. 9. 21	合格	
98	GX-B1328/20-4-22170	2022. 9. 21	合格	
99	GX-B1310/21-4-22138	2022. 9. 23	合格	

100	GX-B1310/21-4-22135 ~22137	2022. 9. 23	合格	
101	GX-B1380/20-4-22008	2022. 9. 26	合格	
102	GX-B1380/20-4-22009	2022. 9. 26	合格	

103	GX-B1380/20-4-22010	2022. 9. 26	合格	
104	GX-B1423/20-4-22215	2022. 9. 28	合格	
105	GX-B1423/20-4-22216	2022. 9. 28	合格	

106	GX-B1423/20-4-22217	2022. 9. 28	合格	
107	GX-B1423/20-4-22218	2022. 9. 28	合格	
108	GX-B1423/20-4-22219	2022. 9. 28	合格	




109	GX-B1423/20-4-22220	2022. 9. 28	合格	
110	GX-B1423/20-4-22221	2022. 9. 28	合格	
111	GX-B1423/20-4-22222	2022. 9. 28	合格	

112	GX-B1423/20-4-22223	2022. 9. 28	合格	
113	GX-B1423/20-4-22224	2022. 9. 28	合格	
114	GX-B1423/20-4-22225	2022. 9. 28	合格	

115	GX-B1423/20-4-22226	2022. 9. 28	合格	
116	GX-B1423/20-4-22227	2022. 9. 28	合格	
117	GX-B1423/20-4-22228	2022. 9. 28	合格	

118	GX-B1423/20-4-22229	2022. 9. 28	合格	 <p>A yellow dump truck with the number '15' on the door. Two workers in safety gear are standing in front of it. A red date stamp '2022.9.20' is in the bottom right corner.</p>
119	GX-B1423/20-4-22230	2022. 9. 28	合格	 <p>A red dump truck with a white cab. Two workers in safety gear are standing in front of it. A red date stamp '2022.9.20' is in the bottom right corner.</p>
120	GX-B1499/21-4-22120	2022. 9. 29	合格	 <p>A close-up view of the engine compartment of a vehicle, showing various mechanical parts. A yellow date stamp '2022.9.9' is in the bottom right corner.</p>

121	GX-B1499/21-4-22121	2022. 9. 29	合格	
122	GX-B1499/21-4-22122	2022. 9. 29	合格	
123	GX-B1350/21-4-22188	2022. 9. 29	合格	

124	GX-B1451/20-4-221626	2022. 9. 30	合格	
125	GX-B1313/21-4-22515	2022. 9. 30	合格	
126	GX-B1451/20-4-221627	2022. 9. 30	合格	

127	GX-B1313/21-4-22516	2022. 9. 30	合格	
128	GX-B1310/21-4-22140	2022. 9. 30	符合标准要求	
129	GX-B1310/21-4-22139	2022. 9. 29	符合标准要求	

130	GX-B1303/21-4-22003	2022. 9. 30	所检项目合格	
131	GX-B1303/21-4-22003	2022. 9. 30	所检项目合格	
132	GX-B1310/21-4-22121	2022. 9. 30	符合标准要求	

133	GX-B1310/21-4-22122	2022. 9. 30	符合标准要求	
134	GX-B1310/21-4-22123	2022. 9. 30	符合标准要求	
135	GX-B1310/21-4-22124	2022. 9. 30	符合标准要求	

136	GX-B1310/21-4-22125	2022. 9. 30	符合标准要求	
137	GX-B1310/21-4-22126	2022. 9. 30	符合标准要求	
138	GX-B1310/21-4-22127	2022. 9. 30	符合标准要求	

139	GX-B1310/21-4-22128	2022. 9. 30	符合标准要求	
140	GX-B1310/21-4-22129	2022. 9. 30	符合标准要求	
141	GX-B1310/21-4-22130	2022. 9. 30	符合标准要求	

142	GX-B1310/21-4-22131	2022. 9. 30	符合标准要求	
143	GX-B1310/21-4-22132	2022. 9. 30	符合标准要求	
144	GX-B1310/21-4-22133	2022. 9. 30	符合标准要求	

145	GX-B1310/21-4-22134	2022. 9. 30	符合标准要求	
-----	---------------------	-------------	--------	---