

序号	报告编号	发布日期	结论	影像资料
1	GX-B1341/21-8-22121	2022. 12. 8	综合判定：合格	 <p>A photograph showing the interior of a tunnel. Several workers in safety gear are visible near a large circular fan or ventilation equipment. The timestamp at the bottom right of the image is 2022-04-17 11:10.</p>
2	GX-B1341/21-8-22122	2022. 12. 8	综合判定：合格	 <p>A photograph of a room labeled '主扇风机硐室' (Main Fan Room). A worker is visible near a large fan. The timestamp at the bottom right of the image is 2022-04-17 09:20.</p>
3	GX-B1340/21-8-22092	2022年12月8日	<p>该通风机共测试4个状态（运行双级、叶片角度$+6^{\circ}$ /$+6^{\circ}$：运行频率分别为38Hz、40Hz、42Hz、44Hz），所检项目合格。</p>	 <p>A photograph showing two men standing next to a large blue industrial fan. One man is wearing a red hard hat and a grey work jacket, while the other is in a dark jacket. The timestamp at the bottom right of the image is 2022.11.25.</p>