




序号	报告编号	发布日期	结论	影像资料
48	GX-B1339/21-1-23007	2023/3/9	所检项目合格	 A photograph showing a worker in a grey jacket and dark pants kneeling in a concrete trench. The worker is holding a yellow handheld device, possibly a gas detector or measuring instrument, and appears to be inspecting the trench. The date '2023 03 09' is visible in the bottom right corner of the photo.
49	GX-B1339/21-1-23008	2023/3/9	所检项目合格	 A photograph showing a worker in a grey jacket and dark pants leaning into a concrete trench. The worker is inspecting the interior of the trench. The date '2023 03 09' is visible in the bottom right corner of the photo.
50	GX-B1339/21-1-23009	2023/3/9	所检项目合格	 A photograph showing a worker in a grey jacket and dark pants sitting on the edge of a concrete trench. The worker is looking towards the camera. The date '2023 03 09' is visible in the bottom right corner of the photo.

51	GX-B1339/21-1-23010	2023/3/9	所检项目合格	
52	GX-B1339/21-1-23011	2023/3/9	所检项目合格	
53	GX-B1339/21-1-23012	2023/3/9	所检项目合格	

54	GX-B1339/21-1-23013	2023/3/9	所检项目合格	
55	GX-B1339/21-1-23014	2023/3/9	所检项目合格	
56	GX-B1339/21-1-23015	2023/3/9	所检项目合格	

57	GX-B1339/21-1-23016	2023/3/9	所检项目合格	
58	GX-B1451/20-1-23023~23053	2023/3/8	所检项目合格	
59	GX-B1451/20-1-23054~23079	2023/3/8	所检项目合格	

60	GX-B1451/20-1-23080~23109	2023/3/8	所检项目合格	
61	GX-B1451/20-1-23110~23118	2023/3/8	所检项目合格	
62	GX-B1451/20-1-23119~23138	2023/3/8	所检项目合格	

63	GX-B1451/20-1-23139~23160	2023/3/8	所检项目合格	
64	GX-B1328/20-1-23001	2023. 3. 10	本次共检绝缘手套6只，6只所检项目合格。	
65	GX-B1328/20-1-23002	2023. 3. 10	本次共检绝缘鞋6只，6只所检项目合格。	

66	GX-B1328/20-1-23003	2023. 3. 10	所检项目合格。			
67	GX-B1328/20-1-23004	2023. 3. 10	所检项目合格。			
68	GX-B1328/20-1-23005	2023. 3. 10	本次共检绝缘手套120只，120只所检项目合格。			

69	GX-B1322/21-1-23021~23035	2023. 3. 10	本次共检验电力电缆15条，15条所检项目合格。	
70	GX-B1322/21-1-23036~23047	2023. 3. 10	本次共检验电力电缆12条，12条所检项目合格。	
71	GX-B1322/21-1-23048~23056	2023. 3. 10	本次共检验电力电缆9条，9条所检项目合格。	

72	GX-B1322/21-1-23057~23062	2023. 3. 10	本次共检验电力电缆6条，6条所检项目合格。	
73	GX-B1307/20-1-23031	2023/3/10	综合判定：合格。	
74	GX-B1307/20-1-23032	2023/3/10	综合判定：合格。	

75	GX-B1307/20-1-23033	2023/3/10	综合判定：合格。	
76	GX-B1307/20-1-23034	2023/3/10	综合判定：合格。	
77	GX-B1423/20-1-23011	2023/3/10	综合判定：合格	

78	GX-B1423/20-1-23012	2023/3/10	综合判定：合格	
79	GX-B1423/20-1-23013	2023/3/10	综合判定：合格	
80	GX-B1423/20-1-23014	2023/3/10	综合判定：合格	

81	GX-B1423/20-1-23015	2023/3/10	综合判定：合格	
82	GX-B1423/20-1-23016	2023/3/10	综合判定：合格	
83	GX-B1423/20-1-23017	2023/3/10	综合判定：合格	

84	GX-B1520/20-1-23006	2023/3/10	综合判定：合格			
85	GX-B1309/21-1-23006	2023. 3. 10	所检项目合格。			
86	GX-B1500/21-1-23021	2023. 3. 10	综合判定：合格。 。			

87	GX-B1500/21-1-23022	2023. 3. 10	综合判定：合格。 。	
88	GX-B1500/21-1-23023	2023. 3. 10	综合判定：合格。 。	
89	GX-B1423/20-1-23035	2023/3/10	综合判定：合格	

90	GX-B1423/20-1-23036	2023/3/10	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Three workers wearing hard hats and safety vests are standing in front of it. One worker is holding a clipboard. A small blue and white equipment case is on the ground in the foreground.
91	GX-B1423/20-1-23037	2023/3/10	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Three workers wearing hard hats and safety vests are standing in front of it. The truck has 'TONLY' written on its side. The background shows a rocky hillside.
92	GX-B1423/20-1-23038	2023/3/10	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Three workers wearing hard hats and safety vests are standing in front of it. The truck has 'TONLY' written on its side. The background shows a rocky hillside.

93	GX-B1423/20-1-23039	2023/3/10	综合判定：合格	
94	GX-B1339/21-1-23007	2023/3/9	所检项目合格	
95	GX-B1339/21-1-23008	2023/3/9	所检项目合格	

96	GX-B1339/21-1-23009	2023/3/9	所检项目合格	
97	GX-B1339/21-1-23010	2023/3/9	所检项目合格	
98	GX-B1339/21-1-23011	2023/3/9	所检项目合格	


99	GX-B1339/21-1-23012	2023/3/9	所检项目合格	
100	GX-B1339/21-1-23013	2023/3/9	所检项目合格	
101	GX-B1339/21-1-23014	2023/3/9	所检项目合格	

102	GX-B1339/21-1-23015	2023/3/9	所检项目合格	
103	GX-B1339/21-1-23016	2023/3/9	所检项目合格	
104	GX-B1339/21-1-23017	2023/3/13	所检项目合格	

105	GX-B1339/21-1-23018	2023/3/13	所检项目合格	
106	GX-B1339/21-1-23019	2023/3/13	所检项目合格	
107	GX-B1339/21-1-23020	2023/3/13	所检项目合格	

108	GX-B1339/21-1-23021	2023/3/13	所检项目合格	
109	GX-B1339/21-1-23022	2023/3/13	所检项目合格	
110	GX-B1424/20-1-23002	2023/3/13	依据NB/T 10176-2019 综 合判定合格	

111	GX-B1424/20-1-23003	2023/3/13	依据NB/T 10176-2019 综 合判定合格	 A photograph showing several workers in dark blue uniforms and hard hats (yellow and blue) inspecting a large, white, cylindrical piece of machinery inside a tunnel. The scene is dimly lit with overhead lights. A timestamp '81 50 6505' is visible in the bottom left corner.
112	GX-B1424/20-1-23004	2023/3/13	依据NB/T 10176-2019 综 合判定合格	 A photograph showing workers in a tunnel. One worker in the foreground is wearing a red hard hat and a blue uniform, pointing towards the machinery. Another worker in a blue uniform and red hard hat is visible in the background. The scene is dimly lit. A timestamp '81 50 7505' is visible in the bottom left corner.
113	GX-B1424/20-1-23005	2023/3/13	依据NB/T 10176-2019 综 合判定合格	 A photograph showing a worker in a blue uniform and red hard hat standing in a tunnel, holding a flashlight. The worker is looking towards the camera. The background shows the tunnel structure and some machinery. A timestamp '81 50 6505' is visible in the bottom left corner.

114	GX-B1424/20-1-23006	2023/3/13	依据NB/T 10176-2019 综 合判定合格	
115	GX-B1424/20-1-23007	2023/3/13	依据NB/T 10176-2019 综 合判定合格	
116	GX-B1424/20-1-23008	2023/3/13	依据NB/T 10176 综合判定合格； 依据MT/T 220- 1990所检项目合 格	