

序号	报告编号	发布日期	结论	影像资料
1	GX-B1423/20-Y-231017	2023年4月2日	综合判定：合格	
2	GX-B1423/20-Y-231018	2023年4月2日	综合判定：合格	

3	GX-B1423/20-Y-231019	2023年4月2日	综合判定：合格	 A yellow dump truck with the number '1139' on its side is parked on a dirt surface. Two workers in safety vests are standing next to it. A red and white traffic cone is visible in the foreground. The date '2023/2/24' is printed in the bottom right corner of the photo.
4	GX-B1423/20-Y-231020	2023年4月2日	综合判定：合格	 A yellow dump truck with the number '1139' on its side is parked on a dirt surface. Two workers in safety vests are standing next to it. A red and white traffic cone is visible in the foreground. The date '2023/2/24' is printed in the bottom right corner of the photo.

5	GX-B1423/20-Y-231021	2023年4月2日	综合判定：合格	 A yellow dump truck with the number 161 on its side is parked on a gravel surface. Two workers in high-visibility vests are standing near the front of the truck. A red and white traffic cone is visible in the foreground. A yellow timestamp '2023/4/2' is in the bottom right corner.
6	GX-B1423/20-Y-231022	2023年4月2日	综合判定：合格	 A yellow dump truck with the number 145 on its side is parked on a gravel surface. Two workers in high-visibility vests are standing near the front of the truck. A red and white traffic cone is visible in the foreground. A yellow timestamp '2023/4/2' is in the bottom right corner.


7	GX-B1423/20-Y-231023	2023年4月2日	综合判定：合格	
8	GX-B1423/20-Y-231024	2023年4月2日	综合判定：合格	

9	GX-B1423/20-Y-231025	2023年4月2日	综合判定：合格	 A yellow dump truck with the number 52 on its side is parked on a dirt surface. Two workers in blue and white uniforms and yellow hard hats are standing next to the truck. A date stamp '2023/2/21' is visible in the bottom right corner of the photo.
10	GX-B1423/20-Y-231026	2023年4月2日	综合判定：合格	 A yellow dump truck with the number 56 on its side is parked on a dirt surface. Two workers in blue and white uniforms and yellow hard hats are standing next to the truck. A traffic cone and a laptop are on the ground in front of the truck. A date stamp '2023/2/21' is visible in the bottom right corner of the photo.

11	GX-B1423/20-Y-231027	2023年4月2日	综合判定：合格	 A yellow dump truck with the number 53 on its side is parked on a dirt surface. Two workers wearing hard hats and safety vests are standing next to the truck. A date stamp '2023/2/21' is visible in the bottom right corner of the photo.
12	GX-B1423/20-Y-231028	2023年4月2日	综合判定：合格	 A yellow dump truck with the number 55 on its side is parked on a dirt surface. Two workers wearing hard hats and safety vests are standing next to the truck. A date stamp '2023/2/21' is visible in the bottom right corner of the photo.



13	GX-B1423/20-Y-231029	2023年4月2日	综合判定：合格	
14	GX-B1423/20-Y-231030	2023年4月2日	综合判定：合格	

15	GX-B1423/20-Y-231031	2023年4月2日	综合判定：合格	 A yellow dump truck with the number 49 on its side is parked on a dirt surface. Two workers in high-visibility vests and hard hats are standing near the front of the truck. A traffic cone and a small equipment case are on the ground. The date 2023/2/21 is visible in the bottom right corner of the photo.
16	GX-B1423/20-Y-231032	2023年4月2日	综合判定：合格	 A yellow dump truck with the number 42 on its side is parked on a dirt surface. Two workers in high-visibility vests and hard hats are standing near the front of the truck. The date 2023/2/21 is visible in the bottom right corner of the photo.



17	GX-B1423/20-Y-231033	2023年4月2日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers in safety gear are standing near the front wheel. A toolbox is on the ground. A date stamp '2023/2/21' is visible in the bottom right corner of the photo.
18	GX-B1423/20-Y-231034	2023年4月2日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers in safety gear are standing near the front wheel. A toolbox is on the ground. A date stamp '2023/2/21' is visible in the bottom right corner of the photo.

19	GX-B1423/20-Y-231035	2023年4月2日	综合判定：合格	
20	GX-B1423/20-Y-231036	2023年4月2日	综合判定：合格	

21	GX-B1423/20-Y-231037	2023年4月2日	综合判定：合格	
22	GX-B1423/20-Y-231038	2023年4月2日	综合判定：合格	

23	GX-B1423/20-Y-231039	2023年4月2日	综合判定：合格	
24	GX-B1423/20-Y-231040	2023年4月2日	综合判定：合格	

25	GX-B1423/20-Y-231041	2023年4月2日	综合判定：合格	
26	GX-B1423/20-Y-231042	2023年4月2日	综合判定：合格	

27	GX-B1423/20-Y-231043	2023年4月2日	综合判定：合格	
28	GX-B1423/20-Y-231044	2023年4月2日	综合判定：合格	

29	GX-B1423/20-Y-231045	2023年4月2日	综合判定：合格	
30	GX-B1557/22-Y-23004	2023年4月4日	所检项目合格。	