

序号	报告编号	发布日期	结论	影像资料
356	GX-B1557/22-Y-23004	2023年4月1日	所检项目合格。	
357	GX-B1522/20-Y-23035	2023年4月4日	所检项目合格。	

358	GX-B1522/20-Y-23036	2023年4月4日	所检项目合格。	
359	GX-B1499/21-Y-23040	2023年4月3日	所检项目合格。	

360	GX-B1499/21-Y-23041	2023年4月3日	所检项目合格。	
361	GX-B1499/21-Y-23042	2023年4月3日	所检项目合格。	

362	GX-B1328/20-Y-23039	2023年4月3日	本次共检绝缘手套30只，30只绝缘手套所检项目合格	
363	GX-B1328/20-Y-23040	2023年4月3日	所检项目合格。	

364	GX-B1328/20-Y-23041	2023年4月3日	所检项目合格。	
365	GX-B1499/21-Y-23037	2023年4月4日	所检项目合格。	

366	GX-B1499/21-Y-23038	2023年4月4日	所检项目合格。	
367	GX-B1499/21-Y-23039	2023年4月4日	所检项目合格。	

368	GX-B1308/21-Y-23005	2023年4月4日	所检项目合格。	 A photograph showing a worker in a dark environment, possibly a tunnel or confined space, using a bright flashlight to inspect a component. The worker is wearing a dark jacket and a headlamp. The date stamp '2023/3/6' is visible in the bottom right corner of the image.
369	GX-B1306/21-Y-23043	2023年4月4日	所检项目合格。	 A photograph showing a worker in a red hard hat and dark jacket inspecting equipment in a control room. The worker is holding a device, possibly a handheld terminal or a camera. The date stamp '2023/3/6' is visible in the bottom right corner of the image.

370	GX-B1306/21-Y-23044	2023年4月4日	所检项目合格。	 A worker in a blue uniform and red helmet is inspecting a large industrial compressor unit. The unit is grey and has "Atlas Copco" written on it. The worker is holding a tool and looking at the unit. A date stamp "2023/3/8" is visible in the bottom right corner of the photo.
371	GX-B1306/21-Y-23040	2023年4月4日	所检项目合格。	 Two workers in blue uniforms and red helmets are inspecting a large white industrial cabinet. One worker is pointing at the cabinet while the other stands nearby. The cabinet has a red circle with the number "1" on it. A date stamp "2023/3/6" is visible in the bottom right corner of the photo.
372	GX-B1306/21-Y-23041	2023年4月4日	所检项目合格。	 A worker in a blue uniform and red helmet is inspecting a large white industrial cabinet. The cabinet has a red circle with the number "2" on it. A date stamp "2023/3/6" is visible in the bottom right corner of the photo.

373	GX-B1306/21-Y-23042	2023年4月4日	所检项目合格。	 <p>2023/3/6</p>
374	GX-B1515/22-Y-23006	2023年4月4日	所检项目合格。	 <p>2023/3/6</p>
375	GX-B1404/20-Y-23003	2023年4月4日	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求	 <p>2023/3/12</p>

376	GX-B1404/20-Y-23004	2023年4月4日	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1994 《电能质量 公用电网谐波》要求	 A worker in a white protective suit and red helmet is working on electrical equipment in a control room. The worker is standing next to a yellow step ladder. The date stamp in the bottom right corner of the photo is 2023-3-13.
377	GX-B1339/21-Y-23009	2023年4月4日	所检项目合格。	 A worker in a blue uniform and red helmet is standing next to a large red industrial tank. The worker is wearing a face mask. The date stamp in the bottom right corner of the photo is 2023-3-6.
378	GX-B1339/21-Y-23010	2023年4月4日	所检项目合格。	 Two workers in red helmets are working on a green pipe in a utility room. One worker is kneeling and the other is standing. A toolbox is open on the floor in front of them. The date stamp in the bottom right corner of the photo is 2023-3-6.

379	GX-B1423/20-Y-23720	2023年4月2日	综合判定：合格	 A yellow dump truck with the number '1281' on its side. Two workers in high-visibility vests are standing near the front wheel. The truck is parked on a dirt surface. A date stamp '2023/3/9' is visible in the bottom right corner of the image.
380	GX-B1423/20-Y-23721	2023年4月2日	综合判定：合格	 A yellow dump truck with the number '195' on its side. Two workers in high-visibility vests are standing near the front wheel. The truck is parked on a dirt surface. A date stamp '2023/3/9' is visible in the bottom right corner of the image.

381	GX-B1423/20-Y-23722	2023年4月2日	综合判定：合格	
382	GX-B1423/20-Y-23723	2023年4月2日	综合判定：合格	

383	GX-B1423/20-Y-23724	2023年4月2日	综合判定：合格	 A yellow XG106 truck is parked on a dirt surface. Two workers in high-visibility vests and hard hats stand in front of the truck. A traffic cone is visible on the ground. The license plate reads X1201. The date 2023/3/9 is visible in the bottom right corner of the photo.
384	GX-B1423/20-Y-23725	2023年4月2日	综合判定：合格	 A yellow XG106 truck is parked on a dirt surface. Two workers in high-visibility vests and hard hats stand in front of the truck. A traffic cone is visible on the ground. The license plate reads X1275. The date 2023/3/9 is visible in the bottom right corner of the photo.

385	GX-B1423/20-Y-23726	2023年4月2日	综合判定：合格	 <p>A yellow XG10E truck with license plate X191 is parked on a dirt surface. Two workers wearing high-visibility vests and hard hats stand in front of the truck. A date stamp '2023/3/9' is visible in the bottom right corner of the photo.</p>
386	GX-B1423/20-Y-23727	2023年4月2日	综合判定：合格	 <p>A yellow XG10E truck with license plate X1216 is parked on a dirt surface. Two workers wearing high-visibility vests and hard hats stand in front of the truck. A date stamp '2023/4/9' is visible in the bottom right corner of the photo.</p>

387	GX-B1423/20-Y-23728	2023年4月2日	综合判定：合格	
388	GX-B1423/20-Y-23729	2023年4月2日	综合判定：合格	

389	GX-B1423/20-Y-23730	2023年4月2日	综合判定：合格	
390	GX-B1423/20-Y-23731	2023年4月2日	综合判定：合格	

391	GX-B1423/20-Y-23732	2023年4月2日	综合判定：合格	 A yellow XCMG dump truck with license plate X1278 is parked on a dirt surface. Two workers in high-visibility vests and hard hats stand in front of the truck. The truck has '1 2 7 8' on its side. A date stamp '2023/3/9' is visible in the bottom right corner of the photo.
392	GX-B1423/20-Y-23733	2023年4月2日	综合判定：合格	 A yellow XCMG dump truck with license plate X1209 is parked on a dirt surface. Two workers in high-visibility vests and hard hats stand in front of the truck. The truck has '1 2 0 9' on its side. A date stamp '2023/3/9' is visible in the bottom right corner of the photo.

393	GX-B1423/20-Y-23734	2023年4月2日	综合判定：合格	
394	GX-B1423/20-Y-23735	2023年4月2日	综合判定：合格	

395	GX-B1423/20-Y-23736	2023年4月2日	综合判定：合格	
396	GX-B1423/20-Y-23737	2023年4月2日	综合判定：合格	

397	GX-B1423/20-Y-23738	2023年4月2日	综合判定：合格	
398	GX-B1423/20-Y-23739	2023年4月2日	综合判定：合格	

399	GX-B1423/20-Y-23740	2023年4月2日	综合判定：合格	 <p>A photograph of a yellow XCMG off-road truck parked on a dirt surface. A person wearing a high-visibility yellow vest and a dark jacket stands in front of the truck. The truck has 'XCMG' visible on the side. A yellow timestamp '2023/3/9' is in the bottom right corner.</p>
400	GX-B1423/20-Y-23741	2023年4月2日	综合判定：合格	 <p>A photograph of a yellow off-road truck with the number '193' on its side. Three people wearing high-visibility yellow vests are standing near the truck. A yellow timestamp '2023/3/9' is in the bottom right corner.</p>

401	GX-B1423/20-Y-23742	2023年4月2日	综合判定：合格	
402	GX-B1423/20-Y-23743	2023年4月2日	综合判定：合格	

403	GX-B1423/20-Y-231860	2023年4月4日	综合判定：合格	
404	GX-B1423/20-Y-231861	2023年4月4日	综合判定：合格	

405	GX-B1423/20-Y-231862	2023年4月4日	综合判定：合格	 A photograph of a yellow MT984 truck parked on a dirt surface. Two workers in high-visibility vests and hard hats are standing in front of the truck. The date stamp '2023/3/17' is visible in the bottom right corner of the image.
406	GX-B1423/20-Y-231863	2023年4月4日	综合判定：合格	 A photograph of a yellow MT984 truck parked on a dirt surface. Two workers in high-visibility vests and hard hats are standing in front of the truck. The date stamp '2023/3/17' is visible in the bottom right corner of the image.

407	GX-B1423/20-Y-231864	2023年4月4日	综合判定：合格	
408	GX-B1423/20-Y-231865	2023年4月4日	综合判定：合格	

409	GX-B1423/20-Y-231866	2023年4月4日	综合判定：合格	
410	GX-B1423/20-Y-231867	2023年4月4日	综合判定：合格	

411	GX-B1423/20-Y-231868	2023年4月4日	综合判定：合格	
412	GX-B1423/20-Y-231869	2023年4月4日	综合判定：合格	

413	GX-B1423/20-Y-231870	2023年4月4日	综合判定：合格	
414	GX-B1423/20-Y-231871	2023年4月4日	综合判定：合格	

415	GX-B1423/20-Y-231872	2023年4月4日	综合判定：合格	
416	GX-B1423/20-Y-231873	2023年4月4日	综合判定：合格	

417	GX-B1423/20-Y-231874	2023年4月4日	综合判定：合格	
418	GX-B1423/20-Y-231875	2023年4月4日	综合判定：合格	

419	GX-B1423/20-Y-231876	2023年4月4日	综合判定：合格	
420	GX-B1423/20-Y-231877	2023年4月4日	综合判定：合格	

421	GX-B1423/20-Y-231878	2023年4月4日	综合判定：合格	 <p>A yellow Mitsui dump truck with the number 19 on its side. Two workers in high-visibility vests are standing next to it. The date 2023/3/17 is visible in the bottom right corner of the photo.</p>
422	GX-B1423/20-Y-231879	2023年4月4日	综合判定：合格	 <p>A yellow Mitsui dump truck with the number 07 on its side. Two workers in high-visibility vests are standing next to it. The date 2023/3/17 is visible in the bottom right corner of the photo.</p>

423	GX-B1521/20-Y-23161	2023年4月4日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》GB/T7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。	
424	GX-B1521/20-Y-23162	2023年4月4日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》GB/T7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。	

425	GX-B1521/20-Y-23163	2023年4月4日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》GB/T7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。	 <p>A yellow CAT hydraulic excavator is shown in operation on a construction site. Two workers in high-visibility vests and hard hats stand near the machine. The date stamp '2023/3/17' is visible in the bottom right corner of the image.</p>
426	GX-B1521/20-Y-23164	2023年4月4日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》GB/T7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。	 <p>A yellow CAT hydraulic excavator is shown with a concrete mixer bucket attachment. Two workers in high-visibility vests and hard hats stand near the machine. The date stamp '2023/3/17' is visible in the bottom right corner of the image.</p>

427	GX-B1539/22-Y-23044	2023年4月4日	所检项目合格。	
428	GX-B1539/22-Y-23045	2023年4月4日	所检项目合格。	

429	GX-B1539/22-Y-23046	2023年4月4日	所检项目合格。	 <p>2023/3/17</p>
430	GX-B1522/20-Y-23035	2023年4月4日	所检项目合格。	 <p>2023/3/17</p>

431	GX-B1522/20-Y-23036	2023年4月4日	所检项目合格。	
432	GX-B1423/20-Y-231909	2023年4月5日	综合判定：合格	

433	GX-B1423/20-Y-231910	2023年4月5日	综合判定：合格	 <p>A photograph showing two workers in safety gear (hard hats, high-visibility vests, and masks) standing in front of a yellow Weichai truck. The worker on the left is wearing a red hard hat and a white face mask, holding a white clipboard. The worker on the right is wearing a yellow hard hat. The truck has 'WEICHAI' written on the front grille. A yellow timestamp '2023/3/20' is visible in the bottom right corner of the photo.</p>
434	GX-B1423/20-Y-231911	2023年4月5日	综合判定：合格	 <p>A photograph showing two workers in safety gear (hard hats, high-visibility vests, and masks) standing in front of a yellow Weichai truck. The worker on the left is wearing a red hard hat and a white face mask. The worker on the right is wearing a yellow hard hat. The truck has 'WEICHAI' written on the front grille and a blue circular logo with the number '15' on the right side. A yellow timestamp '2023/3/20' is visible in the bottom right corner of the photo.</p>

435	GX-B1423/20-Y-231912	2023年4月5日	综合判定：合格	
436	GX-B1423/20-Y-231913	2023年4月5日	综合判定：合格	

437	GX-B1423/20-Y-231914	2023年4月5日	综合判定：合格	
438	GX-B1423/20-Y-231915	2023年4月5日	综合判定：合格	

439	GX-B1423/20-Y-231916	2023年4月5日	综合判定：合格	
440	GX-B1423/20-Y-231917	2023年4月5日	综合判定：合格	

441	GX-B1423/20-Y-231918	2023年4月5日	综合判定：合格	
442	GX-B1423/20-Y-231919	2023年4月5日	综合判定：合格	

443	GX-B1423/20-Y-231920	2023年4月5日	综合判定：合格	
444	GX-B1423/20-Y-231921	2023年4月5日	综合判定：合格	

445	GX-B1423/20-Y-231922	2023年4月5日	综合判定：合格	
446	GX-B1423/20-Y-231923	2023年4月5日	综合判定：合格	

447	GX-B1423/20-Y-231924	2023年4月5日	综合判定：合格	 <p>A photograph of a yellow MT96L truck with license plate 46. Two workers wearing safety vests and hard hats are standing in front of the truck. The date 2023/3/21 is visible in the bottom right corner of the photo.</p>
448	GX-B1423/20-Y-231925	2023年4月5日	综合判定：合格	 <p>A photograph of a yellow MT96L truck with license plate 47. Two workers wearing safety vests and hard hats are standing in front of the truck. The date 2023/3/21 is visible in the bottom right corner of the photo.</p>

449	GX-B1423/20-Y-231926	2023年4月5日	综合判定：合格	
450	GX-B1423/20-Y-231927	2023年4月5日	综合判定：合格	

451	GX-B1423/20-Y-231928	2023年4月5日	综合判定：合格	
452	GX-B1423/20-Y-231929	2023年4月5日	综合判定：合格	

453	GX-B1423/20-Y-231930	2023年4月5日	综合判定：合格	 <p>A photograph showing a yellow truck with license plate number 52. Two workers are standing in front of the truck. The worker on the left is wearing a red hard hat, a white face mask, and a high-visibility yellow safety vest over a grey jacket. The worker on the right is wearing a black jacket and a black hat. A yellow timestamp '2023/3/21' is visible in the bottom right corner of the photo.</p>
454	GX-B1423/20-Y-231931	2023年4月5日	综合判定：合格	 <p>A photograph showing a yellow truck with license plate number 55. Two workers are standing in front of the truck. The worker on the left is wearing a red hard hat, a white face mask, and a high-visibility yellow safety vest over a grey jacket. The worker on the right is wearing a yellow hard hat and a high-visibility yellow safety vest over a dark jacket. A yellow timestamp '2023/3/21' is visible in the bottom right corner of the photo.</p>

455	GX-B1423/20-Y-231932	2023年4月5日	综合判定：合格	
456	GX-B1423/20-Y-231933	2023年4月5日	综合判定：合格	

457	GX-B1423/20-Y-231934	2023年4月5日	综合判定：合格	 <p>A photograph showing the front of a yellow truck with license plate number 35. Two people are standing in front of the truck. The person on the left is wearing a red hard hat, a white face mask, and a high-visibility yellow safety vest over a grey jacket. The person on the right is wearing a dark jacket and blue jeans. A yellow timestamp '2023/3/21' is visible in the bottom right corner of the photo.</p>
458	GX-B1423/20-Y-231935	2023年4月5日	综合判定：合格	 <p>A photograph showing the side of a yellow truck with license plate number 36. A person wearing a red hard hat and a high-visibility yellow safety vest is standing in front of the truck. The truck has '徐工重卡' (Xugong Heavy Duty Truck) written on its side. A yellow timestamp '2023/3/21' is visible in the bottom right corner of the photo.</p>

459	GX-B1423/20-Y-231936	2023年4月5日	综合判定：合格	
460	GX-B1423/20-Y-231937	2023年4月5日	综合判定：合格	