

序号	报告编号	发布日期	结论	影像资料
644	GX-B1423/20-Y-231899	2023年4月5日	综合判定：合格	
645	GX-B1423/20-Y-231900	2023年4月5日	综合判定：合格	
646	GX-B1423/20-Y-231901	2023年4月5日	综合判定：合格	

647	GX-B1423/20-Y-231902	2023年4月5日	综合判定：合格	 A yellow dump truck is shown from a side-rear perspective. Two workers in safety gear are standing near the front of the truck. The truck's bed is raised. A yellow timestamp '2023.3.27' is visible in the bottom right corner of the image.
648	GX-B1423/20-Y-231903	2023年4月5日	综合判定：合格	 A yellow dump truck is shown from a side-front perspective. Two workers in safety gear are standing near the front of the truck. The truck's bed is raised. A yellow timestamp '2023.3.27' is visible in the bottom right corner of the image.
649	GX-B1423/20-Y-231904	2023年4月5日	综合判定：合格	 A yellow dump truck is shown from a side-front perspective. Two workers in safety gear are standing near the front of the truck. The truck's bed is raised. The side of the truck has 'MTB 229' and '矿工机械' written on it. A yellow timestamp '2023.3.27' is visible in the bottom right corner of the image.

650	GX-B1423/20-Y-231905	2023年4月5日	综合判定：合格	 A yellow MTBL dump truck with the number 207 on its side. Two workers in safety gear are standing in front of the truck. A yellow timestamp '2023/3/27' is visible in the bottom right corner of the photo.
651	GX-B1423/20-Y-231906	2023年4月5日	综合判定：合格	 A yellow MTBL dump truck with the number 233 on its side. Two workers in safety gear are standing in front of the truck. A yellow timestamp '2023/3/27' is visible in the bottom right corner of the photo.
652	GX-B1423/20-Y-231907	2023年4月5日	综合判定：合格	 A yellow MTBL dump truck with the number 213 on its side. Two workers in safety gear are standing in front of the truck. A yellow timestamp '2023/3/27' is visible in the bottom right corner of the photo.

653	GX-B1423/20-Y-231908	2023年4月5日	综合判定：合格	
654	GX-B1521/20-Y-23166	2023年4月10日	<p>依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。</p>	
655	GX-B1521/20-Y-23167	2023年4月10日	<p>依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。</p>	

656	GX-B1423/20-Y-231880	2023年4月10日	综合判定：合格	
657	GX-B1423/20-Y-231881	2023年4月10日	综合判定：合格	
658	GX-B1423/20-Y-231882	2023年4月10日	综合判定：合格	

659	GX-B1423/20-Y-231883	2023年4月10日	综合判定：合格	
660	GX-B1423/20-Y-231884	2023年4月10日	综合判定：合格	
661	GX-B1423/20-Y-231885	2023年4月10日	综合判定：合格	

662	GX-B1423/20-Y-231886	2023年4月10日	综合判定：合格	 A yellow MT800 truck is parked on a dirt road. Two workers wearing high-visibility vests and hard hats stand in front of the truck. The date '2023/3/18' is visible in the bottom right corner of the photo.
663	GX-B1423/20-Y-231887	2023年4月10日	综合判定：合格	 A yellow MT800 truck is parked on a dirt road. Two workers wearing high-visibility vests and hard hats stand in front of the truck. The date '2023/3/18' is visible in the bottom right corner of the photo.
664	GX-B1423/20-Y-231888	2023年4月10日	综合判定：合格	 A yellow MT800 truck is parked on a dirt road. Two workers wearing high-visibility vests and hard hats stand in front of the truck. The date '2023/3/18' is visible in the bottom right corner of the photo.

665	GX-B1423/20-Y-231889	2023年4月10日	综合判定：合格	
666	GX-B1423/20-Y-231890	2023年4月10日	综合判定：合格	
667	GX-B1423/20-Y-231891	2023年4月10日	综合判定：合格	

668	GX-B1423/20-Y-231892	2023年4月10日	综合判定：合格	
669	GX-B1423/20-Y-231893	2023年4月10日	综合判定：合格	
670	GX-B1423/20-Y-231894	2023年4月10日	综合判定：合格	

671	GX-B1312/20-Y-23152~23158	2023年4月7日	本次共检电力变压器7台，7台电力变压器所检项目合格。 。	
672	GX-B1312/20-Y-23159~23163	2023年4月7日	本次共检电力变压器5台，5台电力变压器所检项目合格。 。	
673	GX-B1312/20-Y-23164~23173	2023年4月7日	本次共检电力变压器10台，10台电力变压器所检项目合格。	

674	GX-B1312/20-Y-23174~23177	2023年4月7日	本次共检电力变压器4台，4台电力变压器所检项目合格。 。	
675	GX-B1310/21-Y- 23036	2023年4月10日	符合标准要求。	
676	GX-B1310/21-Y- 23037	2023年4月10日	符合标准要求。	

677	GX-B1310/21-Y- 23038	2023年4月10日	符合标准要求。	
678	GX-B1310/21-Y- 23039	2023年4月10日	符合标准要求。	
679	GX-B1310/21-Y- 23040	2023年4月10日	符合标准要求。	

680	GX-B1310/21-Y- 23041	2023年4月10日	符合标准要求。	 <p>A worker wearing a red protective suit and a red helmet is working in a confined space, possibly a tunnel or a large pipe. The worker is holding a device, likely a gas detector or a measuring instrument. The background shows some structural elements of the space. A yellow timestamp '2023/2/18' is visible in the bottom right corner of the image.</p>
681	GX-B1310/21-Y- 23042	2023年4月10日	符合标准要求。	 <p>A worker wearing a red protective suit and a red helmet is working on a large blue component, possibly a piece of machinery or a large pipe. The worker is leaning over the component, and the background shows some structural elements of the space. A yellow timestamp '2023/2/18' is visible in the bottom right corner of the image.</p>
682	GX-B1561/20-Y-23006	2023年4月10日	所检项目合格。	 <p>A worker wearing a red helmet and a grey jacket is working at a computer workstation. The worker is standing and looking at the computer screen. The workstation includes a desk with a monitor, keyboard, and mouse. A television screen is mounted on the wall behind the desk, displaying multiple camera feeds. A yellow timestamp '2023/3/25' is visible in the bottom right corner of the image.</p>

683	GX-B1561/20-Y-23007	2023年4月10日	所检项目合格。	
684	GX-B1423/20-Y-231497	2023年4月10日	综合判定：合格	
685	GX-B1423/20-Y-231498	2023年4月10日	综合判定：合格	

686	GX-B1423/20-Y-231499	2023年4月10日	综合判定：合格	 A yellow TONLY truck with the number 829 on its front. Two men are standing in front of the truck. The man on the left is wearing a grey jacket and a red hard hat. The man on the right is wearing a black jacket. The date 2023/3/12 is visible in the bottom right corner of the photo.
687	GX-B1423/20-Y-231500	2023年4月10日	综合判定：合格	 A yellow TONLY truck with the number 851 on its front. Two men are standing in front of the truck. The man on the left is wearing a grey jacket and a red hard hat. The man on the right is wearing a black jacket. The date 2023/3/12 is visible in the bottom right corner of the photo.

688	GX-B1423/20-Y-231501	2023年4月10日	综合判定：合格	
689	GX-B1423/20-Y-231502	2023年4月10日	综合判定：合格	

690	GX-B1423/20-Y-231503	2023年4月10日	综合判定：合格	
691	GX-B1423/20-Y-231504	2023年4月10日	综合判定：合格	

692	GX-B1423/20-Y-231505	2023年4月10日	综合判定：合格	
693	GX-B1423/20-Y-231506	2023年4月10日	综合判定：合格	

694	GX-B1423/20-Y-231507	2023年4月10日	综合判定：合格	 <p>A photograph of a yellow TONLY 862 dump truck. Two workers in grey work clothes and hard hats are standing in front of the truck. The truck has 'TONLY 862' written on its front. A yellow timestamp '2023/3/12' is visible in the bottom right corner of the photo.</p>
695	GX-B1423/20-Y-231508	2023年4月10日	综合判定：合格	 <p>A photograph of a yellow dump truck. Two workers in work clothes and hard hats are standing next to the truck. A yellow timestamp '2023/3/12' is visible in the bottom right corner of the photo.</p>

696	GX-B1423/20-Y-231509	2023年4月10日	综合判定：合格	
697	GX-B1423/20-Y-231510	2023年4月10日	综合判定：合格	

698	GX-B1423/20-Y-231511	2023年4月10日	综合判定：合格	
699	GX-B1423/20-Y-231512	2023年4月10日	综合判定：合格	

700	GX-B1423/20-Y-231513	2023年4月10日	综合判定：合格	
701	GX-B1423/20-Y-231514	2023年4月10日	综合判定：合格	

702	GX-B1423/20-Y-231515	2023年4月10日	综合判定：合格	
703	GX-B1423/20-Y-231516	2023年4月10日	综合判定：合格	

704	GX-B1423/20-Y-231517	2023年4月10日	综合判定：合格	 A yellow TONLY dump truck is shown from a side-rear perspective. Two workers in grey work clothes and hard hats stand in front of the truck. The truck has 'TONLY' and '718' visible on its side. A yellow date stamp '2023-4-10' is in the bottom right corner.
705	GX-B1423/20-Y-231518	2023年4月10日	综合判定：合格	 A yellow TONLY dump truck is shown from a front-three-quarter view. Two workers in grey work clothes and hard hats stand in front of the truck. The truck has 'TONLY' on the hood and '838' on the license plate area. A yellow date stamp '2023-4-10' is in the bottom right corner.

706	GX-B1423/20-Y-231519	2023年4月10日	综合判定：合格	 <p>A photograph of a yellow TONLY X828 off-road truck. Two workers in safety gear are standing in front of the truck. The truck has 'TONLY' and 'X828' visible on its front. A yellow timestamp '2023/4/10' is in the bottom right corner.</p>
707	GX-B1423/20-Y-231520	2023年4月10日	综合判定：合格	 <p>A photograph of a yellow off-road truck. Two workers in safety gear are standing in front of it. A yellow timestamp '2023/3/13' is in the bottom right corner.</p>

708	GX-B1423/20-Y-231521	2023年4月10日	综合判定：合格	
709	GX-B1423/20-Y-231522	2023年4月10日	综合判定：合格	

710	GX-B1423/20-Y-231523	2023年4月10日	综合判定：合格	 <p>A yellow heavy-duty truck, likely a haul truck, is shown from a side profile. The truck has 'C31' markings on its side and front. Two workers in safety gear are standing in front of the truck. The background is a clear blue sky and a dirt area. A yellow timestamp '2023/3/13' is visible in the bottom right corner of the image.</p>
711	GX-B1423/20-Y-231609	2023年4月10日	综合判定：合格	 <p>A large green and white truck, possibly a haul truck, is shown from a front view. The truck has '1-50' on its front. Two workers in safety gear are standing in front of the truck. The background is a clear blue sky and a dirt area. A yellow timestamp '2023/3/5' is visible in the bottom right corner of the image.</p>

712	GX-B1423/20-Y-231610	2023年4月10日	综合判定：合格	
-----	----------------------	------------	---------	---

713	GX-B1423/20-Y-231611	2023年4月10日	综合判定：合格	
-----	----------------------	------------	---------	---

714	GX-B1423/20-Y-231612	2023年4月10日	综合判定：合格	
-----	----------------------	------------	---------	---

715	GX-B1423/20-Y-231613	2023年4月10日	综合判定：合格	
-----	----------------------	------------	---------	---

716	GX-B1423/20-Y-231614	2023年4月10日	综合判定：合格	
-----	----------------------	------------	---------	---

717	GX-B1423/20-Y-231615	2023年4月10日	综合判定：合格	
-----	----------------------	------------	---------	---

718	GX-B1423/20-Y-231616	2023年4月10日	综合判定：合格	
-----	----------------------	------------	---------	---

719	GX-B1423/20-Y-231617	2023年4月10日	综合判定：合格	
-----	----------------------	------------	---------	---

720	GX-B1423/20-Y-231618	2023年4月10日	综合判定：合格	
-----	----------------------	------------	---------	---

721	GX-B1423/20-Y-231619	2023年4月10日	综合判定：合格	
-----	----------------------	------------	---------	---

722	GX-B1423/20-Y-231620	2023年4月10日	综合判定：合格	
-----	----------------------	------------	---------	---

723	GX-B1423/20-Y-231621	2023年4月10日	综合判定：合格	
-----	----------------------	------------	---------	---

724	GX-B1423/20-Y-231622	2023年4月10日	综合判定：合格	
-----	----------------------	------------	---------	---

725	GX-B1423/20-Y-231623	2023年4月10日	综合判定：合格	
-----	----------------------	------------	---------	---

726	GX-B1423/20-Y-231624	2023年4月10日	综合判定：合格	
-----	----------------------	------------	---------	---

727	GX-B1423/20-Y-231625	2023年4月10日	综合判定：合格	
-----	----------------------	------------	---------	---

728	GX-B1423/20-Y-231626	2023年4月10日	综合判定：合格	
-----	----------------------	------------	---------	---

729	GX-B1423/20-Y-231627	2023年4月10日	综合判定：合格	
-----	----------------------	------------	---------	---

730	GX-B1423/20-Y-231628	2023年4月10日	综合判定：合格	
-----	----------------------	------------	---------	---

731	GX-B1423/20-Y-231629	2023年4月10日	综合判定：合格	
-----	----------------------	------------	---------	---

732	GX-B1423/20-Y-231630	2023年4月10日	综合判定：合格	
-----	----------------------	------------	---------	---

733	GX-B1423/20-Y-231631	2023年4月10日	综合判定：合格	
-----	----------------------	------------	---------	---

734	GX-B1423/20-Y-231632	2023年4月10日	综合判定：合格	
-----	----------------------	------------	---------	---

735	GX-B1423/20-Y-231633	2023年4月10日	综合判定：合格	
-----	----------------------	------------	---------	---

736	GX-B1423/20-Y-231634	2023年4月10日	综合判定：合格	
-----	----------------------	------------	---------	---

737	GX-B1423/20-Y-231635	2023年4月10日	综合判定：合格	
-----	----------------------	------------	---------	---

738	GX-B1423/20-Y-231636	2023年4月10日	综合判定：合格	
-----	----------------------	------------	---------	---

739	GX-B1423/20-Y-231637	2023年4月10日	综合判定：合格	
-----	----------------------	------------	---------	---

740	GX-B1423/20-Y-231638	2023年4月10日	综合判定：合格	
-----	----------------------	------------	---------	---

741	GX-B1423/20-Y-231639	2023年4月10日	综合判定：合格	
-----	----------------------	------------	---------	---

742	GX-B1423/20-Y-231640	2023年4月10日	综合判定：合格	
-----	----------------------	------------	---------	---

743	GX-B1423/20-Y-231641	2023年4月10日	综合判定：合格	
-----	----------------------	------------	---------	---

744	GX-B1423/20-Y-231642	2023年4月10日	综合判定：合格	
-----	----------------------	------------	---------	---

745	GX-B1423/20-Y-231643	2023年4月10日	综合判定：合格	
-----	----------------------	------------	---------	---

746	GX-B1423/20-Y-231644	2023年4月10日	综合判定：合格	
-----	----------------------	------------	---------	---

747	GX-B1423/20-Y-231645	2023年4月10日	综合判定：合格	
-----	----------------------	------------	---------	---

748	GX-B1423/20-Y-231646	2023年4月10日	综合判定：合格	
-----	----------------------	------------	---------	---

749	GX-B1423/20-Y-231647	2023年4月10日	综合判定：合格	
-----	----------------------	------------	---------	---

750	GX-B1423/20-Y-231648	2023年4月10日	综合判定：合格	
-----	----------------------	------------	---------	---

751	GX-B1423/20-Y-231649	2023年4月10日	综合判定：合格	
-----	----------------------	------------	---------	---

752	GX-B1423/20-Y-231650	2023年4月10日	综合判定：合格	
-----	----------------------	------------	---------	---

753	GX-B1423/20-Y-231651	2023年4月10日	综合判定：合格	
-----	----------------------	------------	---------	---

754	GX-B1423/20-Y-231652	2023年4月10日	综合判定：合格	
-----	----------------------	------------	---------	---

755	GX-B1423/20-Y-231653	2023年4月10日	综合判定：合格	
-----	----------------------	------------	---------	---

756	GX-B1423/20-Y-231654	2023年4月10日	综合判定：合格	
-----	----------------------	------------	---------	---

757	GX-B1423/20-Y-231655	2023年4月10日	综合判定：合格	
-----	----------------------	------------	---------	---