



序号	报告编号	发布日期	结论	影像资料
180	GX-B1559/22-2-23003	2023. 4. 20	所检项目合格	
181	GX-B1559/22-2-23004	2023. 4. 20	所检项目合格	



182	GX-B1559/22-2-23005	2023. 4. 20	所检项目合格	 <p>A photograph showing a yellow forklift in a wet industrial setting. Several workers in blue and grey uniforms and red hard hats are gathered around the vehicle, appearing to be conducting an inspection. A toolbox is visible in the foreground. The date '2023/04/05' is printed in the bottom right corner of the image.</p>
183	GX-B1559/22-2-23006	2023. 4. 20	所检项目合格	 <p>A photograph showing a worker in a grey uniform and red hard hat inspecting the rear of a yellow forklift. The worker is standing on a wet surface, and steam or smoke is visible rising from the vehicle's engine area. The date '2023/04/05' is printed in the bottom right corner of the image.</p>

184	GX-B1322/21-2-23079~23091	2023. 4. 20	本次共检电力电缆13条，13条所检项目合格。	
185	GX-B1451/20-2-23193~23205	2023. 4. 18	本次共检高压开关柜13台，13台所检项目合格。	

186	GX-B1451/20-2-23206~23221	2023. 4. 18	本次共检高压开关柜16台，16台所检项目合格。	
187	GX-B1451/20-2-23222~23232	2023. 4. 18	本次共检高压开关柜11台，11台所检项目合格。	

188	GX-B1329/21-2-23078~23090	2023. 4. 21	本次共检氧化锌避雷器13组，13组所检项目合格。	 <p>2023/04/14</p>
189	GX-B1329/21-2-23091~23093	2023. 4. 21	本次共检氧化锌避雷器3组，3组所检项目合格。	 <p>2023/04/15</p>

190	GX-B1451/20-2-23233~23234	2023. 4. 21	本次共检高压开关柜2台，2台所检项目合格。	 <p>2023/04/16</p>
191	GX-B1451/20-2-23235~23238	2023. 4. 21	本次共检高压交流断路器4台，4台所检项目合格。	 <p>2023/04/13</p>

192	GX-B1313/21-2-23082~23083	2023. 4. 21	本次共检电力变压器2台，2台所检项目合格。 。	 <p>2023/04/13</p>
193	GX-B1329/21-2-23084~23086	2023. 4. 21	本次共检电力变压器3台，3台所检项目合格。 。	 <p>2023/04/13</p>

194	GX-B1313/21-2-23087~23089	2023. 4. 21	本次共检电力变压器3台，3台所检项目合格。			
195	GX-B1313/21-2-23090~23103	2023. 4. 21	本次共检电力变压器14台，14台所检项目合格。			

196	GX-B1322/21-2-23092~23106	2023. 4. 21	本次共检电力电缆15条，15条所检项目合格。		
197	GX-B1322/21-2-23107~23112	2023. 4. 21	本次共检电力电缆6条，6条所检项目合格。		

198	GX-B1417/22-2-23025	2023. 4. 21	综合判定：合格	 <p>2023/04/04</p>
199	GX-B1307/20-2-23024	2023. 4. 21	综合判定：合格	 <p>2023/03/21</p>

200	GX-B1307/20-2-23025	2023. 4. 21	综合判定：合格			
201	GX-B1307/20-2-23026	2023. 4. 21	综合判定：合格			

202	GX-B1350/21-2-23016	2023. 4. 19	本次共检验接地装置4处，4处所检项目全部合格。	
203	GX-B1499/21-2-23022	2023. 4. 21	所检项目合格。	

204	GX-B1499/21-2-23023	2023. 4. 21	所检项目合格。	
205	GX-B1499/21-2-23024	2023. 4. 21	所检项目合格。	

206	GX-B1499/21-2-23025	2023. 4. 21	所检项目合格。	
207	GX-B1499/21-2-23026	2023. 4. 21	所检项目合格。	

208	GX-B1499/21-2-23027	2023. 4. 21	所检项目合格。	 <p>2023/03/17</p>
209	GX-B1500/21-2-23014	2023. 4. 21	综合判定：合格。	 <p>2023/03/21</p>

210	GX-B1500/21-2-23015	2023. 4. 21	综合判定：合格。	 <p>2023/03/21</p>
211	GX-B1500/21-2-23016	2023. 4. 21	综合判定：合格。	 <p>2023/03/21</p>

212	GX-B1500/21-2-23017	2023. 4. 21	综合判定：合格。	
213	GX-B1500/21-2-23018	2023. 4. 21	综合判定：合格。	

214	GX-B1500/21-2-23019	2023. 4. 21	综合判定：合格。	
215	GX-B1548/20-2-23001	2023. 4. 23	所检项目合格。	

216	GX-B1310/21-2-23039	2023. 4. 20	符合标准要求。	
217	GX-B1310/21-2-23040	2023. 4. 21	超过Φ2mm当量直径的	

218	GX-B1310/21-2-23043	2023. 4. 23	符合标准要求。	 <p>2023/04/18</p>
219	GX-B1427/21-2-23043	2023. 4. 23	符合标准要求。	 <p>2023/04/18</p>

220	GX-B1310/21-2-23044	2023. 4. 23	符合标准要求。	 <p>2023/04/18</p>
221	GX-B1427/21-2-23044	2023. 4. 23	符合标准要求。	 <p>2023/04/18</p>

222	GX-B1310/21-2-23045	2023. 4. 23	符合标准要求。	
223	GX-B1300/20-2-23004	2023. 4. 24	综合判定：合格	

224	GX-B1300/20-2-23005	2023. 4. 24	综合判定：合格			
-----	---------------------	-------------	---------	--	---	--