

序号	报告编号	发布日期	结论	影像资料
2073	GX-B1521/20-Y-23254	2023年4月25日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。 。	

2074	GX-B1521/20-Y-23255	2023年4月25日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。 。	
------	---------------------	------------	--	---

2075	GX-B1521/20-Y-23256	2023年4月25日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。 。	
------	---------------------	------------	--	---

2076	GX-B1521/20-Y-23257	2023年4月25日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。 。	 A photograph of a red tracked hydraulic excavator, likely a Komatsu model, in an outdoor setting. The excavator is positioned on a dirt surface, and its arm is extended. The background shows a clear blue sky and some other equipment in the distance. A yellow timestamp '2023/4/25' is visible in the bottom right corner of the image.
------	---------------------	------------	--	--

2077	GX-B1521/20-Y-23258	2023年4月25日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。 。	
------	---------------------	------------	--	---

2078	GX-B1521/20-Y-23259	2023年4月25日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。 。	 <p>A photograph of a yellow CAT hydraulic excavator on a dirt field. A person is standing next to the excavator for scale. The date '2023/4/1' is visible in the bottom right corner of the photo.</p>
------	---------------------	------------	--	--

2079	GX-B1521/20-Y-23260	2023年4月25日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。 。	 A yellow CAT hydraulic excavator is shown in operation on a construction site. The excavator is positioned on a dirt and gravel surface, with its arm extended and bucket lowered. The background shows a clear blue sky and a flat horizon. A small yellow timestamp '2023/4/1' is visible in the bottom right corner of the image.
------	---------------------	------------	--	--

2080	GX-B1521/20-Y-23261	2023年4月25日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。 。	
------	---------------------	------------	--	---

2081	GX-B1521/20-Y-23262	2023年4月25日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。 。	 A photograph of a yellow CAT 395 hydraulic excavator at a construction site. A person in a light blue uniform stands next to the machine for scale. The date '2023/4/1' is visible in the bottom right corner of the photo.
------	---------------------	------------	--	---

2082	GX-B1521/20-Y-23263	2023年4月25日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。 。	
------	---------------------	------------	--	---

2083	GX-B1521/20-Y-23264	2023年4月25日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。 。	
------	---------------------	------------	--	---

2084	GX-B1521/20-Y-23265	2023年4月25日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。 。	
------	---------------------	------------	--	---

2085	GX-B1521/20-Y-23266	2023年4月25日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。 。	
------	---------------------	------------	--	---



2086	GX-B1521/20-Y-23267	2023年4月25日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。 。	
------	---------------------	------------	--	---

2087	GX-B1521/20-Y-23268	2023年4月25日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。 。	
------	---------------------	------------	--	---

2088	GX-B1521/20-Y-23269	2023年4月25日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。 。	
------	---------------------	------------	--	---

2089	GX-B1521/20-Y-23270	2023年4月25日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。 。	
------	---------------------	------------	--	---

2090	GX-B1521/20-Y-23271	2023年4月25日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。 。	
------	---------------------	------------	--	---

2091	GX-B1521/20-Y-23272	2023年4月25日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。 。	
------	---------------------	------------	--	---

2092	GX-B1521/20-Y-23273	2023年4月25日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。 。	
------	---------------------	------------	--	---

2093	GX-B1521/20-Y-23274	2023年4月25日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。 。	 A photograph of a yellow Sany tracked hydraulic excavator in a desert setting. The excavator is positioned on a sandy, uneven ground. A person is standing near the tracks of the machine. The background shows a clear blue sky and some distant structures or hills. The Sany logo is visible on the side of the excavator's boom.
------	---------------------	------------	--	--

2094	GX-B1521/20-Y-23275	2023年4月25日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。 。	
------	---------------------	------------	--	---

2095	GX-B1521/20-Y-23276	2023年4月25日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。 。	
------	---------------------	------------	--	---

2096	GX-B1521/20-Y-23277	2023年4月25日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。 。	
------	---------------------	------------	--	---

2097	GX-B1521/20-Y-23278	2023年4月25日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。 。	
------	---------------------	------------	--	---

2098	GX-B1521/20-Y-23279	2023年4月25日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。 。	
------	---------------------	------------	--	---

2099	GX-B1521/20-Y-23280	2023年4月25日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。 。	
------	---------------------	------------	--	---

2100	GX-B1521/20-Y-23281	2023年4月25日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。 。	
------	---------------------	------------	--	---

2101	GX-B1521/20-Y-23282	2023年4月25日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。 。	
------	---------------------	------------	--	---

2102	GX-B1521/20-Y-23283	2023年4月25日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。 。	
------	---------------------	------------	--	---

2103	GX-B1521/20-Y-23284	2023年4月25日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。 。	
------	---------------------	------------	--	---

2104	GX-B1521/20-Y-23285	2023年4月25日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。 。	
------	---------------------	------------	--	---

2105	GX-B1521/20-Y-23286	2023年4月25日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。 。	
------	---------------------	------------	--	---

2106	GX-B1521/20-Y-23287	2023年4月25日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。 。	
------	---------------------	------------	--	---

2107	GX-B1521/20-Y-23288	2023年4月25日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。 。	 A photograph of a blue Sunward hydraulic excavator working on a dirt construction site. The excavator is positioned on the right side of the frame, with its arm extended towards the left. The background shows a clear blue sky and a flat, sandy terrain. A yellow date stamp '2023/6/3' is visible in the bottom right corner of the image.
------	---------------------	------------	--	---

2108	GX-B1521/20-Y-23289	2023年4月25日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》 GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。 。	 <p>A yellow Komatsu hydraulic excavator is shown in an outdoor construction setting. The excavator is positioned on a dirt surface, and its arm is extended. A person in a light-colored uniform stands near the base of the machine. The background shows a clear sky and some distant structures. A yellow timestamp '2023/4/3' is visible in the bottom right corner of the image.</p>
2109	GX-B1423/20-Y-232678	2023年4月25日	综合判定：合格	 <p>A large yellow dump truck is shown in an outdoor construction setting. The truck is parked on a dirt surface, and its bed is raised. Two people in light-colored uniforms and safety vests are standing near the front of the truck. The background shows a clear sky and some distant structures. A yellow timestamp '2023/4/16' is visible in the bottom right corner of the image.</p>

2110	GX-B1423/20-Y-232679	2023年4月25日	综合判定：合格	
2111	GX-B1423/20-Y-232680	2023年4月25日	综合判定：合格	

2112	GX-B1423/20-Y-232681	2023年4月25日	综合判定：合格	
2113	GX-B1423/20-Y-232682	2023年4月25日	综合判定：合格	

2114	GX-B1423/20-Y-232683	2023年4月25日	综合判定：合格	
2115	GX-B1423/20-Y-232684	2023年4月25日	综合判定：合格	

2116	GX-B1423/20-Y-232685	2023年4月25日	综合判定：合格	
2117	GX-B1423/20-Y-232686	2023年4月25日	综合判定：合格	

2118	GX-B1423/20-Y-232687	2023年4月25日	综合判定：合格	
2119	GX-B1423/20-Y-232688	2023年4月25日	综合判定：合格	

2120	GX-B1423/20-Y-232689	2023年4月25日	综合判定：合格	
2121	GX-B1423/20-Y-232690	2023年4月25日	综合判定：合格	

2122	GX-B1423/20-Y-232691	2023年4月25日	综合判定：合格	
2123	GX-B1423/20-Y-232692	2023年4月25日	综合判定：合格	

2124	GX-B1423/20-Y-232693	2023年4月25日	综合判定：合格	
2125	GX-B1423/20-Y-232694	2023年4月25日	综合判定：合格	

2126	GX-B1423/20-Y-232695	2023年4月25日	综合判定：合格	
2127	GX-B1423/20-Y-232696	2023年4月25日	综合判定：合格	

2128	GX-B1423/20-Y-232697	2023年4月25日	综合判定：合格	
2129	GX-B1423/20-Y-232698	2023年4月25日	综合判定：合格	

2130	GX-B1423/20-Y-232699	2023年4月25日	综合判定：合格	
2131	GX-B1423/20-Y-232700	2023年4月25日	综合判定：合格	

2132	GX-B1423/20-Y-232701	2023年4月25日	综合判定：合格	
2133	GX-B1423/20-Y-232702	2023年4月25日	综合判定：合格	

2134	GX-B1423/20-Y-232703	2023年4月25日	综合判定：合格	
2135	GX-B1423/20-Y-232704	2023年4月25日	综合判定：合格	

2136	GX-B1423/20-Y-232705	2023年4月25日	综合判定：合格	
2137	GX-B1423/20-Y-232706	2023年4月25日	综合判定：合格	

2138	GX-B1423/20-Y-232707	2023年4月25日	综合判定：合格	
2139	GX-B1423/20-Y-232708	2023年4月25日	综合判定：合格	

2140	GX-B1423/20-Y-232709	2023年4月25日	综合判定：合格	
2141	GX-B1423/20-Y-232710	2023年4月25日	综合判定：合格	

2142	GX-B1423/20-Y-232655	2023年4月25日	综合判定：合格	
2143	GX-B1423/20-Y-232656	2023年4月25日	综合判定：合格	

2144	GX-B1423/20-Y-232657	2023年4月25日	综合判定：合格	
2145	GX-B1423/20-Y-232658	2023年4月25日	综合判定：合格	

2146	GX-B1423/20-Y-232659	2023年4月25日	综合判定：合格	
2147	GX-B1423/20-Y-232660	2023年4月25日	综合判定：合格	

2148	GX-B1423/20-Y-232661	2023年4月25日	综合判定：合格	
2149	GX-B1423/20-Y-232662	2023年4月25日	综合判定：合格	

2150	GX-B1423/20-Y-232663	2023年4月25日	综合判定：合格	
2151	GX-B1423/20-Y-232664	2023年4月25日	综合判定：合格	

2152	GX-B1423/20-Y-232665	2023年4月25日	综合判定：合格	 A yellow TONLY dump truck is parked on a dirt lot. Two workers in safety gear stand in front of it. The truck has the number 19 on its side. A date stamp '2023/4/15' is visible in the bottom right corner of the photo.
2153	GX-B1423/20-Y-232666	2023年4月25日	综合判定：合格	 A yellow TONLY dump truck is parked on a dirt lot. Two workers in safety gear stand in front of it. The truck has the number 18 on its side. A date stamp '2023/4/15' is visible in the bottom right corner of the photo.

2154	GX-B1423/20-Y-232667	2023年4月25日	综合判定：合格	
2155	GX-B1423/20-Y-232668	2023年4月25日	综合判定：合格	

2156	GX-B1423/20-Y-232669	2023年4月25日	综合判定：合格	 <p>A yellow TONLY dump truck with the number 22 on its side. Two workers in safety gear are standing in front of the truck. The truck is parked on a dirt surface. A yellow timestamp '2023/4/15' is visible in the bottom right corner of the image.</p>
2157	GX-B1423/20-Y-232670	2023年4月25日	综合判定：合格	 <p>A yellow TONLY dump truck with the number 27 on its side. Two workers in safety gear are standing in front of the truck. The truck is parked on a dirt surface. A yellow timestamp '2023/4/15' is visible in the bottom right corner of the image.</p>

2158	GX-B1423/20-Y-232671	2023年4月25日	综合判定：合格	
2159	GX-B1423/20-Y-232672	2023年4月25日	综合判定：合格	

2160	GX-B1423/20-Y-232673	2023年4月25日	综合判定：合格	 A yellow TONLY dump truck is parked on a dirt surface. Two workers in safety gear are standing next to it. The truck has the number 28 on its side and 53 on the top of the dump body. A date stamp '2023/4/16' is visible in the bottom right corner of the photo.
2161	GX-B1423/20-Y-232674	2023年4月25日	综合判定：合格	 A yellow TONLY dump truck is parked on a dirt surface. Two workers in safety gear are standing next to it. The truck has the number 28 on its side and 53 on the top of the dump body. A date stamp '2023/4/16' is visible in the bottom right corner of the photo.

2162	GX-B1423/20-Y-232675	2023年4月25日	综合判定：合格	
2163	GX-B1423/20-Y-232676	2023年4月25日	综合判定：合格	

2164	GX-B1423/20-Y-232677	2023年4月25日	综合判定：合格	 <p>A yellow MT99L dump truck is shown in a mining or construction environment. Two workers in safety gear are standing next to the truck. The truck has 'MT99L' and the number '20' visible on its side. A yellow timestamp '2023/4/16' is in the bottom right corner.</p>
2165	GX-B1423/20-Y-232309	2023年4月25日	综合判定：合格	 <p>An orange dump truck is shown in a mining or construction environment. Two workers in safety gear are standing next to the truck. The truck has the numbers '6 3 1 2' on its side. A yellow timestamp '2023/3/17' is in the bottom right corner.</p>

2166	GX-B1423/20-Y-232310	2023年4月25日	综合判定：合格	 A yellow dump truck with the number 6516 on its side. Two workers in blue and grey uniforms are standing next to it. A traffic cone is visible in the foreground. A timestamp '2023/3/14' is in the bottom right corner.
2167	GX-B1423/20-Y-232311	2023年4月25日	综合判定：合格	 A yellow dump truck with the number 6521 on its side. Two workers in blue and grey uniforms are standing next to it. A traffic cone is visible in the foreground. A timestamp '2023/3/14' is in the bottom right corner.

2168	GX-B1423/20-Y-232312	2023年4月25日	综合判定：合格	 <p>A yellow TONLY dump truck with the number 6322 on its side. Two workers in safety gear are standing next to it. A traffic cone is visible in the foreground. A yellow timestamp '2023/3/14' is in the bottom right corner.</p>
2169	GX-B1423/20-Y-232313	2023年4月25日	综合判定：合格	 <p>A yellow TONLY dump truck with the number 651 on its side. Two workers in safety gear are standing next to it. A yellow timestamp '2023/3/14' is in the bottom right corner.</p>

2170	GX-B1423/20-Y-232314	2023年4月25日	综合判定：合格	 A yellow dump truck with the number '68' on its side. Two workers in safety gear are standing next to it. A yellow timestamp '2023/3/14' is visible in the bottom right corner of the photo.
2171	GX-B1423/20-Y-232315	2023年4月25日	综合判定：合格	 A yellow dump truck with the number '617' on its side. Two workers in safety gear are standing next to it. A yellow timestamp '2023/3/14' is visible in the bottom right corner of the photo.

2172	GX-B1423/20-Y-232316	2023年4月25日	综合判定：合格	
2173	GX-B1423/20-Y-232317	2023年4月25日	综合判定：合格	

2174	GX-B1423/20-Y-232318	2023年4月25日	综合判定：合格	
2175	GX-B1423/20-Y-232319	2023年4月25日	综合判定：合格	

2176	GX-B1423/20-Y-232320	2023年4月25日	综合判定：合格	 A yellow dump truck with the number 6755 on its side. Two workers in safety gear are standing in front of it. The truck has 'TONLY' and 'MG755' branding. A date stamp '2023/4/25' is visible in the bottom right corner of the image.
2177	GX-B1423/20-Y-232321	2023年4月25日	综合判定：合格	 A yellow dump truck with the number 6317 on its side. Two workers in safety gear are standing in front of it. The truck has 'TONLY' and 'MG317' branding. A date stamp '2023/4/25' is visible in the bottom right corner of the image.

2178	GX-B1423/20-Y-232322	2023年4月25日	综合判定：合格	 <p>A yellow dump truck with the number 6752 on its side. Two workers in safety gear are standing next to it. A date stamp '2023/4/25' is visible in the bottom right corner of the photo.</p>
2179	GX-B1423/20-Y-232323	2023年4月25日	综合判定：合格	 <p>A yellow dump truck with the number 6316 on its side. Two workers in safety gear are standing next to it. A date stamp '2023/4/25' is visible in the bottom right corner of the photo.</p>

2180	GX-B1423/20-Y-232324	2023年4月25日	综合判定：合格	 A yellow dump truck with the number 6318 on its side. Two workers in safety gear are standing next to it. A date stamp '2023/4/4' is visible in the bottom right corner of the image.
2181	GX-B1423/20-Y-232325	2023年4月25日	综合判定：合格	 A yellow dump truck with the number 6751 on its side. Two workers in safety gear are standing next to it. A date stamp '2023/4/4' is visible in the bottom right corner of the image.

2182	GX-B1423/20-Y-232326	2023年4月25日	综合判定：合格	 A yellow dump truck with the number 6615 on its side is parked on a dirt surface. Two workers in safety gear are standing near the front of the truck. A traffic cone is visible in the foreground. A yellow timestamp '2023/3/19' is in the bottom right corner of the image.
2183	GX-B1423/20-Y-232327	2023年4月25日	综合判定：合格	 A yellow dump truck with the number 6670 on its side is parked on a dirt surface. Two workers in safety gear are standing near the front of the truck. A traffic cone is visible in the foreground. A yellow timestamp '2023/3/19' is in the bottom right corner of the image.

2184	GX-B1423/20-Y-232328	2023年4月25日	综合判定：合格	 A yellow dump truck with the number 6753 on its side is parked on a dirt surface. Two workers in safety gear are standing near the front of the truck. A traffic cone is visible in the foreground. A timestamp '2023/4/25' is visible in the bottom right corner of the image.
2185	GX-B1423/20-Y-232329	2023年4月25日	综合判定：合格	 A yellow dump truck with the number 6618 on its side is parked on a dirt surface. Two workers in safety gear are standing near the front of the truck. A traffic cone is visible in the foreground. A timestamp '2023/4/25' is visible in the bottom right corner of the image.

2186	GX-B1423/20-Y-232330	2023年4月25日	综合判定：合格	 A yellow dump truck with the number 6616 on its side. Two workers in safety gear are standing near the truck. A traffic cone and a toolbox are on the ground. A timestamp '2023/3/15' is visible in the bottom right corner of the photo.
2187	GX-B1423/20-Y-232331	2023年4月25日	综合判定：合格	 A yellow dump truck with the number 6518 on its side. Two workers in safety gear are standing near the truck. A traffic cone and a toolbox are on the ground. A timestamp '2023/3/15' is visible in the bottom right corner of the photo.

2188	GX-B1423/20-Y-232332	2023年4月25日	综合判定：合格	 A yellow dump truck with the number '6610' on its side. Two workers in safety gear are standing next to it. A date stamp '2023/4/15' is visible in the bottom right corner of the photo.
2189	GX-B1423/20-Y-232333	2023年4月25日	综合判定：合格	 A yellow dump truck with the number '6660' on its side. Two workers in safety gear are standing next to it. A date stamp '2023/4/15' is visible in the bottom right corner of the photo.

2190	GX-B1423/20-Y-232334	2023年4月25日	综合判定：合格	
2191	GX-B1423/20-Y-232335	2023年4月25日	综合判定：合格	

2192	GX-B1423/20-Y-232336	2023年4月25日	综合判定：合格	
2193	GX-B1423/20-Y-232337	2023年4月25日	综合判定：合格	

2194	GX-B1423/20-Y-232338	2023年4月25日	综合判定：合格	 A yellow dump truck with license plate number 6509 is parked on a dirt surface. Two workers in safety gear are standing near the front of the truck. A traffic cone is visible in the foreground. A yellow timestamp '2023/3/15' is in the bottom right corner.
2195	GX-B1423/20-Y-232339	2023年4月25日	综合判定：合格	 A yellow dump truck with license plate number 652 is parked on a dirt surface. Two workers in safety gear are standing near the front of the truck. A yellow timestamp '2023/3/15' is in the bottom right corner.

2196	GX-B1423/20-Y-232340	2023年4月25日	综合判定：合格	
2197	GX-B1423/20-Y-232341	2023年4月25日	综合判定：合格	

2198	GX-B1423/20-Y-232342	2023年4月25日	综合判定：合格	
2199	GX-B1423/20-Y-232343	2023年4月25日	综合判定：合格	

2200	GX-B1423/20-Y-232344	2023年4月25日	综合判定：合格	
2201	GX-B1423/20-Y-232345	2023年4月25日	综合判定：合格	

2202	GX-B1423/20-Y-232346	2023年4月25日	综合判定：合格	
2203	GX-B1423/20-Y-232347	2023年4月25日	综合判定：合格	

2204	GX-B1423/20-Y-232348	2023年4月25日	综合判定：合格	
2205	GX-B1423/20-Y-232349	2023年4月25日	综合判定：合格	

2206	GX-B1423/20-Y-232350	2023年4月25日	综合判定：合格	 A yellow dump truck with license plate number 6319. Two workers in blue and grey uniforms are standing next to it. A date stamp '2023/3/16' is visible in the bottom right corner of the photo.
2207	GX-B1423/20-Y-232351	2023年4月25日	综合判定：合格	 A yellow dump truck with license plate number 6651. Two workers in blue and grey uniforms are standing next to it. A date stamp '2023/3/16' is visible in the bottom right corner of the photo.

2208	GX-B1423/20-Y-232352	2023年4月25日	综合判定：合格	 A yellow dump truck with license plate 6605 is parked on a dirt surface. Two workers in safety gear are standing next to it. A date stamp '2023/3/16' is visible in the bottom right corner of the image.
2209	GX-B1423/20-Y-232353	2023年4月25日	综合判定：合格	 A yellow dump truck with license plate 6519 is parked on a dirt surface. Two workers in safety gear are standing next to it. A date stamp '2023/3/16' is visible in the bottom right corner of the image.

2210	GX-B1423/20-Y-232354	2023年4月25日	综合判定：合格	 A yellow dump truck with the identification number M6607 on the side of the cab. The truck is parked on a dirt surface. Two workers in safety gear are standing next to it. A traffic cone is visible in the foreground. A yellow timestamp '2023/3/15' is in the bottom right corner of the photo.
2211	GX-B1423/20-Y-232355	2023年4月25日	综合判定：合格	 A yellow dump truck with the identification number M6508 on the side of the cab. The truck is parked on a dirt surface. Two workers in safety gear are standing next to it. A traffic cone is visible in the foreground. A yellow timestamp '2023/3/15' is in the bottom right corner of the photo.

2212	GX-B1423/20-Y-232356	2023年4月25日	综合判定：合格	 A yellow TONLY M6608 dump truck is parked on a dirt surface. Two workers wearing safety vests and hard hats stand in front of the truck. The truck has 'TONLY' and 'M6608' written on it. A yellow timestamp '2023/3/17' is visible in the bottom right corner of the photo.
2213	GX-B1423/20-Y-232357	2023年4月25日	综合判定：合格	 A yellow TONLY M6663 dump truck is parked on a dirt surface. Two workers wearing safety vests and hard hats stand in front of the truck. The truck has 'TONLY' and 'M6663' written on it. A yellow timestamp '2023/3/17' is visible in the bottom right corner of the photo.

2214	GX-B1423/20-Y-232358	2023年4月25日	综合判定：合格	 A yellow truck with the number '631' on its side. Two workers in safety gear are standing next to it. A traffic cone is visible in the foreground. A yellow timestamp '2023/4/25' is in the bottom right corner.
2215	GX-B1423/20-Y-232359	2023年4月25日	综合判定：合格	 A yellow truck with the number '662' on its side. Two workers in safety gear are standing next to it. A traffic cone is visible in the foreground. A yellow timestamp '2023/4/25' is in the bottom right corner.

2216	GX-B1423/20-Y-232360	2023年4月25日	综合判定：合格	 A yellow dump truck with license plate number 6663 is parked on a dirt road. Two workers in high-visibility vests are standing near the front of the truck. A traffic cone is visible in the foreground. The date 2023/3/17 is printed in the bottom right corner of the image.
2217	GX-B1423/20-Y-232361	2023年4月25日	综合判定：合格	 A yellow dump truck with license plate number 6656 is parked on a dirt road. Two workers in high-visibility vests are standing near the front of the truck. A traffic cone is visible in the foreground. The date 2023/3/17 is printed in the bottom right corner of the image.

2218	GX-B1423/20-Y-232362	2023年4月25日	综合判定：合格	 <p>A yellow dump truck with license plate number 6511 is parked on a dirt surface. Two workers in safety gear are standing near the front of the truck. A traffic cone is visible in the foreground. The date 2023/3/17 is printed in the bottom right corner of the image.</p>
2219	GX-B1423/20-Y-232363	2023年4月25日	综合判定：合格	 <p>A yellow dump truck with license plate number 660 is parked on a dirt surface. Two workers in safety gear are standing near the front of the truck. The date 2023/3/17 is printed in the bottom right corner of the image.</p>

2220	GX-B1423/20-Y-232364	2023年4月25日	综合判定：合格	 A yellow dump truck with license plate number 6655 is parked on a dirt surface. Two workers in safety gear are standing near the front of the truck. A traffic cone is visible in the foreground. A yellow timestamp '2023/3/17' is in the bottom right corner.
2221	GX-B1423/20-Y-232365	2023年4月25日	综合判定：合格	 A yellow dump truck with license plate number 6606 is parked on a dirt surface. Two workers in safety gear are standing near the front of the truck. A traffic cone is visible in the foreground. A yellow timestamp '2023/3/17' is in the bottom right corner.

2222	GX-B1423/20-Y-232366	2023年4月25日	综合判定：合格	 <p>A yellow dump truck with the number '6601' on its side. Two workers in safety gear are standing next to it. A date stamp '2023/2/17' is visible in the bottom right corner of the photo.</p>
2223	GX-B1423/20-Y-232367	2023年4月25日	综合判定：合格	 <p>A yellow dump truck with the number '6305' on its side. Two workers in safety gear are standing next to it. A date stamp '2023/3/17' is visible in the bottom right corner of the photo.</p>

2224	GX-B1423/20-Y-232368	2023年4月25日	综合判定：合格	 <p>A yellow dump truck with license plate number 6658 is parked on a dirt surface. Two workers in safety gear are standing near the front of the truck. A red and white traffic cone is visible in the foreground. A yellow timestamp '2023/3/17' is present in the bottom right corner of the image.</p>
2225	GX-B1423/20-Y-232369	2023年4月25日	综合判定：合格	 <p>A yellow dump truck with license plate number 6657 is parked on a dirt surface. Two workers in safety gear are standing near the front of the truck. A red and white traffic cone is visible in the foreground. A yellow timestamp '2023/3/17' is present in the bottom right corner of the image.</p>

2226	GX-B1423/20-Y-232370	2023年4月25日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers in safety gear are standing next to it. A traffic cone is visible in the foreground. A yellow timestamp '2023/3/17' is in the bottom right corner of the photo.
2227	GX-B1423/20-Y-232371	2023年4月25日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers in safety gear are standing next to it. A traffic cone is visible in the foreground. A yellow timestamp '2023/3/17' is in the bottom right corner of the photo.

2228	GX-B1423/20-Y-232372	2023年4月25日	综合判定：合格	 A yellow dump truck with the number '6611' on its side is parked on a dirt surface. Two workers in safety gear are standing near the truck. A red and white traffic cone is visible in the foreground. A yellow timestamp '2023/4/17' is in the bottom right corner.
2229	GX-B1423/20-Y-232373	2023年4月25日	综合判定：合格	 A yellow dump truck with the number '6609' on its side is parked on a dirt surface. A worker in safety gear is standing near the truck. A yellow timestamp '2023/4/17' is in the bottom right corner.

2230	GX-B1423/20-Y-232374	2023年4月25日	综合判定：合格	 <p>A yellow TONLY dump truck is parked on a dirt surface. The side of the truck features the license plate number '6662'. Two workers in safety gear are standing in front of the truck. A yellow timestamp '2023/3/17' is visible in the bottom right corner of the photo.</p>
2231	GX-B1423/20-Y-232375	2023年4月25日	综合判定：合格	 <p>A yellow truck is parked on a dirt surface. The front of the truck displays the license plate number '桂B7588'. Two workers in safety gear are standing in front of the truck. A yellow timestamp '2023/3/17' is visible in the bottom left corner of the photo.</p>

2232	GX-B1423/20-Y-232376	2023年4月25日	综合判定：合格	
2233	GX-B1423/20-Y-232377	2023年4月25日	综合判定：合格	

2234	GX-B1539/22-Y-23101	2023年4月26日	所检项目合格。	
2235	GX-B1521/20-Y-23250	2023年4月26日	依据GB/T 9139-2018 《土方机械 液压挖掘机 技术条件》	

2236	GX-B1521/20-Y-23251	2023年4月26日	GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。	
2237	GX-B1521/20-Y-23252	2023年4月26日	GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。	

2238	GX-B1521/20-Y-23253	2023年4月26日	GB/T 7586-2018 《土方机械 液压挖掘机 试验方法》，所检项目合格。	
------	---------------------	------------	--	---