

序号	报告编号	发布日期	结论	影像资料
2249	GX-B1423/20-Y-232378	2023年4月25日	综合判定：合格	

2250	GX-B1423/20-Y-232379	2023年4月25日	综合判定：合格	
------	----------------------	------------	---------	---

2251	GX-B1423/20-Y-232380	2023年4月25日	综合判定：合格	
------	----------------------	------------	---------	---

2252	GX-B1423/20-Y-232381	2023年4月25日	综合判定：合格	
------	----------------------	------------	---------	---

2252

GX-B1423/20-Y-232381

2023年4月25日

综合判定：合格



2253	GX-B1423/20-Y-232382	2023年4月25日	综合判定：合格	
------	----------------------	------------	---------	---

2254	GX-B1423/20-Y-232383	2023年4月25日	综合判定：合格	
------	----------------------	------------	---------	---

2255	GX-B1423/20-Y-232384	2023年4月25日	综合判定：合格	
------	----------------------	------------	---------	---

2256	GX-B1423/20-Y-232385	2023年4月25日	综合判定：合格	
------	----------------------	------------	---------	---

2257	GX-B1423/20-Y-232386	2023年4月25日	综合判定：合格	
------	----------------------	------------	---------	---

2258	GX-B1423/20-Y-232387	2023年4月25日	综合判定：合格	
------	----------------------	------------	---------	---

2259	GX-B1423/20-Y-232388	2023年4月25日	综合判定：合格	
------	----------------------	------------	---------	---

2260	GX-B1423/20-Y-232389	2023年4月25日	综合判定：合格	
------	----------------------	------------	---------	---

2261

GX-B1423/20-Y-232390

2023年4月25日

综合判定：合格



2262

GX-B1423/20-Y-232391

2023年4月25日

综合判定：合格



2263	GX-B1423/20-Y-232392	2023年4月25日	综合判定：合格	
------	----------------------	------------	---------	---

2264	GX-B1423/20-Y-232393	2023年4月25日	综合判定：合格	
------	----------------------	------------	---------	---

2265	GX-B1423/20-Y-232394	2023年4月25日	综合判定：合格	
------	----------------------	------------	---------	---

2266

GX-B1423/20-Y-232395

2023年4月25日

综合判定：合格



2267

GX-B1423/20-Y-232396

2023年4月25日

综合判定：合格



2268	GX-B1423/20-Y-232397	2023年4月25日	综合判定：合格	
------	----------------------	------------	---------	---

2269

GX-B1423/20-Y-232398

2023年4月25日

综合判定：合格



2270

GX-B1423/20-Y-232399

2023年4月25日

综合判定：合格



2271	GX-B1423/20-Y-232400	2023年4月25日	综合判定：合格	
------	----------------------	------------	---------	---

2272

GX-B1423/20-Y-232401

2023年4月25日

综合判定：合格



2273

GX-B1423/20-Y-232402

2023年4月25日

综合判定：合格



2274	GX-B1423/20-Y-232403	2023年4月25日	综合判定：合格	
------	----------------------	------------	---------	---

2275

GX-B1423/20-Y-232404

2023年4月25日

综合判定：合格



2276	GX-B1423/20-Y-232405	2023年4月25日	综合判定：合格	
------	----------------------	------------	---------	---

2277	GX-B1423/20-Y-232406	2023年4月25日	综合判定：合格	
------	----------------------	------------	---------	---

2278	GX-B1423/20-Y-232407	2023年4月25日	综合判定：合格	
------	----------------------	------------	---------	---

2279	GX-B1423/20-Y-232408	2023年4月25日	综合判定：合格	
------	----------------------	------------	---------	---

2280	GX-B1423/20-Y-232409	2023年4月25日	综合判定：合格	
------	----------------------	------------	---------	---

2281

GX-B1423/20-Y-232410

2023年4月25日

综合判定：合格



2282

GX-B1423/20-Y-232411

2023年4月25日

综合判定：合格



2283

GX-B1423/20-Y-232412

2023年4月25日

综合判定：合格



2284

GX-B1423/20-Y-232413

2023年4月25日

综合判定：合格



2285

GX-B1423/20-Y-232414

2023年4月25日

综合判定：合格



2286

GX-B1423/20-Y-232415

2023年4月25日

综合判定：合格



2287	GX-B1423/20-Y-232416	2023年4月25日	综合判定：合格	
------	----------------------	------------	---------	---

2288

GX-B1423/20-Y-232417

2023年4月25日

综合判定：合格



2289	GX-B1423/20-Y-232418	2023年4月25日	综合判定：合格	
------	----------------------	------------	---------	---

2290

GX-B1423/20-Y-232419

2023年4月26日

综合判定：合格



2291	GX-B1423/20-Y-232420	2023年4月26日	综合判定：合格	
------	----------------------	------------	---------	---

2292

GX-B1423/20-Y-232421

2023年4月26日

综合判定：合格



2293	GX-B1423/20-Y-232422	2023年4月26日	综合判定：合格	
------	----------------------	------------	---------	---

2294	GX-B1423/20-Y-232423	2023年4月26日	综合判定：合格	 A photograph of a yellow TONLY M320 dump truck. Two workers wearing blue and yellow safety vests and hard hats are standing in front of the truck. The truck has 'TONLY' and 'M320' written on its side. A red and white traffic cone is visible in the foreground. A yellow timestamp '2023/4/26' is visible in the bottom right corner of the photo.
------	----------------------	------------	---------	--

2295	GX-B1423/20-Y-232424	2023年4月26日	综合判定：合格	
------	----------------------	------------	---------	---

2296	GX-B1423/20-Y-232425	2023年4月26日	综合判定：合格	 A photograph of a yellow dump truck parked on a dirt surface. The truck has the license plate number '6253' on its side. Two workers wearing high-visibility safety vests and hard hats are standing in front of the truck. A red and white traffic cone is visible on the ground to the right of the truck. A yellow timestamp '2023/3/15' is visible in the bottom right corner of the photo.
------	----------------------	------------	---------	---

2297

GX-B1423/20-Y-232426

2023年4月26日

综合判定：合格



2298	GX-B1423/20-Y-232427	2023年4月26日	综合判定：合格	
------	----------------------	------------	---------	---

2299

GX-B1423/20-Y-232428

2023年4月26日

综合判定：合格



2300	GX-B1423/20-Y-232429	2023年4月26日	综合判定：合格	
------	----------------------	------------	---------	---

2300

GX-B1423/20-Y-232429

2023年4月26日

综合判定：合格



2301	GX-B1423/20-Y-232430	2023年4月26日	综合判定：合格	
------	----------------------	------------	---------	---

2302	GX-B1423/20-Y-232431	2023年4月26日	综合判定：合格	
------	----------------------	------------	---------	---

2303

GX-B1423/20-Y-232432

2023年4月26日

综合判定：合格



2304	GX-B1423/20-Y-232433	2023年4月26日	综合判定：合格	
------	----------------------	------------	---------	---

2305	GX-B1423/20-Y-232434	2023年4月26日	综合判定：合格	
------	----------------------	------------	---------	---

2306	GX-B1423/20-Y-232435	2023年4月26日	综合判定：合格	 A photograph of a yellow YONLY 670D dump truck. Two workers wearing high-visibility vests and hard hats are standing in front of the truck. The truck has 'YONLY' and '670D' visible on its side. A date stamp '2023/3/15' is present in the bottom right corner of the image.
------	----------------------	------------	---------	--

2307	GX-B1423/20-Y-232436	2023年4月26日	综合判定：合格	 A photograph of a yellow TONYU dump truck. Two workers wearing safety vests and hard hats are standing in front of the truck. The truck has 'TONYU' and '820' visible on its side. A date stamp '2023/4/26' is present in the bottom right corner of the image.
------	----------------------	------------	---------	---

2308	GX-B1423/20-Y-232437	2023年4月26日	综合判定：合格	
------	----------------------	------------	---------	---

2309

GX-B1423/20-Y-232438

2023年4月26日

综合判定：合格



2310	GX-B1423/20-Y-232439	2023年4月26日	综合判定：合格	
------	----------------------	------------	---------	---

2311	GX-B1423/20-Y-232440	2023年4月26日	综合判定：合格	
------	----------------------	------------	---------	---

2312	GX-B1423/20-Y-232441	2023年4月26日	综合判定：合格	
------	----------------------	------------	---------	---

2313	GX-B1423/20-Y-232442	2023年4月26日	综合判定：合格	
------	----------------------	------------	---------	---

2314

GX-B1423/20-Y-232443

2023年4月26日

综合判定：合格



2315	GX-B1423/20-Y-232444	2023年4月26日	综合判定：合格	 <p>A photograph of a yellow Sany dump truck parked on a dirt surface. A worker wearing a blue uniform and a high-visibility yellow vest is standing next to the front of the truck. The truck has 'SANY' branding on the side. A yellow timestamp '2023/3/15' is visible in the bottom right corner of the photo.</p>
------	----------------------	------------	---------	---

2316

GX-B1423/20-Y-232445

2023年4月26日

综合判定：合格



2317

GX-B1423/20-Y-232446

2023年4月26日

综合判定：合格



2318

GX-B1423/20-Y-232447

2023年4月26日

综合判定：合格



2319

GX-B1423/20-Y-232448

2023年4月26日

综合判定：合格



2320	GX-B1423/20-Y-232449	2023年4月26日	综合判定：合格	
------	----------------------	------------	---------	---

2321	GX-B1423/20-Y-232450	2023年4月26日	综合判定：合格	
------	----------------------	------------	---------	---

2322	GX-B1423/20-Y-232451	2023年4月26日	综合判定：合格	 A photograph of a yellow dump truck parked on a dirt surface. Two workers wearing high-visibility yellow safety vests and hard hats are standing next to the truck. The truck has 'E715' written on its side. A date stamp '2023/3/16' is visible in the bottom right corner of the photo.
------	----------------------	------------	---------	--

2323

GX-B1423/20-Y-232452

2023年4月26日

综合判定：合格



2324

GX-B1423/20-Y-232453

2023年4月26日

综合判定：合格



2325

GX-B1423/20-Y-232454

2023年4月26日

综合判定：合格



2326	GX-B1423/20-Y-232455	2023年4月26日	综合判定：合格	
------	----------------------	------------	---------	---

2327	GX-B1423/20-Y-232456	2023年4月26日	综合判定：合格	 <p>A photograph of a yellow TONY truck, likely a dump truck, parked on a dirt surface. Two workers wearing safety vests and hard hats are standing in front of the truck. The truck has 'TONLY' and 'AM260' visible on its side. A yellow timestamp '2023/3/16' is visible in the bottom right corner of the photo.</p>
------	----------------------	------------	---------	---

2328

GX-B1423/20-Y-232457

2023年4月26日

综合判定：合格



2329	GX-B1423/20-Y-232458	2023年4月26日	综合判定：合格	
------	----------------------	------------	---------	---

2330	GX-B1423/20-Y-232459	2023年4月26日	综合判定：合格	 A photograph of a yellow TONY TRUCKS SG6010 dump truck. Two workers wearing high-visibility yellow safety vests and hard hats are standing in front of the truck. The truck has 'TONY' and 'SG6010' written on its side. A yellow timestamp '2023/3/16' is visible in the bottom right corner of the photo.
------	----------------------	------------	---------	---

2331	GX-B1423/20-Y-232460	2023年4月26日	综合判定：合格	 A photograph of a yellow TONY truck with license plate M6116. Two workers wearing safety vests and hard hats are standing in front of the truck. The date 2023/3/16 is visible in the bottom right corner of the photo.
------	----------------------	------------	---------	---

2332	GX-B1423/20-Y-232461	2023年4月26日	综合判定：合格	
------	----------------------	------------	---------	---

2333

GX-B1423/20-Y-232462

2023年4月26日

综合判定：合格



2334

GX-B1423/20-Y-232463

2023年4月26日

综合判定：合格



2335	GX-B1423/20-Y-232464	2023年4月26日	综合判定：合格	
------	----------------------	------------	---------	---

2336

GX-B1423/20-Y-232465

2023年4月26日

综合判定：合格



2337

GX-B1423/20-Y-232466

2023年4月26日

综合判定：合格



2338	GX-B1423/20-Y-232467	2023年4月26日	综合判定：合格	
------	----------------------	------------	---------	---

2339

GX-B1423/20-Y-232468

2023年4月26日

综合判定：合格



2340	GX-B1423/20-Y-232469	2023年4月26日	综合判定：合格	
------	----------------------	------------	---------	---

2341	GX-B1423/20-Y-232470	2023年4月26日	综合判定：合格	
------	----------------------	------------	---------	---

2342	GX-B1423/20-Y-232471	2023年4月26日	综合判定：合格	
------	----------------------	------------	---------	---

2343	GX-B1423/20-Y-232472	2023年4月26日	综合判定：合格	
------	----------------------	------------	---------	---

2344

GX-B1423/20-Y-232473

2023年4月26日

综合判定：合格



2345	GX-B1423/20-Y-232474	2023年4月26日	综合判定：合格	
------	----------------------	------------	---------	---

2346	GX-B1423/20-Y-232475	2023年4月26日	综合判定：合格	
------	----------------------	------------	---------	---

2347	GX-B1423/20-Y-232476	2023年4月26日	综合判定：合格	
------	----------------------	------------	---------	---

2348	GX-B1423/20-Y-232477	2023年4月26日	综合判定：合格	
------	----------------------	------------	---------	---

2349

GX-B1423/20-Y-232478

2023年4月26日

综合判定：合格



2350

GX-B1423/20-Y-232479

2023年4月26日

综合判定：合格



2351	GX-B1423/20-Y-232480	2023年4月26日	综合判定：合格	 A photograph of a yellow dump truck with a worker in a high-visibility vest standing next to it. The truck has the number '5' on its side and 'MG015' on the front. A date stamp '2023/4/17' is visible in the bottom right corner of the image.
------	----------------------	------------	---------	--

2352

GX-B1423/20-Y-232481

2023年4月26日

综合判定：合格



2353	GX-B1423/20-Y-232482	2023年4月26日	综合判定：合格	 A photograph showing a yellow dump truck with the number '6' on its side. Two workers in safety gear (hard hats and high-visibility vests) are standing in front of the truck. The date '2023/4/27' is visible in the bottom right corner of the photo.
------	----------------------	------------	---------	---

2354	GX-B1423/20-Y-232483	2023年4月26日	综合判定：合格	
------	----------------------	------------	---------	---

2355	GX-B1423/20-Y-232484	2023年4月26日	综合判定：合格	 A photograph showing a yellow TONLY 6213 truck at a construction site. Two workers in safety gear (hard hats and high-visibility vests) are standing near the truck. The truck has 'TONLY 6213' written on its side. A yellow timestamp '2023/3/17' is visible in the bottom right corner of the photo.
------	----------------------	------------	---------	---

2356	GX-B1423/20-Y-232485	2023年4月26日	综合判定：合格	
------	----------------------	------------	---------	---

2357

GX-B1423/20-Y-232486

2023年4月26日

综合判定：合格



2358

GX-B1423/20-Y-232487

2023年4月26日

综合判定：合格



2359	GX-B1423/20-Y-232488	2023年4月26日	综合判定：合格	
------	----------------------	------------	---------	---

2360	GX-B1423/20-Y-232489	2023年4月26日	综合判定：合格	
------	----------------------	------------	---------	---

2361	GX-B1423/20-Y-232490	2023年4月26日	综合判定：合格	
------	----------------------	------------	---------	---

2362	GX-B1423/20-Y-232491	2023年4月26日	综合判定：合格	 A photograph of a yellow TONY truck, likely a dump truck, parked on a dirt surface. Two workers wearing blue and yellow safety vests and hard hats are standing in front of the truck. The truck has the number '22' on its front bumper and '8122' on its side. A date stamp '2023/4/27' is visible in the bottom right corner of the photo.
------	----------------------	------------	---------	---

2363	GX-B1423/20-Y-232492	2023年4月26日	综合判定：合格	 A photograph of a yellow Tomyo MS107 dump truck parked on a dirt surface. Two workers wearing high-visibility safety vests and hard hats are standing in front of the truck. The truck has 'TOMYO' and 'MS107' visible on its side. A date stamp '2023/3/17' is present in the bottom right corner of the image.
------	----------------------	------------	---------	--

2364	GX-B1423/20-Y-232493	2023年4月26日	综合判定：合格	
------	----------------------	------------	---------	---

2365	GX-B1423/20-Y-232494	2023年4月26日	综合判定：合格	 A photograph of a yellow Yohly 810 dump truck parked on a dirt surface. Two workers wearing high-visibility yellow safety vests and hard hats are standing in front of the truck. The truck has 'YOHLY' and '810' visible on its side. A date stamp '2023/4/26' is present in the bottom right corner of the image.
------	----------------------	------------	---------	---

2366	GX-B1423/20-Y-232495	2023年4月26日	综合判定：合格	
------	----------------------	------------	---------	---

2367	GX-B1423/20-Y-232496	2023年4月26日	综合判定：合格	 A photograph of a yellow TONLY MB12H dump truck parked on a dirt surface. Two workers wearing high-visibility vests and hard hats are standing in front of the truck. The truck has 'TONLY' and 'MB12H' visible on its side. A date stamp '2023/04/26' is present in the bottom right corner of the image.
------	----------------------	------------	---------	--

2368	GX-B1423/20-Y-232497	2023年4月26日	综合判定：合格	
------	----------------------	------------	---------	---

2369	GX-B1423/20-Y-232498	2023年4月26日	综合判定：合格	
------	----------------------	------------	---------	---

2370

GX-B1423/20-Y-232499

2023年4月26日

综合判定：合格



2371	GX-B1423/20-Y-232500	2023年4月26日	综合判定：合格	
------	----------------------	------------	---------	---

2372	GX-B1423/20-Y-232501	2023年4月26日	综合判定：合格	
------	----------------------	------------	---------	---

2373	GX-B1423/20-Y-232502	2023年4月26日	综合判定：合格	
------	----------------------	------------	---------	---

2374	GX-B1423/20-Y-232503	2023年4月26日	综合判定：合格	
------	----------------------	------------	---------	---

2375	GX-B1423/20-Y-232504	2023年4月26日	综合判定：合格	
------	----------------------	------------	---------	---

2376	GX-B1423/20-Y-232505	2023年4月26日	综合判定：合格	
------	----------------------	------------	---------	---

2377	GX-B1423/20-Y-232506	2023年4月26日	综合判定：合格	
------	----------------------	------------	---------	---

2378

GX-B1423/20-Y-232507

2023年4月26日

综合判定：合格



2379

GX-B1423/20-Y-232508

2023年4月26日

综合判定：合格



2380

GX-B1423/20-Y-232509

2023年4月26日

综合判定：合格



2381	GX-B1423/20-Y-232510	2023年4月26日	综合判定：合格	
------	----------------------	------------	---------	---

2382

GX-B1423/20-Y-232511

2023年4月26日

综合判定：合格



2383	GX-B1423/20-Y-232512	2023年4月26日	综合判定：合格	
------	----------------------	------------	---------	---

2384

GX-B1423/20-Y-232513

2023年4月26日

综合判定：合格



2385

GX-B1423/20-Y-232514

2023年4月26日

综合判定：合格



2386	GX-B1423/20-Y-232515	2023年4月26日	综合判定：合格	 <p>A photograph of a yellow TONLY M6733 dump truck. Two workers wearing safety vests and hard hats are standing in front of the truck. The truck has 'TONLY' and 'M6733' written on it. A date stamp '2023/3/18' is visible in the bottom right corner of the photo.</p>
------	----------------------	------------	---------	--

2387	GX-B1423/20-Y-232516	2023年4月26日	综合判定：合格	
------	----------------------	------------	---------	---

2388

GX-B1423/20-Y-232517

2023年4月26日

综合判定：合格



2389

GX-B1423/20-Y-232518

2023年4月26日

综合判定：合格



2390	GX-B1423/20-Y-232519	2023年4月26日	综合判定：合格	
------	----------------------	------------	---------	---

2391

GX-B1423/20-Y-232520

2023年4月26日

综合判定：合格



2392

GX-B1423/20-Y-232521

2023年4月26日

综合判定：合格



2393

GX-B1423/20-Y-232522

2023年4月26日

综合判定：合格



2394

GX-B1423/20-Y-232523

2023年4月26日

综合判定：合格



2395

GX-B1423/20-Y-232524

2023年4月26日

综合判定：合格




2396	GX-B1423/20-Y-232525	2023年4月26日	综合判定：合格	
------	----------------------	------------	---------	---

2397

GX-B1423/20-Y-232526

2023年4月26日

综合判定：合格



2398

GX-B1423/20-Y-232527

2023年4月26日

综合判定：合格

