

序号	报告编号	发布日期	结论	影像资料
398	GX-B1350/21-6-23022	2023/4/23	所检项目合格。	
399	GX-B1423/20-6-23297	2023/4/27	综合判定：合格	

400	GX-B1423/20-6-23298	2023/4/27	综合判定：合格	
401	GX-B1423/20-6-23299	2023/4/27	综合判定：合格	
402	GX-B1423/20-6-23300	2023/4/27	综合判定：合格	

403	GX-B1423/20-6-23301	2023/4/27	综合判定：合格	
404	GX-B1423/20-6-23302	2023/4/27	综合判定：合格	
405	GX-B1423/20-6-23303	2023/4/27	综合判定：合格	

406	GX-B1423/20-6-23304	2023/4/27	综合判定：合格	
407	GX-B1423/20-6-23305	2023/4/27	综合判定：合格	
408	GX-B1423/20-6-23306	2023/4/27	综合判定：合格	

409	GX-B1423/20-6-23307	2023/4/27	综合判定：合格	
410	GX-B1423/20-6-23308	2023/4/27	综合判定：合格	
411	GX-B1423/20-6-23309	2023/4/27	综合判定：合格	

412	GX-B1423/20-6-23310	2023/4/27	综合判定：合格	
413	GX-B1423/20-6-23311	2023/4/27	综合判定：合格	
414	GX-B1423/20-6-23312	2023/4/27	综合判定：合格	



415	GX-B1423/20-6-23313	2023/4/27	综合判定：合格	
416	GX-B1423/20-6-23314	2023/4/27	综合判定：合格	
417	GX-B1423/20-6-23315	2023/4/27	综合判定：合格	

418	GX-B1423/20-6-23316	2023/4/27	综合判定：合格	
419	GX-B1423/20-6-23317	2023/4/27	综合判定：合格	
420	GX-B1423/20-6-23318	2023/4/27	综合判定：合格	




421	GX-B1423/20-6-23319	2023/4/27	综合判定：合格	
422	GX-B1423/20-6-23320	2023/4/27	综合判定：合格	
423	GX-B1423/20-6-23321	2023/4/27	综合判定：合格	

424	GX-B1423/20-6-23322	2023/4/27	综合判定：合格	
425	GX-B1423/20-6-23323	2023/4/27	综合判定：合格	
426	GX-B1423/20-6-23324	2023/4/27	综合判定：合格	

427	GX-B1423/20-6-23325	2023/4/27	综合判定：合格	
428	GX-B1350/21-6-23023	2023. 4. 27	所检项目合格	
429	GX-B1350/21-6-23024	2023. 4. 27	所检项目合格	

430	GX-B1350/21-6-23025	2023. 4. 27	所检项目合格	
431	GX-B1350/21-6-23006	2023/4/28	所检项目合格	
432	GX-B1350/21-6-23007	2023/4/28	所检项目合格	

433	GX-B1350/21-6-23008	2023/4/28	所检项目合格	 A worker wearing a blue protective suit and a blue helmet is working in a dark environment. The worker is holding a tool or device. A timestamp '2023 03 02' is visible in the bottom right corner of the image.
434	GX-B1350/21-6-23009	2023/4/28	所检项目合格	 A worker wearing a red helmet and a blue jacket is working on a structure. The worker is holding a tool or device. A timestamp '2023 03 04' is visible in the bottom right corner of the image.
435	GX-B1350/21-6-23010	2023/4/28	所检项目合格	 A worker wearing a blue protective suit and a blue helmet is working in a dark environment. The worker is holding a tool or device. A timestamp '2023 03 06' is visible in the bottom right corner of the image.

436	GX-B1350/21-6-23011	2023/4/28	所检项目合格	
437	GX-B1350/21-6-23012	2023/4/28	所检项目合格	
438	GX-B1350/21-6-23013	2023/4/28	所检项目合格	 

439	GX-B1350/21-6-23014	2023/4/28	所检项目合格	
440	GX-B1350/21-6-23015	2023/4/28	所检项目合格	
441	GX-B1350/21-6-23016	2023/4/28	所检项目合格	

442	GX-B1352/21-6-23015~23022	2023/4/27	所检项目合格	
443	GX-B1352/21-6-23023~23029	2023/4/27	所检项目合格	
444	GX-B1352/21-6-23030~23047	2023/4/27	所检项目合格	

445	GX-B1352/21-6-23048~23062	2023/4/27	所检项目合格	
446	GX-B1352/21-6-23063~23070	2023/4/27	所检项目合格	
447	GX-B1352/21-6-23071~23093	2023/4/27	所检项目合格	

448	GX-B1352/21-6-23094~23104	2023/4/27	所检项目合格	
449	GX-B1352/21-6-23105~23110	2023/4/27	所检项目合格	
450	GX-B1352/21-6-23111	2023/4/27	所检项目合格	

451	GX-B1352/21-6-23112~23120	2023/4/27	所检项目合格	
452	GX-B1352/21-6-23121~23130	2023/4/27	所检项目合格	
453	GX-B1352/21-6-23131~23144	2023/4/27	所检项目合格	

454	GX-B1352/21-6-23145~23156	2023/4/27	所检项目合格	
455	GX-B1359/21-6-23016~23017	2023/4/28	所检项目合格	
456	GX-B1359/21-6-23018	2023/4/28	所检项目合格	

457	GX-B1359/21-6-23019~23021	2023/4/28	所检项目合格	
458	GX-B1359/21-6-23022~23023	2023/4/28	所检项目合格	
459	GX-B1359/21-6-23024	2023/4/28	所检项目合格	

460	GX-B1359/21-6-23025	2023/4/28	所检项目合格	
461	GX-B1359/21-6-23026	2023/4/28	所检项目合格	
462	GX-B1350/21-6-23027	2023/4/28	所检项目合格	

463	GX-B1359/21-6-23028~23029	2023/4/28	所检项目合格	
464	GX-B1359/21-6-23030	2023/4/28	所检项目合格	
465	GX-B1359/21-6-23031	2023/4/28	所检项目合格	


466	GX-B1359/21-6-23032	2023/4/28	所检项目合格	
467	GX-B1359/21-6-23033~23034	2023/4/28	所检项目合格	
468	GX-B1358/21-6-23002	2023/4/27	所检项目合格。	

469	GX-B1358/21-6-23003	2023/4/27	所检项目合格。	
470	GX-B1358/21-6-23004	2023/4/27	所检项目合格。	
471	GX-B1358/21-6-23005	2023/4/27	所检项目合格。	

472	GX-B1358/21-6-23006	2023/4/27	所检项目合格。	
473	GX-B1354/20-6-23001	2023/4/27	电网接地电容电流 符合规定	
474	GX-B1354/20-6-23002	2023/4/27	电网接地电容电流 符合规定	

475	GX-B1354/20-6-23003	2023/4/27	电网接地电容电流 符合规定	
476	GX-B1322/21-6-23071~23094	2023/4/28	所检项目合格	
477	GX-B1322/21-6-23095~23107	2023/4/28	所检项目合格	

478	GX-B1322/21-6-23108~23119	2023/4/28	所检项目合格	
479	GX-B1322/21-6-23120~23126	2023/4/28	所检项目合格	
480	GX-B1313/21-6-23031~23037	2023/4/27	所检项目合格	




481	GX-B1313/21-6-23038~23044	2023/4/27	所检项目合格	
482	GX-B1313/21-6-23045~23050	2023/4/27	所检项目合格	
483	GX-B1313/21-6-23051~23055	2023/4/27	所检项目合格	

484	GX-B1313/21-6-23021~23026	2023/4/27	所检项目合格	
485	GX-B1313/21-6-23027~23030	2023/4/27	所检项目合格	
486	GX-B1404/20-6-23007	2023/4/26	<p>所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合 GB/T 14549-1993 《电能质量 公用电网谐波》要求。</p>	




487	GX-B1404/20-6-23008	2023/4/26	<p>所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合 GB/T 14549-1993 《电能质量 公用电网谐波》要求。</p>	
488	GX-B1404/20-6-23009	2023/4/26	<p>所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合 GB/T 14549-1993 《电能质量 公用电网谐波》要求。</p>	
489	GX-B1404/20-6-23010	2023/4/26	<p>所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合 GB/T 14549-1993 《电能质量 公用电网谐波》要求。</p>	




490	GX-B1404/20-6-23011	2023/4/26	<p>所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993《电能质量 公用电网谐波》要求。</p>	 <p>2023. 4. 12</p>
491	GX-B1310/21-6-23040	2023/4/25	符合标准要求	 <p>2023 03 23</p>
492	GX-B1310/21-6-23041	2023/4/25	符合标准要求	 <p>2023 03 23</p>

493	GX-B1310/21-6-23042	2023/4/25	符合标准要求	
494	GX-B1310/21-6-23043	2023/4/25	符合标准要求	
495	GX-B1427/21-6-23031	2023/4/25	符合标准要求	

496	GX-B1313/21-6-23016	2023/4/25	所检项目合格	
497	GX-B1451/20-6-23048~23059	2023/4/24	所检项目合格	
498	GX-B1495/20-6-23238~23247	2023/4/28	所检项目合格	



499	GX-B1495/20-6-23248~23255	2023/4/28	所检项目合格	
500	GX-B1495/20-6-23256~23266	2023/4/28	所检项目合格	
501	GX-B1495/20-6-23267~23282	2023/4/28	所检项目合格	

502	GX-B1495/20-6-23283~23295	2023/4/28	所检项目合格	
503	GX-B1495/20-6-23296~23302	2023/4/28	所检项目合格	
504	GX-B1495/20-6-23303~23320	2023/4/28	所检项目合格	

505	GX-B1495/20-6-23321~23342	2023/4/28	所检项目合格	
506	GX-B1495/20-6-23343~23352	2023/4/28	所检项目合格	
507	GX-B1495/20-6-23353~23372	2023/4/28	所检项目合格	

508	GX-B1495/20-6-23373~23383	2023/4/28	所检项目合格	
509	GX-B1495/20-6-23384~23392	2023/4/28	所检项目合格	
510	GX-B1321/20-6-23018~23025	2023/4/27	所检项目合格	

511	GX-B1321/20-6-23026~23030	2023/4/27	所检项目合格	
512	GX-B1321/20-6-23031~23033	2023/4/27	所检项目合格	
513	GX-B1321/20-6-23034~23042	2023/4/27	所检项目合格	

514	GX-B1321/20-6-23043~23050	2023/4/27	所检项目合格	
515	GX-B1321/20-6-23051~23061	2023/4/27	所检项目合格	
516	GX-B1321/20-6-23062~23072	2023/4/27	所检项目合格	

517	GX-B1321/20-6-23073~23079	2023/4/27	所检项目合格	 <p>2023 03 08</p>
518	GX-B1321/20-6-23080~23088	2023/4/27	所检项目合格	 <p>2023 03 08</p>
519	GX-B1321/20-6-23089~23092	2023/4/27	所检项目合格	 <p>2023 03 08</p>

520	GX-B1321/20-6-23093~23101	2023/4/27	所检项目合格	
521	GX-B1321/20-6-23102~23108	2023/4/27	所检项目合格	
522	GX-B1321/20-6-23109~23117	2023/4/27	所检项目合格	

523	GX-B1321/20-6-23118~23127	2023/4/27	所检项目合格	
524	GX-B1321/20-6-23128~23135	2023/4/27	所检项目合格	
525	GX-B1321/20-6-23136~23141	2023/4/27	所检项目合格	

526	GX-B1321/20-6-23142~23143	2023/4/27	所检项目合格	
527	GX-B1321/20-6-23144~23145	2023/4/27	所检项目合格	
528	GX-B1321/20-6-23146~23147	2023/4/27	所检项目合格	

529	GX-B1321/20-6-23148	2023/4/27	所检项目合格	
530	GX-B1321/20-6-23149~23154	2023/4/27	所检项目合格	
531	GX-B1321/20-6-23155~23161	2023/4/27	所检项目合格	



532	GX-B1321/20-6-23162~23167	2023/4/27	所检项目合格	 A worker wearing a red hard hat is focused on working with electrical components inside a cabinet. The scene is brightly lit, and the worker is wearing a dark blue uniform. A timestamp '2023 03 22' is visible in the bottom right corner of the photo.
533	GX-B1321/20-6-23168~23173	2023/4/27	所检项目合格	 A worker in a red hard hat is working on a piece of electrical equipment. In the background, a red banner with yellow Chinese characters is visible. The worker is wearing a dark uniform. A timestamp '2023 03 23' is visible in the bottom right corner of the photo.
534	GX-B1321/20-6-23174~23179	2023/4/27	所检项目合格	 A worker in a red hard hat is working on a row of electrical cabinets. A large red banner with yellow Chinese characters '运行中' (In Operation) is prominently displayed. The worker is wearing a dark uniform. A timestamp '2023 03 24' is visible in the bottom right corner of the photo.

535	GX-B1321/20-6-23180~23185	2023/4/27	所检项目合格	 <p>2023 03 25</p>
536	GX-B1321/20-6-23186~23191	2023/4/27	所检项目合格	 <p>2023 03 26</p>
537	GX-B1321/20-6-23192~23198	2023/4/27	所检项目合格	 <p>2023 03 26</p>

538	GX-B1321/20-6-23199~23204	2023/4/27	所检项目合格	
539	GX-B1329/21-6-23020~23031	2023/4/27	所检项目合格	
540	GX-B1329/21-6-23032~23046	2023/4/27	所检项目合格	

541	GX-B1423/20-6-23352	2023/4/28	综合判定：合格	
542	GX-B1423/20-6-23353	2023/4/28	综合判定：合格	
543	GX-B1423/20-6-23354	2023/4/28	综合判定：合格	



544	GX-B1423/20-6-23355	2023/4/28	综合判定：合格	
545	GX-B1520/20-6-23045	2023/4/28	综合判定：合格。	
546	GX-B1520/20-6-23046	2023/4/28	综合判定：合格。	

547	GX-B1404/20-6-23012	2023. 4. 28	<p>所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合 GB/T 14549-1993 《电能质量 公用电网谐波》要求。</p>	
548	GX-B1404/20-6-23013	2023. 4. 28	<p>所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合 GB/T 14549-1994 《电能质量 公用电网谐波》要求。</p>	
549	GX-B1404/20-6-23014	2023. 4. 28	<p>所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合 GB/T 14549-1995 《电能质量 公用电网谐波》要求。</p>	

550	GX-B1404/20-6-23015	2023. 4. 28	<p>所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合 GB/T 14549-1996 《电能质量 公用电网谐波》要求。</p>	 <p>2023. 4. 13</p>
551	GX-B1404/20-6-23016	2023. 4. 28	<p>所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合 GB/T 14549-1997 《电能质量 公用电网谐波》要求。</p>	 <p>2023. 4. 13</p>
552	GX-B1404/20-6-23017	2023. 4. 28	<p>所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合 GB/T 14549-1998 《电能质量 公用电网谐波》要求。</p>	 <p>2023. 4. 13</p>

553	GX-B1307/20-6-23004	2023. 4. 28	合格	 <p>2023 03 28</p>
554	GX-B1300/20-6-23002	2023. 4. 28	合格	 <p>2023. 03. 03</p>
555	GX-B1313/21-6-23056	2023/4/28	所检项目合格	 <p>2023 04 02</p>

556	GX-B1322/21-6-23127~23128	2023/4/28	所检项目合格	
557	GX-B1323/21-6-23030~23031	2023/4/26	所检项目合格	
558	GX-B1323/21-6-23032~23033	2023/4/26	所检项目合格	

559	GX-B1323/21-6-23034~23035	2023/4/26	所检项目合格	
560	GX-B1323/21-6-23036~23041	2023/4/26	所检项目合格	
561	GX-B1323/21-6-23042~23044	2023/4/26	所检项目合格	

562	GX-B1323/21-6-23045~23049	2023/4/26	所检项目合格	 A photograph showing two workers in blue protective suits and reflective gear working in a tunnel. They are positioned near a large piece of equipment, possibly a fan or motor. The tunnel walls are blue and there are various pipes and structures visible. A timestamp '2023 03 05' is visible in the bottom right corner of the image.
563	GX-B1323/21-6-23050~23053	2023/4/26	所检项目合格	 A photograph showing two workers in blue protective suits and reflective gear working in a tunnel. They are positioned near a large piece of equipment, possibly a fan or motor. The tunnel walls are blue and there are various pipes and structures visible. A timestamp '2023 03 08' is visible in the bottom right corner of the image.
564	GX-B1323/21-6-23054~23057	2023/4/26	所检项目合格	 A photograph showing a worker in a blue protective suit and reflective gear working in a tunnel. The worker is focused on a piece of equipment, possibly a fan or motor, which is illuminated by a bright light. The tunnel walls are blue and there are various pipes and structures visible. A timestamp '2023 03 09' is visible in the bottom right corner of the image.




565	GX-B1312/20-6-23049~23050	2023/4/28	所检项目合格	 <p>A photograph showing several workers in safety gear (hard hats, reflective vests) inspecting a red rail vehicle in a tunnel. The workers are gathered around the vehicle, and one is holding a clipboard. The scene is brightly lit by overhead lights. A timestamp '2023 03 01' is visible in the bottom right corner of the image.</p>
566	GX-B1312/20-6-23051	2023/4/28	所检项目合格	 <p>A photograph showing workers in a dark tunnel inspecting a red rail vehicle. The workers are using headlamps for illumination. The scene is dimly lit, with the primary light source being the workers' headlamps. A timestamp '2023 03 02' is visible in the bottom right corner of the image.</p>
567	GX-B1312/20-6-23052~23054	2023/4/28	所检项目合格	 <p>A photograph showing workers in a dark tunnel inspecting a blue rail vehicle. The workers are using headlamps for illumination. The scene is dimly lit, with the primary light source being the workers' headlamps. A timestamp '2023 03 04' is visible in the bottom right corner of the image.</p>




568	GX-B1312/20-6-23055~23057	2023/4/28	所检项目合格	
569	GX-B1312/20-6-23058~23061	2023/4/28	所检项目合格	
570	GX-B1312/20-6-23062~23065	2023/4/28	所检项目合格	


571	GX-B1312/20-6-23066~23067	2023/4/28	所检项目合格	
572	GX-B1312/20-6-23068	2023/4/28	所检项目合格	
573	GX-B1312/20-6-23069~23070	2023/4/28	所检项目合格	




574	GX-B1312/20-6-23071~23072	2023/4/28	所检项目合格	
575	GX-B1312/20-6-23073~23075	2023/4/28	所检项目合格	
576	GX-B1312/20-6-23076~23078	2023/4/28	所检项目合格	



577	GX-B1312/20-6-23079	2023/4/28	所检项目合格	
578	GX-B1312/20-6-23080~23081	2023/4/28	所检项目合格	
579	GX-B1312/20-6-23082~23085	2023/4/28	所检项目合格	

580	GX-B1328/20-6-23023	2023/4/28	所检项目合格	
581	GX-B1328/20-6-23024	2023/4/29	所检项目合格	
582	GX-B1328/20-6-23025	2023/4/30	所检项目合格	

583	GX-B1328/20-6-23026	2023/5/1	所检项目合格	 <p>2023-02-26</p>
584	GX-B1322/21-6-23022~23038	2023/4/28	所检项目合格	 <p>2023 04 22</p>
585	GX-B1322/21-6-23039~23053	2023/4/28	所检项目合格	 <p>2023 04 23</p>




586	GX-B1322/21-6-23054~23059	2023/4/28	所检项目合格	
587	GX-B1322/21-6-23060~23070	2023/4/28	所检项目合格	
588	GX-B1451/20-6-23060~23082	2023. 4. 27	所检项目合格	

589	GX-B1451/20-6-23083~23107	2023. 4. 27	所检项目合格	
590	GX-B1451/20-6-23108~23128	2023. 4. 27	所检项目合格	
591	GX-B1451/20-6-23129~23140	2023. 4. 27	所检项目合格	




592	GX-B1451/20-6-23141~23158	2023. 4. 28	所检项目合格	
593	GX-B1451/20-6-23159~23175	2023. 4. 28	所检项目合格	
594	GX-B1451/20-6-23176~23185	2023. 4. 28	所检项目合格	




595	GX-B1451/20-6-23186~23189	2023. 4. 28	所检项目合格	 <p>2023 04 25</p>
596	GX-B1423/20-6-23427	2023/4/28	综合判定：合格	 <p>2023 04 24</p>
597	GX-B1423/20-6-23428	2023/4/28	综合判定：合格	 <p>2023 04 24</p>




598	GX-B1423/20-6-23429	2023/4/28	综合判定：合格	 <p>2023 04 24</p>
599	GX-B1423/20-6-23430	2023/4/28	综合判定：合格	 <p>2023 04 24</p>
600	GX-B1423/20-6-23431	2023/4/28	综合判定：合格	 <p>2023 04 24</p>




601	GX-B1328/20-6-23064	4.28	本次共检绝缘手套8只，8只绝缘手套所检项目合格。	
602	GX-B1328/20-6-23065	4.28	本次共检全橡胶绝缘胶靴8只，8只全橡胶绝缘胶靴所检项目合格。	
603	GX-B1328/20-6-23066	4.28	本次共检验电器5支，5支验电器所检项目合格	




604	GX-B1328/20-6-23067	4.28	所检项目合格。	 <p>2023 04 03</p>
605	GX-B1328/20-6-23068	4.28	所检项目合格。	
606	GX-B1423/20-6-23205	2023/4/28	综合判定：合格	 <p>2023 3 24</p>

607	GX-B1423/20-6-23206	2023/4/28	综合判定：合格	 <p>2023 3 24</p>
608	GX-B1423/20-6-23207	2023/4/28	综合判定：合格	 <p>2023 3 24</p>
609	GX-B1423/20-6-23208	2023/4/28	综合判定：合格	 <p>2023 3 24</p>

610	GX-B1423/20-6-23209	2023/4/28	综合判定：合格		
611	GX-B1423/20-6-23210	2023/4/28	综合判定：合格		
612	GX-B1423/20-6-23211	2023/4/28	综合判定：合格		

613	GX-B1423/20-6-23212	2023/4/28	综合判定：合格	
614	GX-B1423/20-6-23213	2023/4/28	综合判定：合格	
615	GX-B1423/20-6-23214	2023/4/28	综合判定：合格	

616	GX-B1423/20-6-23215	2023/4/28	综合判定：合格	
617	GX-B1423/20-6-23216	2023/4/28	综合判定：合格	
618	GX-B1423/20-6-23217	2023/4/28	综合判定：合格	

619	GX-B1423/20-6-23218	2023/4/28	综合判定：合格	
620	GX-B1423/20-6-23219	2023/4/28	综合判定：合格	
621	GX-B1423/20-6-23220	2023/4/28	综合判定：合格	

622	GX-B1423/20-6-23221	2023/4/28	综合判定：合格	
623	GX-B1423/20-6-23222	2023/4/28	综合判定：合格	
624	GX-B1423/20-6-23223	2023/4/28	综合判定：合格	

625	GX-B1423/20-6-23224	2023/4/28	综合判定：合格	
626	GX-B1423/20-6-23225	2023/4/28	综合判定：合格	
627	GX-B1423/20-6-23226	2023/4/28	综合判定：合格	

628	GX-B1423/20-6-23227	2023/4/28	综合判定：合格	
629	GX-B1423/20-6-23228	2023/4/28	综合判定：合格	
630	GX-B1423/20-6-23229	2023/4/28	综合判定：合格	

631	GX-B1423/20-6-23230	2023/4/28	综合判定：合格	
632	GX-B1423/20-6-23231	2023/4/28	综合判定：合格	
633	GX-B1423/20-6-23232	2023/4/28	综合判定：合格	

634	GX-B1423/20-6-23233	2023/4/28	综合判定：合格	 A photograph showing two workers in safety gear (one in grey, one in blue) standing next to a yellow cabinet with the number '80' in red. The date '2023 3 28' is visible in the bottom right corner of the photo.
635	GX-B1423/20-6-23234	2023/4/28	综合判定：合格	 A photograph showing two workers in safety gear (one in grey, one in blue) standing next to a yellow cabinet with the number '101' in red. The date '2023 3 28' is visible in the bottom right corner of the photo.
636	GX-B1423/20-6-23235	2023/4/28	综合判定：合格	 A photograph showing two workers in safety gear (one in grey, one in blue) standing next to a yellow cabinet with the number '79' in red. The date '2023 3 28' is visible in the bottom right corner of the photo.

637	GX-B1423/20-6-23236	2023/4/28	综合判定：合格	 A photograph showing two workers in a yellow container. The worker on the left is wearing a grey uniform and a red hard hat. The worker on the right is wearing a blue uniform. The container has the number '78' written in red on its side. A date stamp '2023 3 28' is visible in the bottom right corner of the photo.
638	GX-B1423/20-6-23237	2023/4/28	综合判定：合格	 A photograph showing two workers in a yellow container. The worker on the left is wearing a grey uniform and a red hard hat. The worker on the right is wearing a blue uniform. The container has the number '95' written in red on its side. A date stamp '2023 3 28' is visible in the bottom right corner of the photo.
639	GX-B1423/20-6-23238	2023/4/28	综合判定：合格	 A photograph showing two workers in a yellow container. The worker on the left is wearing a grey uniform and a red hard hat. The worker on the right is wearing a black shirt and blue pants. The container has the number '93' written in red on its side. A date stamp '2023 3 28' is visible in the bottom right corner of the photo.

640	GX-B1423/20-6-23239	2023/4/28	综合判定：合格	 A photograph showing two workers in a yellow enclosure. The worker on the left is wearing a grey jacket and black pants, while the worker on the right is wearing a grey uniform and a red hard hat. The enclosure has the number '98' written in red on the left side. A date stamp '2023 3 28' is visible in the bottom right corner of the photo.
641	GX-B1423/20-6-23240	2023/4/28	综合判定：合格	 A photograph showing two workers in a yellow enclosure. The worker on the left is wearing a grey uniform and a red hard hat, while the worker on the right is wearing a blue uniform. The enclosure has the number '96' written in red on the left side. A date stamp '2023 3 28' is visible in the bottom right corner of the photo.
642	GX-B1423/20-6-23241	2023/4/28	综合判定：合格	 A photograph showing two workers in a yellow enclosure. The worker on the left is wearing a grey uniform and a red hard hat, while the worker on the right is wearing a blue uniform. The enclosure has the number '89' written in red on the left side. A date stamp '2023 3 28' is visible in the bottom right corner of the photo.

643	GX-B1423/20-6-23242	2023/4/28	综合判定：合格	 A photograph showing two workers in a room with green lockers. The locker in the foreground is labeled '108' in red. One worker is wearing a grey uniform and a red hard hat, and the other is wearing a blue uniform and a yellow hard hat. A timestamp '2023 3 28' is visible in the bottom right corner of the photo.
644	GX-B1423/20-6-23243	2023/4/28	综合判定：合格	 A photograph showing two workers in a room with green lockers. The locker in the foreground is labeled '109' in red. One worker is wearing a grey uniform and a red hard hat, and the other is wearing a blue uniform and a yellow hard hat. A timestamp '2023 3 29' is visible in the bottom right corner of the photo.
645	GX-B1423/20-6-23244	2023/4/28	综合判定：合格	 A photograph showing two workers in a room with green lockers. The lockers in the foreground are labeled '126' in red. One worker is wearing a grey uniform and a red hard hat, and the other is wearing a blue uniform and a yellow hard hat. A timestamp '2023 3 29' is visible in the bottom right corner of the photo.

646	GX-B1423/20-6-23245	2023/4/28	综合判定：合格	 A photograph showing two workers in a green industrial enclosure. The enclosure has the number '127' written in large red characters. One worker is wearing a blue uniform and a red hard hat, while the other is wearing a grey uniform and a red hard hat. They are standing on a metal floor. A timestamp '2023 3 20' is visible in the bottom right corner of the photo.
647	GX-B1423/20-6-23246	2023/4/28	综合判定：合格	 A photograph showing two workers in a green industrial enclosure. The enclosure has the number '131' written in large red characters. One worker is wearing a grey uniform and a red hard hat, while the other is wearing a blue uniform and a red hard hat. They are standing on a metal floor. A timestamp '2023 3 20' is visible in the bottom right corner of the photo.
648	GX-B1423/20-6-23247	2023/4/28	综合判定：合格	 A photograph showing two workers in a green industrial enclosure. The enclosure has the number '133' written in large red characters. One worker is wearing a grey uniform and a red hard hat, while the other is wearing a blue uniform and a red hard hat. They are standing on a metal floor. A timestamp '2023 3 20' is visible in the bottom right corner of the photo.

649	GX-B1423/20-6-23248	2023/4/28	综合判定：合格	
650	GX-B1423/20-6-23249	2023/4/28	综合判定：合格	
651	GX-B1423/20-6-23250	2023/4/28	综合判定：合格	

652	GX-B1423/20-6-23251	2023/4/28	综合判定：合格	
653	GX-B1423/20-6-23252	2023/4/28	综合判定：合格	
654	GX-B1423/20-6-23253	2023/4/28	综合判定：合格	

