

序号	报告编号	发布日期	结论	影像资料
1	GX-B1363/22-A-23244	2023/6/2	所检项目合格。	 <p>The photograph shows two men in light blue work shirts and dark trousers inspecting a large, rusted industrial furnace. The furnace has a tall chimney pipe extending from the top. One man is on the left, looking at the furnace, while the other is on the right, touching the top of the furnace. The room has a window with a view of greenery outside and a large green fan on the right. A green trash bin is visible on the left. A date stamp '2023/05/30' is visible in the bottom right corner of the photo.</p>

序号	报告编号	发布日期	结论	影像资料
2	GX-B1364/22-A-23438	2023/6/1	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
3	GX-B1364/22-A-23417	2023/6/1	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
4	GX-B1364/22-A-23409	2023/6/1	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
5	GX-B1364/22-A-23442	2023/6/1	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
6	GX-B1364/22-A-23441	2023/6/1	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
7	GX-B1364/22-A-23440	2023/6/1	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
8	GX-B1364/22-A-23439	2023/6/1	所检项目合格。	 <p>2023/05/26</p>



序号	报告编号	发布日期	结论	影像资料
9	GX-B1364/22-A-23436	2023/6/1	成束电线电缆燃烧试验不合格，其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
10	GX-B1364/22-A-23435	2023/6/1	成束电线电缆燃烧试验不合格；其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
11	GX-B1364/22-A-23434	2023/6/1	成束电线电缆燃烧试验不合格；其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
12	GX-B1364/22-A-23433	2023/6/1	成束电线电缆燃烧试验不合格；其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
13	GX-B1364/22-A-23432	2023/6/1	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
14	GX-B1364/22-A-23431	2023/6/1	成束电线电缆燃烧试验不合格；其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
15	GX-B1364/22-A-23430	2023/6/1	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
16	GX-B1364/22-A-23429	2023/6/1	所检项目合格。	



序号	报告编号	发布日期	结论	影像资料
17	GX-B1364/22-A-23428	2023/6/1	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
18	GX-B1364/22-A-23427	2023/6/1	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
19	GX-B1364/22-A-23425	2023/6/1	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
20	GX-B1364/22-A-23424	2023/6/1	成束电线电缆燃烧试验不合格；其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
21	GX-B1364/22-A-23423	2023/6/1	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
22	GX-B1364/22-A-23421	2023/6/1	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
23	GX-B1364/22-A-23420	2023/6/1	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
24	GX-B1364/22-A-23418	2023/6/1	所检项目合格。	



序号	报告编号	发布日期	结论	影像资料
25	GX-B1364/22-A-23411	2023/6/1	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
26	GX-B1364/22-A-23410	2023/6/1	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
27	GX-B1364/22-A-23406	2023/6/1	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
28	GX-B1364/22-A-23407	2023/6/1	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
29	GX-B1364/22-A-23408	2023/6/1	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
30	GX-B1364/22-A-23405	2023/6/1	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
31	GX-B1364/22-A-23404	2023/6/1	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
32	GX-B1364/22-A-23403	2023/6/1	所检项目合格。	



序号	报告编号	发布日期	结论	影像资料
33	GX-B1364/22-A-23402	2023/6/1	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
34	GX-B1364/22-A-23422	2023/6/1	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
35	GX-B1364/22-A-23426	2023/6/1	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
36	GX-B1364/22-A-23419	2023/6/1	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
37	GX-B1364/22-A-23362	2023/6/1	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
38	GX-B1369/20-A-23005	2023/6/1	所检项目合格。	 <p>The photograph captures two technicians in white lab coats with the '中检公信' (CIC) logo on the back, engaged in a technical inspection or adjustment of a large industrial machine. One technician is focused on a large circular dial with a red border, while the other is positioned inside a green metal safety enclosure, possibly adjusting a component. A date stamp '2023/05/27' is present in the bottom right corner of the image.</p>

序号	报告编号	发布日期	结论	影像资料
39	GX-B1369/20-A-23006	2023/6/1	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
40	GX-B1462/22-A-23005	2023/6/1	所检项目合格。	



序号	报告编号	发布日期	结论	影像资料
41	GX-B1363/22-A-23161	2023/6/8	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
42	GX-B1363/22-A-23162	2023/6/8	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
43	GX-B1363/22-A-23167	2023/6/8	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
44	GX-B1363/22-A-23164	2023/6/8	所检项目合格。	 <p>The photograph shows two technicians in light blue uniforms inspecting a large industrial machine with a tall chimney stack. A green trash bin is visible on the left. A date stamp '2023/05/26' is in the bottom right corner.</p>

序号	报告编号	发布日期	结论	影像资料
45	GX-B1363/22-A-23166	2023/6/8	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
46	GX-B1363/22-A-23165	2023/6/8	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
47	GX-B1363/22-A-23163	2023/6/8	所检项目合格。	 <p>2023/05/26</p>

序号	报告编号	发布日期	结论	影像资料
48	GX-B1363/22-A-23160	2023/6/8	所检项目合格。	



序号	报告编号	发布日期	结论	影像资料
49	GX-B1363/22-A-23159	2023/6/8	所检项目合格。	 <p>The image shows two men in light blue work shirts inspecting a large, rusted industrial machine. One man is wearing green gloves. The machine has a vertical pipe on top and several doors with yellow warning labels. A date stamp '2023/05/18' is visible in the bottom right corner of the photo. The setting appears to be an indoor industrial or laboratory space with a window in the background.</p>

序号	报告编号	发布日期	结论	影像资料
50	GX-B1363/22-A-23158	2023/6/8	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
51	GX-B1363/22-A-23157	2023/6/8	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
52	GX-B1363/22-A-23156	2023/6/8	所检项目合格。	 <p>The photograph shows two men in light blue work shirts inspecting a large, rusted metal cabinet. One man is on the left, looking into an open compartment. The other man is on the right, wearing green gloves and looking at the cabinet's exterior. A white chimney pipe extends from the top of the cabinet. The scene is indoors, with a window in the background showing greenery outside. A date stamp '2023/05/15' is visible in the bottom right corner of the image.</p>

53

GX-B1364/22-A-23489

2023/6/9

所检项目合格。

