

序号	报告编号	发布日期	结论	影像资料
368	GX-B1495/20-Y-231334~231335	2023年6月10日	本次共检电压互感器2组，2组电压互感器所检项目合格。	
369	GX-B1495/20-Y-231336~231337	2023年6月10日	本次共检电压互感器2组，2组电压互感器所检项目合格。	

370	GX-B1495/20-Y-231338~231347	2023年6月10日	本次共检电压互感器10组，10组电压互感器所检项目合格。	
371	GX-B1495/20-Y-231348~231349	2023年6月10日	本次共检电压互感器2组，2组电压互感器所检项目合格。	

372	GX-B1495/20-Y-231350~231351	2023年6月10日	本次共检电压互感器2组，2组电压互感器所检项目合格。	
373	GX-B1495/20-Y-231352~231353	2023年6月10日	本次共检电压互感器2组，2组电压互感器所检项目合格。	

374	GX-B1495/20-Y-231354~231365	2023年6月10日	本次共检电压互感器12组，12组电压互感器所检项目合格。	 <p>A photograph showing a worker in a red safety suit and helmet working on a red electrical cabinet. The worker is using a tool to inspect or adjust a component inside the cabinet. The date 2023/5/6 is visible in the bottom right corner of the image.</p>
375	GX-B1495/20-Y-2313566~231377	2023年6月10日	本次共检电压互感器12组，12组电压互感器所检项目合格。	 <p>A photograph showing two workers in red safety suits and helmets working on a red electrical cabinet. One worker is standing and looking at the cabinet, while the other is kneeling and working on a component inside. The date 2023/5/7 is visible in the bottom right corner of the image.</p>

376	GX-B1495/20-Y-2313578~231389	2023年6月10日	本次共检电压互感器12组，12组电压互感器所检项目合格。	
377	GX-B1423/20-Y-232847	2023年6月13日	综合判定：合格	

378	GX-B1423/20-Y-232848	2023年6月13日	综合判定：合格	 A yellow MTBGA dump truck is parked on a dirt surface. Two workers in safety gear stand in front of it. The license plate reads AH-2224. A yellow timestamp '2023/6/28' is visible in the bottom right corner of the photo.
379	GX-B1423/20-Y-232849	2023年6月13日	综合判定：合格	 A yellow MTBGA dump truck is parked on a dirt surface. Two workers in safety gear stand in front of it. The license plate reads AH-2226. A yellow timestamp '2023/6/28' is visible in the bottom right corner of the photo.

380	GX-B1423/20-Y-232850	2023年6月13日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers in safety gear stand in front of it. The license plate reads GX-B1423/20-Y-232850. A yellow timestamp '2023-6-13' is visible in the bottom right corner of the photo.
381	GX-B1423/20-Y-232851	2023年6月13日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers in safety gear stand in front of it. The license plate reads GX-B1423/20-Y-232851. A yellow timestamp '2023-6-13' is visible in the bottom right corner of the photo.

382	GX-B1423/20-Y-232852	2023年6月13日	综合判定：合格	
383	GX-B1423/20-Y-232853	2023年6月13日	综合判定：合格	

384	GX-B1423/20-Y-232854	2023年6月13日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers wearing hard hats and safety vests are standing in front of the truck. The truck has a license plate that reads 'A-K-2223'. A yellow timestamp '2023/6/28' is visible in the bottom right corner of the image.
385	GX-B1423/20-Y-232855	2023年6月13日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers wearing hard hats and safety vests are standing in front of the truck. The truck has a license plate that reads 'A-K-2223'. A yellow timestamp '2023/6/28' is visible in the bottom right corner of the image.

386	GX-B1423/20-Y-232856	2023年6月13日	综合判定：合格	 A yellow MT884 dump truck is shown from a front-three-quarter view. The truck bed is empty. Two workers in safety gear stand in front of the truck. The license plate area displays '桂H-2204'. A yellow date stamp '2023/6/28' is visible in the bottom right corner of the image.
387	GX-B1423/20-Y-232857	2023年6月13日	综合判定：合格	 A yellow MT884 dump truck is shown from a front-three-quarter view. The truck bed is filled with a light-colored material. Two workers in safety gear stand in front of the truck. The license plate area displays '桂H-2203'. A yellow date stamp '2023/6/28' is visible in the bottom right corner of the image.

388	GX-B1423/20-Y-232858	2023年6月13日	综合判定：合格	 A yellow dump truck is parked on a dirt field. Two workers in safety gear are standing near the front of the truck. The truck has 'WTECH' written on its side. A yellow timestamp '2023-4-28' is visible in the bottom right corner of the image.
389	GX-B1423/20-Y-232859	2023年6月13日	综合判定：合格	 A yellow dump truck is parked on a dirt field. Two workers in safety gear are standing near the front of the truck. The truck has 'WTECH' written on its side. A yellow timestamp '2023-4-28' is visible in the bottom right corner of the image.

390	GX-B1423/20-Y-232860	2023年6月13日	综合判定：合格	 A yellow MT800 dump truck is parked on a dirt surface. Two workers wearing hard hats and safety vests are standing in front of the truck. The license plate on the truck reads 'H-2215'. A yellow timestamp '2023/4/28' is visible in the bottom right corner of the photo.
391	GX-B1423/20-Y-232861	2023年6月13日	综合判定：合格	 A yellow MT800 dump truck is parked on a dirt surface. Two workers wearing hard hats and safety vests are standing in front of the truck. The license plate on the truck reads 'H-2245'. A yellow timestamp '2023/4/28' is visible in the bottom right corner of the photo.

392	GX-B1423/20-Y-232862	2023年6月13日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers in safety gear are standing in front of the truck. The truck has 'MTBE' and '4-208' visible on its side. A yellow timestamp '2023/4/28' is in the bottom right corner.
393	GX-B1423/20-Y-232863	2023年6月13日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. A worker in safety gear is standing next to the truck. The truck has 'MTBE' and '4-208' visible on its side. A yellow timestamp '2023/4/28' is in the bottom right corner.

394	GX-B1423/20-Y-232864	2023年6月13日	综合判定：合格	 A yellow MTBE H-2220 dump truck is shown from a side-rear perspective. A person in a white uniform and red helmet is standing next to the truck, looking at a clipboard. The truck has 'MTBE H-2220' written on its side. A yellow date stamp '2023/4/28' is visible in the bottom right corner of the image.
395	GX-B1423/20-Y-232865	2023年6月13日	综合判定：合格	 A yellow MTBE H-2220 dump truck is shown from a side-rear perspective. A person in a white uniform and red helmet is standing next to the truck, looking at a clipboard. The truck has 'MTBE H-2220' written on its side. A yellow date stamp '2023/4/28' is visible in the bottom right corner of the image.

396	GX-B1423/20-Y-232866	2023年6月13日	综合判定：合格	 A yellow dump truck with the identification number H-2213 and MTB on the side. A person in a white uniform and red helmet stands next to the truck. A yellow date stamp '2023/6/28' is visible in the bottom right corner of the photo.
397	GX-B1423/20-Y-232867	2023年6月13日	综合判定：合格	 A yellow dump truck with the identification number H-2205 and 05 on the side. A person in a white uniform and red helmet stands next to the truck. A yellow date stamp '2023/6/28' is visible in the bottom right corner of the photo.

398	GX-B1423/20-Y-232868	2023年6月13日	综合判定：合格	
399	GX-B1423/20-Y-232869	2023年6月13日	综合判定：合格	

400	GX-B1423/20-Y-232870	2023年6月13日	综合判定：合格	 A yellow dump truck with license plate H-2244 is parked on a dirt surface. Two workers in safety gear stand in front of it. A yellow timestamp '2023/4/29' is visible in the bottom right corner of the photo.
401	GX-B1423/20-Y-232871	2023年6月13日	综合判定：合格	 A yellow dump truck with license plate H-2243 is parked on a dirt surface. Two workers in safety gear stand in front of it. A yellow timestamp '2023/4/29' is visible in the bottom right corner of the photo.

402	GX-B1423/20-Y-232872	2023年6月13日	综合判定：合格	 A yellow MT980 dump truck is parked on a dirt surface. The truck has the number '78' on its side and 'MT980' on the front. Two workers wearing hard hats and safety vests are standing in front of the truck. A yellow timestamp '2023428' is visible in the bottom right corner of the image.
403	GX-B1423/20-Y-232873	2023年6月13日	综合判定：合格	 A yellow MT980 dump truck is parked on a dirt surface. The truck has the number '78' on its side and 'MT980' on the front. Two workers wearing hard hats and safety vests are standing in front of the truck. A yellow timestamp '2023428' is visible in the bottom right corner of the image.

404	GX-B1423/20-Y-232874	2023年6月13日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two men in work clothes and hard hats are standing next to it. The truck has 'MT96L' and 'H-2209' visible on its side. A yellow date stamp '2023/6/29' is in the bottom right corner.
405	GX-B1423/20-Y-232875	2023年6月13日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two men in work clothes and hard hats are standing next to it. The truck has 'H-2210' visible on its side. A yellow date stamp '2023/6/29' is in the bottom right corner.

406	GX-B1423/20-Y-232876	2023年6月13日	综合判定：合格	
407	GX-B1423/20-Y-232877	2023年6月13日	综合判定：合格	

408	GX-B1423/20-Y-232878	2023年6月13日	综合判定：合格	 A yellow MT96L dump truck is parked on a dirt surface. Two workers in safety gear stand in front of it. The license plate reads H-2241. A date stamp '2023-6-29' is visible in the bottom right corner of the photo.
409	GX-B1423/20-Y-232879	2023年6月13日	综合判定：合格	 A yellow MT96L dump truck is parked on a dirt surface. Two workers in safety gear stand in front of it. The license plate reads H-2229. A date stamp '2023-6-29' is visible in the bottom right corner of the photo.

410	GX-B1423/20-Y-232880	2023年6月13日	综合判定：合格	
411	GX-B1423/20-Y-232881	2023年6月13日	综合判定：合格	



412	GX-B1423/20-Y-232882	2023年6月13日	综合判定：合格	 A yellow MT96L dump truck is shown from a front-three-quarter view. Two workers in safety gear stand in front of the truck. The license plate reads 'H-2211'. A yellow timestamp '2023/4/28' is visible in the bottom right corner of the photo.
413	GX-B1423/20-Y-232883	2023年6月13日	综合判定：合格	 A yellow MT96L dump truck is shown from a front-three-quarter view. A worker in safety gear stands in front of the truck. The license plate reads 'H-2242'. A yellow timestamp '2023/4/29' is visible in the bottom right corner of the photo.

414	GX-B1423/20-Y-232884	2023年6月13日	综合判定：合格	 A yellow MT963 dump truck is parked on a dirt surface. Two workers wearing hard hats and safety vests are standing in front of the truck. The truck has the number '89' on its side and 'MT963' on the front. A yellow timestamp '2023/6/29' is visible in the bottom right corner of the photo.
415	GX-B1423/20-Y-232885	2023年6月13日	综合判定：合格	 A yellow MT963 dump truck is parked on a dirt surface. Two workers wearing hard hats and safety vests are standing in front of the truck. The truck has the number '14-2070' on its side and 'MT963' on the front. A yellow timestamp '2023/6/29' is visible in the bottom right corner of the photo.

416	GX-B1423/20-Y-232886	2023年6月13日	综合判定：合格	
417	GX-B1423/20-Y-232887	2023年6月13日	综合判定：合格	

418	GX-B1423/20-Y-232888	2023年6月13日	综合判定：合格	 A yellow MT550 truck is shown from a front-three-quarter view. Two workers in safety gear stand in front of it. The truck has 'MT550' and 'H-2227' visible on its side. A date stamp '2023/4/30' is in the bottom right corner.
419	GX-B1423/20-Y-232889	2023年6月13日	综合判定：合格	 A yellow MT550 truck is shown from a rear-three-quarter view. Two workers in safety gear stand in front of it. The truck has 'MT550' and 'H-2240' visible on its side. A date stamp '2023/4/30' is in the bottom right corner.

420	GX-B1423/20-Y-232890	2023年6月13日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers wearing hard hats and safety vests are standing in front of the truck. The license plate on the truck reads "H-2231". A yellow timestamp "2023-4-26" is visible in the bottom right corner of the image.
421	GX-B1423/20-Y-232891	2023年6月13日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers wearing hard hats and safety vests are standing in front of the truck. The license plate on the truck reads "H-2229". A yellow timestamp "2023-4-26" is visible in the bottom right corner of the image.

422	GX-B1423/20-Y-232892	2023年6月13日	综合判定：合格	 A yellow dump truck with license plate H-2217 is parked on a dirt surface. Two workers in safety gear are standing next to it. A date stamp '2023/4/30' is visible in the bottom right corner.
423	GX-B1423/20-Y-232893	2023年6月13日	综合判定：合格	 A yellow dump truck with license plate H-2214 is parked on a dirt surface. A worker in safety gear is standing next to it. A date stamp '2023/4/30' is visible in the bottom right corner.

424	GX-B1423/20-Y-232894	2023年6月13日	综合判定：合格	
425	GX-B1423/20-Y-232895	2023年6月13日	综合判定：合格	

426	GX-B1423/20-Y-232896	2023年6月13日	综合判定：合格	 A yellow MT96LC dump truck with the number 92 on its side. Two workers in safety gear are standing in front of the truck. A yellow date stamp '2023/6/13' is visible in the bottom right corner of the photo.
427	GX-B1423/20-Y-232897	2023年6月13日	综合判定：合格	 A yellow MT96LC dump truck with the number 78 on its side. Two workers in safety gear are standing in front of the truck. A yellow date stamp '2023/6/13' is visible in the bottom right corner of the photo.

428	GX-B1423/20-Y-232898	2023年6月13日	综合判定：合格	 A yellow MT980 dump truck with the number 5 on its side. Two workers in safety gear are standing in front of the truck. A yellow date stamp '2023/6/2' is visible in the bottom right corner of the photo.
429	GX-B1423/20-Y-232899	2023年6月13日	综合判定：合格	 A yellow MT980 dump truck with the number 86 on its side. Two workers in safety gear are standing in front of the truck. A yellow date stamp '2023/6/2' is visible in the bottom right corner of the photo.

430	GX-B1423/20-Y-232900	2023年6月13日	综合判定：合格	
431	GX-B1423/20-Y-232901	2023年6月13日	综合判定：合格	

432	GX-B1423/20-Y-232902	2023年6月13日	综合判定：合格	 A yellow dump truck with the number 84 on its side. Two workers in safety gear are standing next to it. A yellow timestamp '2023/5/2' is in the bottom right corner.
433	GX-B1423/20-Y-232903	2023年6月13日	综合判定：合格	 A yellow dump truck with the number 93 on its side. Two workers in safety gear are standing next to it. A yellow timestamp '2023/5/2' is in the bottom right corner.

434	GX-B1423/20-Y-232904	2023年6月13日	综合判定：合格	 A yellow dump truck with the number 91 on its side. Two workers in safety gear are standing next to it. The truck has 'MT96' and 'H-2091' written on it. A yellow date stamp '2023/6/2' is visible in the bottom right corner of the photo.
435	GX-B1423/20-Y-232905	2023年6月13日	综合判定：合格	 A yellow dump truck with the number 90 on its side. Two workers in safety gear are standing next to it. The truck has 'MT96' and 'H-2090' written on it. A yellow date stamp '2023/6/2' is visible in the bottom right corner of the photo.

436	GX-B1423/20-Y-232906	2023年6月13日	综合判定：合格	 A yellow MT96 dump truck with the number 97 on its side. Two workers in safety gear are standing next to it. The date 2023/5/2 is visible in the bottom right corner of the photo.
437	GX-B1423/20-Y-232907	2023年6月13日	综合判定：合格	 A yellow MT96 dump truck with the number 94 on its side. Two workers in safety gear are standing next to it. The date 2023/5/2 is visible in the bottom right corner of the photo.

438	GX-B1423/20-Y-232908	2023年6月13日	综合判定：合格	 A yellow MT96 dump truck with the number 100 on its side. Two workers in safety gear are standing in front of the truck. The date 2023/5/2 is visible in the bottom right corner of the photo.
439	GX-B1423/20-Y-232909	2023年6月13日	综合判定：合格	 A yellow MT96 dump truck with the number 20 on its side. Two workers in safety gear are standing in front of the truck. The date 2023/5/2 is visible in the bottom right corner of the photo.

440	GX-B1423/20-Y-232910	2023年6月13日	综合判定：合格	
441	GX-B1423/20-Y-232911	2023年6月13日	综合判定：合格	

442	GX-B1423/20-Y-232912	2023年6月13日	综合判定：合格	
443	GX-B1423/20-Y-232913	2023年6月13日	综合判定：合格	

444	GX-B1423/20-Y-232914	2023年6月13日	综合判定：合格	 A yellow MT98 dump truck is shown from a side-front perspective. The truck has the number '98' on its side and 'MT98' on the front. Two workers in safety gear are standing in front of the truck. A yellow timestamp '2023/6/2' is visible in the bottom right corner of the photo.
445	GX-B1423/20-Y-232915	2023年6月13日	综合判定：合格	 A yellow MT89 dump truck is shown from a side-front perspective. The truck has the number '89' on its side and 'MT89' on the front. Two workers in safety gear are standing in front of the truck. A yellow timestamp '2023/6/2' is visible in the bottom right corner of the photo.

446	GX-B1423/20-Y-232916	2023年6月13日	综合判定：合格	
447	GX-B1423/20-Y-232917	2023年6月13日	综合判定：合格	

448	GX-B1404/20-Y-23015	2023年6月13日	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。	
449	GX-B1404/20-Y-23016	2023年6月13日	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。	

450	GX-B1404/20-Y-23017	2023年6月13日	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。	
451	GX-B1404/20-Y-23018	2023年6月13日	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。	

452	GX-B1495/20-Y-231334~231335	2023年6月10日	本次共检电压互感器2组，2组电压互感器所检项目合格。	
453	GX-B1495/20-Y-231336~231337	2023年6月10日	本次共检电压互感器2组，2组电压互感器所检项目合格。	

454	GX-B1495/20-Y-231338~231347	2023年6月10日	本次共检电压互感器10组，10组电压互感器所检项目合格。	
455	GX-B1495/20-Y-231348~231349	2023年6月10日	本次共检电压互感器2组，2组电压互感器所检项目合格。	

456	GX-B1495/20-Y-231350~231351	2023年6月10日	本次共检电压互感器2组，2组电压互感器所检项目合格。	
457	GX-B1495/20-Y-231352~231353	2023年6月10日	本次共检电压互感器2组，2组电压互感器所检项目合格。	

458	GX-B1495/20-Y-231354~231365	2023年6月10日	本次共检电压互感器12组，12组电压互感器所检项目合格。	
459	GX-B1495/20-Y-2313566~231377	2023年6月10日	本次共检电压互感器12组，12组电压互感器所检项目合格。	

460	GX-B1495/20-Y-2313578~231389	2023年6月10日	本次共检电压互感器12组，12组电压互感器所检项目合格。	
461	GX-B1328/20-Y-23077	2023年6月13日	本次共检绝缘手套14只，14只绝缘手套合格。	

462	GX-B1328/20-Y-23078	2023年6月13日	本次共检绝缘鞋14只，14只绝缘鞋合格。	
463	GX-B1328/20-Y-23079	2023年6月13日	本次共检验电器7支，7支验电器合格。	

464	GX-B1328/20-Y-23080	2023年6月13日	本次共检绝缘杆7支，7支绝缘杆合格。	 <p>2023/6/13</p>
465	GX-B1321/20-Y-23469~23474	2023年6月13日	本次共检验电力电缆6条，6条电力电缆所检项目合格。	 <p>2023/6/13</p>

466	GX-B1321/20-Y-23475~23477	2023年6月13日	本次共检验电力电缆3条，3条电力电缆所检项目合格。	
467	GX-B1312/20-Y-23278~23279	2023年6月13日	本次共检电力变压器2台，2台电力变压器所检项目合格。	

468	GX-B1312/20-Y-23280~23283	2023年6月13日	4台，4台电力变压器所检项目合格。	 A photograph showing three workers in safety gear (hard hats, jackets) inspecting a green power transformer. One worker is holding a tool, and another is looking at a device on the ground. The transformer is mounted on a wooden frame. A red fence is visible in the background. A yellow timestamp '2023/5/17' is in the bottom right corner.
469	GX-B1312/20-Y-23284~23292	2023年6月13日	9台，9台电力变压器所检项目合格。	 A photograph showing two workers in blue uniforms and red hard hats inspecting a power transformer in a dark, possibly underground, environment. One worker is holding a document, and the other is looking at it. A red fence with a white sign that says '高压危险' (High Voltage Danger) is visible. A yellow timestamp '2023/5/16' is in the bottom right corner.

470	GX-B1312/20-Y-23293~23301	2023年6月13日	本次共检电力变压器9台，9台电力变压器所检项目合格。	
471	GX-B1312/20-Y-23302~23304	2023年6月13日	本次共检电力变压器3台，3台电力变压器所检项目合格。	

472	GX-B1312/20-Y-23305~23306	2023年6月13日	本次共检电力变压器2台，2台电力变压器所检项目合格。	
473	GX-B1321/20-Y-23352~23353	2023年6月13日	本次共检电力电缆2条，2条电力电缆所检项目合格。	

474	GX-B1321/20-Y-23438~23439	2023年6月13日	本次共检电力电缆2条，2条电力电缆所检项目合格。	
475	GX-B1312/20-Y-23277	2023年6月13日	所检项目合格。	

476	GX-B1354/20-Y-23011	2023年6月15日	电网接地电容电流符合规定。	
477	GX-B1354/20-Y-23012	2023年6月15日	电网接地电容电流符合规定。	

478	GX-B1404/20-Y-23013	2023年6月15日	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。	
479	GX-B1404/20-Y-23014	2023年6月15日	所检电网谐波电压总谐波畸变率、各次谐波电压含有率、谐波电流符合GB/T 14549-1993 《电能质量 公用电网谐波》要求。	

480	GX-B1321/20-Y-23478~23486	2023年6月15日	本次共检验电力电缆9条，9条电力电缆所检项目合格。	
481	GX-B1321/20-Y-23487~23494	2023年6月15日	本次共检验电力电缆8条，8条电力电缆所检项目合格。	

482	GX-B1321/20-Y-23495~23496	2023年6月15日	本次共检验电力电缆 2条，2条电力电缆所检项目合格。	
483	GX-B1321/20-Y-23497~23498	2023年6月15日	本次共检验电力电缆 2条，2条电力电缆所检项目合格。	

484	GX-B1354/20-Y-23007	2023年6月15日	电网接地电容电流符合规定。	
485	GX-B1354/20-Y-23010	2023年6月15日	电网接地电容电流符合规定。	

486	GX-B1321/20-Y-23499~23504	2023年6月15日	本次共检验电力电缆6条，6条电力电缆所检项目合格。	
487	GX-B1321/20-Y-23505~23508	2023年6月15日	本次共检验电力电缆4条，4条电力电缆所检项目合格。	

488	GX-B1321/20-Y-23509~23514	2023年6月15日	本次共检验电力电缆6条，6条电力电缆所检项目合格。	
489	GX-B1321/20-Y-23515~23516	2023年6月15日	本次共检验电力电缆2条，2条电力电缆所检项目合格。	

490	GX-B1321/20-Y-23517~23518	2023年6月15日	本次共检验电力电缆 2条，2条电力电缆所检项目合格。	
491	GX-B1321/20-Y-23519~23520	2023年6月15日	本次共检验电力电缆 2条，2条电力电缆所检项目合格。	

492	GX-B1321/20-Y-23521~23522	2023年6月15日	本次共检验电力电缆2条，2条电力电缆所检项目合格。	
493	GX-B1321/20-Y-23523~23532	2023年6月15日	本次共检验电力电缆10条，10条电力电缆所检项目合格。	