

序号	报告编号	发布日期	结论	影像资料
54	GX-B1369/20-A-23004	2023/6/1	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
55	GX-B1363/22-A-23247	2023/6/12	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
56	GX-B1363/22-A-23249	2023/6/12	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
57	GX-B1363/22-A-23248	2023/6/12	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
58	GX-B1363/22-A-23240	2023/6/12	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
59	GX-B1363/22-A-23237	2023/6/12	所检项目合格。	 <p>The photograph shows two technicians in white uniforms with the '中融公信' logo on their backs, inspecting a large, rusted metal furnace or boiler. One technician is wearing blue gloves and is touching the furnace door. To the left is a green trash bin with a white circular logo. A date stamp '2023/06/01' is visible in the bottom right corner of the image.</p>

序号	报告编号	发布日期	结论	影像资料
60	GX-B1363/22-A-23236	2023/6/12	所检项目合格。	 A photograph showing two technicians in light blue uniforms inspecting a large, rusted metal electrical cabinet. One technician is wearing gloves and looking into the cabinet. The other is standing to the right. A green trash bin is visible on the left. A date stamp '2023/06/02' is in the bottom right corner of the photo.

序号	报告编号	发布日期	结论	影像资料
61	GX-B1363/22-A-23187	2023/6/12	全厚度拉伸强度 17.3MPa 全厚度拉断伸长率 653.3%；其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
62	GX-B1363/22-A-23188	2023/6/12	全厚度拉伸强度 17.7MPa 全厚度拉断伸长率 641.7%；其余所检项目合格。	 <p>2023/05/17</p>

序号	报告编号	发布日期	结论	影像资料
63	GX-B1363/22-A-23224	2023/6/12	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
64	GX-B1363/22-A-23220	2023/6/12	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
65	GX-B1367/22-A-23049	2023/6/12	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
66	GX-B1367/22-A-23048	2023/6/12	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
67	GX-B1363/22-A-23181	2023/6/12	全厚度拉伸强度 17.8MPa 全 厚度拉断 伸长率 660.7%；其 余所检项 目合格。	

序号	报告编号	发布日期	结论	影像资料
68	GX-B1363/22-A-23171	2023/6/9	全厚度拉伸强度 18.6MPa 全厚度拉断伸长率 682.3%；其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
69	GX-B1363/22-A-23172	2023/6/9	全厚度拉伸强度 18.6MPa 全厚度拉断伸长率 661.5%；其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
70	GX-B1363/22-A-23189	2023/6/12	全厚度拉伸强度 18.0MPa 全厚度拉断伸长率 651.5%；其余所检项目合格。	


序号	报告编号	发布日期	结论	影像资料
71	GX-B1363/22-A-23190	2023/6/12	全厚度拉伸强度 18.2MPa 全 厚度拉断 伸长率 680.3%；其 余所检项 目合格。	

序号	报告编号	发布日期	结论	影像资料
72	GX-B1363/22-A-23255	2023/6/12	所检项目合格。	 <p>2023/06/04</p>

序号	报告编号	发布日期	结论	影像资料
73	GX-B1363/22-A-23253	2023/6/12	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
74	GX-B1363/22-A-23252	2023/6/12	所检项目合格。	 <p>2023/06/05</p>

序号	报告编号	发布日期	结论	影像资料
75	GX-B1367/20-A-23053	2023/6/13	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
76	GX-B1366/20-A-23059	2023/6/16	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
77	GX-B1366/20-A-23060	2023/6/16	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
78	GX-B1363/22-A-23279	2023/6/16	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
79	GX-B1363/22-A-23280	2023/6/16	所检项目合格。	