

序号	报告编号	发布日期	结论	影像资料
589	GX-B1539/22-Y-23119	2023年6月25日	所检项目合格。	
590	GX-B1539/22-Y-23120	2023年6月25日	所检项目合格。	

591	GX-B1539/22-Y-23121	2023年6月25日	所检项目合格。	
592	GX-B1539/22-Y-23122	2023年6月25日	所检项目合格。	

593	GX-B1539/22-Y-23123	2023年6月25日	所检项目合格。	
594	GX-B1539/22-Y-23124	2023年6月25日	所检项目合格。	

595	GX-B1539/22-Y-23125	2023年6月25日	所检项目合格。	 A yellow wheel loader is shown from a side-rear perspective. A person in a white protective suit and red helmet is standing on the side of the machine. The license plate reads 'S-1176'. A yellow timestamp '2023/5/6' is visible in the bottom right corner of the photo.
596	GX-B1539/22-Y-23126	2023年6月25日	所检项目合格。	 A yellow wheel loader is shown from a side-front perspective. Two people in red protective suits and helmets are standing near the front of the machine. The license plate reads 'H-1620'. A yellow timestamp '2023/5/14' is visible in the bottom right corner of the photo.

597	GX-B1539/22-Y-23127	2023年6月25日	所检项目合格。	
598	GX-B1539/22-Y-23128	2023年6月25日	所检项目合格。	

599	GX-B1310/21-Y-23077	2023年6月18日	符合标准要求。	
600	GX-B1428/21-Y-23077	2023年6月18日	无缺陷迹痕显示。	

601	GX-B1310/21-Y-23078	2023年6月18日	符合标准要求。	 <p>A photograph showing a worker in a red hard hat and grey uniform inspecting a large green cylindrical component. The worker is holding a tool and looking at the component. A yellow timestamp '2023/4/26' is visible in the bottom left corner of the image.</p>
602	GX-B1428/21-Y-23078	2023年6月18日	无缺陷迹痕显示。	 <p>A photograph showing a worker in a red hard hat and grey uniform inspecting a large green cylindrical component. The worker is holding a tool and looking at the component. A yellow timestamp '2023/4/26' is visible in the bottom left corner of the image.</p>

603	GX-B1381/20-Y-23008	2023年6月23日	综合判定：合格。	 <p>A photograph showing a worker in a blue uniform and red helmet working on a blue structure in a tunnel. The worker is holding a tool and looking at the structure. The date 2023/5/23 is visible in the bottom right corner of the photo.</p>
604	GX-B1310/21-Y-23089	2023年6月18日	符合标准要求。	 <p>A photograph showing a worker in a pink helmet and light-colored uniform working on a yellow machine. The worker is focused on the machine, which has various components and a chain. The date 2023/6/21 is visible in the bottom right corner of the photo.</p>

605	GX-B1310/21-Y-23090	2023年6月18日	符合标准要求。	 A photograph showing a worker in a blue uniform and a red helmet with a headlamp. The worker is focused on operating a piece of machinery or equipment in an industrial environment. A yellow date stamp '2023/5/24' is visible in the bottom right corner of the image.
606	GX-B1310/21-Y-23094	2023年6月18日	符合标准要求。	 A photograph showing a worker in a blue uniform and a red helmet with a headlamp. The worker is in a dark, confined space, possibly a tunnel or a large pipe, and is reaching up towards a structure. A yellow date stamp '2023/5/23' is visible in the bottom right corner of the image.

607	GX-B1423/20-Y-232958	2023年6月25日	综合判定：合格	 <p>A yellow dump truck is parked on a dirt surface. Two workers wearing hard hats and safety gear are standing in front of the truck. The truck has a license plate that reads 'S-1087'. A yellow timestamp '2023/5/6' is visible in the bottom right corner of the photo.</p>
608	GX-B1423/20-Y-232959	2023年6月25日	综合判定：合格	 <p>A yellow dump truck is parked on a dirt surface. Two workers wearing hard hats and safety gear are standing in front of the truck. The truck has a license plate that reads 'S-1087'. A yellow timestamp '2023/5/6' is visible in the bottom right corner of the photo.</p>

609	GX-B1423/20-Y-232960	2023年6月25日	综合判定：合格	 <p>A photograph of a yellow XCMG S1088 dump truck. Two workers wearing safety gear (hard hats and high-visibility vests) are standing in front of the truck. The truck has '徐工' (XCMG) and 'S-1088' visible on its side. A yellow timestamp '2023/5/6' is in the bottom right corner.</p>
610	GX-B1423/20-Y-232961	2023年6月25日	综合判定：合格	 <p>A close-up photograph of the front of a yellow XCMG dump truck. Two workers wearing safety gear (hard hats and work clothes) are standing in front of the truck. A yellow timestamp '2023/5/6' is in the bottom right corner.</p>

611	GX-B1423/20-Y-232962	2023年6月25日	综合判定：合格	
612	GX-B1423/20-Y-232963	2023年6月25日	综合判定：合格	

613	GX-B1423/20-Y-232964	2023年6月25日	综合判定：合格	
614	GX-B1423/20-Y-232965	2023年6月25日	综合判定：合格	

615	GX-B1423/20-Y-232966	2023年6月25日	综合判定：合格	 A photograph showing two workers standing in front of a yellow truck. The worker on the left is wearing a blue jumpsuit, a yellow hard hat, and a white face mask. The worker on the right is wearing a grey jumpsuit, a red hard hat, and is holding a blue clipboard. The truck is yellow with a large front grille and a diamond-plate pattern. A yellow timestamp '2023/5/6' is visible in the bottom right corner of the photo.
616	GX-B1423/20-Y-232967	2023年6月25日	综合判定：合格	 A photograph showing two workers standing next to a yellow dump truck. The worker on the left is wearing a yellow safety vest over a white shirt, a yellow hard hat, and is holding a clipboard. The worker on the right is wearing a grey jumpsuit, a red hard hat, and is holding a clipboard. The truck is yellow with a large dump body and a diamond-plate pattern. A yellow timestamp '2023/5/6' is visible in the bottom right corner of the photo.

617	GX-B1423/20-Y-232968	2023年6月25日	综合判定：合格	
618	GX-B1423/20-Y-232969	2023年6月25日	综合判定：合格	

619	GX-B1423/20-Y-232970	2023年6月25日	综合判定：合格	 A photograph showing two workers standing in front of a yellow truck. The worker on the left is wearing a grey uniform and a red hard hat. The worker on the right is wearing a grey uniform, a yellow high-visibility vest, and a yellow hard hat. The truck has the number '93' on its front. A yellow timestamp '2023/5/6' is visible in the bottom right corner of the photo.
620	GX-B1423/20-Y-232971	2023年6月25日	综合判定：合格	 A photograph showing a single worker standing in front of a yellow truck. The worker is wearing a grey uniform and a red hard hat, and is holding a clipboard. The truck has the number '93' on its front. A yellow timestamp '2023/5/6' is visible in the bottom right corner of the photo.

621	GX-B1423/20-Y-232972	2023年6月25日	综合判定：合格	 <p>A photograph of a yellow dump truck with the identification number 'S-1101' on its side. Two workers wearing hard hats and safety vests are standing in front of the truck. The date '2023/5/6' is visible in the bottom right corner of the image.</p>
622	GX-B1423/20-Y-232973	2023年6月25日	综合判定：合格	 <p>A photograph of a worker wearing a red hard hat and a grey uniform, holding a clipboard. The worker is standing in front of the front of a yellow dump truck. The date '2023/5/6' is visible in the bottom right corner of the image.</p>

623	GX-B1423/20-Y-232974	2023年6月25日	综合判定：合格	
624	GX-B1423/20-Y-232975	2023年6月25日	综合判定：合格	

625	GX-B1423/20-Y-232976	2023年6月25日	综合判定：合格	
626	GX-B1423/20-Y-232977	2023年6月25日	综合判定：合格	

627	GX-B1423/20-Y-232978	2023年6月25日	综合判定：合格	 <p>A yellow XCMG S-1066 dump truck is shown from a side-rear perspective. A worker in a red hard hat and light-colored clothing is crouching down to inspect the front-left tire. The truck's license plate area displays 'S-1066'. A yellow timestamp '2023/5/6' is visible in the bottom right corner of the photo.</p>
628	GX-B1423/20-Y-232979	2023年6月25日	综合判定：合格	 <p>A yellow XCMG S-1073 dump truck is shown from a side-rear perspective. Two workers, one in a red hard hat and high-visibility vest, and another in a grey uniform and red hard hat, are standing in front of the truck. The truck's license plate area displays 'S-1073'. A yellow timestamp '2023/5/6' is visible in the bottom right corner of the photo.</p>

629	GX-B1423/20-Y-232980	2023年6月25日	综合判定：合格	 A yellow dump truck is shown from a side profile. Two workers in safety gear are standing in front of it. The truck has 'S-1102' on the side and '102' on the body. A yellow timestamp '2023/5/6' is in the bottom right corner.
630	GX-B1423/20-Y-232981	2023年6月25日	综合判定：合格	 A yellow dump truck is shown from a side profile. Two workers in safety gear are standing in front of it. The truck has 'S-1102' on the side and '102' on the body. A yellow timestamp '2023/5/7' is in the bottom right corner.

631	GX-B1423/20-Y-232982	2023年6月25日	综合判定：合格	
632	GX-B1423/20-Y-232983	2023年6月25日	综合判定：合格	

633	GX-B1423/20-Y-232984	2023年6月25日	综合判定：合格	
634	GX-B1423/20-Y-232985	2023年6月25日	综合判定：合格	

635	GX-B1423/20-Y-232986	2023年6月25日	综合判定：合格	 <p>A photograph showing two workers standing in front of a yellow truck. The worker on the left is wearing a blue uniform and a yellow hard hat. The worker on the right is wearing a grey uniform and a red hard hat. The truck is a large yellow dump truck. A yellow timestamp '2023/5/7' is visible in the bottom right corner of the photo.</p>
636	GX-B1423/20-Y-232987	2023年6月25日	综合判定：合格	 <p>A photograph showing a worker in a grey uniform and red hard hat inspecting the rear of a yellow truck. The truck is a large yellow dump truck. A yellow timestamp '2023/5/7' is visible in the bottom right corner of the photo.</p>

637	GX-B1423/20-Y-232988	2023年6月25日	综合判定：合格	
638	GX-B1423/20-Y-232989	2023年6月25日	综合判定：合格	

639	GX-B1423/20-Y-232990	2023年6月25日	综合判定：合格	
640	GX-B1423/20-Y-232991	2023年6月25日	综合判定：合格	

641	GX-B1423/20-Y-232992	2023年6月25日	综合判定：合格	
642	GX-B1423/20-Y-232993	2023年6月25日	综合判定：合格	

643	GX-B1423/20-Y-232994	2023年6月25日	综合判定：合格	
644	GX-B1423/20-Y-232995	2023年6月25日	综合判定：合格	

645	GX-B1423/20-Y-232996	2023年6月25日	综合判定：合格	 A red dump truck with the number 1177 on its side is parked on a dirt surface. Two workers in safety gear are standing next to it. A yellow timestamp '2023/5/7' is visible in the bottom right corner of the photo.
646	GX-B1423/20-Y-232997	2023年6月25日	综合判定：合格	 A red dump truck with the number 1180 on its side is parked on a dirt surface. Two workers in safety gear are standing next to it. Some equipment is on the ground in front of the truck. A yellow timestamp '2023/5/7' is visible in the bottom right corner of the photo.

647	GX-B1423/20-Y-232998	2023年6月25日	综合判定：合格	
648	GX-B1423/20-Y-232999	2023年6月25日	综合判定：合格	

649	GX-B1423/20-Y-233000	2023年6月25日	综合判定：合格	
650	GX-B1423/20-Y-233001	2023年6月25日	综合判定：合格	

651	GX-B1423/20-Y-233002	2023年6月25日	综合判定：合格	 <p>A red MT95LP S-1190 dump truck is shown in a construction setting. Two workers wearing hard hats and safety vests are standing in front of the truck. The truck has the number 1190 on its side. A yellow timestamp '2023/5/7' is visible in the bottom right corner of the image.</p>
652	GX-B1423/20-Y-233003	2023年6月25日	综合判定：合格	 <p>A yellow S-116MS50 tanker truck is shown in a construction setting. Two workers wearing hard hats and safety vests are standing in front of the truck. The truck has the number S-116MS50 on its side. A yellow timestamp '2023/5/7' is visible in the bottom right corner of the image.</p>

653	GX-B1424/20-Y-23003	2023年6月25日	依据NB/T 10176-2019单轨吊车综合判定合格。	
654	GX-B1424/20-Y-23004	2023年6月25日	依据NB/T 10176-2019单轨吊车综合判定合格。	

655	GX-B1424/20-Y-23005	2023年6月25日	依据NB/T 10176-2019单轨吊车综合判定合格；依据MT/T 220-1990 尾气所检项目合格。	
656	GX-B1424/20-Y-23006	2023年6月25日	依据NB/T 10176-2019单轨吊车综合判定合格；依据MT/T 220-1990 尾气所检项目合格。	

657	GX-B1310/21-Y-23055	2023年6月25日	符合标准要求。	 <p>A photograph showing a worker in a blue protective suit and helmet working on a large industrial structure in a factory setting. The worker is standing on a platform and appears to be inspecting or working on a component. The background shows industrial equipment and structures. A yellow timestamp '2023/4/19' is visible in the bottom right corner of the image.</p>
658	GX-B1427/21-Y-23055	2023年6月25日	符合标准要求。	 <p>A photograph showing two workers in red hard hats and grey jackets working on a large, dark, cylindrical object. They are kneeling on the ground and appear to be inspecting or working on the object. The background shows industrial equipment and structures. A yellow timestamp '2023/4/19' is visible in the bottom left corner of the image.</p>

659	GX-B1310/21-Y-23056	2023年6月25日	符合标准要求。	 <p>A photograph showing two workers in hard hats and safety gear inspecting a large piece of yellow machinery with cables. The date stamp '2023/4/19' is visible in the bottom right corner of the image.</p>
660	GX-B1427/21-Y-23056	2023年6月25日	符合标准要求。	 <p>A photograph showing a worker in a red hard hat and safety gear working on a concrete structure. The date stamp '2023/4/19' is visible in the bottom left corner of the image.</p>

661	GX-B1310/21-Y-23057	2023年6月25日	符合标准要求。	 A photograph showing two workers wearing hard hats and safety gear. They are standing in an industrial setting, looking at a piece of machinery with large cables and pulleys. One worker is holding a clipboard. A yellow timestamp '2023.4.19' is visible in the bottom right corner of the image.
662	GX-B1427/21-Y-23057	2023年6月25日	符合标准要求。	 A photograph of a worker wearing a red hard hat and a light-colored jacket, kneeling on the ground. The worker is focused on a task involving a concrete structure or equipment. A yellow timestamp '2023.4.19' is visible in the bottom left corner of the image.

663	GX-B1310/21-Y-23058	2023年6月25日	符合标准要求。	
664	GX-B1427/21-Y-23058	2023年6月25日	符合标准要求。	

665	GX-B1310/21-Y-23086	2023年6月26日	符合标准要求。	 A photograph showing a worker in a grey uniform and red helmet inspecting a large, curved industrial component. The worker is looking closely at the surface. A yellow timestamp '2023/6/17' is visible in the bottom right corner of the image.
666	GX-B1428/21-Y-23086	2023年6月26日	无缺陷迹痕显示。	 A photograph showing two workers in grey uniforms and red helmets inspecting a large, blue, curved industrial component. They are looking at the surface of the component. A yellow timestamp '2023/6/17' is visible in the bottom left corner of the image.

667	GX-B1310/21-Y-23087	2023年6月26日	符合标准要求。	
668	GX-B1428/21-Y-23087	2023年6月26日	无缺陷迹痕显示。	

669	GX-B1423/20-Y-232842	2023年6月26日	综合判定：合格	
670	GX-B1423/20-Y-232843	2023年6月26日	综合判定：合格	

671	GX-B1423/20-Y-232844	2023年6月26日	综合判定：合格	 <p>A photograph of a yellow FOMLY A203 truck parked on a dirt surface. A person in a light-colored jacket and dark pants is standing in front of the truck, looking at something in their hands. The truck has 'FOMLY' written on the top of the cab and 'A203' on the front. The date '2023/6/26' is visible in the bottom right corner of the photo.</p>
-----	----------------------	------------	---------	--