

序号	报告编号	发布日期	结论	影像资料
104	GX-B1495/20-5-231277~231279	2023/6/16	本次共检高压防爆开关3台，3台高压防爆开关所检项目合格。	 <p>2023/3/31</p>
105	GX-B1495/20-5-231280~231294	2023/6/16	本次共检高压开关柜15台，15台高压开关柜所检项目合格。	 <p>2023/4/1</p>
106	GX-B1515/22-5-23012	2023/6/16	所检项目合格。	 <p>2023/4/18</p>

107	GX-B1515/22-5-23013	2023/6/16	所检项目合格。	
108	GX-B1310/21-5-23159	2023. 6. 18	符合标准要求。	
109	GX-B1310/21-5-23160	2023. 6. 18	符合标准要求。	
110	GX-B1310/21-5-23161	2023. 6. 18	符合标准要求。	

111	GX-B1310/21-5-23162	2023. 6. 18	符合标准要求。	
112	GX-B1310/21-5-23163	2023. 6. 18	符合标准要求。	
113	GX-B1310/21-5-23164	2023. 6. 18	符合标准要求。	
114	GX-B1310/21-5-23165	2023. 6. 18	符合标准要求。	

115	GX-B1310/21-5-23166	2023. 6. 18	符合标准要求。	
116	GX-B1310/21-5-23167	2023. 6. 18	符合标准要求。	
117	GX-B1310/21-5-23168	2023. 6. 18	符合标准要求。	
118	GX-B1336/22-5-23003~23004	2023. 6. 19	本次共检母线 2段，2段母线所检 项目合格。	

119	GX-B1336/22-5-23005~23006	2023. 6. 19	本次共检母线 2段，2段母线所检 项目合格。	
120	GX-B1336/22-5-23007~23008	2023. 6. 19	本次共检母线 2段，2段母线所检 项目合格。	
121	GX-B1336/22-5-23009~23010	2023. 6. 19	本次共检母线 2段，2段母线所检 项目合格。	
122	GX-B1336/22-5-23021~23022	2023. 6. 19	本次共检母线 2段，2段母线所检 项目合格。	

123	GX-B1336/22-5-23011~23012	2023. 6. 19	本次共检母线 2段，2段母线所检 项目合格。	
124	GX-B1336/22-5-23013~23014	2023. 6. 19	本次共检母线 2段，2段母线所检 项目合格。	
125	GX-B1336/22-5-23015~23016	2023. 6. 19	本次共检母线 2段，2段母线所检 项目合格。	
126	GX-B1336/22-5-23001~23002	2023. 6. 19	本次共检母线 2段，2段母线所检 项目合格。	

127	GX-B1336/22-5-23017~23018	2023. 6. 19	本次共检母线 2段，2段母线所检 项目合格。	
128	GX-B1336/22-5-23019~23020	2023. 6. 19	本次共检母线 2段，2段母线所检 项目合格。	
129	GX-B1336/22-5-23025~23026	2023. 6. 19	本次共检母线 2段，2段母线所检 项目合格。	
130	GX-B1336/22-5-23023~23024	2023. 6. 19	本次共检母线 2段，2段母线所检 项目合格。	

131	GX-B1336/22-5-23027~23028	2023. 6. 19	本次共检母线2段，2段母线所检项目合格。	
132	GX-B1329/21-5-23140~23149	2023. 6. 19	本次共检氧化锌避雷器10组，10组氧化锌避雷器所检项目合格。	
133	GX-B1329/21-5-23150~23171	2023. 6. 19	本次共检氧化锌避雷器22组，22组氧化锌避雷器所检项目合格。	
134	GX-B1495/20-5-231315~231326	2023. 6. 19	本次共检高压开关柜12台，12台高压开关柜所检项目合格。	

135	GX-B1495/20-5-231327~231348	2023. 6. 19	本次共检高压开关柜22台，22台高压开关柜所检项目合格。	
136	GX-B1495/20-5-231349~231351	2023. 6. 19	本次共检高压防爆开关3台，3台高压防爆开关所检项目合格。	
137	GX-B1328/20-5-23103	2023/6/19	本次共检绝缘手套10只，10只绝缘手套合格。	
138	GX-B1328/20-5-23104	2023/6/19	本次共检携带式接地和接地短路装置10套，10套携带式接地和接地短路装置合格。	

139	GX-B1328/20-5-23105	2023/6/19	本次共检验电器4支，4支验电器合格。	
140	GX-B1499/21-5-23084	2023/6/19	所检项目合格。	
141	GX-B1499/21-5-23085	2023/6/19	所检项目合格。	
142	GX-B1559/22-5-23021	2023. 6. 21	所检项目合格	

143	GX-B1380/20-5-23005	2023/6/21	所检项目合格。	
144	GX-B1321/20-5-23742-23750	2023/6/21	所检项目合格。	
145	GX-B1323/21-5-23145-23146	2023/6/19	所检项目合格。	

146	GX-B1495/20-5-231434-231435	2023/6/20	所检项目合格。	 A man wearing glasses and a dark jacket is standing in front of an electrical control panel. He is holding a document and looking at it. The panel has various gauges, switches, and a digital display. A date stamp '2023.5.21' is visible in the bottom right corner of the photo.
147	GX-B1350/21-5-23058	2023/6/20	所检项目合格。	 A man wearing a dark uniform and a hard hat is kneeling on a concrete floor. He is using a handheld electronic device. The floor has some markings and a date stamp '2023.5.21' is visible in the bottom right corner of the photo.

148	GX-B1300/20-5-23010	2023/6/20	所检项目合格。	
149	GX-B1328/20-5-23117	2023/6/21	所检项目合格。	

150	GX-B1328/20-5-23118	2023/6/21	所检项目合格。	
151	GX-B1328/20-5-23119	2023/6/21	所检项目合格。	

152	GX-B1328/20-5-23120	2023/6/21	所检项目合格。	
153	GX-B1310/21-5-23160	2023/6/20	符合标准要求。	

154	GX-B1310/21-5-23161	2023/6/20	符合标准要求。	 A photograph showing two workers in safety gear (hard hats and work clothes) inspecting a large, dark-colored pipe joint. One worker is kneeling on the ground, while the other is leaning over. The scene is outdoors, possibly at a construction or industrial site, with various equipment and materials visible in the background.
155	GX-B1310/21-5-23162	2023/6/20	符合标准要求。	 A photograph showing two workers in safety gear (hard hats and work clothes) handling a large, dark-colored pipe section. One worker is kneeling on the ground, while the other is standing and leaning over. The scene is outdoors, possibly at a construction or industrial site, with various equipment and materials visible in the background. A yellow timestamp "2023/6/22" is visible in the bottom right corner of the image.

156	GX-B1310/21-5-23163	2023/6/20	符合标准要求。	
157	GX-B1310/21-5-23164	2023/6/20	符合标准要求。	

158	GX-B1310/21-5-23165	2023/6/20	符合标准要求。	
159	GX-B1310/21-5-23166	2023/6/20	符合标准要求。	

160	GX-B1310/21-5-23167	2023/6/20	符合标准要求。	
161	GX-B1310/21-5-23168	2023/6/20	符合标准要求。	