

序号	报告编号	发布日期	结论	影像资料
851	GX-B1423/20-Y-233004	2023年6月30日	综合判定：合格	
852	GX-B1423/20-Y-233005	2023年6月30日	综合判定：合格	

853	GX-B1423/20-Y-233006	2023年6月30日	综合判定：合格	
854	GX-B1423/20-Y-233007	2023年6月30日	综合判定：合格	

855	GX-B1423/20-Y-233008	2023年6月30日	综合判定：合格	 A yellow CMT106 truck is shown in a desert environment. Two workers in safety gear are standing next to the truck. The truck has 'CMT106' and '船工造船' written on its side. A yellow timestamp '2023/6/8' is visible in the bottom right corner of the image.
856	GX-B1423/20-Y-233009	2023年6月30日	综合判定：合格	 A light green RTH106 truck is shown in a desert environment. Two workers in safety gear are standing next to the truck. The truck has 'RTH106' written on its side. A yellow timestamp '2023/6/8' is visible in the bottom right corner of the image.

857	GX-B1423/20-Y-233010	2023年6月30日	综合判定：合格	
858	GX-B1423/20-Y-233011	2023年6月30日	综合判定：合格	

859	GX-B1423/20-Y-233012	2023年6月30日	综合判定：合格	 A red dump truck with the number 1299 on its side. Two workers in safety gear are standing next to it. A yellow timestamp '2023/5/8' is visible in the bottom right corner of the photo.
860	GX-B1423/20-Y-233013	2023年6月30日	综合判定：合格	 A red dump truck with the number 1298 on its side. Two workers in safety gear are standing next to it. A yellow timestamp '2023/5/8' is visible in the bottom right corner of the photo.

861	GX-B1423/20-Y-233014	2023年6月30日	综合判定：合格	
862	GX-B1423/20-Y-233015	2023年6月30日	综合判定：合格	

863	GX-B1423/20-Y-233016	2023年6月30日	综合判定：合格	
864	GX-B1423/20-Y-233017	2023年6月30日	综合判定：合格	

865	GX-B1423/20-Y-233018	2023年6月30日	综合判定：合格	
866	GX-B1423/20-Y-233019	2023年6月30日	综合判定：合格	

867	GX-B1423/20-Y-233020	2023年6月30日	综合判定：合格	 A photograph of a red dump truck with its bed raised. Two workers in safety gear are standing in front of the truck. A yellow timestamp '2023/5/8' is visible in the bottom right corner of the image.
868	GX-B1423/20-Y-233021	2023年6月30日	综合判定：合格	 A photograph of a red dump truck with its bed raised. Two workers in safety gear are standing in front of the truck. A yellow timestamp '2023/5/8' is visible in the bottom right corner of the image.

869	GX-B1423/20-Y-233022	2023年6月30日	综合判定：合格	
870	GX-B1423/20-Y-233023	2023年6月30日	综合判定：合格	

871	GX-B1423/20-Y-233024	2023年6月30日	综合判定：合格	
872	GX-B1423/20-Y-233025	2023年6月30日	综合判定：合格	

873	GX-B1423/20-Y-233026	2023年6月30日	综合判定：合格	
874	GX-B1423/20-Y-233027	2023年6月30日	综合判定：合格	

875	GX-B1423/20-Y-233028	2023年6月30日	综合判定：合格	
876	GX-B1423/20-Y-233029	2023年6月30日	综合判定：合格	

877	GX-B1423/20-Y-233030	2023年6月30日	综合判定：合格	
878	GX-B1423/20-Y-233031	2023年6月30日	综合判定：合格	

879	GX-B1423/20-Y-233032	2023年6月30日	综合判定：合格	
880	GX-B1423/20-Y-233033	2023年6月30日	综合判定：合格	

881	GX-B1423/20-Y-233034	2023年6月30日	综合判定：合格	 <p>A photograph of a red dump truck with the number 477 on its side. Two workers in safety gear are standing in front of the truck. A yellow timestamp '2023/5/9' is visible in the bottom right corner of the image.</p>
882	GX-B1423/20-Y-233035	2023年6月30日	综合判定：合格	 <p>A photograph of a red dump truck with the number 471 on its side. Two workers in safety gear are standing in front of the truck. A yellow timestamp '2023/5/9' is visible in the bottom right corner of the image.</p>

883	GX-B1423/20-Y-233036	2023年6月30日	综合判定：合格	 A red dump truck with the number 483 on its side is parked on a dirt surface. Two people wearing safety gear are standing next to it. A yellow timestamp '2023/5/9' is visible in the bottom right corner of the photo.
884	GX-B1423/20-Y-233037	2023年6月30日	综合判定：合格	 A red dump truck with the number 472 on its side is parked on a dirt surface. Two people wearing safety gear are standing next to it. A yellow timestamp '2023/5/9' is visible in the bottom right corner of the photo.

885	GX-B1423/20-Y-233038	2023年6月30日	综合判定：合格	
886	GX-B1423/20-Y-233039	2023年6月30日	综合判定：合格	

887	GX-B1423/20-Y-233040	2023年6月30日	综合判定：合格	 A red dump truck with the number 462 on its side, parked on a dirt surface. Two workers in safety gear are standing next to it. A yellow timestamp '2023/5/9' is visible in the bottom right corner of the photo.
888	GX-B1423/20-Y-233041	2023年6月30日	综合判定：合格	 A red dump truck with the number 458 on its side, parked on a dirt surface. Two workers in safety gear are standing next to it. A yellow timestamp '2023/5/9' is visible in the bottom right corner of the photo.

889	GX-B1423/20-Y-233042	2023年6月30日	综合判定：合格	 A photograph of a red MTBLLP dump truck with the number 461 on its side. Two workers in safety gear are standing in front of the truck on a dirt surface. A yellow timestamp '2023/5/9' is visible in the bottom right corner of the image.
890	GX-B1423/20-Y-233043	2023年6月30日	综合判定：合格	 A photograph of a red MTBLLP dump truck with the number 476 on its side. Two workers in safety gear are standing in front of the truck on a dirt surface. A yellow timestamp '2023/5/9' is visible in the bottom right corner of the image.

891	GX-B1423/20-Y-233044	2023年6月30日	综合判定：合格	
892	GX-B1423/20-Y-233045	2023年6月30日	综合判定：合格	

893	GX-B1423/20-Y-233046	2023年6月30日	综合判定：合格	 A red dump truck with the number 475 on its side is parked on a dirt surface. Two workers in safety gear are standing in front of the truck. A yellow timestamp '2023/5/9' is visible in the bottom right corner of the photo.
894	GX-B1423/20-Y-233047	2023年6月30日	综合判定：合格	 A red dump truck with the number 460 on its side is parked on a dirt surface. Two workers in safety gear are standing in front of the truck. A yellow timestamp '2023/5/9' is visible in the bottom right corner of the photo.

895	GX-B1423/20-Y-233048	2023年6月30日	综合判定：合格	 A red dump truck with the number 484 on its side is parked on a dirt surface. Two workers in safety gear are standing in front of the truck. A yellow timestamp '2023/5/9' is visible in the bottom right corner of the image.
896	GX-B1423/20-Y-233049	2023年6月30日	综合判定：合格	 A red dump truck with the number 473 on its side is parked on a dirt surface. Two workers in safety gear are standing in front of the truck. A yellow timestamp '2023/5/9' is visible in the bottom right corner of the image.

897	GX-B1423/20-Y-233050	2023年6月30日	综合判定：合格	
898	GX-B1423/20-Y-233051	2023年6月30日	综合判定：合格	

899	GX-B1423/20-Y-233052	2023年6月30日	综合判定：合格	 <p>A red dump truck with the number 470 on its side and license plate H-1423. Two workers in safety gear are standing in front of the truck. A yellow timestamp '2023/5/9' is visible in the bottom right corner of the photo.</p>
900	GX-B1423/20-Y-233053	2023年6月30日	综合判定：合格	 <p>A red dump truck with the number 456 on its side and license plate H-1423. Two workers in safety gear are standing in front of the truck. A yellow timestamp '2023/5/9' is visible in the bottom right corner of the photo.</p>

901	GX-B1423/20-Y-233054	2023年6月30日	综合判定：合格	 A red dump truck with the number 463 on its side, parked on a dirt surface. Two workers in safety gear are standing next to it. A yellow timestamp '2023/5/10' is visible in the bottom right corner of the photo.
902	GX-B1423/20-Y-233055	2023年6月30日	综合判定：合格	 A red dump truck with the number 478 on its side, parked on a dirt surface. Two workers in safety gear are standing next to it. A yellow timestamp '2023/5/10' is visible in the bottom right corner of the photo.

903	GX-B1423/20-Y-233056	2023年6月30日	综合判定：合格	
904	GX-B1423/20-Y-233057	2023年6月30日	综合判定：合格	

905	GX-B1423/20-Y-233058	2023年6月30日	综合判定：合格	
906	GX-B1423/20-Y-233059	2023年6月30日	综合判定：合格	

907	GX-B1423/20-Y-233060	2023年6月30日	综合判定：合格	
908	GX-B1423/20-Y-233061	2023年6月30日	综合判定：合格	

909	GX-B1423/20-Y-233062	2023年6月30日	综合判定：合格	 A red dump truck with the number 1172 on its side is parked on a dirt surface. Two workers in safety gear are standing next to it. A yellow timestamp '2023/5/10' is visible in the bottom right corner of the photo.
910	GX-B1423/20-Y-233063	2023年6月30日	综合判定：合格	 A red dump truck with the number 1172 on its side is parked on a dirt surface. Two workers in safety gear are standing next to it. A yellow timestamp '2023/5/10' is visible in the bottom right corner of the photo.

911	GX-B1423/20-Y-233064	2023年6月30日	综合判定：合格	 A red dump truck is parked on a dirt surface. Two workers in safety gear are standing next to it. The truck has the number '1179' on its side. A yellow timestamp '2023/5/10' is visible in the bottom right corner of the photo.
912	GX-B1423/20-Y-233065	2023年6月30日	综合判定：合格	 A red dump truck is parked on a dirt surface. Two workers in safety gear are standing next to it. The truck has the number '1180' on its side. A yellow timestamp '2023/5/10' is visible in the bottom right corner of the photo.

913	GX-B1423/20-Y-233066	2023年6月30日	综合判定：合格	
914	GX-B1423/20-Y-233067	2023年6月30日	综合判定：合格	



915	GX-B1423/20-Y-233068	2023年6月30日	综合判定：合格	
916	GX-B1423/20-Y-233069	2023年6月30日	综合判定：合格	

917	GX-B1423/20-Y-233070	2023年6月30日	综合判定：合格	 A red dump truck with the number 1173 on its side. Two workers in safety gear are standing in front of it. A yellow timestamp '2023/5/10' is in the bottom right corner.
918	GX-B1423/20-Y-233071	2023年6月30日	综合判定：合格	 A red dump truck with the number 1178 on its side. Two workers in safety gear are standing in front of it. A yellow timestamp '2023/5/10' is in the bottom right corner.

919	GX-B1423/20-Y-233072	2023年6月30日	综合判定：合格	
920	GX-B1423/20-Y-233073	2023年6月30日	综合判定：合格	

921	GX-B1423/20-Y-233074	2023年6月30日	综合判定：合格	 A red dump truck is parked on a dirt surface. Two workers in safety gear are standing in front of it. The truck has '1177' and 'MTBELY' visible on its side. A yellow timestamp '2023/5/10' is in the bottom right corner.
922	GX-B1423/20-Y-233075	2023年6月30日	综合判定：合格	 A red dump truck is parked on a dirt surface. Two workers in safety gear are standing in front of it. The truck has '1177' and 'MTBELY' visible on its side. A yellow timestamp '2023/5/10' is in the bottom right corner.

923	GX-B1423/20-Y-233076	2023年6月30日	综合判定：合格	
924	GX-B1423/20-Y-233077	2023年6月30日	综合判定：合格	

925	GX-B1423/20-Y-233078	2023年6月30日	综合判定：合格	
926	GX-B1423/20-Y-233079	2023年6月30日	综合判定：合格	

927	GX-B1423/20-Y-233080	2023年6月30日	综合判定：合格	 <p>A photograph of a red truck, likely a construction vehicle, with two workers standing in front of it. One worker is wearing a grey uniform and a red hard hat, while the other is wearing a blue uniform, a yellow hard hat, and a high-visibility vest. The truck has a large front grille and headlights. A yellow timestamp '2023/5/11' is visible in the bottom right corner of the photo.</p>
928	GX-B1423/20-Y-233081	2023年6月30日	综合判定：合格	 <p>A photograph of a yellow dump truck, likely a construction vehicle, with two workers standing next to it. One worker is wearing a grey uniform and a red hard hat, while the other is wearing a blue uniform, a yellow hard hat, and a high-visibility vest. The truck has a large dump body and multiple axles. A yellow timestamp '2023/5/11' is visible in the bottom right corner of the photo.</p>