

序号	报告编号	发布日期	结论	影像资料
239	GX-B1366/20-A-23055	2023/6/25	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
240	GX-B1366/20-A-23056	2023/6/25	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
241	GX-B1364/22-A-23460	2023/6/25	所检项目合格。	 <p>The photograph shows two individuals in white work uniforms and face masks. They are standing in an industrial setting, looking at a large, dark, rectangular piece of equipment. The person on the left is wearing a pink face mask, and the person on the right is wearing a white face mask. In the background, there is a large white cylindrical tank and a control panel with a screen. A date stamp '2023/06/03' is located in the bottom right corner of the image.</p>

序号	报告编号	发布日期	结论	影像资料
242	GX-B1364/22-A-23454	2023/6/25	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
243	GX-B1364/22-A-23455	2023/6/25	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
244	GX-B1364/22-A-23457	2023/6/25	成束电线电缆燃烧试验不合格；其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
245	GX-B1364/22-A-23479	2023/6/25	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
246	GX-B1364/22-A-23480	2023/6/25	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
247	GX-B1364/22-A-23446	2023/6/25	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
248	GX-B1364/22-A-23444	2023/6/25	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
249	GX-B1364/22-A-23450	2023/6/25	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
250	GX-B1364/22-A-23451	2023/6/25	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
251	GX-B1364/22-A-23443	2023/6/25	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
252	GX-B1364/22-A-23453	2023/6/25	成束电线电缆燃烧试验不合格；其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
253	GX-B1364/22-A-23448	2023/6/25	成束电线电缆燃烧试验不合格；其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
254	GX-B1364/22-A-23463	2023/6/25	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
255	GX-B1364/22-A-23468	2023/6/25	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
256	GX-B1364/22-A-23466	2023/6/25	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
257	GX-B1364/22-A-23478	2023/6/25	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
258	GX-B1364/22-A-23477	2023/6/25	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
259	GX-B1364/22-A-23487	2023/6/25	成束电线电缆燃烧试验不合格；其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
260	GX-B1364/22-A-23476	2023/6/25	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
261	GX-B1364/22-A-23475	2023/6/25	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
262	GX-B1364/22-A-23474	2023/6/25	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
263	GX-B1364/22-A-23473	2023/6/25	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
264	GX-B1364/22-A-23471	2023/6/25	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
265	GX-B1364/22-A-23470	2023/6/25	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
266	GX-B1364/22-A-23469	2023/6/25	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
267	GX-B1364/22-A-23445	2023/6/25	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
268	GX-B1364/22-A-23447	2023/6/25	所检项目合格。	 <p>The photograph shows two individuals in light-colored work uniforms and white face masks. They are standing in an industrial or utility room, looking at a piece of equipment. The person on the left is wearing a mask and glasses, and the person on the right is wearing a mask, glasses, and gloves. The background includes a wall with electrical panels and a red door. A date stamp '2023/05/30' is visible in the bottom right corner of the image.</p>

序号	报告编号	发布日期	结论	影像资料
269	GX-B1364/22-A-23447	2023/6/25	所检项目合格。	 <p>The photograph shows two individuals in light-colored work uniforms and white face masks. They are standing in an industrial or utility room, looking at a piece of equipment. The person on the left is wearing a mask and glasses, and the person on the right is wearing a mask, glasses, and gloves. The background includes a wall with electrical panels and a red door. A date stamp '2023/05/30' is visible in the bottom right corner of the image.</p>

序号	报告编号	发布日期	结论	影像资料
270	GX-B1364/22-A-23486	2023/6/25	成束电线电缆燃烧试验不合格；其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
271	GX-B1364/22-A-23481	2023/6/25	所检项目合格。	 <p>The photograph shows two individuals in light blue work uniforms, white face masks, and blue gloves. They are standing in an industrial setting, looking at a control panel or piece of machinery. The panel has a yellow warning triangle and a digital display. A date stamp '2023/06/06' is visible in the bottom right corner of the image.</p>

序号	报告编号	发布日期	结论	影像资料
272	GX-B1364/22-A-23482	2023/6/25	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
273	GX-B1364/22-A-23483	2023/6/25	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
274	GX-B1364/22-A-23484	2023/6/25	所检项目合格。	 <p>2023/06/06</p>

序号	报告编号	发布日期	结论	影像资料
275	GX-B1364/22-A-23485	2023/6/25	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
276	GX-B1364/22-A-23462	2023/6/25	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
277	GX-B1364/22-A-23464	2023/6/25	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
278	GX-B1364/22-A-23456	2023/6/25	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
279	GX-B1364/22-A-23458	2023/6/25	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
280	GX-B1364/22-A-23449	2023/6/25	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
281	GX-B1364/22-A-23452	2023/6/25	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
282	GX-B1364/22-A-23465	2023/6/25	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
283	GX-B1364/22-A-23461	2023/6/25	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
284	GX-B1364/22-A-23459	2023/6/25	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
285	GX-B1363/22-A-23257	2023/6/27	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
286	GX-B1363/22-A-23258	2023/6/27	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
287	GX-B1363/22-A-23285	2023/6/27	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
288	GX-B1363/22-A-23254	2023/6/29	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
289	GX-B1363/22-A-23239	2023/6/29	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
290	GX-B1363/22-A-23238	2023/6/29	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
291	GX-B1363/22-A-23170	2023/6/29	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
292	GX-B1363/22-A-23168	2023/6/29	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
293	GX-B1363/22-A-23169	2023/6/29	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
294	GX-B1367/22-A-23057	2023/6/30	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
295	GX-B1367/22-A-23058	2023/6/30	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
296	GX-B1367/22-A-23059	2023/6/30	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
297	GX-B1363/22-A-23284	2023/6/30	所检项目合格。	 <p>The photograph shows two men in white short-sleeved shirts and dark trousers inspecting a large, rusted metal cabinet. The cabinet has a prominent yellow radiation warning symbol on its front. One man is wearing blue gloves and is touching the cabinet. The other man is looking at the cabinet. The scene is indoors, with a window in the background showing greenery outside. A date stamp '2023/06/27' is visible in the bottom right corner of the photo.</p>