

序号	报告编号	发布日期	结论	影像资料
298	GX-B1366/20-A-23058	2023/6/30	所检项目全部合格。	


序号	报告编号	发布日期	结论	影像资料
299	GX-B1364/22-A-23554	2023/6/30	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
300	GX-B1364/22-A-23550	2023/6/30	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
301	GX-B1364/22-A-23549	2023/6/30	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
302	GX-B1364/22-A-23542	2023/6/30	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
303	GX-B1364/22-A-23541	2023/6/30	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
304	GX-B1364/22-A-23540	2023/6/30	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
305	GX-B1364/22-A-23539	2023/6/30	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
306	GX-B1364/22-A-23538	2023/6/30	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
307	GX-B1364/22-A-23543	2023/6/30	成束电线电缆燃烧试验不合格；其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
309	GX-B1364/22-A-23533	2023/6/30	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
310	GX-B1364/22-A-23532	2023/6/30	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
311	GX-B1364/22-A-23531	2023/6/30	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
312	GX-B1364/22-A-23530	2023/6/30	成束电线电缆燃烧试验不合格；其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
313	GX-B1364/22-A-23529	2023/6/30	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
313	GX-B1364/22-A-23552	2023/6/30	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
314	GX-B1364/22-A-23553	2023/6/30	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
315	GX-B1365/20-A-23039	2023/6/30	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
316	GX-B1364/22-A-23537	2023/6/30	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
317	GX-B1364/22-A-23536	2023/6/30	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
318	GX-B1364/22-A-23535	2023/6/30	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
319	GX-B1364/22-A-23534	2023/6/30	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
320	GX-B1366/20-A-23066	2023/6/30	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
321	GX-B1366/20-A-23068	2023/6/30	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
322	GX-B1365/20-A-23043	2023/6/30	所检项目全部合格。	 <p>The photograph captures two technicians in white lab coats, one with the '中检公估' (Zhongjian Gongtu) logo on the back, operating a large industrial testing machine. The machine features a prominent circular dial on the left and a safety cage on the right. A date stamp '2023/06/21' is located in the bottom right corner of the image.</p>

序号	报告编号	发布日期	结论	影像资料
323	GX-B1366/20-A-23064	2023/6/30	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
324	GX-B1366/20-A-23065	2023/6/30	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
325	GX-B1366/20-A-23063	2023/6/30	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
326	GX-B1366/20-A-23067	2023/6/30	所检项目全部合格。	 <p>The photograph captures a laboratory setting where two technicians are operating a large industrial testing machine. The technician in the foreground is wearing a white lab coat with the '中检公信' (CIC) logo on the back. The machine features a prominent circular gauge and a safety cage. A date stamp '2023/06/21' is located in the bottom right corner of the image.</p>

序号	报告编号	发布日期	结论	影像资料
327	GX-B1364/22-A-23544	2023/6/30	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
328	GX-B1364/22-A-23547	2023/6/30	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
329	GX-B1364/22-A-23546	2023/6/30	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
330	GX-B1364/22-A-23545	2023/6/30	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
331	GX-B1364/22-A-23526	2023/6/30	成束电线电缆燃烧试验不合格；其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
332	GX-B1365/20-A-23042	2023/6/30	所检项目全部合格。	


序号	报告编号	发布日期	结论	影像资料
333	GX-B1366/20-A-23062	2023/6/30	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
334	GX-B1366/20-A-23061	2023/6/30	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
335	GX-B1365/20-A-23041	2023/6/30	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
336	GX-B1364/22-A-23527	2023/6/30	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
337	GX-B1364/22-A-23525	2023/6/30	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
338	GX-B1364/22-A-23522	2023/6/30	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
339	GX-B1364/22-A-23521	2023/6/30	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
340	GX-B1364/22-A-23524	2023/6/30	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
341	GX-B1364/22-A-23520	2023/6/30	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
342	GX-B1364/22-A-23496	2023/6/30	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
343	GX-B1364/22-A-23495	2023/6/30	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
344	GX-B1364/22-A-23497	2023/6/30	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
345	GX-B1364/22-A-23523	2023/6/30	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
346	GX-B1364/22-A-23505	2023/6/30	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
347	GX-B1364/22-A-23498	2023/6/30	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
348	GX-B1364/22-A-23499	2023/6/30	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
349	GX-B1364/22-A-23488	2023/6/30	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
350	GX-B1364/22-A-23490	2023/6/30	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
351	GX-B1364/22-A-23493	2023/6/30	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
352	GX-B1364/22-A-23491	2023/6/30	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
353	GX-B1364/22-A-23492	2023/6/30	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
354	GX-B1364/22-A-23504	2023/6/30	成束电线电缆燃烧试验不合格；其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
355	GX-B1364/22-A-23503	2023/6/30	成束电线电缆燃烧试验不合格；其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
356	GX-B1364/22-A-23502	2023/6/30	成束电线电缆燃烧试验不合格；其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
357	GX-B1364/22-A-23508	2023/6/30	成束电线电缆燃烧试验不合格。	

序号	报告编号	发布日期	结论	影像资料
358	GX-B1364/22-A-23509	2023/6/30	成束电线电缆燃烧试验不合格。	

序号	报告编号	发布日期	结论	影像资料
359	GX-B1364/22-A-23510	2023/6/30	成束电线电缆燃烧试验不合格。	

序号	报告编号	发布日期	结论	影像资料
360	GX-B1364/22-A-23507	2023/6/30	成束电线电缆燃烧试验不合格。	

序号	报告编号	发布日期	结论	影像资料
361	GX-B1364/22-A-23494	2023/6/30	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
362	GX-B1364/22-A-23528	2023/6/30	所检项目合格。	