



序号	报告编号	发布日期	结论	影像资料
12	GX-B1451/20-3-23166~23181	2023.7.4	本次共检高压开关设备16台，16台高压开关设备所检项目合格。	
13	GX-B1517/20-3-23015	2023.7.5	综合判定：合格	

14	GX-B1517/20-3-23016	2023. 7. 5	综合判定：合格		 <p>2023.04.15</p>
15	GX-B1495/20-3-232868~232886	2023. 7. 4	所检项目合格。		 <p>2023. 05. 31</p>

16	GX-B1451/20-3-23186~23199	2023. 7. 6	所检项目合格。		
17	GX-B1451/20-3-23200~23218	2023. 7. 6	所检项目合格。		

18	GX-B1471/23-3-23001	2023. 7. 6	符合DL/T 724-2021《电力系统用蓄电池直流电源装置运行与维护技术规程》5.3.2的要求	
19	GX-B1312/20-3-23471~23474	2023. 7. 6	本次共检电力变压器4台，4台电力变压器所检项目合格。	 A photograph showing a male worker wearing a red hard hat and safety glasses, kneeling on a dark floor in a control room or technical area. He is working with a yellow toolbox. In the background, there are electrical control panels and a fire extinguisher. A yellow timestamp '2023.07.18' is visible in the bottom right corner of the photo.



20	GX-B1312/20-3-23475~23476	2023. 7. 6	本次共检电力变压器2台，2台电力变压器所检项目合格。	
21	GX-B1312/20-3-23477~23478	2023. 7. 6	本次共检电力变压器2台，2台电力变压器所检项目合格。	

22	GX-B1312/20-3-23479~23480	2023. 7. 6	本次共检电力变压器2台，2台电力变压器所检项目合格。	
23	GX-B1312/20-3-23481	2023. 7. 6	所检项目合格。	



24	GX-B1312/20-3-23482~23483	2023. 7. 6	本次共检电力变压器2台，2台电力变压器所检项目合格。	
25	GX-B1312/20-3-23484~23488	2023. 7. 6	本次共检电力变压器5台，5台电力变压器所检项目合格。	



26	GX-B1321/20-3-231252~231258	2023. 7. 6	本次共检电力电缆7条，7条电力电缆所检项目合格。	
27	GX-B1321/20-3-231259~231265	2023. 7. 6	本次共检电力电缆7条，7条电力电缆所检项目合格。	




28	GX-B1321/20-3-231266~231271	2023. 7. 6	本次共检电力电缆6条，6条电力电缆所检项目合格。	
29	GX-B1321/20-3-231272~231277	2023. 7. 6	本次共检电力电缆6条，6条电力电缆所检项目合格。	


30	GX-B1321/20-3-231278~231281	2023. 7. 6	本次共检电力电缆4条，4条电力电缆所检项目合格。	
31	GX-B1321/20-3-231282~231287	2023. 7. 6	本次共检电力电缆6条，6条电力电缆所检项目合格。	

32	GX-B1321/20-3-231288~231297	2023. 7. 6	本次共检电力电缆10条，10条电力电缆所检项目合格。	
33	GX-B1321/20-3-231298~231305	2023. 7. 6	本次共检电力电缆8条，8条电力电缆所检项目合格。	

34	GX-B1312/20-3-23491~23494	2023. 7. 3	本次共检电力变压器4台，4台电力变压器所检项目合格。	 <p>A photograph showing a worker wearing a blue long-sleeved shirt, a blue face mask, and safety glasses. The worker is positioned next to a large red electrical transformer, appearing to be performing maintenance or inspection. The background shows other industrial equipment. A yellow timestamp '2023.06.10' is visible in the bottom right corner of the photo.</p>
35	GX-B1312/20-3-23495~23496	2023. 7. 3	本次共检电力变压器2台，2台电力变压器所检项目合格。	 <p>A photograph showing a worker wearing a blue long-sleeved shirt, a blue face mask, and safety glasses. The worker is standing next to a red electrical transformer, holding a tool or cable. The background shows an industrial setting with other equipment. A yellow timestamp '2023.06.11' is visible in the bottom right corner of the photo.</p>

36	GX-B1312/20-3-23497~23500	2023. 7. 3	本次共检电力变压器4台，4台电力变压器所检项目合格。	
37	GX-B1312/20-3-23501~23504	2023. 7. 3	本次共检电力变压器4台，4台电力变压器所检项目合格。	

38	GX-B1321/20-3-231311~231318	2023. 7. 3	本次共检电力电缆8条，8条电力电缆所检项目合格。	
39	GX-B1321/20-3-231319~231330	2023. 7. 3	本次共检电力电缆12条，12条电力电缆所检项目合格。	

40	GX-B1321/20-3-231331~231338	2023. 7. 3	本次共检电力电缆8条，8条电力电缆所检项目合格。	
41	GX-B1321/20-3-231339~231346	2023. 7. 3	本次共检电力电缆8条，8条电力电缆所检项目合格。	

42	GX-B1310/21-3-23076	2023. 7. 4	符合标准要求。	
43	GX-B1310/21-3-23077	2023. 7. 5	符合标准要求。	



44	GX-B1310/21-3-23078	2023. 7. 6	符合标准要求。	
45	GX-B1310/21-3-23079	2023. 7. 6	符合标准要求。	

46	GX-B1427/21-3-23020	2023. 7. 6	符合标准要求。	
47	GX-B1427/21-3-23021	2023. 7. 6	符合标准要求。	

48	GX-B1427/21-3-23022	2023. 7. 6	符合标准要求。	
49	GX-B1427/21-3-23023	2023. 7. 6	符合标准要求。	

50	GX-B1313/21-3-23066~23069	2023. 7. 4	本次共检电力变压器4台，4台电力变压器所检项目合格。	
51	GX-B1322/21-3-23104~23119	2023. 7. 4	本次共检验电力电缆16条，16条所检项目合格。	

52	GX-B1301/21-3-23007	2023. 7. 10	综合判定:合格。 。	
53	GX-B1301/21-3-23008	2023. 7. 10	综合判定:合格。 。	

54	GX-B1324/21-3-23033~23036	2023. 7. 7	所检项目合格。		 A worker in a red uniform and helmet is operating a device in an industrial setting. The device has a yellow label. The date 2023.06.10 is visible in the bottom right corner of the image.	
55	GX-B1324/21-3-23037~23046	2023. 7. 7	所检项目合格。		 Two workers in red uniforms and helmets are inspecting a large blue cylindrical object in an industrial setting. The date 2023.06.11 is visible in the bottom right corner of the image.	

56	GX-B1322/21-3-23121~23134	2023. 7. 6	所检项目合格。			
57	GX-B1322/21-3-23135~23150	2023. 7. 6	所检项目合格。			

58	GX-B1313/21-3-23071~23073	2023. 7. 6	所检项目合格。		 <p>2023.06.10</p>	
59	GX-B1313/21-3-23074~23075	2023. 7. 6	所检项目合格。		 <p>2023.06.11</p>	



60	GX-B1321/20-3-231351	2023. 7. 10	所检项目合格。	
61	GX-B1312/20-3-23511	2023. 7. 10	所检项目合格。	

62	GX-B1328/20-3-23166	2023. 7. 11	本次共检绝缘手套56只，56只绝缘手套合格。	
63	GX-B1328/20-3-23167	2023. 7. 11	本次共检绝缘鞋56只，56只绝缘鞋合格。	

64	GX-B1423/20-3-23013	2023. 7. 12	综合判定：合格		
65	GX-B1423/20-3-23014	2023. 7. 12	综合判定：合格		

66	GX-B1423/20-3-23015	2023. 7. 12	综合判定：合格	 A photograph showing a yellow dump truck parked on a dirt surface. Two workers are standing in front of the truck. One worker is wearing a red jumpsuit and a blue hard hat, while the other is wearing a light blue shirt, light blue pants, and a blue hard hat. The truck has a red number '5' on its front. The background shows some greenery and a clear sky. A yellow timestamp '2023/6/23' is visible in the bottom right corner of the photo.
67	GX-B1423/20-3-23016	2023. 7. 12	综合判定：合格	 A photograph showing a yellow dump truck parked in an indoor or semi-enclosed area. Two workers are standing in front of the truck. One worker is wearing a light blue shirt, light blue pants, and a blue hard hat. The other worker is wearing a red jumpsuit, a yellow high-visibility vest, and a blue hard hat. The truck has a red number '5' on its front. The background shows a concrete floor and some industrial structures. A yellow timestamp '2023/6/23' is visible in the bottom right corner of the photo.

68	GX-B1423/20-3-23017	2023. 7. 12	综合判定：合格		 A photograph showing a yellow dump truck. A worker in a light blue uniform is crouching to inspect the tire of the truck. Another worker in a red uniform and a high-visibility vest is standing nearby. The date '2023/6/23' is visible in the bottom right corner of the image.
69	GX-B1423/20-3-23018	2023. 7. 12	综合判定：合格		 A photograph showing a yellow dump truck. Two workers are standing in front of the truck. One is wearing a light blue uniform and a blue hard hat, and the other is wearing a red uniform. The date '2023/6/23' is visible in the bottom right corner of the image.

70	GX-B1423/20-3-23019	2023. 7. 12	综合判定：合格		 A photograph showing a worker wearing a blue hard hat and a light blue uniform sitting in the driver's seat of a yellow truck cab. The truck is parked outdoors, and the worker is looking towards the camera. A yellow timestamp '2023/6/23' is visible in the bottom right corner of the image.
71	GX-B1423/20-3-23020	2023. 7. 12	综合判定：合格		 A photograph showing a worker wearing a blue hard hat and a light blue uniform standing next to a yellow truck. The worker is holding a clipboard and looking towards the camera. The truck is parked outdoors, and there are other yellow trucks visible in the background. A yellow timestamp '2023/6/23' is visible in the bottom right corner of the image.

72	GX-B1423/20-3-23021	2023. 7. 12	综合判定：合格	 A photograph showing two men standing in front of a yellow dump truck. The man on the left is wearing a light blue uniform and a blue hard hat. The man on the right is wearing a black uniform, a blue hard hat, and a high-visibility yellow safety vest. They are standing on a dirt or gravel surface. The truck has a red number '10' on its windshield. A date stamp '2023/6/23' is visible in the bottom right corner of the photo.
73	GX-B1423/20-3-23022	2023. 7. 12	综合判定：合格	 A photograph showing a man in a light blue uniform and a blue hard hat standing next to a yellow dump truck. He is looking at a mobile device. The truck is parked on a dirt or gravel surface. A date stamp '2023/6/23' is visible in the bottom right corner of the photo.



74	GX-B1423/20-3-23023	2023. 7. 12	综合判定：合格	
75	GX-B1423/20-3-23024	2023. 7. 12	综合判定：合格	



76	GX-B1423/20-3-23025	2023. 7. 12	综合判定：合格		
----	---------------------	-------------	---------	--	---