










序号	报告编号	发布日期	结论	影像资料
58	GX-B1417/22-P-23506	2023. 7. 7	综合判定：合格。	
59	GX-B1417/22-P-23507	2023. 7. 7	综合判定：合格。	




60	GX-B1417/22-P-23405	2023. 7. 7	综合判定：合格。	
61	GX-B1417/22-P-23406	2023. 7. 7	综合判定：合格。	
62	GX-B1417/22-P-23407	2023. 7. 7	综合判定：合格。	

63	GX-B1416/22-P-23055	2023.7.5	综合判定：合格。	
64	GX-B1416/22-P-23056	2023.7.5	综合判定：合格。	
65	GX-B1416/22-P-23057	2023.7.5	综合判定：合格。	

66	GX-B1416/22-P-23058	2023. 7. 5	综合判定：合格。	
67	GX-B1416/22-P-23059	2023. 7. 5	综合判定：合格。	
68	GX-B1416/22-P-23060	2023. 7. 5	综合判定：合格。	

69	GX-B1416/22-P-23061	2023.7.5	综合判定：合格。	
70	GX-B1322/21-P-23001~23002	2023/7/6	本次共检电力电缆2条，2条电力电缆所检项目合格。	
71	GX-B1312/20-P-23077	2023.7.4	所检项目合格	




72	GX-B1312/20-P-23078-23081	2023. 7. 4	本次共检电力变压器4台，4台电力变压器所检项目合格。 。	
73	GX-B1312/20-P-23082-23083	2023. 7. 4	本次共检电力变压器2台，2台电力变压器所检项目合格。 。	
74	GX-B1312/20-P-23084-23086	2023. 7. 4	本次共检电力变压器3台，3台电力变压器所检项目合格。 。	

75	GX-B1312/20-P-23087-23088	2023. 7. 6	本次共检电力变压器2台，2台电力变压器所检项目合格。	
76	GX-B1312/20-P-23052-23053	2023. 7. 6	本次共检测电力变压器2台，2台电力变压器所检项目合格。	
77	GX-B1312/20-P-23070~23074	2023. 7. 5	本次共检测电力变压器5台，5台电力变压器所检项目合格。	




78	GX-B1321/20-P-23094~23095	2023.7.4	本次共检电力电缆 2条，2条电力电缆 所检项目合格。	
79	GX-B1321/20-P-23096~23102	2023.7.4	本次共检电力电缆 7条，7条电力电缆 所检项目合格。	
80	GX-B1321/20-P-23103~23105	2023.7.4	本次共检电力电缆 3条，3条电力电缆 所检项目合格。	









81	GX-B1321/20-P-23106~23113	2023.7.4	本次共检电力电缆8条，8条电力电缆所检项目合格。	
82	GX-B1321/20-P-23114~23120	2023.7.4	本次共检电力电缆7条，7条电力电缆所检项目合格。	
83	GX-B1321/20-P-23121~23122	2023.7.4	本次共检电力电缆2条，2条电力电缆所检项目合格。	




84	GX-B1321/20-P-23123~23125	2023.7.4	本次共检电力电缆3条，3条电力电缆所检项目合格。	
85	GX-B1321/20-P-23064~23071	2023年7月6日	本次共检电力电缆8条，8条电力电缆所检项目合格。	
86	GX-B1321/20-P-23072~23080	2023年7月6日	本次共检电力电缆9条，9条电力电缆所检项目合格。	




87	GX-B1321/20-P-23081	2023年7月6日	所检项目合格。		
88	GX-B1321/20-P-23082~23083	2023年7月6日	本次共检电力电缆 2条，2条电力电缆 所检项目合格。		
89	GX-B1321/20-P-23084~23085	2023年7月6日	本次共检电力电缆 2条，2条电力电缆 所检项目合格。		

90	GX-B1321/20-P-23086~23089	2023年7月6日	本次共检电力电缆4条，4条电力电缆所检项目合格。	
91	GX-B1321/20-P-23090~23091	2023年7月6日	本次共检电力电缆2条，2条电力电缆所检项目合格。	
92	GX-B1321/20-P-23092	2023年7月6日	所检项目合格。	

93	GX-B1329/21-P-23013~23016	2023年7月6日	本次共检氧化锌避雷器4组，4组氧化锌避雷器所检项目合格。		
94	GX-B1329/21-P-23017~23026	2023年7月6日	本次共检氧化锌避雷器10组，10组氧化锌避雷器所检项目合格。		
95	GX-B1329/21-P-23027~23035	2023年7月6日	本次共检氧化锌避雷器9组，9组氧化锌避雷器所检项目合格。		

96	GX-B1329/21-P-23036~23043	2023年7月6日	本次共检氧化锌避雷器8组，8组氧化锌避雷器所检项目合格。	
97	GX-B1329/21-P-23044~23048	2023年7月6日	本次共检氧化锌避雷器5组，5组氧化锌避雷器所检项目合格。	
98	GX-B1329/21-P-23049~23063	2023年7月6日	本次共检氧化锌避雷器15组，15组氧化锌避雷器所检项目合格。	

99	GX-B1329/21-P-23064~23066	2023年7月6日	本次共检氧化锌避雷器3组，3组氧化锌避雷器所检项目合格。	
100	GX-B1329/21-P-23067~23082	2023年7月6日	本次共检氧化锌避雷器16组，16组氧化锌避雷器所检项目合格。	
101	GX-B1329/21-P-23083	2023年7月6日	所检项目合格。	


102	GX-B1329/21-P-23084~23092	2023年7月6日	本次共检氧化锌避雷器9组，9组氧化锌避雷器所检项目合格。	
103	GX-B1329/21-P-23093~23102	2023年7月6日	本次共检氧化锌避雷器10组，10组氧化锌避雷器所检项目合格。	
104	GX-B1329/21-P-23104~23105	2023年7月6日	本次共检氧化锌避雷器2组，2组氧化锌避雷器所检项目合格。	



105	GX-B1329/21-P-23106~23108	2023年7月6日	本次共检氧化锌避雷器3组，3组氧化锌避雷器所检项目合格。	
106	GX-B1329/21-P-23109~23112	2023年7月6日	本次共检氧化锌避雷器4组，4组氧化锌避雷器所检项目合格。	
107	GX-B1329/21-P-23113~23116	2023年7月6日	本次共检氧化锌避雷器4组，4组氧化锌避雷器所检项目合格。	



108	GX-B1329/21-P-23117~23119	2023年7月6日	本次共检氧化锌避雷器3组，3组氧化锌避雷器所检项目合格。	 <p>2023 05 27</p>
109	GX-B1451/21-P-23001	2023. 7. 7	所检项目合格。	 <p>2023.2.23</p>
110	GX-B1306/21-P-23037	2023. 7. 7	所检项目合格	 <p>2023.4.2</p>

111	GX-B1306/21-P-23038	2023. 7. 7	所检项目合格	 A worker wearing a blue jacket and a red hard hat is inspecting a blue industrial machine. The machine has a control panel with a digital display. A timestamp '2023.4.28' is visible in the bottom right corner of the photo.
112	GX-B1306/21-P-23039	2023. 7. 7	所检项目合格	 A worker wearing a blue jacket and a red hard hat is inspecting a blue industrial machine in a factory setting. The machine has a control panel with a digital display. A timestamp '2023.4.28' is visible in the bottom right corner of the photo.
113	GX-B1339/21-P-23011	2023. 7. 7	所检项目合格	 A worker wearing a grey jacket and a red hard hat is inspecting a green industrial machine. The machine has a control panel with a digital display. A timestamp '2023.6.3' is visible in the bottom right corner of the photo.

114	GX-B1339/21-P-23012	2023. 7. 7	所检项目合格	 A worker wearing a red hard hat and a grey jacket is inspecting a large green industrial machine. The machine has a circular opening with a white arrow pointing upwards. A date stamp '2023.6.3' is visible in the bottom right corner of the photo.
115	GX-B1339/21-P-23013	2023. 7. 7	所检项目合格	 A worker wearing a red hard hat and a grey jacket is inspecting a green industrial machine. The machine has a circular opening. A date stamp '2023.6.3' is visible in the bottom right corner of the photo.
116	GX-B1339/21-P-23014	2023. 7. 7	所检项目合格	 A worker wearing a red hard hat and a grey jacket is inspecting a green industrial machine. The machine is labeled '4号泵' (No. 4 Pump). The worker is crouching down, looking at a document. A date stamp '2023.6.3' is visible in the bottom right corner of the photo.

117	GX-B1339/21-P-23015	2023. 7. 7	所检项目合格	
118	GX-B1339/21-P-23016	2023. 7. 7	所检项目合格	
119	GX-B1339/21-P-23017	2023. 7. 7	所检项目合格	




120	GX-B1339/21-P-23018	2023. 7. 7	所检项目合格	
121	GX-B1339/21-P-23019	2023. 7. 7	所检项目合格	
122	GX-B1339/21-P-23020	2023. 7. 7	所检项目合格	

123	GX-B1495/20-P-23187~23189	2023年7月6日	本次共检高压开关设备3台，3台高压开关设备所检项目合格。	
124	GX-B1495/20-P-23190~23192	2023年7月6日	本次共检高压开关设备3台，3台高压开关设备所检项目合格。	
125	GX-B1495/20-P-23193~23195	2023年7月6日	本次共检高压开关设备3台，3台高压开关设备所检项目合格。	


126	GX-B1495/20-P-23196~23199	2023年7月6日	本次共检高压开关设备4台，4台高压开关设备所检项目合格。	 2023 4 26
127	GX-B1495/20-P-23202~23208	2023年7月6日	本次共检高压开关设备7台，7台高压开关设备所检项目合格。	 2023 04 27
128	GX-B1495/20-P-23209~23210	2023年7月6日	本次共检高压开关设备2台，2台高压开关设备所检项目合格。	 2023 04 27









129	GX-B1495/20-P-23211~23212	2023年7月6日	本次共检高压开关设备2台，2台高压开关设备所检项目合格。	 2023 04 27
130	GX-B1495/20-P-23213	2023年7月6日	所检项目合格。	 2023 04 27
131	GX-B1495/20-P-23214~23215	2023年7月6日	本次共检高压开关设备2台，2台高压开关设备所检项目合格。	 2023 04 28



132	GX-B1495/20-P-23216~23218	2023年7月6日	本次共检高压开关设备3台，3台高压开关设备所检项目合格。	
133	GX-B1495/20-P-23219	2023年7月6日	所检项目合格。	
134	GX-B1495/20-P-23488~23494	2023年7月6日	本次共检高压开关设备7台，7台高压开关设备所检项目合格。	

135	GX-B1495/20-P-23495~23496	2023年7月6日	本次共检高压开关设备2台，2台高压开关设备所检项目合格。	
136	GX-B1495/20-P-23497	2023年7月6日	所检项目合格。	
137	GX-B1495/20-P-23498~23499	2023年7月6日	本次共检高压开关设备2台，2台高压开关设备所检项目合格。	

138	GX-B1495/20-P-23500~23501	2023年7月6日	本次共检高压开关设备2台，2台高压开关设备所检项目合格。	
139	GX-B1495/20-P-23502	2023年7月6日	所检项目合格。	
140	GX-B1495/20-P-23503~23514	2023年7月6日	本次共检高压开关设备12台，12台高压开关设备所检项目合格。	

141	GX-B1312/20-P-23050~23051	2023年7月6日	本次共检电力变压器2台，2台电力变压器所检项目合格。 。	
142	GX-B1312/20-P-23054~23055	2023年7月6日	本次共检电力变压器2台，2台电力变压器所检项目合格。 。	
143	GX-B1312/20-P-23056~23057	2023年7月6日	本次共检电力变压器2台，2台电力变压器所检项目合格。 。	




144	GX-B1312/20-P-23058~23059	2023年7月6日	本次共检电力变压器2台，2台电力变压器所检项目合格。	
145	GX-B1312/20-P-23062~23065	2023年7月6日	本次共检电力变压器4台，4台电力变压器所检项目合格。	
146	GX-B1312/20-P-23066	2023年7月6日	所检项目合格。	

147	GX-B1312/20-P-23067	2023年7月6日	所检项目合格。	 <p>2023 05 26</p>
148	GX-B1312/20-P-23068	2023年7月6日	所检项目合格。	 <p>2023 05 26</p>
149	GX-B1312/20-P-23069	2023年7月6日	所检项目合格。	 <p>2023 05 27</p>

150	GX-B1312/20-P-23091~23093	2023年7月6日	<p>本次共检电力变压器3台，3台电力变压器所检项目合格。</p> <p>。</p>	
151	GX-B1310/21-P-23043	2023年7月6日	符合标准要求。	
152	GX-B1310/21-P-23044	2023年7月6日	<p>符合标准要求。</p> <p>。</p>	



153	GX-B1310/21-P-23045	2023年7月6日	符合标准要求。 。		
154	GX-B1310/21-P-23046	2023年7月6日	符合标准要求。		
155	GX-B1310/21-P-23047	2023年7月6日	符合标准要求。 。		

156	GX-B1310/21-P-23048	2023年7月6日	符合标准要求。 。	
157	GX-B1310/21-P-23049	2023年7月6日	符合标准要求。	
158	GX-B1310/21-P-23050	2023年7月6日	符合标准要求。 。	

159	GX-B1310/21-P-23051	2023年7月6日	符合标准要求。 。	 2023.4.10	
160	GX-B1310/21-P-23052	2023年7月6日	符合标准要求。	 2023.4.10	
161	GX-B1310/21-P-23053	2023年7月6日	符合标准要求。 。	 2023.4.10	

162	GX-B1310/21-P-23054	2023年7月6日	符合标准要求。 。		
163	GX-B1427/21-P-23004	2023年7月6日	符合标准要求。 。		
164	GX-B1427/21-P-23005	2023年7月6日	符合标准要求。 。		

165	GX-B1427/21-P-23006	2023年7月6日	符合标准要求。 。	 2023.4.10	
166	GX-B1427/21-P-23007	2023年7月6日	符合标准要求。 。	 2023.4.10	
167	GX-B1417/22-P-23441	2023年7月7日	综合判定：合格。	 2023.5.11	

168	GX-B1417/22-P-23442	2023年7月7日	综合判定：合格。	
169	GX-B1417/22-P-23443	2023年7月7日	综合判定：合格。	
170	GX-B1417/22-P-23444	2023年7月7日	综合判定：合格。	

171	GX-B1417/22-P-23445	2023年7月7日	综合判定：合格。		
172	GX-B1417/22-P-23446	2023年7月7日	综合判定：合格。		
173	GX-B1417/22-P-23447	2023年7月7日	综合判定：合格。		

174	GX-B1417/22-P-23448	2023年7月7日	综合判定：合格。	
175	GX-B1417/22-P-23449	2023年7月7日	综合判定：合格。	
176	GX-B1417/22-P-23450	2023年7月7日	综合判定：合格。	



177	GX-B1417/22-P-23451	2023年7月7日	综合判定：合格。	 <p>2023.5.12</p>	
178	GX-B1417/22-P-23452	2023年7月7日	综合判定：合格。	 <p>2023.5.12</p>	
179	GX-B1417/22-P-23453	2023年7月7日	综合判定：合格。	 <p>2023.5.12</p>	

180	GX-B1417/22-P-23454	2023年7月7日	综合判定：合格。	 <p>2023.5.12</p>
181	GX-B1417/22-P-23455	2023年7月7日	综合判定：合格。	 <p>2023.5.12</p>
182	GX-B1417/22-P-23456	2023年7月7日	综合判定：合格。	 <p>2023.5.12</p>

183	GX-B1417/22-P-23457	2023年7月7日	综合判定：合格。	 <p>2023.5.12</p>
184	GX-B1417/22-P-23458	2023年7月7日	综合判定：合格。	 <p>2023.5.12</p>
185	GX-B1417/22-P-23459	2023年7月7日	综合判定：合格。	 <p>2023.5.13</p>

186	GX-B1417/22-P-23460	2023年7月7日	综合判定：合格。	
187	GX-B1417/22-P-23461	2023年7月7日	综合判定：合格。	
188	GX-B1417/22-P-23462	2023年7月7日	综合判定：合格。	

189	GX-B1417/22-P-23463	2023年7月7日	综合判定：合格。	 2023.5.13	
190	GX-B1417/22-P-23464	2023年7月7日	综合判定：合格。	 2023.5.13	