

序号	报告编号	发布日期	结论	影像资料
503	GX-B1423/20-Y-234504	2023年8月11日	综合判定：合格	
504	GX-B1423/20-Y-234505	2023年8月11日	综合判定：合格	

505	GX-B1423/20-Y-234506	2023年8月11日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers in high-visibility vests stand in front of it. The license plate number '2490' is visible on the side of the truck. A yellow timestamp '2023/7/12' is in the bottom right corner.
506	GX-B1423/20-Y-234507	2023年8月11日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers in high-visibility vests stand in front of it. The license plate number '2483' is visible on the side of the truck. A yellow timestamp '2023/7/12' is in the bottom right corner.

507	GX-B1423/20-Y-234508	2023年8月11日	综合判定：合格	 A yellow dump truck with the number 2101 on its side is parked on a dirt surface. Three workers in safety gear are standing near the truck. A yellow timestamp '2023/7/12' is visible in the bottom right corner of the photo.
508	GX-B1423/20-Y-234509	2023年8月11日	综合判定：合格	 A yellow dump truck with the number 2106 on its side is parked on a dirt surface. Three workers in safety gear are standing near the truck. A yellow timestamp '2023/7/12' is visible in the bottom right corner of the photo.

509	GX-B1423/20-Y-234510	2023年8月11日	综合判定：合格	 A red dump truck is parked on a dirt surface with its bed lowered. Two workers in high-visibility vests stand near the front. A yellow timestamp '2023/7/12' is in the bottom right corner.
510	GX-B1423/20-Y-234511	2023年8月11日	综合判定：合格	 A red dump truck is parked on a dirt surface with its bed raised. Two workers in high-visibility vests stand near the front. A yellow timestamp '2023/7/12' is in the bottom right corner.

511	GX-B1423/20-Y-234512	2023年8月11日	综合判定：合格	
512	GX-B1423/20-Y-234513	2023年8月11日	综合判定：合格	

513	GX-B1423/20-Y-234514	2023年8月11日	综合判定：合格	
514	GX-B1423/20-Y-234515	2023年8月11日	综合判定：合格	

515	GX-B1423/20-Y-234516	2023年8月11日	综合判定：合格	
516	GX-B1423/20-Y-234517	2023年8月11日	综合判定：合格	

517	GX-B1423/20-Y-234518	2023年8月11日	综合判定：合格	
518	GX-B1423/20-Y-234519	2023年8月11日	综合判定：合格	



519	GX-B1423/20-Y-234520	2023年8月11日	综合判定：合格	 A red dump truck with the number 2350 on its side is parked on a dirt surface. Two workers in high-visibility vests are standing next to it. The truck's bed is raised and filled with material. A yellow timestamp '2023/7/12' is visible in the bottom right corner of the photo.
520	GX-B1423/20-Y-234521	2023年8月11日	综合判定：合格	 A red dump truck with the number 2370 on its side is parked on a dirt surface. Two workers in high-visibility vests are standing next to it. The truck's bed is raised and filled with material. A yellow timestamp '2023/7/12' is visible in the bottom right corner of the photo.

521	GX-B1423/20-Y-234522	2023年8月11日	综合判定：合格	
522	GX-B1423/20-Y-234523	2023年8月11日	综合判定：合格	

523	GX-B1423/20-Y-234524	2023年8月11日	综合判定：合格	
524	GX-B1423/20-Y-234525	2023年8月11日	综合判定：合格	

525	GX-B1423/20-Y-234526	2023年8月11日	综合判定：合格	
526	GX-B1423/20-Y-234527	2023年8月11日	综合判定：合格	

527	GX-B1423/20-Y-234528	2023年8月11日	综合判定：合格	
528	GX-B1423/20-Y-234344	2023年8月11日	综合判定：合格	

529	GX-B1423/20-Y-234345	2023年8月11日	综合判定：合格	
530	GX-B1423/20-Y-234346	2023年8月11日	综合判定：合格	

531	GX-B1423/20-Y-234347	2023年8月11日	综合判定：合格	
532	GX-B1423/20-Y-234348	2023年8月11日	综合判定：合格	

533	GX-B1423/20-Y-234349	2023年8月11日	综合判定：合格	
534	GX-B1423/20-Y-234350	2023年8月11日	综合判定：合格	



535	GX-B1423/20-Y-234351	2023年8月11日	综合判定：合格	
536	GX-B1423/20-Y-234352	2023年8月11日	综合判定：合格	

537	GX-B1423/20-Y-234353	2023年8月11日	综合判定：合格	 <p>A yellow dump truck is shown from a side-rear perspective. The truck has 'MX3296' written on its side panel and '3326' on the side of the dump body. Two workers wearing yellow safety vests and hard hats are standing in front of the truck. A yellow timestamp '2023/7/28' is visible in the bottom right corner of the image.</p>
538	GX-B1423/20-Y-234354	2023年8月11日	综合判定：合格	 <p>A yellow dump truck is shown from a side-rear perspective. The truck has 'DW105A' and 'MX3296' written on its side panel. Two workers wearing yellow safety vests and hard hats are standing in front of the truck. A yellow timestamp '2023/7/28' is visible in the bottom right corner of the image.</p>

539	GX-B1423/20-Y-234355	2023年8月11日	综合判定：合格	
540	GX-B1423/20-Y-234356	2023年8月11日	综合判定：合格	

541	GX-B1423/20-Y-234357	2023年8月11日	综合判定：合格	 A yellow dump truck, model DW105A, with license plate MX3275, is parked on a dirt surface. Two workers in high-visibility vests and hard hats are standing next to the truck. A yellow timestamp '2023/7/28' is visible in the bottom right corner of the photo.
542	GX-B1423/20-Y-234358	2023年8月11日	综合判定：合格	 A yellow dump truck, model DW105A, with license plate MX3281, is parked on a dirt surface. Two workers in high-visibility vests and hard hats are standing next to the truck. A yellow timestamp '2023/7/28' is visible in the bottom right corner of the photo.

543	GX-B1423/20-Y-234359	2023年8月11日	综合判定：合格	
544	GX-B1423/20-Y-234360	2023年8月11日	综合判定：合格	

545	GX-B1423/20-Y-234361	2023年8月11日	综合判定：合格	 A yellow dump truck with the model 'DW105A' and identification 'MX3207' is shown from a rear-quarter perspective. Two workers in high-visibility vests and hard hats stand in front of the truck. A yellow timestamp '2023/7/25' is visible in the bottom right corner of the photo.
546	GX-B1423/20-Y-234362	2023年8月11日	综合判定：合格	 A yellow dump truck with the model 'DW105A' and identification 'MX3207' is shown from a rear-quarter perspective. Two workers in high-visibility vests and hard hats stand in front of the truck. A yellow timestamp '2023/7/25' is visible in the bottom right corner of the photo.

547	GX-B1423/20-Y-234363	2023年8月11日	综合判定：合格	 A yellow dump truck, model DW105A, with license plate GX3263, is parked on a dirt surface. Two workers in safety gear are standing next to it. A yellow timestamp '2023/7/29' is visible in the bottom right corner of the photo.
548	GX-B1423/20-Y-234364	2023年8月11日	综合判定：合格	 A yellow dump truck, model DW105A, with license plate GX3271, is parked on a dirt surface. Two workers in safety gear are standing next to it. A yellow timestamp '2023/7/29' is visible in the bottom right corner of the photo.

549	GX-B1423/20-Y-234365	2023年8月11日	综合判定：合格	
550	GX-B1423/20-Y-234366	2023年8月11日	综合判定：合格	



551	GX-B1423/20-Y-234367	2023年8月11日	综合判定：合格	
552	GX-B1423/20-Y-234368	2023年8月11日	综合判定：合格	

553	GX-B1423/20-Y-234369	2023年8月11日	综合判定：合格	
554	GX-B1423/20-Y-234370	2023年8月11日	综合判定：合格	

555	GX-B1423/20-Y-234371	2023年8月11日	综合判定：合格	 <p>A yellow dump truck, model DW105A, with license plate WX3245, is parked on a dirt surface. Two workers in high-visibility vests and hard hats stand in front of the truck. A yellow timestamp '2023/7/29' is visible in the bottom right corner of the photo.</p>
556	GX-B1423/20-Y-234372	2023年8月11日	综合判定：合格	 <p>A yellow dump truck, model DW105A, with license plate WX3301, is parked on a dirt surface. Two workers in high-visibility vests and hard hats stand in front of the truck. A yellow timestamp '2023/7/29' is visible in the bottom right corner of the photo.</p>

557	GX-B1423/20-Y-234373	2023年8月11日	综合判定：合格	 A yellow dump truck with model number MX3280 and DW105A on its side. Two workers in high-visibility vests and hard hats stand in front of the truck. A yellow timestamp '2023/7/29' is visible in the bottom right corner of the photo.
558	GX-B1423/20-Y-234374	2023年8月11日	综合判定：合格	 A yellow dump truck with model number MX3281 and DW105A on its side. The side of the truck has the numbers '3291' written on it. Two workers in high-visibility vests and hard hats stand in front of the truck. A yellow timestamp '2023/7/29' is visible in the bottom right corner of the photo.

559	GX-B1423/20-Y-234375	2023年8月11日	综合判定：合格	
560	GX-B1423/20-Y-234376	2023年8月11日	综合判定：合格	

561	GX-B1423/20-Y-234377	2023年8月11日	综合判定：合格	 A yellow dump truck with the model number DW105A is shown from a side-rear perspective. The truck's bed is raised. Two workers in high-visibility vests and hard hats are standing near the rear of the truck. A yellow timestamp '2023/7/29' is visible in the bottom right corner of the photo.
562	GX-B1423/20-Y-234378	2023年8月11日	综合判定：合格	 A yellow dump truck with the model number DW105A is shown from a side-rear perspective. The truck's bed is raised. Two workers in high-visibility vests and hard hats are standing near the rear of the truck. A yellow timestamp '2023/7/29' is visible in the bottom right corner of the photo.

563	GX-B1423/20-Y-234379	2023年8月11日	综合判定：合格	 A yellow dump truck, model DW105A, is shown from a side-rear perspective. The truck's bed is raised. Two workers in high-visibility vests and hard hats stand in front of the truck. The date stamp '2023/7/30' is visible in the bottom right corner of the image.
564	GX-B1423/20-Y-234380	2023年8月11日	综合判定：合格	 A yellow dump truck, model DW105A, is shown from a side-rear perspective. The truck's bed is raised. A single worker in a high-visibility vest stands in front of the truck. The date stamp '2023/7/30' is visible in the bottom right corner of the image.

565	GX-B1423/20-Y-234381	2023年8月11日	综合判定：合格	 A yellow Komatsu DW105A dump truck is parked on a dirt surface. Two workers in high-visibility vests and hard hats are standing next to the truck. The truck's body is raised. A yellow timestamp '2023/7/30' is visible in the bottom right corner of the photo.
566	GX-B1423/20-Y-234382	2023年8月11日	综合判定：合格	 A yellow Komatsu DW105A dump truck is parked on a dirt surface. Two workers in high-visibility vests and hard hats are standing next to the truck. The truck's body is raised. A yellow timestamp '2023/7/30' is visible in the bottom right corner of the photo.



567	GX-B1423/20-Y-234383	2023年8月11日	综合判定：合格	
568	GX-B1423/20-Y-234384	2023年8月11日	综合判定：合格	

569	GX-B1423/20-Y-234385	2023年8月11日	综合判定：合格	
570	GX-B1423/20-Y-234386	2023年8月11日	综合判定：合格	

571	GX-B1423/20-Y-234387	2023年8月11日	综合判定：合格	
572	GX-B1423/20-Y-234388	2023年8月11日	综合判定：合格	

573	GX-B1423/20-Y-234389	2023年8月11日	综合判定：合格	
574	GX-B1423/20-Y-234390	2023年8月11日	综合判定：合格	

575	GX-B1423/20-Y-234391	2023年8月11日	综合判定：合格	
576	GX-B1423/20-Y-234392	2023年8月11日	综合判定：合格	

577	GX-B1423/20-Y-234393	2023年8月11日	综合判定：合格	
578	GX-B1423/20-Y-234394	2023年8月11日	综合判定：合格	

579	GX-B1423/20-Y-234395	2023年8月11日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. A worker in a high-visibility vest and hard hat stands next to the front of the truck. The truck has the number '5' on its side. A yellow timestamp '2023/7/30' is visible in the bottom right corner of the image.
580	GX-B1423/20-Y-234396	2023年8月11日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers in high-visibility vests and hard hats stand next to the truck. The truck has 'DW120A' and 'MX284' written on its side. A yellow timestamp '2023/7/30' is visible in the bottom right corner of the image.