

序号	报告编号	发布日期	结论	影像资料
249	GX-B1311/21-3-23050	2023年8月22日	<p>1#（副立井）无缝钢管实测最小壁厚为10.64/21.23mm，2#（副立井）无缝钢管实测最小壁厚为10.58/19.33mm，3#（副立井）无缝钢管实测最小壁厚为10.67/21.04mm，4#（副立井）无缝钢管实测最小壁厚为9.77mm，1#（副箕斗）无缝钢管实测最小壁厚为6.21mm，2#（副箕斗）无缝钢管实测最小壁厚为10.75/22.12mm，3#（副箕斗）无缝钢管实测最小壁厚为25.16mm，4#（主箕斗）无缝钢管实测最小壁厚为10.49/20.24mm，5#（主箕斗）无缝钢管实测最小壁厚为25.01mm。</p>	
250	GX-B1311/21-3-23051	2023年8月22日	<p>6#（大罐南侧）方形空心钢罐道实测最小壁厚为12.16mm，7#（大罐北侧）方形空心钢罐道实测最小壁厚为12.40mm，8#（大罐平衡锤北侧）方形空心钢罐道实测最小壁厚为11.87mm，9#（大罐平衡锤南侧）方形空心钢罐道实测最小壁厚为12.08mm，10#（交通罐南侧）方形空心钢罐道实测最小壁厚为7.59mm，11#（交通罐北侧）方形空心钢罐道实测最小壁厚为7.87mm，12#（交通罐平衡锤北侧）方形空心钢罐道实测最小壁厚为7.93mm，13#（交通罐平衡锤南侧）方形空心钢罐道实测最小壁厚为7.85mm，6#（副箕斗东侧）方形空心钢罐道实测最小壁厚为12.02mm，7#（副箕斗西侧）方形空心钢罐道实测最小壁厚为12.02mm，8#（主箕斗东侧）方形空心钢罐道实测最小壁厚为11.96mm，9#（主箕斗西侧）方形空心钢罐道实测最小壁厚</p>	

251	GX-B1311/21-3-23052	2023年8月22日	5#无缝钢管实测最小壁厚为7.71mm。	 A photograph showing a worker in a red safety vest and helmet using a flashlight to inspect a structure. The date 2023.06.25 is visible in the bottom right corner of the photo.
252	GX-B1534/20-3-23033	2023年8月23日	所检项目合格。	 A photograph showing a worker in a red helmet and white shirt kneeling next to a piece of equipment, possibly a pump or motor, outdoors.

253	GX-B1534/20-3-23034	2023年8月23日	所检项目合格。	
254	GX-B1534/20-3-23035	2023年8月23日	所检项目合格。	

255	GX-B1423/20-3-23050	2023年8月23日	综合判定：合格	
256	GX-B1423/20-3-23051	2023年8月23日	综合判定：合格	



257	GX-B1423/20-3-23052	2023年8月23日	综合判定：合格	
258	GX-B1423/20-3-23053	2023年8月23日	综合判定：合格	

259	GX-B1423/20-3-23054	2023年8月23日	综合判定：合格	
260	GX-B1423/20-3-23055	2023年8月23日	综合判定：合格	

261	GX-B1423/20-3-23056	2023年8月23日	综合判定：合格	
262	GX-B1423/20-3-23057	2023年8月23日	综合判定：合格	

263	GX-B1423/20-3-23058	2023年8月23日	综合判定：合格	 A photograph showing a worker in a blue uniform and red helmet working on the rear of a red truck. The worker is holding a tool and appears to be inspecting or working on the rear wheel area. The truck has a green tarp covering the cargo area. A yellow timestamp '2023.8.18' is visible in the bottom right corner of the photo.
264	GX-B1423/20-3-23059	2023年8月23日	综合判定：合格	 A photograph showing a worker in a blue uniform and red helmet standing next to a red truck. The worker is holding a clipboard and looking towards the camera. The truck is parked on a paved area with trees in the background. A yellow timestamp '2023.8.18' is visible in the bottom right corner of the photo.

265	GX-B1423/20-3-23060	2023年8月23日	综合判定：合格	
266	GX-B1423/20-3-23061	2023年8月23日	综合判定：合格	

267	GX-B1423/20-3-23062	2023年8月23日	综合判定：合格	
268	GX-B1423/20-3-23063	2023年8月23日	综合判定：合格	



269	GX-B1423/20-3-23064	2023年8月23日	综合判定：合格	
270	GX-B1423/20-3-23065	2023年8月23日	综合判定：合格	

271	GX-B1423/20-3-23066	2023年8月23日	综合判定：合格	
272	GX-B1423/20-3-23067	2023年8月23日	综合判定：合格	

273	GX-B1423/20-3-23068	2023年8月23日	综合判定：合格	
274	GX-B1423/20-3-23069	2023年8月23日	综合判定：合格	

275	GX-B1423/20-3-23070	2023年8月23日	综合判定：合格	
276	GX-B1423/20-3-23071	2023年8月23日	综合判定：合格	

277	GX-B1423/20-3-23072	2023年8月23日	综合判定：合格	
278	GX-B1423/20-3-23073	2023年8月23日	综合判定：合格	

279	GX-B1423/20-3-23074	2023年8月23日	综合判定：合格	
280	GX-B1423/20-3-23075	2023年8月23日	综合判定：合格	

281	GX-B1423/20-3-23076	2023年8月23日	综合判定：合格	
282	GX-B1423/20-3-23077	2023年8月23日	综合判定：合格	

283	GX-B1423/20-3-23078	2023年8月23日	综合判定：合格	
284	GX-B1423/20-3-23079	2023年8月23日	综合判定：合格	

285	GX-B1423/20-3-23080	2023年8月23日	综合判定：合格	
286	GX-B1423/20-3-23081	2023年8月23日	综合判定：合格	

287	GX-B1423/20-3-23082	2023年8月23日	综合判定：合格	
288	GX-B1423/20-3-23083	2023年8月23日	综合判定：合格	

289	GX-B1423/20-3-23084	2023年8月23日	综合判定：合格	
290	GX-B1423/20-3-23085	2023年8月23日	综合判定：合格	

291	GX-B1423/20-3-23086	2023年8月23日	综合判定：合格	
292	GX-B1423/20-3-23087	2023年8月23日	综合判定：合格	



293	GX-B1423/20-3-23088	2023年8月23日	综合判定：合格	
294	GX-B1423/20-3-23089	2023年8月23日	综合判定：合格	

295	GX-B1548/20-3-23010	2023年8月23日	所检项目合格。	
296	GX-B1522/20-3-23002	2023年8月24日	所检项目合格。	
297	GX-B1328/20-3-23201	2023年8月24日	本次共检验电器11支，11支验电器合格	
298	GX-B1328/20-3-23202	2023年8月24日	本次共检便携式接地和接地短路装置11套，11套便携式接地和接地短路装置合格	

299	GX-B1328/20-3-23203	2023年8月24日	本次共检绝缘杆11套，11套绝缘杆合格	
300	GX-B1328/20-3-23199	2023年8月24日	本次共检绝缘手套2只，2只绝缘手套合格	
301	GX-B1328/20-3-23200	2023年8月24日	本次共检绝缘鞋2只，2只绝缘鞋合格	

302	GX-B1313/21-3-23076	2023年8月24日	所检项目合格	
303	GX-B1322/21-3-23162	2023年8月24日	所检项目合格	

304	GX-B1310/21-3-23150	2023. 8. 25	符合标准要求	
305	GX-B1328/20-3-23193	2023. 8. 25	合格	

306	GX-B1328/20-3-23194	2023. 8. 25	合格	
307	GX-B1517/20-3-23044	2023. 8. 24	综合判定：合格	

308	GX-B1307/20-3-23035	2023. 8. 24	综合判定：合格。	
309	GX-B1520/20-3-23032	2023. 8. 24	综合判定：合格。	

310	GX-B1520/20-3-23033	2023. 8. 24	综合判定：合格。	 A worker wearing a red safety helmet and a blue uniform with a logo is operating a piece of machinery. The date stamp '2023.8.18' is visible in the bottom right corner of the photo.
311	GX-B1520/20-3-23034	2023. 8. 24	综合判定：合格。	 A worker wearing a red safety helmet and a blue uniform is standing next to a blue trailer. A piece of equipment is on the ground in front of him. The date stamp '2023.8.18' is visible in the bottom right corner of the photo.

312	GX-B1520/20-3-23036	2023. 8. 24	综合判定：合格。	
313	GX-B1520/20-3-23037	2023. 8. 24	综合判定：合格。	

314	GX-B1520/20-3-23038	2023. 8. 24	综合判定：合格。	
315	GX-B1548/20-3-23011	2023. 8. 25	所检项目合格。	



316	GX-B1548/20-3-23012	2023. 8. 25	所检项目合格。	
317	GX-B1548/20-3-23013	2023. 8. 25	所检项目合格。	

318	GX-B1500/21-3-23074	2023年8月24日	综合判定：合格			
319	GX-B1500/21-3-23075	2023年8月24日	综合判定：合格			

320	GX-B1500/21-3-23076	2023年8月24日	综合判定：合格			
321	GX-B1500/21-3-23077	2023年8月24日	综合判定：合格			



322	GX-B1500/21-3-23078	2023年8月24日	综合判定：合格			
323	GX-B1500/21-3-23079	2023年8月24日	综合判定：合格			

324	GX-B1423/20-3-23091	2023年8月24日	综合判定：合格	 A photograph showing two men in safety gear (hard hats and high-visibility vests) standing next to a yellow truck. One man is looking at a device, while the other stands beside him. The truck has some Chinese characters on its side. A timestamp '2023/08/24' is visible in the bottom right corner of the photo.
325	GX-B1423/20-3-23092	2023年8月24日	综合判定：合格	 A photograph showing a man in a red hard hat and a grey shirt crouching down to inspect the underside of a truck. He is holding a tool or flashlight. The truck is yellow and has some rust on its undercarriage. A timestamp '2023/08/24' is visible in the bottom right corner of the photo.

326	GX-B1423/20-3-23093	2023年8月24日	综合判定：合格	
327	GX-B1423/20-3-23094	2023年8月24日	综合判定：合格	

328	GX-B1423/20-3-23095	2023年8月24日	综合判定：合格	 A photograph showing two men standing in front of a yellow truck. The man on the left is wearing an orange safety suit and a yellow hard hat. The man on the right is wearing a grey short-sleeved shirt, black shorts, and a red hard hat. A yellow timestamp '2023/7/14' is visible in the bottom right corner of the photo.
329	GX-B1423/20-3-23096	2023年8月24日	综合判定：合格	 A photograph showing a man in a grey short-sleeved shirt, black shorts, and a red hard hat standing next to a yellow truck. He is pointing towards the truck. A yellow timestamp '2023/7/14' is visible in the bottom right corner of the photo.

330	GX-B1423/20-3-23097	2023年8月24日	综合判定：合格	
331	GX-B1423/20-3-23098	2023年8月24日	综合判定：合格	

332	GX-B1423/20-3-23099	2023年8月24日	综合判定：合格	
333	GX-B1423/20-3-23100	2023年8月24日	综合判定：合格	

334	GX-B1534/20-3-23036	2023年8月25日	所检项目合格。	
335	GX-B1534/20-3-23037	2023年8月25日	所检项目合格。	


336	GX-B1328/20-3-23195	2023. 8. 25	合格	
337	GX-B1328/20-3-23196	2023. 8. 25	合格	

338	GX-B1548/20-3-23015	2023. 8. 28	所检项目合格。	
339	GX-B1548/20-3-23016	2023. 8. 29	所检项目合格。	

340	GX-B1382/21-3-23020	2023年8月28日	所检项目合格。	
341	GX-B1382/21-3-23021	2023年8月28日	所检项目合格。	

342	GX-B1382/21-3-23022	2023年8月28日	所检项目合格。	
343	GX-B1382/21-3-23023	2023年8月28日	所检项目合格。	

344	GX-B1382/21-3-23024	2023年8月28日	所检项目合格。	
345	GX-B1382/21-3-23025	2023年8月28日	所检项目合格。	

346	GX-B1495/20-3-235481~235483	2023年8月28日	本次共检高压开关柜3台，3台高压开关柜所检项目合格。	
-----	-----------------------------	------------	----------------------------	---