

序号	报告编号	发布日期	结论	影像资料
684	GX-B1539/22-Y-23212	2023年8月22日	所检项目合格。	
685	GX-B1539/22-Y-23213	2023年8月22日	所检项目合格。	

686	GX-B1539/22-Y-23214	2023年8月22日	所检项目合格。	
687	GX-B1539/22-Y-23215	2023年8月22日	所检项目合格。	

688	GX-B1539/22-Y-23216	2023年8月22日	所检项目合格。	
689	GX-B1539/22-Y-23217	2023年8月22日	所检项目合格。	

690	GX-B1539/22-Y-23218	2023年8月22日	所检项目合格。	
691	GX-B1539/22-Y-23219	2023年8月22日	所检项目合格。	

692	GX-B1539/22-Y-23220	2023年8月22日	所检项目合格。	
693	GX-B1539/22-Y-23221	2023年8月22日	所检项目合格。	

694	GX-B1539/22-Y-23222	2023年8月22日	所检项目合格。	 A yellow wheel loader is parked on a dirt surface under a clear blue sky. Two workers wearing high-visibility safety vests and hard hats stand in front of the loader. The loader has a bucket attached to its front. A yellow date stamp '2023/7/21' is visible in the bottom right corner of the photo.
695	GX-B1539/22-Y-23223	2023年8月22日	所检项目合格。	 A yellow wheel loader is parked on a dirt surface under a clear blue sky. Two workers wearing high-visibility safety vests and hard hats stand in front of the loader. The loader has a bucket attached to its front. A yellow date stamp '2023/7/21' is visible in the bottom right corner of the photo.


696	GX-B1539/22-Y-23224	2023年8月22日	所检项目合格。	
697	GX-B1539/22-Y-23225	2023年8月22日	所检项目合格。	

698	GX-B1539/22-Y-23226	2023年8月22日	所检项目合格。	
699	GX-B1539/22-Y-23227	2023年8月22日	所检项目合格。	

700	GX-B1522/20-Y-23126	2023年8月22日	所检项目合格。	
701	GX-B1522/20-Y-23127	2023年8月22日	所检项目合格。	

702	GX-B1522/20-Y-23128	2023年8月22日	所检项目合格。	
703	GX-B1522/20-Y-23129	2023年8月22日	所检项目合格。	

704	GX-B1522/20-Y-23130	2023年8月22日	所检项目合格。	
705	GX-B1515/22-Y-23010	2023年8月22日	所检项目合格。	

706	GX-B1539/22-Y-23228	2023年8月18日	所检项目合格。	
707	GX-B1521/20-Y-23515	2023年8月18日	所检项目合格。	

708	GX-B1521/20-Y-23516	2023年8月18日	所检项目合格。	
709	GX-B1521/20-Y-23517	2023年8月18日	所检项目合格。	

710	GX-B1521/20-Y-23518	2023年8月18日	所检项目合格。	
711	GX-B1521/20-Y-23519	2023年8月18日	所检项目合格。	

712	GX-B1521/20-Y-23520	2023年8月18日	所检项目合格。	
713	GX-B1423/20-Y-234894	2023年8月24日	综合判定：合格	

714	GX-B1521/20-Y-23521	2023年8月24日	所检项目合格。	
715	GX-B1521/20-Y-23522	2023年8月24日	所检项目合格。	

716	GX-B1521/20-Y-23523	2023年8月24日	所检项目合格。	
717	GX-B1521/20-Y-23524	2023年8月24日	所检项目合格。	

718	GX-B1521/20-Y-23525	2023年8月24日	所检项目合格。	
719	GX-B1521/20-Y-23526	2023年8月24日	所检项目合格。	

720	GX-B1521/20-Y-23527	2023年8月24日	所检项目合格。	 A yellow excavator with a blue logo on its arm is positioned on a rocky construction site. A worker in a red hard hat and yellow safety vest stands next to the machine. The date '2023/8/1' is visible in the bottom right corner of the photo.
721	GX-B1521/20-Y-23528	2023年8月24日	所检项目合格。	 A yellow excavator with a blue logo on its arm is positioned on a dirt construction site. A worker in a red hard hat and yellow safety vest stands next to the machine. The date '2023/8/1' is visible in the bottom right corner of the photo.

722	GX-B1521/20-Y-23529	2023年8月24日	所检项目合格。	
723	GX-B1521/20-Y-23530	2023年8月24日	所检项目合格。	

724	GX-B1521/20-Y-23531	2023年8月24日	所检项目合格。	 A photograph showing a worker wearing a red hard hat and a high-visibility green safety vest. The worker is seated and appears to be operating or inspecting a piece of machinery. The background is somewhat blurry, suggesting an industrial or construction setting. A yellow timestamp '2023/8/1' is visible in the bottom right corner of the image.
725	GX-B1521/20-Y-23532	2023年8月24日	所检项目合格。	 A photograph of a yellow excavator at a construction site. The excavator is positioned on a dirt surface, and its bucket is raised. A worker in a high-visibility vest and red helmet stands near the base of the excavator. The background shows a large excavation pit under a clear blue sky. A yellow timestamp '2023/8/1' is visible in the bottom right corner of the image.

726	GX-B1521/20-Y-23533	2023年8月24日	所检项目合格。	 A yellow tracked excavator is shown at a quarry site. The excavator is positioned on a dirt surface, and its arm is extended. A person in a high-visibility vest is standing near the excavator. The background shows a large quarry wall. A yellow timestamp '2023/8/1' is visible in the bottom right corner of the image.
727	GX-B1521/20-Y-23534	2023年8月24日	所检项目合格。	 A yellow tracked excavator is shown at a quarry site. The excavator is positioned on a dirt surface, and its arm is extended. A person in a high-visibility vest is standing near the excavator. The background shows a large quarry wall. A yellow timestamp '2023/8/1' is visible in the bottom right corner of the image.

728	GX-B1521/20-Y-23514	2023年8月24日	所检项目合格。	
729	GX-B1499/21-Y-23107	2023年8月24日	所检项目合格。	

730	GX-B1499/21-Y-23108	2023年8月24日	所检项目合格。	
731	GX-B1499/21-Y-23109	2023年8月24日	所检项目合格。	

732	GX-B1499/21-Y-23110	2023年8月24日	所检项目合格。	
733	GX-B1499/21-Y-23111	2023年8月24日	所检项目合格。	

734	GX-B1499/21-Y-23112	2023年8月24日	所检项目合格。	
735	GX-B1308/21-Y-23017	2023年8月24日	所检项目合格。	

736	GX-B1306/21-Y-23126	2023年8月24日	所检项目合格。	
737	GX-B1310/21-Y-23111	2023年8月24日	符合标准要求。	

738	GX-B1310/21-Y-23133	2023年8月24日	符合标准要求。	
739	GX-B1310/21-Y-23134	2023年8月24日	符合标准要求。	

740	GX-B1428/21-Y-23133	2023年8月24日	无缺陷迹痕显示。	 <p>A worker wearing a white uniform and a red hard hat is inspecting a large, light-colored curved surface, likely a component of a turbine or generator. The worker is positioned on the right side of the frame, looking towards the left. A yellow timestamp '2023/8/2' is visible in the bottom right corner of the image.</p>
741	GX-B1428/21-Y-23134	2023年8月24日	无缺陷迹痕显示。	 <p>A worker wearing a white uniform and a red hard hat is inspecting a large, dark-colored curved surface, likely a component of a turbine or generator. The worker is positioned on the left side of the frame, looking towards the right. A yellow timestamp '2023/8/2' is visible in the bottom right corner of the image.</p>

742	GX-B1428/21-Y-23135	2023年8月24日	无缺陷迹痕显示。	
743	GX-B1428/21-Y-23136	2023年8月24日	无缺陷迹痕显示。	

744	GX-B1310/21-Y-23135	2023年8月24日	符合标准要求。	
745	GX-B1310/21-Y-23136	2023年8月24日	符合标准要求。	

746	GX-B1310/21-Y-23125	2023年8月22日	符合标准要求。	
747	GX-B1427/21-Y-23125	2023年8月22日	符合标准要求。	

748	GX-B1310/21-Y-23126	2023年8月22日	符合标准要求。	 A worker in an orange safety suit and red helmet is working on a large, circular, metallic component. The worker is wearing a headlamp and has a date stamp '2023/7/17' in the bottom right corner of the photo.
749	GX-B1310/21-Y-23127	2023年8月22日	符合标准要求。	 A worker in a grey safety suit and red helmet is working on a large, cylindrical, metallic component. The worker is wearing a headlamp and has a date stamp '2023/7/17' in the bottom right corner of the photo.

750	GX-B1310/21-Y-23128	2023年8月22日	符合标准要求。	 <p>A worker wearing a grey uniform and a red safety helmet is leaning over a large, dark-colored industrial component. The worker is holding a white document and appears to be inspecting or measuring the component. The component is mounted on a green base. A yellow timestamp '2023/7/17' is visible in the bottom right corner of the image.</p>
751	GX-B1310/21-Y-23129	2023年8月22日	符合标准要求。	 <p>A worker wearing a bright orange protective suit and a red safety helmet with a headlamp is working on a large, green industrial component. The worker is using a tool, possibly a flashlight, to inspect the component. The component is mounted on a green base. A yellow timestamp '2023/7/19' is visible in the bottom right corner of the image.</p>

752	GX-B1310/21-Y-23130	2023年8月22日	符合标准要求。	 <p>A worker in an orange safety suit and red helmet is working on a large red mechanical component, possibly a part of a crane or hoist. The worker is wearing a headlamp and is focused on the task. The background shows some papers or notices pinned to a wall. A yellow timestamp '2023/7/19' is visible in the bottom right corner of the photo.</p>
753	GX-B1310/21-Y-23131	2023年8月22日	符合标准要求。	 <p>A worker in an orange safety suit and red helmet is working on a large green mechanical component, possibly a part of a crane or hoist. The worker is wearing a headlamp and is focused on the task. The background shows some papers or notices pinned to a wall. A yellow timestamp '2023/7/19' is visible in the bottom right corner of the photo.</p>

754	GX-B1557/22-Y-23029	2023年8月29日	所检项目合格。	
755	GX-B1556/22-Y-23004	2023年8月28日	所检项目合格。	

756	GX-B1423/20-Y-235154	2023年8月31日	综合判定：合格	 A photograph of a yellow MTB60 truck parked on a paved surface. Two workers wearing red hard hats and high-visibility vests are standing in front of the truck. The date stamp in the bottom right corner of the photo is 2023/7/24.
757	GX-B1423/20-Y-234895	2023年8月31日	综合判定：合格	 A photograph showing a worker wearing a red hard hat and a light-colored uniform sitting in the driver's seat of a vehicle. The worker is looking towards the camera. The date stamp in the bottom right corner of the photo is 2023/8/11.

758	GX-B1423/20-Y-234896	2023年8月31日	综合判定：合格	
759	GX-B1423/20-Y-234897	2023年8月31日	综合判定：合格	

760	GX-B1423/20-Y-234898	2023年8月31日	综合判定：合格	
761	GX-B1423/20-Y-234899	2023年8月31日	综合判定：合格	

762	GX-B1423/20-Y-234900	2023年8月31日	综合判定：合格	 A photograph of a white Weichai truck with a dump body, number 49, parked on a dirt surface. Two workers in safety gear are standing near the front. A yellow timestamp '2023/8/14' is visible in the bottom right corner.
763	GX-B1423/20-Y-234901	2023年8月31日	综合判定：合格	 A photograph of a white Weichai truck with a dump body, number 51, parked on a dirt surface. Two workers in safety gear are standing near the front. A yellow timestamp '2023/8/14' is visible in the bottom right corner.