





序号	报告编号	发布日期	结论	影像资料
542	GX-B1499/21-2-23086	2023. 8. 23	所检项目合格。	
543	GX-B1499/21-2-23087	2023. 8. 23	所检项目合格。	

544	GX-B1499/21-2-23088	2023. 8. 23	所检项目合格。	
545	GX-B1499/21-2-23089	2023. 8. 23	所检项目合格。	

546	GX-B1499/21-2-23090	2023. 8. 23	所检项目合格。			
547	GX-B1499/21-2-23098	2023. 8. 23	所检项目合格。			

548	GX-B1321/20-2-23749~23758	2023/8/30	所检项目合格		
549	GX-B1329/21-2-23167~23172	2023. 8. 29	本次共检氧化锌避雷器 6组，6组所检项目合格 。		

550	GX-B1329/21-2-23173~23176	2023. 8. 29	本次共检氧化锌避雷器 4组，4组所检项目合格 。	
551	GX-B1329/21-2-23177~23178	2023. 8. 29	本次共检氧化锌避雷器 2组，2组所检项目合格 。	

552	GX-B1329/21-2-23179~23180	2023. 8. 29	本次共检氧化锌避雷器 2组，2组所检项目合格 。	
553	GX-B1329/21-2-23181~23182	2023. 8. 29	本次共检氧化锌避雷器 2组，2组所检项目合格 。	

554	GX-B1329/21-2-23183~23186	2023. 8. 29	本次共检氧化锌避雷器 4组，4组所检项目合格 。	
555	GX-B1329/21-2-23187~23192	2023. 8. 29	本次共检氧化锌避雷器 6组，6组所检项目合格 。	

556	GX-B1329/21-2-23193~23198	2023. 8. 29	本次共检氧化锌避雷器 6组，6组所检项目合格 。	 <p>2023/07/22</p>
557	GX-B1329/21-2-23199~23201	2023. 8. 29	本次共检氧化锌避雷器 2组，2组所检项目合格 。	 <p>2023/07/23</p>

558	GX-B1329/21-2-23202~23205	2023. 8. 29	本次共检氧化锌避雷器4组，4组所检项目合格。 。			
559	GX-B1312/20-2-23389~23397	2023. 8. 29	本次共检电力变压器9台，9台所检项目合格。 。			



560	GX-B1312/20-2-23398~23411	2023. 8. 29	本次共检电力变压器14台，14台所检项目合格		 <p>2023/08/07</p>	
561	GX-B1495/20-2-232413~232415	2023. 8. 29	本次共检高压防爆开关3台，3台高压防爆开关所检项目合格。		 <p>2023/08/06</p>	

562	GX-B1350/21-2-23042	2023. 8. 29	本次共检验接地装置32处，32处所检项目合格。 。		 <p>2023/07/28</p>	
563	GX-B1350/21-2-23043	2023. 8. 29	本次共检验接地装置4处，4处所检项目合格。 。		 <p>2023/07/29</p>	

564	GX-B1350/21-2-23044	2023. 8. 29	本次共检验接地装置4处，4处所检项目合格。 。		 <p>2023/07/31</p>	
565	GX-B1350/21-2-23045	2023. 8. 29	本次共检验接地装置2处，2处所检项目合格。 。		 <p>2023/08/01</p>	

566	GX-B1350/21-2-23046	2023. 8. 29	本次共检验接地装置2处，2处所检项目合格。 。		
567	GX-B1350/21-2-23047	2023. 8. 29	本次共检验接地装置2处，2处所检项目合格。 。		

568	GX-B1350/21-2-23048	2023. 8. 29	本次共检验接地装置6处，6处所检项目合格。 。			
569	GX-B1350/21-2-23049	2023. 8. 29	本次共检验接地装置14处，14处所检项目合格。 。			

570	GX-B1321/20-2-23759~23760	2023/8/30	所检项目合格	
571	GX-B1321/20-2-23761~23762	2023/8/30	所检项目合格	

572	GX-B1321/20-2-23765~23770	2023/8/30	所检项目合格		
573	GX-B1321/20-2-23771~23776	2023/8/30	所检项目合格		

574	GX-B1321/20-2-23777~23782	2023/8/30	所检项目合格	
575	GX-B1321/20-2-23783	2023/8/30	所检项目合格	

576	GX-B1321/20-2-23784~23788	2023/8/30	所检项目合格	
577	GX-B1321/20-2-23795~23798	2023/8/30	所检项目合格	

578	GX-B1495/20-2-232409	2023/8/30	所检项目合格	
579	GX-B1495/20-2-232410	2023/8/30	所检项目合格	

580	GX-B1321/20-2-23601~23612	2023/8/30	所检项目合格	
581	GX-B1312/20-2-23301~23306	2023/8/30	所检项目合格	

582	GX-B1523/20-2-23001	2023/8/25	所检项目合格			
583	GX-B1321/20-2-23763~23764	2023/8/30	所检项目合格			

584	GX-B1312/20-2-23376~23382	2023. 8. 28	<p>本次共检电力变压器7台，7台所检项目合格。</p> <p>。</p>		 <p>2023/07/31</p>	
585	GX-B1328/20-2-23117	2023. 8. 30	<p>本次共检绝缘手套25双，25双所检项目合格。</p>		 <p>2023/08/17</p>	

586	GX-B1328/20-2-23118	2023. 8. 30	本次共检绝缘鞋25双， 25双所检项目合格。	
587	GX-B1328/20-2-23119	2023. 8. 30	本次共检绝缘手套 46只，46只所检项目合格。	

588	GX-B1328/20-2-23120	2023. 8. 30	本次共检绝缘鞋46只， 46只所检项目合格。	
589	GX-B1328/20-2-23121	2023. 8. 30	本次共检验电器12支， 12支所检项目合格。	


590	GX-B1328/20-2-23122	2023. 8. 30	本次共检绝缘杆3只，3只所检项目合格。	
591	GX-B1383/21-2-23007	2023. 8. 30	综合判定：合格	

592	GX-B1321/20-2-23701~23709	2023. 8. 31	本次共检验电力电缆9条, 9条所检项目合格。			
593	GX-B1321/20-2-23710~23717	2023. 8. 31	本次共检验电力电缆8条, 8条所检项目合格。			

594	GX-B1321/20-2-23718~23720	2023. 8. 31	本次共检验电力电缆3条, 3条所检项目合格。			
595	GX-B1321/20-2-23721~23727	2023. 8. 31	本次共检验电力电缆7条, 7条所检项目合格。			

596	GX-B1321/20-2-23728~23729	2023. 8. 31	本次共检验电力电缆2条, 2条所检项目合格。			
597	GX-B1321/20-2-23730~23738	2023. 8. 31	本次共检验电力电缆9条, 9条所检项目合格。			

598	GX-B1321/20-2-23739~23741	2023. 8. 31	本次共检验电力电缆3条, 3条所检项目合格。		 <p>2023/08/03</p>	
599	GX-B1321/20-2-23742~23744	2023. 8. 31	本次共检验电力电缆3条, 3条所检项目合格。		 <p>2023/08/04</p>	

600	GX-B1321/20-2-23745~23748	2023. 8. 31	本次共检验电力电缆4条, 4条所检项目合格。			
-----	---------------------------	-------------	------------------------	--	---	--