

序号	报告编号	发布日期	结论	影像资料
178	GX-B1367/22-A-23086	2023/9/13	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
179	GX-B1367/22-A-23087	2023/9/13	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
180	GX-B1367/22-A-23089	2023/9/13	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
181	GX-B1367/22-A-23090	2023/9/13	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
182	GX-B1363/22-A-23367	2023/9/13	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
183	GX-B1363/22-A-23368	2023/9/13	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
184	GX-B1363/22-A-23377	2023/9/13	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
185	GX-B1363/22-A-23378	2023/9/13	所检项目合格。	 A photograph showing two men in light blue work shirts inspecting a large, rusted industrial furnace. The furnace has a tall, white, cylindrical chimney pipe extending upwards. One man is on the left, wearing glasses and gloves, looking into the furnace's opening. The other man is on the right, also looking into the furnace. A green trash bin is visible on the left. A window with a red frame is on the right. A date stamp '2023/09/05' is in the bottom right corner of the photo.

序号	报告编号	发布日期	结论	影像资料
186	GX-B1364/22-A-23832	2023/9/14	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
187	GX-B1364/22-A-23833	2023/9/14	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
188	GX-B1364/22-A-23834	2023/9/14	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
189	GX-B1458/22-A-23005	2023/9/15	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
190	GX-B1363/22-A-23381	2023/9/14	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
191	GX-B1363/22-A-23395	2023/9/14	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
192	GX-B1509/20-A-23011	2023/9/12	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
193	GX-B1509/20-A-23012	2023/9/12	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
194	GX-B1363/22-A-23362	2023/9/18	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
195	GX-B1363/22-A-23363	2023/9/18	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
196	GX-B1363/22-A-23364	2023/9/17	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
197	GX-B1363/22-A-23360	2023/9/17	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
198	GX-B1363/22-A-23355	2023/9/17	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
199	GX-B1364/22-A-23857	2023/9/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
200	GX-B1364/22-A-23861	2023/9/19	所检项目合格。	 <p>The photograph shows two men in grey work uniforms operating a large, dark-colored industrial machine. The man on the left is looking into the machine's opening, while the man on the right is adjusting a control panel on the right side of the machine. The control panel features a digital display and several analog gauges. A date stamp '2023/09/10' is visible in the bottom right corner of the image. The background shows a typical industrial setting with pipes and a window.</p>

序号	报告编号	发布日期	结论	影像资料
201	GX-B1364/22-A-23862	2023/9/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
202	GX-B1364/22-A-23863	2023/9/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
203	GX-B1364/22-A-23864	2023/9/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
204	GX-B1364/22-A-23865	2023/9/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
205	GX-B1364/22-A-23866	2023/9/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
206	GX-B1364/22-A-23835	2023/9/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
207	GX-B1364/22-A-23856	2023/9/19	成束电线电缆燃烧试验不合格；其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
208	GX-B1364/22-A-23855	2023/9/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
209	GX-B1364/22-A-23838	2023/9/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
210	GX-B1364/22-A-23815	2023/9/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
211	GX-B1364/22-A-23814	2023/9/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
212	GX-B1364/22-A-23851	2023/9/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
213	GX-B1364/22-A-23847	2023/9/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
214	GX-B1364/22-A-23843	2023/9/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
215	GX-B1364/22-A-23844	2023/9/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
216	GX-B1364/22-A-23846	2023/9/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
217	GX-B1364/22-A-23845	2023/9/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
218	GX-B1509/20-A-23013	2023/9/19	所检项目合格。	 <p>The photograph shows two individuals in light-colored uniforms working at a table. One person is writing on a document, while the other is using a handheld electronic device. On the table, there is a small circular object with wires connected to it. A date stamp '2023/09/05' is visible in the bottom right corner of the image.</p>

序号	报告编号	发布日期	结论	影像资料
219	GX-B1364/22-A-23852	2023/9/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
220	GX-B1364/22-A-23853	2023/9/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
221	GX-B1364/22-A-23850	2023/9/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
222	GX-B1364/22-A-23849	2023/9/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
223	GX-B1364/22-A-23848	2023/9/19	成束电线电缆燃烧试验不合格；其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
224	GX-B1364/22-A-23842	2023/9/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
225	GX-B1364/22-A-23841	2023/9/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
226	GX-B1364/22-A-23840	2023/9/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
227	GX-B1364/22-A-23839	2023/9/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
228	GX-B1364/22-A-23837	2023/9/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
229	GX-B1364/22-A-23836	2023/9/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
230	GX-B1366/20-A-23098	2023/9/19	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
231	GX-B1365/20-A-23058	2023/9/19	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
232	GX-B1365/20-A-23064	2023/9/19	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
233	GX-B1364/22-A-23858	2023/9/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
234	GX-B1364/22-A-23859	2023/9/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
235	GX-B1364/22-A-23860	2023/9/19	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
236	GX-B1364/22-A-23884	2023/9/22	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
237	GX-B1364/22-A-23874	2023/9/22	所检项目合格。	