

序号	报告编号	发布日期	结论	影像资料
476	GX-B1557/22-Y-23034	2023年9月25日	所检项目合格。	
477	GX-B1557/22-Y-23035	2023年9月25日	所检项目合格。	

478	GX-B1557/22-Y-23033	2023年9月25日	所检项目合格。	
479	GX-B1556/22-Y-23006	2023年9月25日	所检项目合格。	

480	GX-B1556/22-Y-23007	2023年9月25日	所检项目合格。	
481	GX-B1557/22-Y-23031	2023年9月25日	所检项目合格。	

482	GX-B1557/22-Y-23032	2023年9月25日	所检项目合格。	
483	GX-B1428/21-Y-23144	2023年9月25日	无缺陷痕迹显示。	

484	GX-B1310/21-Y-23144	2023年9月25日	符合标准要求。	
485	GX-B1310/21-Y-23113	2023年9月25日	符合标准要求。	

486	GX-B1310/21-Y-23142	2023年9月25日	符合标准要求。	
487	GX-B1310/21-Y-23143	2023年9月25日	符合标准要求。	
488	GX-B1417/22-Y-23094	2023年9月26日	综合判定：合格。	

489	GX-B1417/22-Y-23095	2023年9月26日	综合判定：合格。	
490	GX-B1423/20-Y-234902	2023年9月26日	综合判定：合格	
491	GX-B1423/20-Y-234903	2023年9月26日	综合判定：合格	

492	GX-B1423/20-Y-234904	2023年9月26日	综合判定：合格	
493	GX-B1423/20-Y-234905	2023年9月26日	综合判定：合格	
494	GX-B1423/20-Y-234906	2023年9月26日	综合判定：合格	

495	GX-B1423/20-Y-234907	2023年9月26日	综合判定：合格	
496	GX-B1423/20-Y-234908	2023年9月26日	综合判定：合格	
497	GX-B1423/20-Y-234909	2023年9月26日	综合判定：合格	

498	GX-B1423/20-Y-234910	2023年9月26日	综合判定：合格	
499	GX-B1423/20-Y-234911	2023年9月26日	综合判定：合格	
500	GX-B1423/20-Y-234912	2023年9月26日	综合判定：合格	

501	GX-B1423/20-Y-234913	2023年9月26日	综合判定：合格	
502	GX-B1423/20-Y-234914	2023年9月26日	综合判定：合格	
503	GX-B1423/20-Y-234915	2023年9月26日	综合判定：合格	

504	GX-B1423/20-Y-234916	2023年9月26日	综合判定：合格	
505	GX-B1423/20-Y-234917	2023年9月26日	综合判定：合格	
506	GX-B1423/20-Y-234918	2023年9月26日	综合判定：合格	


507	GX-B1423/20-Y-234919	2023年9月26日	综合判定：合格	
508	GX-B1423/20-Y-234920	2023年9月26日	综合判定：合格	
509	GX-B1423/20-Y-234921	2023年9月26日	综合判定：合格	

510	GX-B1423/20-Y-234922	2023年9月26日	综合判定：合格	
511	GX-B1423/20-Y-234923	2023年9月26日	综合判定：合格	
512	GX-B1423/20-Y-234924	2023年9月26日	综合判定：合格	

513	GX-B1423/20-Y-234925	2023年9月26日	综合判定：合格	
514	GX-B1423/20-Y-234926	2023年9月26日	综合判定：合格	
515	GX-B1423/20-Y-234927	2023年9月26日	综合判定：合格	

516	GX-B1423/20-Y-235112	2023年9月26日	综合判定：合格	
517	GX-B1423/20-Y-235422	2023年9月26日	综合判定：合格	
518	GX-B1423/20-Y-235423	2023年9月26日	综合判定：合格	

519	GX-B1423/20-Y-235424	2023年9月26日	综合判定：合格	
520	GX-B1423/20-Y-235425	2023年9月26日	综合判定：合格	
521	GX-B1423/20-Y-235426	2023年9月26日	综合判定：合格	

522	GX-B1423/20-Y-235427	2023年9月26日	综合判定：合格	
523	GX-B1423/20-Y-235147	2023年9月26日	综合判定：合格	
524	GX-B1423/20-Y-235148	2023年9月26日	综合判定：合格	

525	GX-B1423/20-Y-235149	2023年9月26日	综合判定：合格	
526	GX-B1423/20-Y-235150	2023年9月26日	综合判定：合格	
527	GX-B1423/20-Y-235151	2023年9月26日	综合判定：合格	

528	GX-B1423/20-Y-235241	2023年9月26日	综合判定：合格	 A yellow dump truck with its lid raised, parked on a dirt surface. Two people are standing near the front of the truck. The truck has the number '11-11' on its side. A small yellow date stamp '2023/9/3' is visible in the bottom right corner of the image.
529	GX-B1423/20-Y-235242	2023年9月26日	综合判定：合格	 A yellow dump truck with its lid closed, parked on a dirt surface. A person is standing near the front of the truck. The truck has the number '12-11' on its side. A small yellow date stamp '2023/9/3' is visible in the bottom right corner of the image.
530	GX-B1423/20-Y-235303	2023年9月26日	综合判定：合格	 A yellow dump truck with its lid closed, parked on a dirt surface. Two people are standing near the front of the truck. The truck has the number '15-11' on its side. A small yellow date stamp '2023/9/9' is visible in the bottom right corner of the image.

531	GX-B1423/20-Y-235304	2023年9月26日	综合判定：合格	
532	GX-B1423/20-Y-235305	2023年9月26日	综合判定：合格	
533	GX-B1423/20-Y-235306	2023年9月26日	综合判定：合格	

534	GX-B1423/20-Y-235307	2023年9月26日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers in high-visibility vests and hard hats are standing in front of the truck. The truck has the number '15-182' on its side. A small yellow timestamp '2023/9/26' is visible in the bottom right corner of the photo.
535	GX-B1423/20-Y-235308	2023年9月26日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. One worker in a high-visibility vest and hard hat is standing in front of the truck. The truck has the number '15-182' on its side. A small yellow timestamp '2023/9/26' is visible in the bottom right corner of the photo.
536	GX-B1423/20-Y-235309	2023年9月26日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers in high-visibility vests and hard hats are standing in front of the truck. The truck has the number '15-182' on its side. A small yellow timestamp '2023/9/26' is visible in the bottom right corner of the photo.

537	GX-B1423/20-Y-235310	2023年9月26日	综合判定：合格	
538	GX-B1423/20-Y-235311	2023年9月26日	综合判定：合格	
539	GX-B1423/20-Y-235312	2023年9月26日	综合判定：合格	

540	GX-B1423/20-Y-235313	2023年9月26日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers in safety gear are standing near the front of the truck. The truck has "235313" written on its side. A small yellow timestamp "2023年9月" is visible in the bottom right corner of the image.
541	GX-B1423/20-Y-235314	2023年9月26日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers in safety gear are standing near the front of the truck. The truck has "235314" written on its side. A small yellow timestamp "2023年9月" is visible in the bottom right corner of the image.
542	GX-B1423/20-Y-235315	2023年9月26日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers in safety gear are standing near the front of the truck. The truck has "235315" written on its side. A small yellow timestamp "2023年9月" is visible in the bottom right corner of the image.

543	GX-B1423/20-Y-235316	2023年9月26日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers in safety gear are standing next to it. A yellow timestamp '2023-9-9' is visible in the bottom right corner of the image.
544	GX-B1423/20-Y-235317	2023年9月26日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers in safety gear are standing next to it. A yellow timestamp '2023-9-9' is visible in the bottom right corner of the image.
545	GX-B1423/20-Y-235318	2023年9月26日	综合判定：合格	 A yellow dump truck is parked on a dirt surface. Two workers in safety gear are standing next to it. A yellow timestamp '2023-9-9' is visible in the bottom right corner of the image.

546	GX-B1423/20-Y-235319	2023年9月26日	综合判定：合格	
547	GX-B1339/21-Y-23015	2023年9月27日	所检项目合格	
548	GX-B1339/21-Y-23016	2023年9月27日	所检项目合格	