







序号	报告编号	发布日期	结论	影像资料
14	GX-B1362/20-A-23331	2023/10/4	安全系数结果10.49, 其余所检项目合格	
15	GX-B1362/20-A-23332	2023/10/4	安全系数结果10.38, 其余所检项目合格	


序号	报告编号	发布日期	结论	影像资料
16	GX-B1362/20-A-23333	2023/10/4	安全系数结果9.81，其余所检项目合格	
17	GX-B1362/20-A-23334	2023/10/4	安全系数结果9.78，其余所检项目合格	

序号	报告编号	发布日期	结论	影像资料
18	GX-B1362/20-A-23335	2023/10/4	安全系数结果10.55, 其余所检项目合格	
19	GX-B1362/20-A-23338	2023/10/4	安全系数结果10.57, 其余所检项目合格	

序号	报告编号	发布日期	结论	影像资料
20	GX-B1362/20-A-23339	2023/10/4	安全系数结果11.25, 其余所检项目合格	
21	GX-B1362/20-A-23340	2023/10/4	安全系数结果11.19, 其余所检项目合格	



序号	报告编号	发布日期	结论	影像资料
22	GX-B1362/20-A-23341	2023/10/4	安全系数结果11.19, 其余所检项目合格	
23	GX-B1362/20-A-23342	2023/10/4	安全系数结果10.36, 其余所检项目合格	

序号	报告编号	发布日期	结论	影像资料
24	GX-B1362/20-A-23363	2023/10/4	合格	
25	GX-B1362/20-A-23364	2023/10/4	合格	

序号	报告编号	发布日期	结论	影像资料
26	GX-B1361/22-A-23935	2023/10/4	不合格	
27	GX-B1361/22-A-23936	2023/10/4	不合格	

序号	报告编号	发布日期	结论	影像资料
28	GX-B1361/22-A-23937	2023/10/4	不合格	 A photograph showing a male worker in a light-colored short-sleeved shirt operating a lathe machine in a workshop. The machine is a large, dark-colored industrial tool. The worker is focused on his task. In the background, another person is partially visible working at a different station. A yellow timestamp '2023/9/12' is visible in the bottom right corner of the image.
29	GX-B1361/22-A-23984	2023/10/4	所检项目合格	 A photograph showing two male workers in light-colored short-sleeved shirts operating industrial machinery in a workshop. One worker is in the foreground, looking at a piece of equipment, while the other is in the background, also working. The machinery includes a large circular dial or gauge. A yellow timestamp '2023/9/22' is visible in the bottom right corner of the image.

序号	报告编号	发布日期	结论	影像资料
30	GX-B1361/22-A-23985	2023/10/4	所检项目合格	
31	GX-B1361/22-A-23987	2023/10/4	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
32	GX-B1361/22-A-23988	2023/10/4	所检项目合格	
33	GX-B1361/22-A-23989	2023/10/4	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
34	GX-B1361/22-A-23990	2023/10/4	所检项目合格	
35	GX-B1361/22-A-23991	2023/10/4	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
36	GX-B1361/22-A-23992	2023/10/4	所检项目合格	
37	GX-B1361/22-A-23993	2023/10/4	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
38	GX-B1361/22-A-23994	2023/10/4	所检项目合格	
39	GX-B1361/22-A-23995	2023/10/4	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
40	GX-B1361/22-A-23996	2023/10/4	所检项目合格	
41	GX-B1361/22-A-23997	2023/10/4	所检项目合格	



序号	报告编号	发布日期	结论	影像资料
42	GX-B1361/22-A-231012	2023/10/4	所检项目合格	
43	GX-B1361/22-A-231013	2023/10/4	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
44	GX-B1361/22-A-231018	2023/10/9	合格	
45	GX-B1361/22-A-231019	2023/10/9	合格	


序号	报告编号	发布日期	结论	影像资料
46	GX-B1361/22-A-231020	2023/10/9	合格	
47	GX-B1361/22-A-231021	2023/10/9	合格	

序号	报告编号	发布日期	结论	影像资料
48	GX-B1361/22-A-231022	2023/10/9	合格	
49	GX-B1361/22-A-231023	2023/10/9	合格	

序号	报告编号	发布日期	结论	影像资料
50	GX-B1361/22-A-231024	2023/10/9	合格	
51	GX-B1361/22-A-231025	2023/10/9	合格	

序号	报告编号	发布日期	结论	影像资料
52	GX-B1361/22-A-231031	2023/10/9	所检项目合格	
53	GX-B1361/22-A-231032	2023/10/9	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
54	GX-B1361/22-A-231033	2023/10/9	所检项目合格	
55	GX-B1361/22-A-231034	2023/10/9	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
56	GX-B1361/22-A-231035	2023/10/9	所检项目合格	
57	GX-B1361/22-A-231036	2023/10/9	所检项目合格	