

序号	报告编号	发布日期	结论	影像资料
334	GX-B1416/22-Y-23084	2023年10月13日	综合判定：合格。	 A photograph showing a worker in a red uniform and helmet inspecting a metal structure in a dark environment. The worker is holding a flashlight. The date '2023/9/20' is visible in the bottom right corner of the image.
335	GX-B1385/21-Y-23085	2023年10月13日	所检项目合格。	 A photograph showing a worker in a red uniform and helmet inspecting a metal structure in a dark environment. The worker is holding a flashlight. The date '2023/9/20' is visible in the bottom right corner of the image.

336	GX-B1415/22-Y-23017	2023年10月16日	综合判定：合格。	
337	GX-B1385/21-Y-23084	2023年10月17日	所检项目合格。	

338	GX-B1385/21-Y-23085	2023年10月17日	所检项目合格。	 A photograph of a worker in a red uniform and red helmet, holding a handheld device and looking at it. The worker is standing in a dark, industrial environment. A yellow timestamp "2023/9/20" is visible in the bottom right corner of the image.
339	GX-B1539/22-Y-23240	2023年10月18日	所检项目合格。	 A photograph of a worker in a grey uniform and yellow safety vest, wearing a red helmet, operating a vehicle. The worker is sitting in the driver's seat, looking at a handheld device. The background shows a view through the vehicle's window. A yellow timestamp "2023/9/30" is visible in the bottom right corner of the image.

340	GX-B1539/22-Y-23241	2023年10月18日	所检项目合格。	 A photograph showing a person wearing a grey uniform, a yellow safety vest, and a red hard hat. The person is sitting in the driver's seat of a vehicle, holding a handheld device. The background shows a cloudy sky and the interior of the vehicle. A yellow timestamp '2023/9/30' is visible in the bottom right corner.
341	GX-B1539/22-Y-23242	2023年10月18日	所检项目合格。	 A photograph of a yellow wheel loader parked on a gravel surface. Two people in yellow safety vests and hard hats are standing next to the loader. The background shows a hilly landscape under a blue sky with white clouds. A yellow timestamp '2023/9/30' is visible in the bottom right corner.

342	GX-B1539/22-Y-23243	2023年10月18日	所检项目合格。	
343	GX-B1539/22-Y-23244	2023年10月18日	所检项目合格。	

344	GX-B1539/22-Y-23245	2023年10月18日	所检项目合格。	 <p>A photograph showing a worker wearing a red hard hat and a high-visibility yellow safety vest operating a piece of heavy machinery, likely a loader or excavator, in an outdoor setting. The date stamp '2023/10/1' is visible in the bottom right corner of the image.</p>
345	GX-B1539/22-Y-23246	2023年10月18日	所检项目合格。	 <p>A photograph showing a worker in a yellow safety vest standing next to a yellow wheel loader (numbered 958) in an outdoor setting. The date stamp '2023/10/2' is visible in the bottom right corner of the image.</p>

346	GX-B1539/22-Y-23247	2023年10月18日	所检项目合格。	
347	GX-B1539/22-Y-23248	2023年10月18日	所检项目合格。	

348	GX-B1539/22-Y-23249	2023年10月18日	所检项目合格。	
349	GX-B1423/20-Y-235641	2023年10月18日	综合判定：合格	

350	GX-B1423/20-Y-235642	2023年10月18日	综合判定：合格	
351	GX-B1423/20-Y-235643	2023年10月18日	综合判定：合格	

352	GX-B1423/20-Y-235644	2023年10月18日	综合判定：合格	 A yellow SANY SKT1055 truck is parked on a dirt lot. Two workers in high-visibility vests are standing in front of the truck. The date stamp '2023/10/6' is visible in the bottom right corner of the photo.	
353	GX-B1423/20-Y-235645	2023年10月18日	综合判定：合格	 A yellow SANY SKT1055 truck is parked on a dirt lot. Two workers in high-visibility vests are standing in front of the truck. The date stamp '2023/10/6' is visible in the bottom right corner of the photo.	

354	GX-B1423/20-Y-235646	2023年10月18日	综合判定：合格	
355	GX-B1423/20-Y-235647	2023年10月18日	综合判定：合格	

356	GX-B1423/20-Y-235648	2023年10月18日	综合判定：合格	 <p>A photograph of a yellow SANY SKT1055 truck with the number 32 on its side. Two workers in safety gear are standing in front of the truck. The date 2023/10/6 is visible in the bottom right corner of the photo.</p>
357	GX-B1423/20-Y-235649	2023年10月18日	综合判定：合格	 <p>A photograph of a yellow SANY SKT1055 truck with the number 36 on its side. Two workers in safety gear are standing in front of the truck. The date 2023/10/6 is visible in the bottom right corner of the photo.</p>

358	GX-B1423/20-Y-235650	2023年10月18日	综合判定：合格	 A photograph of a yellow SANY SKT1058 truck at a construction site. Two workers in safety gear are standing next to the truck. The license plate is FF-2027. A date stamp '2023/10/6' is visible in the bottom right corner of the photo.	
359	GX-B1423/20-Y-235651	2023年10月18日	综合判定：合格	 A photograph of a yellow SANY SKT1058 truck at a construction site. Two workers in safety gear are standing next to the truck. The license plate is FF-2028. Various pieces of equipment are on the ground in front of the truck. A date stamp '2023/10/6' is visible in the bottom right corner of the photo.	

360	GX-B1423/20-Y-235652	2023年10月18日	综合判定：合格		
361	GX-B1423/20-Y-235653	2023年10月18日	综合判定：合格		

362	GX-B1423/20-Y-235654	2023年10月18日	综合判定：合格		
363	GX-B1423/20-Y-235655	2023年10月18日	综合判定：合格		

364	GX-B1423/20-Y-235656	2023年10月18日	综合判定：合格	
365	GX-B1423/20-Y-235657	2023年10月18日	综合判定：合格	

366	GX-B1423/20-Y-235658	2023年10月18日	综合判定：合格	
367	GX-B1423/20-Y-235659	2023年10月18日	综合判定：合格	

368	GX-B1423/20-Y-235660	2023年10月18日	综合判定：合格	
369	GX-B1423/20-Y-235661	2023年10月18日	综合判定：合格	

370	GX-B1423/20-Y-235662	2023年10月18日	综合判定：合格	
371	GX-B1423/20-Y-235663	2023年10月18日	综合判定：合格	

372	GX-B1423/20-Y-235664	2023年10月18日	综合判定：合格	
373	GX-B1423/20-Y-235665	2023年10月18日	综合判定：合格	

374	GX-B1423/20-Y-235666	2023年10月18日	综合判定：合格	
375	GX-B1423/20-Y-235621	2023年10月17日	综合判定：合格	

376	GX-B1423/20-Y-235622	2023年10月17日	综合判定：合格	
377	GX-B1423/20-Y-235623	2023年10月17日	综合判定：合格	

378	GX-B1423/20-Y-235624	2023年10月17日	综合判定：合格	
379	GX-B1423/20-Y-235625	2023年10月17日	综合判定：合格	

380	GX-B1423/20-Y-235626	2023年10月17日	综合判定：合格	
381	GX-B1423/20-Y-235627	2023年10月17日	综合判定：合格	

382	GX-B1423/20-Y-235628	2023年10月17日	综合判定：合格	
383	GX-B1423/20-Y-235629	2023年10月17日	综合判定：合格	

384	GX-B1423/20-Y-235630	2023年10月17日	综合判定：合格	
385	GX-B1423/20-Y-235631	2023年10月17日	综合判定：合格	

386	GX-B1423/20-Y-235632	2023年10月17日	综合判定：合格	
387	GX-B1423/20-Y-235633	2023年10月17日	综合判定：合格	

388	GX-B1423/20-Y-235634	2023年10月17日	综合判定：合格	
389	GX-B1423/20-Y-235635	2023年10月17日	综合判定：合格	

390	GX-B1423/20-Y-235636	2023年10月17日	综合判定：合格	
391	GX-B1423/20-Y-235637	2023年10月17日	综合判定：合格	

392	GX-B1423/20-Y-235638	2023年10月17日	综合判定：合格	
393	GX-B1423/20-Y-235639	2023年10月17日	综合判定：合格	

394	GX-B1423/20-Y-235640	2023年10月17日	综合判定：合格	
395	GX-B1423/20-Y-235597	2023年10月17日	综合判定：合格	

396	GX-B1423/20-Y-235598	2023年10月17日	综合判定：合格	
397	GX-B1423/20-Y-235599	2023年10月17日	综合判定：合格	

398	GX-B1423/20-Y-235600	2023年10月17日	综合判定：合格	 A yellow Weichai dump truck is parked on a dirt surface under a clear blue sky. Two workers wearing high-visibility vests and hard hats stand in front of the truck. The truck has 'WEICHAI' and the number '180' visible on its side. A yellow timestamp '2023/9/30' is in the bottom right corner.
399	GX-B1423/20-Y-235601	2023年10月17日	综合判定：合格	 A yellow Weichai dump truck is parked on a dirt surface under a clear blue sky. Two workers wearing high-visibility vests and hard hats stand in front of the truck. The truck has 'WEICHAI' and the number '180' visible on its side. A yellow timestamp '2023/9/30' is in the bottom right corner.

400	GX-B1423/20-Y-235602	2023年10月17日	综合判定：合格	
401	GX-B1423/20-Y-235603	2023年10月17日	综合判定：合格	

402	GX-B1423/20-Y-235604	2023年10月17日	综合判定：合格	 A yellow Weichai dump truck with license plate K-208 is parked on a dirt surface. Two workers in high-visibility vests are standing in front of the truck. The date 2023/9/30 is visible in the bottom right corner of the photo.
403	GX-B1423/20-Y-235605	2023年10月17日	综合判定：合格	 A yellow Weichai dump truck with license plate K-199 is parked on a dirt surface. Two workers in high-visibility vests are standing in front of the truck. The date 2023/9/30 is visible in the bottom right corner of the photo.

404	GX-B1423/20-Y-235606	2023年10月17日	综合判定：合格	 A yellow Weichai dump truck is parked on a dirt surface under a clear blue sky. Two workers wearing high-visibility vests and hard hats stand in front of the truck. The truck has 'WEICHAI' and 'K-195' visible on its side. A yellow timestamp '2023/9/30' is in the bottom right corner of the photo.
405	GX-B1423/20-Y-235607	2023年10月17日	综合判定：合格	 A yellow Weichai dump truck is parked on a dirt surface under a clear blue sky. Two workers wearing high-visibility vests and hard hats stand in front of the truck. The truck has 'WEICHAI' and 'K-195' visible on its side. A yellow timestamp '2023/9/30' is in the bottom right corner of the photo.

406	GX-B1423/20-Y-235608	2023年10月17日	综合判定：合格	 A yellow dump truck is parked on a dirt surface under a clear blue sky. Two workers in high-visibility vests and hard hats are standing next to the truck. A date stamp '2023/9/30' is visible in the bottom right corner of the photo.
407	GX-B1423/20-Y-235609	2023年10月17日	综合判定：合格	 A yellow dump truck is parked on a dirt surface under a clear blue sky. Two workers in high-visibility vests and hard hats are standing next to the truck. Some equipment is on the ground in front of them. A date stamp '2023/9/30' is visible in the bottom right corner of the photo.

408	GX-B1423/20-Y-235610	2023年10月17日	综合判定：合格	
409	GX-B1423/20-Y-235611	2023年10月17日	综合判定：合格	



410	GX-B1423/20-Y-235612	2023年10月17日	综合判定：合格	 A yellow Weichai dump truck is parked on a dirt surface under a clear blue sky. Two workers in high-visibility vests are standing near the front of the truck. A date stamp '2023/10/17' is visible in the bottom right corner of the photo.
411	GX-B1423/20-Y-235613	2023年10月17日	综合判定：合格	 A yellow Weichai dump truck is parked on a dirt surface under a clear blue sky. Two workers in high-visibility vests are standing near the front of the truck. A date stamp '2023/10/17' is visible in the bottom right corner of the photo.

412	GX-B1423/20-Y-235614	2023年10月17日	综合判定：合格	
413	GX-B1423/20-Y-235615	2023年10月17日	综合判定：合格	

414	GX-B1423/20-Y-235616	2023年10月17日	综合判定：合格	 A yellow dump truck is parked on a dirt surface under a clear blue sky. Two workers in high-visibility vests and hard hats stand in front of the truck. A yellow timestamp '2023/10/17' is visible in the bottom right corner of the photo.
415	GX-B1423/20-Y-235617	2023年10月17日	综合判定：合格	 A yellow dump truck is parked on a dirt surface under a clear blue sky. Two workers in high-visibility vests and hard hats stand in front of the truck. A yellow timestamp '2023/10/17' is visible in the bottom right corner of the photo.

416	GX-B1423/20-Y-235618	2023年10月17日	综合判定：合格	
417	GX-B1423/20-Y-235619	2023年10月17日	综合判定：合格	

418	GX-B1423/20-Y-235620	2023年10月17日	综合判定：合格	
-----	----------------------	-------------	---------	---