

序号	报告编号	发布日期	结论	影像资料
220	GX-B1415/22-2-23021	2023/10/19	综合判定：合格。	
221	GX-B1415/22-2-23022	2023/10/19	综合判定：合格。	




222	GX-B1415/22-2-23023	2023/10/19	综合判定：合格。		
223	GX-B1310/21-2-23338	2023/10/25	符合标准要求。		
224	GX-B1310/21-2-23339	2023/10/25	符合标准要求。		

225	GX-B1310/21-2-23340	2023/10/25	符合标准要求。	
226	GX-B1310/21-2-23341	2023/10/25	符合标准要求。	
227	GX-B1310/21-2-23355	2023/10/25	未发现超过 $\Phi 2\text{mm}$ 当量直径的缺陷。	

228	GX-B1428/21-2-23355	2023/10/25	无缺陷迹痕显示。	
229	GX-B1310/21-2-23356	2023. 10. 25	符合标准要求。	
230	GX-B1427/21-2-23356	2023. 10. 25	符合标准要求。	

231	GX-B1500/21-2-23119	2023. 10. 25	综合判定：合格。	 <p>2023/09/23</p>
232	GX-B1500/21-2-23120	2023. 10. 25	综合判定：合格。	 <p>2023/09/23</p>
233	GX-B1500/21-2-23121	2023. 10. 25	综合判定：合格。	 <p>2023/09/23</p>

234	GX-B1308/21-2-23012	2023. 10. 25	所检项目合格。	
235	GX-B1499/21-2-23099	2023. 10. 25	所检项目合格。	
236	GX-B1499/21-2-23100	2023. 10. 25	所检项目合格。	

237	GX-B1307/20-2-23075	2023. 10. 24	综合判定：合格	
238	GX-B1307/20-2-23076	2023. 10. 24	综合判定：合格	
239	GX-B1307/20-2-23077	2023. 10. 24	综合判定：合格	

240	GX-B1312/20-2300054	2023. 10. 23	所检项目合格		
241	GX-B1312/20-2300055	2023. 10. 23	所检项目合格		
242	GX-B1312/20-2300056	2023. 10. 23	所检项目合格		



243	GX-B1300/20-2-23012	2023/10/27	综合判定：合格。		
244	GX-B1300/20-2-23013	2023/10/27	综合判定：合格。		
245	GX-B1415/22-2-23025	2023/10/27	综合判定：合格。		

246	GX-B1521/20-2-23022	2023/10/27	所检项目合格。	 A photograph showing the cab of a red tracked excavator. A worker wearing a yellow hard hat and a light-colored jacket is visible inside the cab. The excavator is positioned on a dirt surface. A date stamp '2023/09/22' is visible in the bottom right corner of the image.	
247	GX-B1521/20-2-23023	2023/10/27	所检项目合格。	 A photograph of a worker in a light blue jacket and yellow hard hat standing next to a yellow tracked excavator. The excavator is parked on a dirt surface. A date stamp '2023/09/22' is visible in the bottom right corner of the image.	
248	GX-B1521/20-2-23024	2023/10/27	所检项目合格。	 A photograph of a worker in a light blue jacket and yellow hard hat standing next to a yellow tracked excavator. The excavator is parked on a dirt surface. A date stamp '2023/09/22' is visible in the bottom right corner of the image.	

249	GX-B1521/20-2-23025	2023/10/27	所检项目合格。	 A photograph showing a person wearing a face mask and a light-colored shirt operating a yellow CAT tracked loader. The person is seated in the driver's seat, looking towards the front of the machine. The loader is positioned on a wooden pallet. The background shows a large, curved structure, possibly a tunnel or a large storage container. A timestamp "2023/09/22" is visible in the bottom right corner of the image.	
250	GX-B1521/20-2-23026	2023/10/27	所检项目合格。	 A photograph of a yellow CAT tracked loader. The loader is positioned on a wooden pallet. A person is visible in the driver's seat, looking towards the front of the machine. The background shows a large, curved structure, possibly a tunnel or a large storage container. A timestamp "2023/09/22" is visible in the bottom right corner of the image.	
251	GX-B1521/20-2-23027	2023/10/27	所检项目合格。	 A photograph showing a person wearing a face mask and a light-colored shirt operating a yellow CAT tracked loader. The person is seated in the driver's seat, looking towards the front of the machine. The loader is positioned on a wooden pallet. The background shows a large, curved structure, possibly a tunnel or a large storage container. A timestamp "2023/09/22" is visible in the bottom right corner of the image.	

252	GX-B1416/22-2-23059	2023/10/27	综合判定：合格。	
253	GX-B1416/22-2-23060	2023/10/27	综合判定：合格。	
254	GX-B1424/20-2-23025	2023/10/27	据NB/T 10176-2019单轨吊车 综合判定不合格。	

255	GX-B1539/22-2-23017	2023. 10. 30	所检项目合格。	
256	GX-B1539/22-2-23018	2023. 10. 30	所检项目合格。	
257	GX-B1539/22-2-23019	2023. 10. 30	所检项目合格。	

258	GX-B1539/22-2-23020	2023. 10. 30	所检项目合格。	
259	GX-B1539/22-2-23021	2023. 10. 30	所检项目合格。	
260	GX-B1539/22-2-23022	2023. 10. 30	所检项目合格。	



261	GX-B1521/20-2-23028	2023. 10. 30	所检项目合格。		
262	GX-B1521/20-2-23029	2023. 10. 30	所检项目合格。		
263	GX-B1521/20-2-23030	2023. 10. 30	所检项目合格。		

264	GX-B1521/20-2-23031	2023. 10. 30	所检项目合格。	
265	GX-B1521/20-2-23032	2023. 10. 30	所检项目合格。	
266	GX-B1521/20-2-23033	2023. 10. 30	所检项目合格。	



267	GX-B1521/20-2-23034	2023. 10. 30	所检项目合格。	 A photograph showing a yellow excavator with a worker in a red hard hat and white shirt operating the machine. The excavator's arm is visible on the left. A date stamp '2023/09/16' is at the bottom right.
268	GX-B1521/20-2-23035	2023. 10. 30	所检项目合格。	 A photograph of a yellow excavator with a worker in the cab. The excavator's arm is on the left. A license plate '4000-525' is visible on the front. A date stamp '2023/09/16' is at the bottom right.
269	GX-B1521/20-2-23036	2023. 10. 30	所检项目合格。	 A photograph showing a worker in a red hard hat and white shirt sitting in the cab of a yellow excavator. The worker is looking down at something in their hands. A date stamp '2023/09/16' is at the bottom right.

270	GX-B1522/20-2-23010	2023. 10. 30	所检项目合格。	
271	GX-B1522/20-2-23011	2023. 10. 30	所检项目合格。	
272	GX-B1522/20-2-23012	2023. 10. 30	所检项目合格。	

273	GX-B1522/20-2-23013	2023. 10. 30	所检项目合格。	
274	GX-B1522/20-2-23014	2023. 10. 30	所检项目合格。	
275	GX-B1522/20-2-23015	2023. 10. 30	所检项目合格。	

276	GX-B1321/20-2-23831~23834	2023. 10. 30	本次共检验电力电缆4条，4条所检项目合格。	
277	GX-B1495/20-2-232472~232481	2023. 10. 30	本次共检高压开关柜10台，10台所检项目合格。	
278	GX-B1310/21-2-23349	2023. 10. 30	符合标准要求。	

279	GX-B1310/21-2-23350	2023. 10. 30	符合标准要求。	
280	GX-B1427/21-2-23349	2023. 10. 30	符合标准要求。	
281	GX-B1427/21-2-23350	2023. 10. 30	符合标准要求。	

282	GX-B1548/20-2-23122	2023. 10. 30	所检项目合格。	
283	GX-B1424/20-2-23029	2023. 10. 31	T 10176-2019单轨吊车综合判定	
284	GX-B1310/21-2-23333	2023. 10. 31	符合标准要求。	

285	GX-B1310/21-2-23346	2023. 10. 31	发现超过 $\Phi 2\text{mm}$ 当量直径的缺陷	 <p>2023/10/10</p>
286	GX-B1428/21-2-23346	2023. 10. 31	无缺陷痕迹显示。	 <p>2023/10/10</p>
287	GX-B1310/21-2-23347	2023. 10. 31	发现超过 $\Phi 2\text{mm}$ 当量直径的缺陷	 <p>2023/10/10</p>

288	GX-B1428/21-2-23347	2023. 10. 31	无缺陷痕迹显示。	
289	GX-B1310/21-2-23348	2023. 10. 31	符合标准要求。	
290	GX-B1310/21-2-23352	2023. 10. 31	发现超过 $\Phi 2\text{mm}$ 当量直径的缺陷	



291	GX-B1428/21-2-23352	2023. 10. 31	无缺陷痕迹显示。	
292	GX-B1310/21-2-23357	2023. 10. 31	发现超过 $\Phi 2\text{mm}$ 当量直径的缺陷	