

| 序号 | 报告编号 | 发布日期 | 结论 | 影像资料 |
|-----|----------------------|-------------|---------|--|
| 649 | GX-B1423/20-Y-235708 | 2023年10月25日 | 综合判定：合格 |  |
| 650 | GX-B1423/20-Y-235709 | 2023年10月25日 | 综合判定：合格 |  |

| | | | | |
|-----|----------------------|-------------|---------|--|
| 651 | GX-B1423/20-Y-235710 | 2023年10月25日 | 综合判定：合格 |  |
| 652 | GX-B1423/20-Y-235711 | 2023年10月25日 | 综合判定：合格 |  |

| | | | | |
|-----|----------------------|-------------|---------|--|
| 653 | GX-B1423/20-Y-235712 | 2023年10月25日 | 综合判定：合格 |  |
| 654 | GX-B1423/20-Y-235713 | 2023年10月25日 | 综合判定：合格 |  |

| | | | | |
|-----|----------------------|-------------|---------|--|
| 655 | GX-B1423/20-Y-235714 | 2023年10月25日 | 综合判定：合格 |  |
| 656 | GX-B1423/20-Y-235715 | 2023年10月25日 | 综合判定：合格 |  |

| | | | | |
|-----|----------------------|-------------|---------|--|
| 657 | GX-B1423/20-Y-235716 | 2023年10月25日 | 综合判定：合格 |  |
| 658 | GX-B1423/20-Y-235717 | 2023年10月25日 | 综合判定：合格 |  |

| | | | | |
|-----|----------------------|-------------|---------|--|
| 659 | GX-B1423/20-Y-235718 | 2023年10月25日 | 综合判定：合格 |  |
| 660 | GX-B1423/20-Y-235719 | 2023年10月25日 | 综合判定：合格 |  |

| | | | | |
|-----|----------------------|-------------|---------|--|
| 661 | GX-B1423/20-Y-235720 | 2023年10月25日 | 综合判定：合格 |  |
| 662 | GX-B1423/20-Y-235721 | 2023年10月25日 | 综合判定：合格 |  |

| | | | | |
|-----|----------------------|-------------|---------|--|
| 663 | GX-B1423/20-Y-235722 | 2023年10月25日 | 综合判定：合格 |  A photograph of a yellow dump truck parked on a dirt surface. Two workers in high-visibility vests are standing near the front of the truck. The date '2023/9/24' is visible in the bottom right corner of the photo. |
| 664 | GX-B1423/20-Y-235723 | 2023年10月25日 | 综合判定：合格 |  A photograph of a yellow dump truck parked on a dirt surface. Three workers in high-visibility vests are standing near the front of the truck. The date '2023/9/24' is visible in the bottom right corner of the photo. |

| | | | | |
|-----|----------------------|-------------|---------|--|
| 665 | GX-B1423/20-Y-235724 | 2023年10月25日 | 综合判定：合格 |  |
| 666 | GX-B1423/20-Y-235725 | 2023年10月25日 | 综合判定：合格 |  |

| | | | | |
|-----|----------------------|-------------|---------|--|
| 667 | GX-B1423/20-Y-235726 | 2023年10月25日 | 综合判定：合格 |  |
| 668 | GX-B1423/20-Y-235727 | 2023年10月25日 | 综合判定：合格 |  |

| | | | | |
|-----|----------------------|-------------|---------|--|
| 669 | GX-B1423/20-Y-235728 | 2023年10月25日 | 综合判定：合格 |  A photograph of a yellow dump truck parked on a dirt surface. Two people are standing in front of the truck for scale. The person on the left is wearing a black jacket and dark pants, while the person on the right is wearing a high-visibility yellow vest and a red hard hat. The truck has the number '1710' on its side. A yellow timestamp '2023/9/25' is visible in the bottom right corner of the image. |
| 670 | GX-B1423/20-Y-235729 | 2023年10月25日 | 综合判定：合格 |  A photograph of a yellow dump truck parked on a dirt surface. Two people are standing in front of the truck for scale. The person on the left is wearing a red jacket and pants, while the person on the right is wearing a high-visibility yellow vest and a red hard hat. The truck has the number '1710' on its side. A yellow timestamp '2023/9/25' is visible in the bottom right corner of the image. |

| | | | | |
|-----|----------------------|-------------|---------|--|
| 671 | GX-B1423/20-Y-235730 | 2023年10月25日 | 综合判定：合格 |  |
| 672 | GX-B1423/20-Y-235731 | 2023年10月25日 | 综合判定：合格 |  |

| | | | | |
|-----|----------------------|-------------|---------|--|
| 673 | GX-B1423/20-Y-235732 | 2023年10月25日 | 综合判定：合格 |  |
| 674 | GX-B1423/20-Y-235733 | 2023年10月25日 | 综合判定：合格 |  |

| | | | | |
|-----|----------------------|-------------|---------|--|
| 675 | GX-B1423/20-Y-235734 | 2023年10月25日 | 综合判定：合格 |  |
| 676 | GX-B1423/20-Y-235735 | 2023年10月25日 | 综合判定：合格 |  |

| | | | | |
|-----|----------------------|-------------|---------|--|
| 677 | GX-B1423/20-Y-235736 | 2023年10月25日 | 综合判定：合格 |  |
| 678 | GX-B1563/21-Y-23037 | 2023年10月27日 | 所检项目合格。 |  |

| | | | | |
|-----|---------------------|-------------|---------|--|
| 679 | GX-B1563/21-Y-23038 | 2023年10月27日 | 所检项目合格。 |  |
| 680 | GX-B1563/21-Y-23039 | 2023年10月27日 | 所检项目合格。 |  |

| | | | | |
|-----|---------------------|-------------|---------|--|
| 681 | GX-B1563/21-Y-23040 | 2023年10月27日 | 所检项目合格。 |  |
| 682 | GX-B1563/21-Y-23041 | 2023年10月27日 | 所检项目合格。 |  |

| | | | | |
|-----|----------------------|-------------|---------|--|
| 683 | GX-B1563/21-Y-23042 | 2023年10月27日 | 所检项目合格。 |  |
| 684 | GX-B1423/20-Y-235823 | 2023年10月28日 | 综合判定：合格 |  |

| | | | | |
|-----|----------------------|-------------|---------|--|
| 685 | GX-B1423/20-Y-235824 | 2023年10月28日 | 综合判定：合格 |  |
| 686 | GX-B1423/20-Y-235825 | 2023年10月28日 | 综合判定：合格 |  |

| | | | | |
|-----|----------------------|-------------|---------|--|
| 687 | GX-B1423/20-Y-235826 | 2023年10月28日 | 综合判定：合格 |  |
| 688 | GX-B1423/20-Y-235827 | 2023年10月28日 | 综合判定：合格 |  |

| | | | | |
|-----|----------------------|-------------|---------|--|
| 689 | GX-B1423/20-Y-235828 | 2023年10月28日 | 综合判定：合格 |  |
| 690 | GX-B1423/20-Y-235829 | 2023年10月28日 | 综合判定：合格 |  |

| | | | | |
|-----|----------------------|-------------|---------|--|
| 691 | GX-B1423/20-Y-235830 | 2023年10月28日 | 综合判定：合格 |  |
| 692 | GX-B1423/20-Y-235831 | 2023年10月28日 | 综合判定：合格 |  |

| | | | | |
|-----|----------------------|-------------|---------|--|
| 693 | GX-B1423/20-Y-235832 | 2023年10月28日 | 综合判定：合格 |  |
| 694 | GX-B1423/20-Y-235833 | 2023年10月28日 | 综合判定：合格 |  |

| | | | | |
|-----|----------------------|-------------|---------|---|
| 695 | GX-B1423/20-Y-235834 | 2023年10月28日 | 综合判定：合格 |  A yellow Weichai truck is parked on a dirt surface under a clear blue sky. Two workers in safety gear are standing near the front of the truck. The truck has 'WEICHAI' and the number '20' visible on its side. A date stamp '2023/10/4' is in the bottom right corner. |
| 696 | GX-B1423/20-Y-235835 | 2023年10月28日 | 综合判定：合格 |  A yellow Weichai truck is parked on a dirt surface under a clear blue sky. Two workers in safety gear are standing near the front of the truck. The truck has 'WEICHAI' and the number '20' visible on its side. A date stamp '2023/10/4' is in the bottom right corner. |

| | | | | |
|-----|----------------------|-------------|---------|--|
| 697 | GX-B1423/20-Y-235836 | 2023年10月28日 | 综合判定：合格 |  |
| 698 | GX-B1423/20-Y-235837 | 2023年10月28日 | 综合判定：合格 |  |

| | | | | |
|-----|----------------------|-------------|---------|--|
| 699 | GX-B1423/20-Y-235838 | 2023年10月28日 | 综合判定：合格 |  |
| 700 | GX-B1423/20-Y-235839 | 2023年10月28日 | 综合判定：合格 |  |

| | | | | |
|-----|----------------------|-------------|---------|--|
| 701 | GX-B1423/20-Y-235840 | 2023年10月28日 | 综合判定：合格 |  |
| 702 | GX-B1423/20-Y-235841 | 2023年10月28日 | 综合判定：合格 |  |

| | | | | |
|-----|----------------------|-------------|---------|--|
| 703 | GX-B1423/20-Y-235842 | 2023年10月28日 | 综合判定：合格 |  |
| 704 | GX-B1423/20-Y-235843 | 2023年10月28日 | 综合判定：合格 |  |

| | | | | |
|-----|----------------------|-------------|---------|---|
| 705 | GX-B1423/20-Y-235844 | 2023年10月28日 | 综合判定：合格 |  A yellow dump truck is parked on a flat, sandy surface under a clear blue sky with a bright sun. A person in a white uniform and a red hard hat stands next to the truck. Various pieces of equipment, including a blue toolbox and a black bag, are scattered on the ground in front of the truck. A yellow timestamp '2023/10/5' is visible in the bottom right corner of the photo. |
| 706 | GX-B1423/20-Y-235845 | 2023年10月28日 | 综合判定：合格 |  A yellow dump truck is parked on a flat, sandy surface under a clear blue sky with a bright sun. A person in a white uniform and a red hard hat stands next to the truck. Various pieces of equipment, including a blue toolbox and a black bag, are scattered on the ground in front of the truck. A yellow timestamp '2023/10/5' is visible in the bottom right corner of the photo. |

| | | | | |
|-----|----------------------|-------------|---------|---|
| 707 | GX-B1423/20-Y-235846 | 2023年10月28日 | 综合判定：合格 |  A yellow Weichai dump truck with the number '07' on its side is parked on a dark, paved surface. Two workers in blue uniforms and orange safety vests are standing near the front of the truck. The background shows a clear blue sky and a bright sun. A yellow timestamp '2023/10/5' is visible in the bottom right corner of the photo. |
| 708 | GX-B1423/20-Y-235847 | 2023年10月28日 | 综合判定：合格 |  A yellow Weichai dump truck with the number '07' on its side is parked on a dark, paved surface. Two workers in blue uniforms and orange safety vests are standing near the front of the truck. The background shows a clear blue sky and a bright sun. A yellow timestamp '2023/10/5' is visible in the bottom right corner of the photo. |

| | | | | |
|-----|----------------------|-------------|---------|--|
| 709 | GX-B1423/20-Y-235848 | 2023年10月28日 | 综合判定：合格 |  |
| 710 | GX-B1423/20-Y-235849 | 2023年10月28日 | 综合判定：合格 |  |

| | | | | |
|-----|----------------------|-------------|---------|--|
| 711 | GX-B1423/20-Y-235850 | 2023年10月28日 | 综合判定：合格 |  |
| 712 | GX-B1423/20-Y-235851 | 2023年10月28日 | 综合判定：合格 |  |

| | | | | |
|-----|----------------------|-------------|---------|--|
| 713 | GX-B1423/20-Y-235852 | 2023年10月28日 | 综合判定：合格 |  |
| 714 | GX-B1423/20-Y-235853 | 2023年10月28日 | 综合判定：合格 |  |

| | | | | |
|-----|----------------------|-------------|---------|--|
| 715 | GX-B1423/20-Y-235854 | 2023年10月28日 | 综合判定：合格 |  A yellow dump truck is parked on a sandy surface under a clear blue sky. The truck has the license plate number '2029' on its side. A person in a white shirt and red cap stands to the left of the truck. A yellow timestamp '2023/10/8' is visible in the bottom right corner of the photo. |
| 716 | GX-B1423/20-Y-235855 | 2023年10月28日 | 综合判定：合格 |  A yellow dump truck is parked on a sandy surface under a clear blue sky. The truck has the license plate number '2025' on its side. A person in a white shirt and red cap stands to the left of the truck. A yellow timestamp '2023/10/8' is visible in the bottom right corner of the photo. |

| | | | | |
|-----|----------------------|-------------|---------|---|
| 717 | GX-B1423/20-Y-235856 | 2023年10月28日 | 综合判定：合格 |  A yellow dump truck is parked on a dirt surface under a clear blue sky. The truck has the license plate number '2030' on its side. A person in a red hard hat and white shirt is standing to the left of the truck. A yellow timestamp '2023/10/9' is visible in the bottom right corner of the photo. |
| 718 | GX-B1423/20-Y-235857 | 2023年10月28日 | 综合判定：合格 |  A yellow dump truck is parked on a dirt surface under a clear blue sky. The truck has the license plate number '2024' on its side. A person in a red hard hat and white shirt is standing to the left of the truck. A yellow timestamp '2023/10/9' is visible in the bottom right corner of the photo. |

| | | | | |
|-----|----------------------|-------------|---------|--|
| 719 | GX-B1423/20-Y-235858 | 2023年10月28日 | 综合判定：合格 |  A yellow dump truck with the number '2028' on its side is parked on a sandy surface. A person in a white uniform and red helmet stands to the left of the truck. A date stamp '2023/10/6' is visible in the bottom right corner of the image. |
| 720 | GX-B1423/20-Y-235859 | 2023年10月28日 | 综合判定：合格 |  A yellow dump truck with the number '2007' on its side is parked on a sandy surface. A person in a white uniform and red helmet stands to the left of the truck. A date stamp '2023/10/6' is visible in the bottom right corner of the image. |

| | | | | |
|-----|----------------------|-------------|---------|---|
| 721 | GX-B1423/20-Y-235860 | 2023年10月28日 | 综合判定：合格 |  A yellow dump truck with the number '2006' on its side is parked on a sandy surface. A person in a white uniform and red cap stands to the left of the truck. The background shows a clear blue sky and a flat horizon. A yellow timestamp '2023/10/6' is visible in the bottom right corner of the image. |
| 722 | GX-B1423/20-Y-235861 | 2023年10月28日 | 综合判定：合格 |  A yellow dump truck with the number '2002' on its side is parked on a sandy surface. A person in a white uniform and red cap stands to the left of the truck. The background shows a clear blue sky and a flat horizon. A yellow timestamp '2023/10/6' is visible in the bottom right corner of the image. |

| | | | | |
|-----|----------------------|-------------|---------|---|
| 723 | GX-B1423/20-Y-235862 | 2023年10月28日 | 综合判定：合格 |  A yellow dump truck is parked on a sandy surface under a clear blue sky. The truck has the license plate number '2031' on its side. A person in a red hard hat and white shirt stands to the left of the truck. A yellow timestamp '2023/10/8' is visible in the bottom right corner of the photo. |
| 724 | GX-B1423/20-Y-235863 | 2023年10月28日 | 综合判定：合格 |  A yellow dump truck is parked on a sandy surface under a clear blue sky. The truck has the license plate number '2032' on its side. A person in a red hard hat and white shirt stands to the left of the truck. A yellow timestamp '2023/10/8' is visible in the bottom right corner of the photo. |

| | | | | |
|-----|----------------------|-------------|---------|--|
| 725 | GX-B1423/20-Y-235864 | 2023年10月28日 | 综合判定：合格 |  A yellow dump truck with the number '2033' on its side is parked on a sandy surface. A person in a white shirt and red hard hat stands to the left of the truck. The background shows a clear blue sky and a flat horizon. A yellow timestamp '2023/10/8' is visible in the bottom right corner of the image. |
| 726 | GX-B1423/20-Y-235865 | 2023年10月28日 | 综合判定：合格 |  A yellow dump truck with the number '2001' on its side is parked on a sandy surface. A person in a white shirt and red hard hat stands to the left of the truck. The background shows a clear blue sky and a flat horizon. A yellow timestamp '2023/10/8' is visible in the bottom right corner of the image. |

| | | | | |
|-----|----------------------|-------------|---------|--|
| 727 | GX-B1423/20-Y-235866 | 2023年10月28日 | 综合判定：合格 |  A yellow dump truck with the number '2009' on its side is parked on a sandy surface. A person in a white uniform and red helmet stands to the left of the truck. A small pile of equipment is on the ground in front of the truck. A yellow timestamp '2023/10/6' is visible in the bottom right corner of the image. |
| 728 | GX-B1423/20-Y-235867 | 2023年10月28日 | 综合判定：合格 |  A yellow dump truck with the number '2003' on its side is parked on a sandy surface. A person in a white uniform and red helmet stands to the left of the truck. A small pile of equipment is on the ground in front of the truck. A yellow timestamp '2023/10/6' is visible in the bottom right corner of the image. |

| | | | | |
|-----|----------------------|-------------|---------|--|
| 729 | GX-B1423/20-Y-235868 | 2023年10月28日 | 综合判定：合格 |  |
| 730 | GX-B1423/20-Y-235869 | 2023年10月28日 | 综合判定：合格 |  |

| | | | | |
|-----|----------------------|-------------|---------|---|
| 731 | GX-B1423/20-Y-235870 | 2023年10月28日 | 综合判定：合格 |  A yellow dump truck is parked on a dirt surface under a clear blue sky. The truck has the license plate number '2027' on its side. A person in a grey uniform is standing to the left of the truck. A yellow timestamp '2023/10/6' is visible in the bottom right corner of the image. |
| 732 | GX-B1423/20-Y-235871 | 2023年10月28日 | 综合判定：合格 |  A yellow dump truck is parked on a dirt surface under a blue sky with light clouds. The truck has the license plate number '2004' on its side. A person in a grey uniform is standing to the left of the truck. A yellow timestamp '2023/10/6' is visible in the bottom right corner of the image. |

| | | | | |
|-----|----------------------|-------------|---------|---|
| 733 | GX-B1423/20-Y-235872 | 2023年10月28日 | 综合判定：合格 |  A yellow dump truck with the number 2005 on its side, parked on a dirt surface. Two workers in safety gear are standing near the front. A yellow timestamp '2023/10/8' is visible in the bottom right corner of the image. |
| 734 | GX-B1423/20-Y-235873 | 2023年10月28日 | 综合判定：合格 |  A yellow dump truck with the number 2010 on its side, parked on a dirt surface. Two workers in safety gear are standing near the front. A yellow timestamp '2023/10/8' is visible in the bottom right corner of the image. |

| | | | | |
|-----|---------------------|-------------|---------|---|
| 735 | GX-B1539/22-Y-23255 | 2023年10月27日 | 所检项目合格。 |  A photograph of a yellow wheel loader parked on a dirt lot. Two workers, one in a grey uniform and one in a blue uniform, are standing in front of the loader. The date '2023/9/26' is visible in the bottom right corner of the photo. |
| 736 | GX-B1539/22-Y-23256 | 2023年10月27日 | 所检项目合格。 |  A photograph of a yellow wheel loader parked on a dirt lot. One worker in a grey uniform is standing in front of the loader. The date '2023/9/26' is visible in the bottom right corner of the photo. |

| | | | | |
|-----|----------------------|-------------|---------|--|
| 737 | GX-B1423/20-Y-235687 | 2023年10月28日 | 综合判定：合格 |  |
| 738 | GX-B1423/20-Y-235688 | 2023年10月28日 | 综合判定：合格 |  |

| | | | | |
|-----|----------------------|-------------|---------|--|
| 739 | GX-B1423/20-Y-235689 | 2023年10月28日 | 综合判定：合格 |  |
| 740 | GX-B1423/20-Y-235690 | 2023年10月28日 | 综合判定：合格 |  |

| | | | | |
|-----|----------------------|-------------|---------|--|
| 741 | GX-B1423/20-Y-235691 | 2023年10月28日 | 综合判定：合格 |  |
| 742 | GX-B1423/20-Y-235692 | 2023年10月28日 | 综合判定：合格 |  |

| | | | | |
|-----|----------------------|-------------|---------|--|
| 743 | GX-B1423/20-Y-235693 | 2023年10月28日 | 综合判定：合格 |  |
| 744 | GX-B1423/20-Y-235694 | 2023年10月28日 | 综合判定：合格 |  |

| | | | | |
|-----|----------------------|-------------|---------|--|
| 745 | GX-B1423/20-Y-235695 | 2023年10月28日 | 综合判定：合格 |  |
| 746 | GX-B1423/20-Y-235696 | 2023年10月28日 | 综合判定：合格 |  |

| | | | | |
|-----|----------------------|-------------|---------|--|
| 747 | GX-B1423/20-Y-235697 | 2023年10月28日 | 综合判定：合格 |  |
| 748 | GX-B1423/20-Y-235698 | 2023年10月28日 | 综合判定：合格 |  |

| | | | | |
|-----|----------------------|-------------|---------|--|
| 749 | GX-B1423/20-Y-235699 | 2023年10月28日 | 综合判定：合格 |  |
| 750 | GX-B1423/20-Y-235700 | 2023年10月28日 | 综合判定：合格 |  |

| | | | | |
|-----|----------------------|-------------|---------|--|
| 751 | GX-B1423/20-Y-235701 | 2023年10月28日 | 综合判定：合格 |  |
| 752 | GX-B1423/20-Y-235702 | 2023年10月28日 | 综合判定：合格 |  |

| | | | | |
|-----|----------------------|-------------|---------|--|
| 753 | GX-B1423/20-Y-235703 | 2023年10月28日 | 综合判定：合格 |  |
| 754 | GX-B1423/20-Y-235704 | 2023年10月28日 | 综合判定：合格 |  |

| | | | | |
|-----|----------------------|-------------|---------|--|
| 755 | GX-B1423/20-Y-235705 | 2023年10月28日 | 综合判定：合格 |  |
| 756 | GX-B1423/20-Y-235706 | 2023年10月28日 | 综合判定：合格 |  |

| | | | | |
|-----|----------------------|-------------|---------|--|
| 757 | GX-B1423/20-Y-236054 | 2023年10月27日 | 综合判定：合格 |  |
| 758 | GX-B1423/20-Y-236055 | 2023年10月27日 | 综合判定：合格 |  |


| | | | | |
|-----|----------------------|-------------|---------|--|
| 759 | GX-B1423/20-Y-236056 | 2023年10月27日 | 综合判定：合格 |  |
| 760 | GX-B1423/20-Y-236057 | 2023年10月27日 | 综合判定：合格 |  |

| | | | | |
|-----|----------------------|-------------|---------|--|
| 761 | GX-B1423/20-Y-236058 | 2023年10月27日 | 综合判定：合格 |  |
| 762 | GX-B1423/20-Y-236059 | 2023年10月27日 | 综合判定：合格 |  |

| | | | | |
|-----|----------------------|-------------|---------|--|
| 763 | GX-B1423/20-Y-236060 | 2023年10月27日 | 综合判定：合格 |  A photograph of a red dump truck parked on a dirt surface. Two workers in high-visibility vests are standing near the front of the truck. The truck's bed is raised. A yellow timestamp '2023/10/8' is visible in the bottom right corner of the image. |
| 764 | GX-B1423/20-Y-236061 | 2023年10月27日 | 综合判定：合格 |  A photograph of a red dump truck parked on a dirt surface. Two workers in high-visibility vests are standing near the front of the truck. The truck's bed is raised. A yellow timestamp '2023/10/8' is visible in the bottom right corner of the image. |

| | | | | |
|-----|----------------------|-------------|---------|--|
| 765 | GX-B1423/20-Y-236062 | 2023年10月27日 | 综合判定：合格 |  |
| 766 | GX-B1423/20-Y-236063 | 2023年10月27日 | 综合判定：合格 |  |

| | | | | |
|-----|----------------------|-------------|---------|--|
| 767 | GX-B1423/20-Y-236064 | 2023年10月27日 | 综合判定：合格 |  |
| 768 | GX-B1423/20-Y-236065 | 2023年10月27日 | 综合判定：合格 |  |

| | | | | |
|-----|----------------------|-------------|---------|--|
| 769 | GX-B1423/20-Y-236066 | 2023年10月27日 | 综合判定：合格 |  A photograph showing a worker from the chest up, wearing a red hard hat, safety glasses, and a white long-sleeved uniform. The worker is seated in the driver's seat of a vehicle, with hands on the steering wheel. The background shows the interior of the vehicle and a glimpse of the outside. A yellow timestamp '2023/10/8' is visible in the bottom right corner of the image. |
| 770 | GX-B1423/20-Y-236067 | 2023年10月27日 | 综合判定：合格 |  A photograph of a large red dump truck parked on a dirt surface. Two workers are standing in front of the truck. One worker is wearing a yellow high-visibility vest, and the other is in a white uniform. The truck's bed is raised. The background shows a clear blue sky and some distant structures. A yellow timestamp '2023/10/8' is visible in the bottom right corner of the image. |

| | | | | |
|-----|----------------------|-------------|---------|--|
| 771 | GX-B1423/20-Y-236068 | 2023年10月27日 | 综合判定：合格 |  |
| 772 | GX-B1423/20-Y-236069 | 2023年10月27日 | 综合判定：合格 |  |

| | | | | |
|-----|----------------------|-------------|---------|---|
| 773 | GX-B1423/20-Y-236070 | 2023年10月27日 | 综合判定：合格 |  A photograph of a red dump truck parked on a dirt surface. Two people are standing near the front of the truck. The truck has a large dump body. A yellow date stamp '2023/10/9' is visible in the bottom right corner of the image. |
| 774 | GX-B1423/20-Y-236071 | 2023年10月27日 | 综合判定：合格 |  A photograph of a red dump truck parked on a dirt surface. Two people are standing near the front of the truck. The truck has a large dump body. A yellow date stamp '2023/10/9' is visible in the bottom right corner of the image. |

| | | | | |
|-----|----------------------|-------------|---------|--|
| 775 | GX-B1423/20-Y-236072 | 2023年10月27日 | 综合判定：合格 |  |
| 776 | GX-B1423/20-Y-236073 | 2023年10月27日 | 综合判定：合格 |  |

| | | | | |
|-----|----------------------|-------------|---------|--|
| 777 | GX-B1423/20-Y-236044 | 2023年10月28日 | 综合判定：合格 |  |
| 778 | GX-B1423/20-Y-236045 | 2023年10月28日 | 综合判定：合格 |  |

| | | | | |
|-----|----------------------|-------------|---------|--|
| 779 | GX-B1423/20-Y-236046 | 2023年10月28日 | 综合判定：合格 |  |
| 780 | GX-B1423/20-Y-236047 | 2023年10月28日 | 综合判定：合格 |  |

| | | | | |
|-----|----------------------|-------------|---------|--|
| 781 | GX-B1423/20-Y-236048 | 2023年10月28日 | 综合判定：合格 |  |
| 782 | GX-B1423/20-Y-236049 | 2023年10月28日 | 综合判定：合格 |  |

| | | | | |
|-----|----------------------|-------------|---------|--|
| 783 | GX-B1423/20-Y-236050 | 2023年10月28日 | 综合判定：合格 |  |
| 784 | GX-B1423/20-Y-236051 | 2023年10月28日 | 综合判定：合格 |  |

| | | | | |
|-----|----------------------|-------------|---------|--|
| 785 | GX-B1423/20-Y-236052 | 2023年10月28日 | 综合判定：合格 |  |
| 786 | GX-B1423/20-Y-236053 | 2023年10月28日 | 综合判定：合格 |  |

| | | | | |
|-----|---------------------|-------------|---------|--|
| 787 | GX-B1521/20-Y-23609 | 2023年10月27日 | 所检项目合格。 |  |
| 788 | GX-B1521/20-Y-23610 | 2023年10月27日 | 所检项目合格。 |  |

| | | | | |
|-----|---------------------|-------------|---------|---|
| 789 | GX-B1521/20-Y-23611 | 2023年10月27日 | 所检项目合格。 |  |
|-----|---------------------|-------------|---------|---|