

序号	报告编号	发布日期	结论	影像资料
19	GX-B1427/21-6-23084	2023/11/5	符合标准要求	 A photograph showing a worker in a white shirt and dark pants kneeling on a large stack of metal beams. The worker is inspecting the beams. In the background, there is a blue metal fence with diamond-shaped panels. The date '2023 10 8' is visible in the bottom right corner of the image.
20	GX-B1310/21-6-23156	2023/11/5	符合标准要求	 A photograph showing a worker wearing a red hard hat and a blue shirt kneeling on a stack of metal beams. The worker is holding a clipboard and appears to be inspecting the beams. The background shows a blue metal fence. The date '2023 10 8' is visible in the bottom right corner of the image.

21	GX-B1423/20-6-231082	2023/11/6	综合判定合格	
22	GX-B1423/20-6-231083	2023/11/6	综合判定合格	
23	GX-B1316/23-6-23001 替代报告 编号: GX-B1500/21-6-23127	2023/11/9	所检项目合格	

24	GX-B1316/23-6-23002 替代报告 编号: GX-B1500/21-6-23128	2023/11/9	所检项目合格		
25	GX-B1316/23-6-23003 替代报告 编号: GX-B1500/21-6-23129	2023/11/9	所检项目合格		
26	GX-B1316/23-6-23004 替代报告 编号: GX-B1500/21-6-23130	2023/11/9	所检项目合格		




27	GX-B1316/23-6-23005 替代报告 编号: GX-B1500/21-6-23131	2023/11/9	所检项目合格	
28	GX-B1316/23-6-23006 替代报告 编号: GX-B1500/21-6-23132	2023/11/9	所检项目合格	
29	GX-B1316/23-6-23007 替代报告 编号: GX-B1500/21-6-23133	2023/11/9	所检项目合格	

30	GX-B1316/23-6-23008 替代报告 编号: GX-B1500/21-6-23134	2023/11/9	所检项目合格	
31	GX-B1427/21-6-23085	2023/11/9	符合标准要求	
32	GX-B1427/21-6-23086	2023/11/9	符合标准要求	




33	GX-B1427/21-6-23087	2023/11/9	符合标准要求	
34	GX-B1427/21-6-23088	2023/11/9	符合标准要求	
35	GX-B1427/21-6-23090	2023/11/9	符合标准要求	

36	GX-B1427/21-6-23091	2023/11/9	符合标准要求	
37	GX-B1310/21-6-23157	2023/11/9	符合标准要求	
38	GX-B1310/21-6-23158	2023/11/9	符合标准要求	

39	GX-B1310/21-6-23159	2023/11/9	符合标准要求		
40	GX-B1310/21-6-23160	2023/11/9	符合标准要求		
41	GX-B1310/21-6-23161	2023/11/9	符合标准要求		

42	GX-B1310/21-6-23162	2023/11/9	符合标准要求			
43	GX-B1310/21-6-23168	2023/11/9	符合标准要求			
44	GX-B1310/21-6-23169	2023/11/9	符合标准要求			

45	GX-B1300/20-6-23009	2023/11/10	综合判定合格	
46	GX-B1305/21-6-23014	2023/11/9	综合判定合格	
47	GX-B1305/21-6-23015	2023/11/9	综合判定合格	

48	GX-B1305/21-6-23016	2023/11/9	综合判定合格		
49	GX-B1305/21-6-23017	2023/11/9	综合判定合格		
50	GX-B1305/21-6-23018	2023/11/9	综合判定合格		

51	GX-B1305/21-6-23019	2023/11/9	综合判定合格	
52	GX-B1305/21-6-23020	2023/11/9	综合判定合格	
53	GX-B1305/21-6-23021	2023/11/9	综合判定合格	

54	GX-B1305/21-6-23022	2023/11/9	综合判定合格	 <p>2023 10 27</p>	
55	GX-B1382/21-6-23026	2023/11/13	所检项目合格	 <p>2023 11 04</p>	
56	GX-B1382/21-6-23027	2023/11/13	所检项目合格	 <p>2023 11 04</p>	

57	GX-B1382/21-6-23028	2023/11/13	所检项目合格		 A photograph showing two workers in grey work clothes and red hard hats standing in an industrial environment. They appear to be inspecting or working on a piece of machinery. The background shows metal structures and a yellow safety barrier. A timestamp '2023/11/04' is visible in the bottom right corner of the photo.	
----	---------------------	------------	--------	--	---	--