

序号	报告编号	发布日期	结论	影像资料
1	GX-B1310/21-Y-23156	2023年12月4日	符合标准要求。	 A photograph showing a worker in a blue jacket and red helmet working on a metal structure outdoors. The worker is crouching and appears to be using a tool. The background shows a clear sky and some industrial structures. A yellow timestamp '2023/11/22' is visible in the bottom right corner of the image.
2	GX-B1310/21-Y-23157	2023年12月4日	符合标准要求。	 A photograph showing a worker in a blue jacket and orange pants working on a large industrial machine. The worker is standing and appears to be inspecting or working on the machine. The background shows an industrial setting with various pipes and structures. A yellow timestamp '2023-11-22' is visible in the bottom right corner of the image.

3	GX-B1310/21-Y-23158	2023年12月4日	符合标准要求。	
4	GX-B1310/21-Y-23159	2023年12月4日	符合标准要求。	

5	GX-B1306/23-Y-23143	2023年12月4日	综合判定：合格。	
6	GX-B1306/23-Y-23144	2023年12月4日	综合判定：合格。	

7	GX-B1306/23-Y-23145	2023年12月4日	综合判定：合格。	
8	GX-B1328/20-Y-23163	2023年12月4日	本次共检验电器6支，6支验电器合格。	

9	GX-B1328/20-Y-23164	2023年12月4日	本次共检携带式接地和接地短路装置6组，6组携带式接地和接地短路装置合格。	
10	GX-B1561/20-Y-23008	2023年12月4日	所检项目合格。	

11	GX-B1559/22-Y-23019	2023年12月4日	所检项目合格。	 A photograph showing a worker in a blue jacket and red helmet using a handheld device in a dark environment. The worker is wearing a red helmet with a headlamp and a blue jacket with reflective stripes. The device is held in the worker's hands, and the worker is looking at the screen. The background is dark, suggesting an underground or confined space. A yellow timestamp '2023/11/25' is visible in the bottom right corner of the photo.
----	---------------------	------------	---------	--