

序号	报告编号	发布日期	结论	影像资料
68	GX-B1361/22-A-231197	2023/12/7	合格	 A photograph showing two men in light-colored work jackets working in a workshop. They are positioned around a large, light-colored industrial machine, possibly a lathe or a similar tool. The man in the foreground is wearing white gloves and is focused on adjusting or operating the machine. The man in the background is also working on the machine. The room has a plain wall and a wooden chair is visible in the background. A yellow date stamp '2023/11/15' is located in the bottom right corner of the image.

序号	报告编号	发布日期	结论	影像资料
69	GX-B1361/22-A-231198	2023/12/7	合格	

序号	报告编号	发布日期	结论	影像资料
70	GX-B1361/22-A-231199	2023/12/7	合格	

序号	报告编号	发布日期	结论	影像资料
71	GX-B1361/22-A-231200	2023/12/7	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
72	GX-B1361/22-A-231208	2023/12/7	不合格	

序号	报告编号	发布日期	结论	影像资料
73	GX-B1361/22-A-231209	2023/12/7	合格	

序号	报告编号	发布日期	结论	影像资料
74	GX-B1361/22-A-231210	2023/12/7	不合格	

序号	报告编号	发布日期	结论	影像资料
75	GX-B1361/22-A-231266	2023/12/7	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
76	GX-B1361/22-A-231267	2023/12/7	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
77	GX-B1361/22-A-231268	2023/12/7	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
78	GX-B1361/22-A-231269	2023/12/7	不合格	

序号	报告编号	发布日期	结论	影像资料
79	GX-B1361/22-A-231211	2023/12/8	不合格	

序号	报告编号	发布日期	结论	影像资料
80	GX-B1361/22-A-231214	2023/12/8	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
81	GX-B1361/22-A-231215	2023/12/8	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
82	GX-B1361/22-A-231216	2023/12/8	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
83	GX-B1361/22-A-231217	2023/12/8	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
84	GX-B1361/22-A-231218	2023/12/8	不合格	

序号	报告编号	发布日期	结论	影像资料
85	GX-B1362/20-A-23460	2023/12/11	合格	

序号	报告编号	发布日期	结论	影像资料
86	GX-B1361/22-A-231224	2023/12/8	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
87	GX-B1361/22-A-231225	2023/12/8	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
88	GX-B1361/22-A-231245	2023/12/11	不合格	

序号	报告编号	发布日期	结论	影像资料
89	GX-B1361/22-A-231246	2023/12/11	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
90	GX-B1361/22-A-231247	2023/12/11	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
91	GX-B1361/22-A-231248	2023/12/11	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
92	GX-B1361/22-A-231249	2023/12/11	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
93	GX-B1361/22-A-231250	2023/12/11	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
94	GX-B1361/22-A-231251	2023/12/11	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
95	GX-B1361/22-A-231262	2023/12/11	合格	

序号	报告编号	发布日期	结论	影像资料
96	GX-B1361/22-A-231263	2023/12/11	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
97	GX-B1362/20-A-23496	2023/12/12	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
98	GX-B1361/22-A-231226	2023/12/12	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
99	GX-B1361/22-A-231227	2023/12/12	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
100	GX-B1361/22-A-231228	2023/12/12	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
101	GX-B1361/22-A-231229	2023/12/12	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
102	GX-B1361/22-A-231230	2023/12/12	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
103	GX-B1361/22-A-231231	2023/12/12	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
104	GX-B1361/22-A-231232	2023/12/12	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
105	GX-B1361/22-A-231233	2023/12/12	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
106	GX-B1361/22-A-231252	2023/12/14	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
107	GX-B1361/22-A-231253	2023/12/14	所检项目合格	

序号	报告编号	发布日期	结论	影像资料
108	GX-B1361/22-A-231254	2023/12/14	合格	 A photograph showing two men in light-colored work jackets operating a large, white industrial machine in a laboratory or workshop. The machine has a control panel and a tray. A date stamp '2023/11/28' is visible in the bottom right corner of the image.