

序号	报告编号	发布日期	结论	影像资料
272	GX-B1363/22-A-23562	2023/12/22	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
273	GX-B1363/22-A-23555	2023/12/22	全厚度拉伸强度为：1525N/mm，拉断伸长率为：35%；其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
274	GX-B1367/22-A-23103	2023/12/22	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
275	GX-B1367/22-A-23104	2023/12/22	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
276	GX-B1367/22-A-23106	2023/12/22	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
277	GX-B1367/22-A-23107	2023/12/22	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
278	GX-B1363/22-A-23549	2023/12/22	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
279	GX-B1363/22-A-23553	2023/12/22	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
280	GX-B1363/22-A-23576	2023/12/25	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
281	GX-B1363/22-A-23575	2023/12/25	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
282	GX-B1363/22-A-23573	2023/12/25	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
283	GX-B1363/22-A-23565	2023/12/22	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
284	GX-B1363/22-A-23554	2023/12/25	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
285	GX-B1363/22-A-23564	2023/12/25	所检项目合格。	 <p data-bbox="1599 1050 1727 1074">2023/12/11</p>

序号	报告编号	发布日期	结论	影像资料
286	GX-B1364/22-A-231246	2023/12/21	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
287	GX-B1364/22-A-231247	2023/12/21	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
288	GX-B1364/22-A-231248	2023/12/21	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
289	GX-B1364/22-A-231249	2023/12/21	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
290	GX-B1364/22-A-231250	2023/12/21	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
291	GX-B1364/22-A-231251	2023/12/21	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
292	GX-B1364/22-A-231252	2023/12/21	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
293	GX-B1364/22-A-231253	2023/12/21	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
294	GX-B1364/22-A-231254	2023/12/21	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
295	GX-B1364/22-A-231255	2023/12/21	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
296	GX-B1364/22-A-231274	2023/12/21	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
297	GX-B1364/22-A-231275	2023/12/21	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
298	GX-B1364/22-A-231276	2023/12/21	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
299	GX-B1364/22-A-231277	2023/12/21	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
300	GX-B1364/22-A-231278	2023/12/21	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
301	GX-B1364/22-A-231279	2023/12/21	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
302	GX-B1364/22-A-231280	2023/12/21	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
303	GX-B1364/22-A-231281	2023/12/21	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
304	GX-B1364/22-A-231282	2023/12/21	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
305	GX-B1364/22-A-231283	2023/12/21	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
306	GX-B1364/22-A-231284	2023/12/21	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
307	GX-B1365/20-A-23096	2023/12/21	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
308	GX-B1366/20-A-23130	2023/12/21	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
309	GX-B1363/22-A-23588	2023/12/25	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
400	GX-B1363/22-A-23590	2023/12/25	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
401	GX-B1363/22-A-23591	2023/12/25	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
402	GX-B1363/22-A-23592	2023/12/25	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
403	GX-B1367/22-A-23114	2023/12/26	阻燃性不合格，其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
404	GX-B1367/22-A-23115	2023/12/26	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
405	GX-B1367/22-A-23116	2023/12/26	阻燃性不合格，其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
406	GX-B1364/22-A-231345	2023/12/27	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
407	GX-B1364/22-A-231343	2023/12/27	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
408	GX-B1364/22-A-231342	2023/12/27	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
409	GX-B1364/22-A-231341	2023/12/27	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
410	GX-B1364/22-A-231340	2023/12/27	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
411	GX-B1364/22-A-231339	2023/12/27	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
412	GX-B1364/22-A-231338	2023/12/27	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
413	GX-B1364/22-A-231337	2023/12/27	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
414	GX-B1364/22-A-231336	2023/12/27	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
415	GX-B1364/22-A-231335	2023/12/27	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
416	GX-B1364/22-A-231334	2023/12/27	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
417	GX-B1364/22-A-231333	2023/12/27	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
418	GX-B1364/22-A-231332	2023/12/27	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
419	GX-B1364/22-A-231330	2023/12/27	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
420	GX-B1364/22-A-231331	2023/12/27	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
421	GX-B1363/22-A-23595	2023/12/27	所检项目合格。	 A photograph showing two workers in light-colored jackets and masks inspecting a large, complex industrial machine. The machine has a prominent vertical pipe and a large rectangular panel. One worker is on the left, and the other is on the right, both looking at the machine. A date stamp '2023/12/26' is visible in the bottom right corner of the photo.