

序号	报告编号	发布日期	结论	影像资料
422	GX-B1364/22-A-231328	2023/12/27	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
423	GX-B1364/22-A-231323	2023/12/27	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
424	GX-B1364/22-A-231324	2023/12/27	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
425	GX-B1364/22-A-231346	2023/12/27	所检项目合格。	 A photograph of an industrial interior. A person wearing a high-visibility safety vest is visible on the left side of the frame, looking towards the right. The scene includes a large piece of machinery or equipment with a control panel. The date '2023/12/22' is printed in the bottom right corner of the image.

序号	报告编号	发布日期	结论	影像资料
426	GX-B1364/22-A-231321	2023/12/28	所检项目合格。	 A photograph showing two men in a room. One man is standing on the left, looking towards the right. The other man is standing on the right, looking at a large, light-colored machine or cabinet. The room has a concrete floor and a wall with some discoloration.

序号	报告编号	发布日期	结论	影像资料
427	GX-B1364/22-A-231293	2023/12/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
428	GX-B1364/22-A-231290	2023/12/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
429	GX-B1364/22-A-231289	2023/12/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
430	GX-B1364/22-A-231344	2023/12/27	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
431	GX-B1364/22-A-231329	2023/12/27	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
432	GX-B1364/22-A-231326	2023/12/27	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
433	GX-B1364/22-A-231325	2023/12/27	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
434	GX-B1364/22-A-231322	2023/12/27	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
435	GX-B1364/22-A-231347	2023/12/27	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
436	GX-B1364/22-A-231327	2023/12/27	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
437	GX-B1509/20-A-23028	2023/12/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
438	GX-B1509/20-A-23029	2023/12/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
439	GX-B1365/20-A-23104	2023/12/27	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
440	GX-B1365/20-A-23100	2023/12/28	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
441	GX-B1365/20-A-23102	2023/12/28	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
442	GX-B1365/20-A-23101	2023/12/28	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
443	GX-B1366/20-A-23133	2023/12/28	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
444	GX-B1366/20-A-23137	2023/12/28	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
445	GX-B1366/20-A-23134	2023/12/28	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
446	GX-B1366/20-A-23136	2023/12/28	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
447	GX-B1365/20-A-23103	2023/12/28	所检项目全部合格。	

序号	报告编号	发布日期	结论	影像资料
448	GX-B1364/22-A-231291	2023/12/28	成束电线电缆燃烧试验不合格；其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
449	GX-B1364/22-A-231292	2023/12/28	成束电线电缆燃烧试验不合格；其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
450	GX-B1364/22-A-231308	2023/12/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
451	GX-B1364/22-A-231297	2023/12/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
452	GX-B1364/22-A-231296	2023/12/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
453	GX-B1364/22-A-231295	2023/12/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
454	GX-B1364/22-A-231294	2023/12/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
455	GX-B1364/22-A-231288	2023/12/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
456	GX-B1364/22-A-231287	2023/12/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
457	GX-B1364/22-A-231286	2023/12/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
458	GX-B1364/22-A-231298	2023/12/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
459	GX-B1364/22-A-231262	2023/12/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
460	GX-B1364/22-A-231265	2023/12/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
461	GX-B1364/22-A-231266	2023/12/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
462	GX-B1364/22-A-231264	2023/12/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
463	GX-B1364/22-A-231263	2023/12/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
464	GX-B1364/22-A-231348	2023/12/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
465	GX-B1365/20-A-231357	2023/12/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
466	GX-B1364/22-A-231351	2023/12/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
467	GX-B1364/22-A-231352	2023/12/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
468	GX-B1364/22-A-231353	2023/12/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
469	GX-B1364/22-A-231354	2023/12/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
470	GX-B1364/22-A-231260	2023/12/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
471	GX-B1364/22-A-231261	2023/12/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
472	GX-B1364/22-A-231256	2023/12/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
473	GX-B1364/22-A-231257	2023/12/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
474	GX-B1364/22-A-231258	2023/12/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
475	GX-B1364/22-A-231259	2023/12/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
476	GX-B1364/22-A-231356	2023/12/28	成束燃烧试验不合格； 其余所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
477	GX-B1364/22-A-231271	2023/12/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
478	GX-B1364/22-A-231270	2023/12/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
479	GX-B1364/22-A-231311	2023/12/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
480	GX-B1364/22-A-231310	2023/12/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
481	GX-B1364/22-A-231309	2023/12/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
482	GX-B1364/22-A-231307	2023/12/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
483	GX-B1364/22-A-231306	2023/12/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
484	GX-B1364/22-A-231305	2023/12/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
485	GX-B1364/22-A-231304	2023/12/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
486	GX-B1364/22-A-231303	2023/12/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
487	GX-B1364/22-A-231302	2023/12/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
488	GX-B1364/22-A-231301	2023/12/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
489	GX-B1364/22-A-231300	2023/12/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
490	GX-B1364/22-A-231299	2023/12/28	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
491	GX-B1364/22-A-231358	2023/12/29	所检项目合格。	

序号	报告编号	发布日期	结论	影像资料
492	GX-B1364/22-A-231359	2023/12/29	所检项目合格。	