

序号	报告编号	发布日期	结论	影像资料
49	GX-B1428/21-2-24022	2024. 3. 22	无缺陷迹痕显示。	 A worker wearing a red safety helmet, a blue face mask, and a grey work jacket is kneeling on a light-colored tiled floor. He is looking at a white sheet of paper on the floor, which has a grey, irregularly shaped object (possibly a defect or sample) on it. There are some small red and yellow containers nearby. A timestamp '2024/03/03' is visible in the bottom right corner of the photo.
50	GX-B1310/21-2-24023	2024. 3. 22	符合标准要求。	 A worker wearing a white long-sleeved shirt, a blue apron, and black shoes is kneeling on a light-colored tiled floor. He is working with various pieces of equipment, including a yellow and black toolbox, a black bag, and some cables. A red door is visible in the background. A timestamp '2024/03/04' is visible in the bottom right corner of the photo.



51	GX-B1451/20-2-24069~24073	2024. 3. 22	本次共检高压交流断路器5台，5台所检项目合格。	
52	GX-B1598/21-2-24044	2024. 3. 22	实测钢丝绳有效截面积损失百分比最大为4.84%，小于5%为正常。	

53	GX-B1598/21-2-24045	2024. 3. 22	实测钢丝绳有效截面积 损失百分比最大为 4. 71%，小于5%为正常。	
54	GX-B1598/21-2-24046	2024. 3. 22	实测钢丝绳有效截面积 损失百分比最大为 4. 66%，小于5%为正常。	

55	GX-B1598/21-2-24047	2024. 3. 22	实测钢丝绳有效截面积 损失百分比最大为 4.72%，小于5%为正常。	
56	GX-B1598/21-2-24048	2024. 3. 22	实测钢丝绳有效截面积 损失百分比最大为 2.88%，小于5%为正常。	

57	GX-B1598/21-2-24049	2024. 3. 22	实测钢丝绳有效截面积 损失百分比最大为 2.41%，小于5%为正常。	
58	GX-B1451/20-2-24086~24089	2024. 3. 25	本次共检高压开关柜 4台，4台所检项目合格 。	

59	GX-B1451/20-2-24090~24099	2024. 3. 25	本次共检高压开关柜10台，10台所检项目合格。	
60	GX-B1451/20-2-24100~24113	2024. 3. 25	本次共检高压开关柜14台，14台所检项目合格。	

61	GX-B1451/20-2-24086~24089	2024. 3. 25	本次共检高压开关柜 4台，4台所检项目合格 。	
62	GX-B1451/20-2-24090~24099	2024. 3. 25	本次共检高压开关柜10 台，10台所检项目合格 。	

63	GX-B1451/20-2-24100~24113	2024. 3. 25	本次共检高压开关柜14台，14台所检项目合格。	
64	GX-B1521/20-2-24001	2024. 3. 25	所检项目合格。	





65	GX-B1521/20-2-24002	2024. 3. 25	所检项目合格。	
66	GX-B1521/20-2-24003	2024. 3. 25	所检项目合格。	



67	GX-B1521/20-2-24004	2024. 3. 25	所检项目合格。	
68	GX-B1521/20-2-24005	2024. 3. 25	所检项目合格。	

69	GX-B1521/20-2-24006	2024. 3. 25	所检项目合格。	
70	GX-B1521/20-2-24007	2024. 3. 25	所检项目合格。	

71	GX-B1451/20-2-24114~24130	2024. 3. 24	本次共检高压开关柜17台，17台所检项目合格。 。	
72	GX-B1451/20-2-24131~24137	2024. 3. 24	本次共检高压开关柜7台，7台所检项目合格。 。	

73	GX-B1451/20-2-24138~24143	2024. 3. 24	本次共检高压开关柜 6台，6台所检项目合格。 。		
74	GX-B1309/21-2-24001	2024. 3. 24	所检项目合格。		

75	GX-B1500/21-2-24001	2024. 3. 24	综合判定：合格。	
76	GX-B1500/21-2-24002	2024. 3. 24	综合判定：合格。	

77	GX-B1500/21-2-24003	2024. 3. 24	综合判定：合格。	
78	GX-B1500/21-2-24004	2024. 3. 24	综合判定：合格。	

79	GX-B1598/21-2-24038	2024. 3. 25	实测钢丝绳有效截面积 损失百分比最大为 1.08%，小于5%为正常。	
80	GX-B1598/21-2-24039	2024. 3. 25	实测钢丝绳有效截面积 损失百分比最大为 1.23%，小于5%为正常。	



81	GX-B1598/21-2-24040	2024. 3. 25	实测钢丝绳有效截面积 损失百分比最大为 1. 52%，小于5%为正常。	
82	GX-B1598/21-2-24041	2024. 3. 25	实测钢丝绳有效截面积 损失百分比最大为 1. 41%，小于5%为正常。	

83	GX-B1598/21-2-24042	2024. 3. 25	实测钢丝绳有效截面积 损失百分比最大为 1.65%，小于5%为正常。	
84	GX-B1598/21-2-24043	2024. 3. 25	实测钢丝绳有效截面积 损失百分比最大为 1.63%，小于5%为正常。	

85	GX-B1328/20-2-24031	2024. 3. 25	所检项目合格	
86	GX-B1328/20-2-24032	2024. 3. 25	所检项目合格	

87	GX-B1328/20-2-24033	2024. 3. 25	所检项目合格	
88	GX-B1328/20-2-24034	2024. 3. 25	所检项目合格	

89	GX-B1328/20-2-24035	2024. 3. 25	所检项目合格	
90	GX-B1328/20-2-24036	2024. 3. 25	所检项目合格	

91	GX-B1328/20-2-24024	2024/3/25	本次共检验电器7支，7支所检项目合格。	 <p>2024/03/04</p>
92	GX-B1328/20-2-24025	2024/3/25	本次共检便携式接地和接地短路装置5组，5组所检项目合格。	 <p>2024/03/04</p>

93	GX-B1328/20-2-24026	2024/3/25	本次共检绝缘杆2组，2组所检项目合格。	 <p>2024/03/04</p>
94	GX-B1328/20-2-24028	2024/3/25	本次共检验电器20支，20支所检项目合格。	 <p>2024/03/04</p>

95	GX-B1328/20-2-24029	2024/3/25	本次共检便携式接地和接地短路装置18组，18组所检项目合格。	
96	GX-B1328/20-2-24030	2024/3/25	本次共检绝缘杆4组，4组所检项目合格。	



97	GX-B1322/21-2-24021~24034	2024/3/25	本次共检验电力电缆14条，14条所检项目合格。 。	
98	GX-B1322/21-2-24035~24044	2024/3/25	本次共检验电力电缆10条，10条所检项目合格。 。	

99	GX-B1322/21-2-24045~24052	2024/3/25	本次共检验电力电缆 8条，8条所检项目合格 。	
100	GX-B1328/20-2-24037	2024. 3. 26	所检项目合格	

101	GX-B1307/20-2-24001	2024. 3. 26	综合判定：合格。	
102	GX-B1307/20-2-24002	2024. 3. 26	综合判定：合格。	

103	GX-B1307/20-2-24003	2024. 3. 26	综合判定：合格。	
104	GX-B1307/20-2-24004	2024. 3. 26	综合判定：合格。	



105	GX-B1307/20-2-24005	2024. 3. 26	综合判定：合格。	
106	GX-B1307/20-2-24006	2024. 3. 26	综合判定：合格。	

107	GX-B1307/20-2-24007	2024. 3. 26	综合判定：合格。	
108	GX-B1309/21-2-24002	2024. 3. 25	所检项目合格。	



109	GX-B1309/21-2-24003	2024. 3. 25	所检项目合格。	 <p>2024/03/13</p>
110	GX-B1309/21-2-24004	2024. 3. 25	所检项目合格。	 <p>2024/03/14</p>



111	GX-B1309/21-2-24005	2024. 3. 25	所检项目合格。	
112	GX-B1500/21-2-24005	2024. 3. 25	综合判定：合格。	





113	GX-B1500/21-2-24006	2024. 3. 25	综合判定：合格。	
114	GX-B1500/21-2-24007	2024. 3. 25	综合判定：合格。	



115	GX-B1500/21-2-24008	2024. 3. 25	综合判定：合格。	 A photograph showing a worker in a white uniform and red hard hat inspecting industrial machinery. The worker is standing next to a large, rusted metal component. The date '2024/03/13' is visible in the bottom right corner of the image.
116	GX-B1500/21-2-24009	2024. 3. 25	综合判定：合格。	 A photograph showing a worker in a white uniform and red hard hat inspecting industrial machinery. The worker is standing next to a large, rusted metal component. The date '2024/03/13' is visible in the bottom right corner of the image.



117	GX-B1500/21-2-24010	2024. 3. 25	综合判定：合格。	 <p>2024/03/13</p>
118	GX-B1500/21-2-24011	2024. 3. 25	综合判定：合格。	 <p>2024/03/14</p>

119	GX-B1500/21-2-24012	2024. 3. 25	综合判定：合格。	 <p>2024/03/14</p>
120	GX-B1500/21-2-24013	2024. 3. 25	综合判定：合格。	 <p>2024/03/14</p>


121	GX-B1500/21-2-24014	2024. 3. 25	综合判定：合格。	
122	GX-B1500/21-2-24015	2024. 3. 25	综合判定：合格。	

123	GX-B1500/21-2-24016	2024. 3. 25	综合判定：合格。	 <p>2024/03/14</p>
124	GX-B1451/20-2-24079~24085	2024. 3. 26	本次共检继电保护装置7台，7台继电保护装置所检项目合格。	 <p>2024-03-02</p>

125	GX-B1307/20-2-24008	2024. 3. 27	综合判定：合格	
126	GX-B1307/20-2-24009	2024. 3. 27	综合判定：合格	

127	GX-B1307/20-2-24010	2024. 3. 27	综合判定：合格	
128	GX-B1307/20-2-24011	2024. 3. 27	综合判定：合格	



129	GX-B1307/20-2-24012	2024. 3. 27	综合判定：合格	
130	GX-B1307/20-2-24013	2024. 3. 27	综合判定：合格	

131	GX-B1307/20-2-24014	2024. 3. 27	综合判定：合格	
132	GX-B1428/21-2-24026	2024. 3. 28	无缺陷迹痕显示	

133	GX-B1428/21-2-24027	2024. 3. 28	无缺陷迹痕显示			
134	GX-B1428/21-2-24028	2024. 3. 28	无缺陷迹痕显示			

135	GX-B1322/21-2-24016~24020	2024. 3. 28	所检项目合格	
-----	---------------------------	-------------	--------	---