




序号	报告编号	发布日期	结论	影像资料
1	GX-B1380/20-1-24002	2024. 4. 1	所检项目合格	
2	GX-B1380/20-1-24003	2024. 4. 1	所检项目合格	



3	GX-B1380/20-1-24004	2024. 4. 1	所检项目合格	
4	GX-B1380/20-1-24005	2024. 4. 1	所检项目合格	

5	GX-B1380/20-1-24006	2024. 4. 1	所检项目合格	
6	GX-B1380/20-1-24007	2024. 4. 1	所检项目合格	

7	GX-B1380/20-1-24008	2024. 4. 1	所检项目合格	 <p>2024. 03. 17</p>
8	GX-B1380/20-1-24009	2024. 4. 1	所检项目合格	 <p>2024. 03. 17</p>

9	GX-B1380/20-1-24010	2024. 4. 1	所检项目合格	
10	GX-B1382/21-1-24011	2024. 4. 1	综合判定:合格	

11	GX-B1382/21-1-24012	2024. 4. 1	综合判定:合格	
12	GX-B1382/21-1-24013	2024. 4. 1	综合判定:合格	

13	GX-B1382/21-1-24014	2024. 4. 1	综合判定:合格	
14	GX-B1382/21-1-24015	2024. 4. 1	综合判定:合格	



15	GX-B1382/21-1-24016	2024. 4. 1	综合判定:合格	
16	GX-B1380/20-1-24015	2024. 4. 1	所检项目合格	





17	GX-B1380/20-1-24016	2024. 4. 1	所检项目合格	
18	GX-B1380/20-1-24017	2024. 4. 1	所检项目合格	



19	GX-B1304/21-1-24003	2024. 4. 2	综合判定：合格	
20	GX-B1304/21-1-24004	2024. 4. 2	综合判定：合格	

21	GX-B1598/21-1-24019	2024. 4. 2	实测钢丝绳有效截面积损失百分比最大为1.63%，小于5%为正常	
22	GX-B1598/21-1-24020	2024. 4. 2	实测钢丝绳有效截面积损失百分比最大为1.33%，小于5%为正常	

23	GX-B1598/21-1-24021	2024. 4. 2	实测钢丝绳有效截面积损失百分比最大为1.48%，小于5%为正常	
24	GX-B1598/21-1-24022	2024. 4. 2	实测钢丝绳有效截面积损失百分比最大为1.59%，小于5%为正常	

25	GX-B1598/21-1-24023	2024. 4. 2	实测钢丝绳有效截面积损失百分比最大为2.12%，小于5%为正常	
26	GX-B1598/21-1-24024	2024. 4. 2	实测钢丝绳有效截面积损失百分比最大为1.93%，小于5%为正常	

27	GX-B1598/21-1-24025	2024. 4. 2	实测钢丝绳有效截面积损失百分比最大为2.04%，小于5%为正常	
28	GX-B1424/20-1-24001	2024/4/2	依据NB/T 10176-2019单轨吊车综合判定合格；依据MT/T 220-1990尾气所检项目合格。	

29	GX-B1310/21-1-24030	2024/4/3	符合标准要求	
30	GX-B1310/21-1-24031	2024/4/3	符合标准要求	



31	GX-B1310/21-1-24032	2024/4/3	符合标准要求	
32	GX-B1427/21-1-24030	2024/4/3	符合标准要求	

33	GX-B1309/21-1-24012	2024. 4. 3	所检项目合格		
34	GX-B1500/21-1-24046	2024. 4. 3	合格		

35	GX-B1500/21-1-24047	2024. 4. 3	合格	
36	GX-B1500/21-1-24048	2024. 4. 3	合格	

37	GX-B1500/21-1-24049	2024. 4. 3	合格	
38	GX-B1309/21-1-24011	2024. 4. 3	所检项目合格	

39	GX-B1500/21-1-24042	2024. 4. 3	合格	
40	GX-B1500/21-1-24043	2024. 4. 3	合格	



41	GX-B1500/21-1-24044	2024. 4. 3	合格	
42	GX-B1500/21-1-24045	2024. 4. 3	合格	



43	GX-B1309/21-1-24013	2024. 4. 3	所检项目合格	 <p>2024. 03. 17</p>
44	GX-B1500/21-1-24050	2024. 4. 3	合格	 <p>2024. 03. 17</p>





45	GX-B1500/21-1-24051	2024. 4. 3	合格	
46	GX-B1500/21-1-24052	2024. 4. 3	合格	

47	GX-B1500/21-1-24053	2024. 4. 3	合格	
48	GX-B1307/20-1-24005	2024. 4. 3	综合判定：合格	

49	GX-B1307/20-1-24006	2024. 4. 3	综合判定：合格	
50	GX-B1307/20-1-24007	2024. 4. 3	综合判定：合格	

51	GX-B1307/20-1-24008	2024. 4. 3	综合判定：合格	
52	GX-B1307/20-1-24009	2024. 4. 3	综合判定：合格	

53	GX-B1307/20-1-24010	2024. 4. 3	综合判定：合格	
54	GX-B1300/23-1-24002	2024. 4. 3	综合判定：合格	

55	GX-B1352/21-1-245002~245006	2024. 4. 3	本次共检矿用防爆低压交流真空馈电开关漏电保护5台, 5台所检项目合格	
56	GX-B1385/21-1-24001	2024. 4. 3	所检项目合格	

57	GX-B1352/21-1-245002~245006	204. 4. 3	本次共检矿用防爆低压交流真空馈电开关漏电保护5台, 5台所检项目合格	
58	GX-B1352/21-1-245007~245010	204. 4. 3	本次共检矿用防爆低压交流真空馈电开关漏电保护4台, 4台所检项目合格	



59	GX-B1495/20-1-24018~24036	2024/4/3	本次共检高压开关设备19台， 19台高压开关设备所检项目合格。	
60	GX-B1495/20-1-24037~24056	2024/4/3	本次共检高压开关设备20台， 20台高压开关设备所检项目合格。	

61	GX-B1321/20-1-24007~24012	2024/4/7	本次共检电力电缆6条，6条电力电缆所检项目合格。	
62	GX-B1321/20-1-24013~24016	2024/4/7	本次共检电力电缆4条，4条电力电缆所检项目合格。	

63	GX-B1351-21-1-24001~24002	2024. 4. 7	所检项目合格	
64	GX-B1323/21-1-24001~24006	2024. 4. 7	本次共检三相交流电动机6台，6台三相交流电动机所检项目合格	

23045





































































