

序号	报告编号	发布日期	结论	影像资料
72	GX-B1377/22-F-24095	2024. 4. 23	所检项目合格	
73	GX-B1377/22-F-24096	2024. 4. 23	所检项目合格	

74	GX-B1377/22-F-24097	2024. 4. 23	所检项目合格	 A photograph showing four technicians in a laboratory or industrial setting. They are gathered around a large, white, boxy piece of equipment. One technician is operating the machine, while the others are observing. A date stamp '2024.4.11' is visible in the bottom right corner of the image.
75	GX-B1377/22-F-24098	2024. 4. 23	所检项目合格	 A photograph showing four technicians in a laboratory setting. They are gathered around a white piece of equipment placed on a green table. The technicians are looking at the machine, and one appears to be adjusting it. A date stamp '2024.4.11' is visible in the bottom right corner of the image.

76	GX-B1377/22-F-24091	2024. 4. 23	所检项目合格	 A photograph showing four technicians in a laboratory or industrial setting. They are gathered around a piece of white equipment, possibly a testing machine or a control unit. The technicians are wearing grey work uniforms. The background shows a clean, well-lit environment with glass partitions and other equipment. A timestamp '2024.4.10' is visible in the bottom right corner of the image.
77	GX-B1377/22-F-24092	2024. 4. 23	所检项目合格	 A photograph showing four technicians in a laboratory or industrial setting. They are gathered around a piece of white equipment, possibly a testing machine or a control unit. The technicians are wearing grey work uniforms. The background shows a clean, well-lit environment with glass partitions and other equipment. A timestamp '2024.4.10' is visible in the bottom right corner of the image.

78	GX-B1377/22-F-24093	2024. 4. 23	所检项目合格	
79	GX-B1377/22-F-24094	2024. 4. 23	所检项目合格	

80	GX-B1378/22-F-24105	2024. 4. 23	所检项目合格	
81	GX-B1378/22-F-24096~F-24098	2024. 4. 23	本次共检空气压缩机油油样3个，3个油样所检项目合格。	

82	GX-B1377/22-F-24116	2024. 4. 23	所检项目合格	
83	GX-B1377/22-F-24117	2024. 4. 23	所检项目合格	

84	GX-B1378/22-F-24110~F-24111	2024. 4. 23	所检项目合格	
85	GX-B1378/22-F-24108	2024. 4. 23	所检项目合格	

86	GX-B1378/22-F-24109	2024. 4. 23	所检项目合格	
87	GX-B1378/22-F-24099~F-24102	2024. 4. 23	所检项目合格	

88	GX-B1377 22-F-24105	2024. 4. 23	所检项目合格	
89	GX-B1377 22-F-24106	2024. 4. 23	所检项目合格	
90	GX-B1501/21-F-24029	2024. 4. 23	具有爆炸性	

91	GX-B1502/21-F-24029	2024. 4. 23	II类, 自燃	
92	GX-B1502/21-F-24031	2024. 4. 29	I类, 容易自燃。	
93	GX-B1501/21-F-24031	2024. 4. 29	煤尘具有爆炸性	
94	GX-B1600/21-F-24007	2024. 4. 29	可不注水煤层	
95	GX-B1377/22-F-24118	2024. 4. 29	所检项目合格	

96	GX-B1377/22-F-24119	2024. 4. 29	所检项目合格	 <p>2024.4.19</p>
97	GX-B1377/22-F-24120	2024. 4. 29	所检项目合格	 <p>2024.4.19</p>

98	GX-B1377/22-F-24121	2024. 4. 29	所检项目合格	
99	GX-B1377/22-F-24122	2024. 4. 29	所检项目合格	

100	GX-B1377/22-F-24123	2024. 4. 29	所检项目合格	 A photograph showing four laboratory staff members in white coats working at a laboratory bench. They are focused on a piece of equipment, possibly a balance or a small furnace. The room has a window with yellow curtains and a radiation warning sign on the wall. A timestamp '2024.4.19' is visible in the bottom right corner of the photo.
101	GX-B1377/22-F-24124	2024. 4. 29	所检项目合格	 A photograph showing four laboratory staff members in white coats working in a laboratory. They are gathered around a large piece of equipment, possibly a furnace or a large balance, and appear to be conducting an inspection or adjustment. The room has a window and a radiation warning sign. A timestamp '2024/4/22' is visible in the bottom right corner of the photo.

102	GX-B1377/22-F-24125	2024. 4. 29	所检项目合格	
103	GX-B1377/22-F-24126	2024. 4. 29	所检项目合格	

104	GX-B1377/22-F-24127	2024. 4. 29	所检项目合格	
105	GX-B1377/22-F-24128	2024. 4. 29	所检项目合格	

106	GX-B1377/22-F-24129	2024. 4. 29	所检项目合格	
107	GX-B1378/22-F-24113~F-24116	2024. 4. 29	所检项目合格	

108	GX-B1378/22-F-24112	2024. 4. 29	所检项目合格	
109	GX-B1377/22-F-24134	2024. 4. 29	所检项目合格	

110	GX-B1377/22-F-24130	2024. 4. 30	所检项目合格	
111	GX-B1377/22-F-24131	2024. 4. 30	所检项目合格	

112	GX-B1377/22-F-24132	2024. 4. 30	所检项目合格	
113	GX-B1377/22-F-24133	2024. 4. 30	所检项目合格	