






序号	报告编号	发布日期	结论	影像资料
1	GX-B1539/22-6-24001	2024/5/1	所检项目合格	 A photograph showing a worker wearing a red hard hat and a safety vest, operating a piece of machinery. The worker is looking towards the camera. The date stamp '2024 03 26' is visible in the bottom right corner of the image.
2	GX-B1539/22-6-24002	2024/5/1	所检项目合格	 A photograph showing a worker wearing a white hard hat and a safety vest, operating a piece of machinery. The worker is looking towards the camera. The date stamp '2024 04 18' is visible in the bottom right corner of the image.

3	GX-B1380/20-6-24017	2024/5/3	所检项目合格。	
4	GX-B1380/20-6-24018	2024/5/3	所检项目合格。	
5	GX-B1380/20-6-24019	2024/5/3	所检项目合格。	

6	GX-B1380/20-6-24020	2024/5/3	所检项目合格。	
7	GX-B1380/20-6-24021	2024/5/3	所检项目合格。	
8	GX-B1380/20-6-24022	2024/5/3	所检项目合格。	

9	GX-B1380/20-6-24023	2024/5/3	所检项目合格。	 <p>2024 04 09</p>
10	GX-B1380/20-6-24024	2024/5/3	所检项目合格。	 <p>2024 04 10</p>
11	GX-B1380/20-6-24025	2024/5/3	所检项目合格。	 <p>2024 04 10</p>

12	GX-B1500/21-6-24058	2024/5/3	综合判定：合格。	 <p>2024.04.10</p>
13	GX-B1500/21-6-24059	2024/5/3	综合判定：合格。	 <p>2024.04.10</p>
14	GX-B1500/21-6-24060	2024/5/3	综合判定：合格。	 <p>2024.04.10</p>

15	GX-B1500/21-6-24061	2024/5/3	综合判定：合格。	
16	GX-B1500/21-6-24062	2024/5/3	综合判定：合格。	
17	GX-B1500/21-6-24063	2024/5/3	综合判定：合格。	

18	GX-B1309/21-6-24015	2024/5/3	所检项目合格。	
19	GX-B1309/21-6-24016	2024/5/3	所检项目合格。	
20	GX-B1309/21-6-24017	2024/5/3	所检项目合格。	

21	GX-B1309/21-6-24018	2024/5/3	所检项目合格。		
22	GX-B1309/21-6-24019	2024/5/3	所检项目合格。		
23	GX-B1309/21-6-24020	2024/5/3	所检项目合格。		




24	GX-B1500/21-6-24064	2024/5/3	综合判定：合格。	
25	GX-B1500/21-6-24065	2024/5/3	综合判定：合格。	
26	GX-B1500/21-6-24066	2024/5/3	综合判定：合格。	

27	GX-B1500/21-6-24067	2024/5/3	综合判定：合格。	
28	GX-B1500/21-6-24068	2024/5/3	综合判定：合格。	
29	GX-B1500/21-6-24069	2024/5/3	综合判定：合格。	

30	GX-B1500/21-6-24070	2024/5/3	综合判定：合格。	
31	GX-B1500/21-6-24071	2024/5/3	综合判定：合格。	
32	GX-B1500/21-6-24072	2024/5/3	综合判定：合格。	

33	GX-B1500/21-6-24073	2024/5/3	综合判定：合格。	
34	GX-B1500/21-6-24074	2024/5/3	综合判定：合格。	
35	GX-B1500/21-6-24075	2024/5/3	综合判定：合格。	




36	GX-B1500/21-6-24076	2024/5/3	综合判定：合格。	 A worker in a blue uniform and red helmet is operating a large industrial machine, possibly a lathe or mill, in a factory setting. The machine is blue and red. The worker is standing on a yellow platform. The date 2024 04 30 is visible in the bottom right corner of the photo.
37	GX-B1427/21-6-24027	2024/5/3	符合标准要求。	 A worker in a blue uniform and red helmet is inspecting a large metal component, possibly a valve or flange, which is being lifted by a crane. The worker is standing on a wooden platform. The date 2024 04 27 is visible in the bottom right corner of the photo.
38	GX-B1427/21-6-24028	2024/5/3	符合标准要求。	 A worker in a blue uniform and red helmet is inspecting a large metal component, possibly a valve or flange, which is being lifted by a crane. The worker is standing on a wooden platform. The date 2024 04 27 is visible in the bottom right corner of the photo.



39	GX-B1427/21-6-24029	2024/5/3	符合标准要求。		 <p>2024 04 28</p>
40	GX-B1427/21-6-24030	2024/5/3	符合标准要求。		 <p>2024 04 28</p>
41	GX-B1310/21-6-24062	2024/5/3	符合标准要求		 <p>2024 04 27</p>

42	GX-B1310/21-6-24063	2024/5/3	符合标准要求	 <p>2024 04 27</p>
43	GX-B1310/21-6-24064	2024/5/3	符合标准要求	 <p>2024 04 27</p>
44	GX-B1310/21-6-24065	2024/5/3	符合标准要求	 <p>2024 04 27</p>

45	GX-B1310/21-6-24066	2024/5/3	符合标准要求	
46	GX-B1310/21-6-24067	2024/5/3	符合标准要求	
47	GX-B1310/21-6-24068	2024/5/3	符合标准要求	



48	GX-B1310/21-6-24069	2024/5/3	符合标准要求。	 <p>2024 04 27</p>
49	GX-B1310/21-6-24070	2024/5/3	符合标准要求。	 <p>2024 04 27</p>
50	GX-B1310/21-6-24071	2024/5/3	符合标准要求。	 <p>2024 04 28</p>

51	GX-B1310/21-6-24072	2024/5/3	符合标准要求。	
52	GX-B1310/21-6-24073	2024/5/3	符合标准要求。	
53	GX-B1310/21-6-24074	2024/5/3	符合标准要求。	




54	GX-B1310/21-6-24075	2024/5/3	符合标准要求。		 <p>2024 04 28</p>	
55	GX-B1310/21-6-24076	2024/5/3	符合标准要求。		 <p>2024 04 28</p>	
56	GX-B1310/21-6-24077	2024/5/3	符合标准要求。		 <p>2024 04 28</p>	

57	GX-B1310/21-6-24078	2024/5/3	符合标准要求。		
58	GX-B1310/21-6-24079	2024/5/3	符合标准要求。		
59	GX-B1310/21-6-24080	2024/5/3	符合标准要求。		




60	GX-B1310/21-6-24081	2024/5/3	符合标准要求。	
61	GX-B1310/21-6-24082	2024/5/3	符合标准要求。	
62	GX-B1304/21-6-24017	2024/5/3	综合判定：合格。	



63	GX-B1304/21-6-24018	2024/5/3	综合判定：合格。	
64	GX-B1304/21-6-24019	2024/5/3	综合判定：合格。	
65	GX-B1304/21-6-24020	2024/5/3	综合判定：合格。	

66	GX-B1305/21-6-24012	2024/5/3	综合判定：合格。	
67	GX-B1305/21-6-24013	2024/5/3	综合判定：合格。	
68	GX-B1305/21-6-24014	2024/5/3	综合判定：合格。	




69	GX-B1451/20-6-24491~24493	2024/5/3	所检项目合格。	
70	GX-B1451/20-6-24494~24499	2024/5/3	所检项目合格。	
71	GX-B1451/20-6-24500~24514	2024/5/3	所检项目合格。	






72	GX-B1451/20-6-24515~24522	2024/5/3	所检项目合格。	
73	:GX-B1451/20-6-24523~24524	2024/5/3	所检项目合格。	
74	GX-B1451/20-6-24525~24542	2024/5/3	所检项目合格。	

75	:GX-B1324/21-6-24033~24035	2024/5/3	所检项目合格。	
76	:GX-B1324/21-6-24036~24039	2024/5/3	所检项目合格。	
77	GX-B1427/21-6-24031	2024/5/3	符合标准要求。	

78	GX-B1427/21-6-24032	2024/5/3	符合标准要求。	 <p>2024 04 06</p>
79	GX-B1427/21-6-24033	2024/5/3	符合标准要求。	 <p>2024 04 07</p>
80	GX-B1427/21-6-24034	2024/5/3	符合标准要求。	 <p>2024 04 07</p>

81	GX-B1427/21-6-24035	2024/5/3	符合标准要求。	 A worker wearing a red helmet, a grey long-sleeved shirt, blue pants, and a safety harness is working on a metal structure. The worker is holding a tool and appears to be inspecting or adjusting something. The background shows a building with a red railing. A timestamp "2024 04 10" is visible in the bottom right corner of the photo.
82	GX-B1427/21-6-24036	2024/5/3	符合标准要求。	 A worker wearing a red helmet, a grey long-sleeved shirt, blue pants, and a safety harness is working on a metal structure. The worker is holding a tool and appears to be inspecting or adjusting something. The background shows a building with a red railing. A timestamp "2024 04 09" is visible in the bottom right corner of the photo.
83	GX-B1427/21-6-24037	2024/5/3	符合标准要求。	 A worker wearing a red helmet, a grey long-sleeved shirt, blue pants, and a safety harness is working on a metal structure. The worker is holding a tool and appears to be inspecting or adjusting something. The background shows a building with a red railing. A timestamp "2024 04 09" is visible in the bottom right corner of the photo.

84	GX-B1427/21-6-24038	2024/5/3	符合标准要求。	 A worker wearing a red helmet, safety glasses, and a blue safety harness is working on a vertical metal structure. The worker is holding a tool and appears to be inspecting or working on the structure. The background shows a concrete wall and some pipes. A timestamp "2024 04 09" is visible in the bottom right corner of the image.
85	GX-B1310/21-6-24083	2024/5/7	符合标准要求	 A worker wearing a red helmet and safety glasses is working on a large, red cylindrical component. The worker is using a tool to work on the surface of the cylinder. The background shows a green wall and some pipes. A timestamp "2024 04 06" is visible in the bottom right corner of the image.
86	GX-B1310/21-6-24084	2024/5/7	符合标准要求	 A view of a complex metal structure, possibly a staircase or platform. The structure is made of silver-colored metal beams and plates, forming a grid-like pattern. The background shows a concrete wall and some pipes. A timestamp "2024 04 06" is visible in the bottom right corner of the image.

87	GX-B1310/21-6-24085	2024/5/7	符合标准要求	 A worker wearing a red hard hat, safety glasses, and a blue safety harness is working on a complex steel structure. The worker is positioned on a platform or scaffolding, and the background shows more of the industrial structure. A timestamp '2024 04 06' is visible in the bottom right corner of the photo.
88	GX-B1310/21-6-24086	2024/5/7	符合标准要求	 A worker wearing a red hard hat and safety glasses is inspecting a large, red, cylindrical component. The worker is holding a tool or device, possibly a flashlight or a measuring instrument, and is looking intently at the component. A timestamp '2024 04 06' is visible in the bottom right corner of the photo.
89	GX-B1310/21-6-24087	2024/5/7	符合标准要求	 A worker wearing a red hard hat and safety glasses is smiling at the camera. The worker is wearing a grey work jacket. In the background, there is a large, dark-colored steel coil. A timestamp '2024 04 06' is visible in the bottom right corner of the photo.

90	GX-B1310/21-6-24088	2024/5/7	符合标准要求	
91	GX-B1310/21-6-24089	2024/5/7	符合标准要求	
92	GX-B1310/21-6-24090	2024/5/7	符合标准要求	

93	GX-B1310/21-6-24091	2024/5/7	符合标准要求	
94	GX-B1310/21-6-24092	2024/5/7	符合标准要求	
95	GX-B1310/21-6-24093	2024/5/7	符合标准要求	






96	GX-B1310/21-6-24094	2024/5/7	符合标准要求	
97	GX-B1310/21-6-24095	2024/5/7	符合标准要求	
98	GX-B1310/21-6-24096	2024/5/7	符合标准要求	

99	GX-B1310/21-6-24097	2024/5/7	符合标准要求	 <p>2024 04 07</p>
100	GX-B1310/21-6-24098	2024/5/7	符合标准要求	 <p>2024 04 10</p>
101	GX-B1310/21-6-24099	2024/5/7	符合标准要求	 <p>2024 04 10</p>

102	GX-B1310/21-6-24100	2024/5/7	符合标准要求	
103	GX-B1310/21-6-24101	2024/5/7	符合标准要求	
104	GX-B1310/21-6-24102	2024/5/7	符合标准要求	

105	GX-B1310/21-6-24103	2024/5/7	符合标准要求	 <p>2024 04 09</p>
106	GX-B1310/21-6-24104	2024/5/7	符合标准要求	 <p>2024 04 09</p>
107	GX-B1310/21-6-24105	2024/5/7	符合标准要求	 <p>2024 04 09</p>




108	GX-B1310/21-6-24106	2024/5/7	符合标准要求	
109	GX-B1310/21-6-24107	2024/5/7	符合标准要求	
110	GX-B1310/21-6-24108	2024/5/7	符合标准要求	

111	GX-B1310/21-6-24109	2024/5/7	符合标准要求	 <p>2024 04 09</p>	
112	GX-B1310/21-6-24110	2024/5/7	符合标准要求	 <p>2024 04 10</p>	
113	GX-B1310/21-6-24111	2024/5/7	符合标准要求	 <p>2024 04 10</p>	

114	GX-B1310/21-6-24112	2024/5/7	符合标准要求	 <p>2024 04 10</p>
115	GX-B1324/21-6-24040~24043	2024/5/7	本次共检三相交流电动机4台，4台三相交流电动机所检项目合格。	 <p>2024 04 11</p>
116	GX-B1328/20-6-24064	2024/5/8	本次共检验验电器2支，2支验电器所检项目合格。	 <p>2024 04 05</p>

117	GX-B1328/20-6-24065	2024/5/8	<p>本次共检便携式接地和接地短路装置6组，6组便携式接地和接地短路装置所检项目合格。</p>	
118	GX-B1322/21-6-24221~24223	2024/5/8	<p>本次共检验电力电缆3条，3条电力电缆所检项目合格。</p>	
119	GX-B1451/20-6-24543~24558	2024/5/8	<p>本次共检高压开关柜16台，16台高压开关柜所检项目合格。</p>	



120	GX-B1451/20-6-24559~24563	2024/5/8	本次共检高压开关柜5台, 5台高压开关柜所检项目合格。	
121	GX-B1451/20-6-24564~24569	2024/5/8	本次共检高压开关柜6台, 6台高压开关柜所检项目合格。	
122	GX-B1451/20-6-24570~24573	2024/5/8	本次共检高压开关柜4台, 4台高压开关柜所检项目合格。	

123	GX-B1451/20-6-24574~24576	2024/5/8	本次共检高压开关柜3台, 3台高压开关柜所检项目合格。	
124	GX-B1451/20-6-24577~24584	2024/5/8	本次共检高压开关柜8台, 8台高压开关柜所检项目合格。	
125	GX-B1451/20-6-24585~24589	2024/5/8	本次共检高压开关柜5台, 5台高压开关柜所检项目合格。	