


序号	报告编号	发布日期	结论	影像资料
38	GX-B1495/20-3-242071 ~ 242090	2024年6月7日	本次共检高压开关柜 20台，20台高压开关柜所检 项目合格。	
39	GX-B1495/20-3-242091	2024年6月7日	所检项目合格	
40	GX-B1495/20-3-242576 ~ 242579	2024年6月7日	本次共检高压开关设备 4台，4台高压开关设备所检 项目合格。	

41	GX-B1451/20-3-24092 ~ 24103	2024年6月7日	本次共检高压开关柜12台，12台高压开关柜所检项目合格。	
42	GX-B1495/20-3-242341 ~ 242350	2024年6月7日	本次共检高压开关设备10台，10台高压开关设备所检项目合格。	
43	GX-B1495/20-3-242351 ~ 242360	2024年6月7日	本次共检高压开关设备10台，10台高压开关设备所检项目合格。	

44	GX-B1495/20-3-242361 ~ 242369	2024年6月7日	本次共检高压开关设备 9台，9台高压开关设备所检 项目合格。	
45	GX-B1495/20-3-242370 ~ 242377	2024年6月7日	本次共检高压开关设备 8台，8台高压开关设备所检 项目合格。	
46	GX-B1495/20-3-242378 ~ 242385	2024年6月7日	本次共检高压开关设备 8台，8台高压开关设备所检 项目合格。	

47	GX-B1495/20-3-242386 ~ 242403	2024年6月7日	本次共检高压开关设备18台，18台高压开关设备所检项目合格。	
48	GX-B1495/20-3-242404 ~ 242415	2024年6月7日	本次共检高压开关设备12台，12台高压开关设备所检项目合格。	
49	GX-B1495/20-3-242416 ~ 242418	2024年6月7日	本次共检高压开关设备3台，3台高压开关设备所检项目合格。	

50	GX-B1495/20-3-242419 ~ 242423	2024年6月7日	本次共检高压开关设备5台，5台高压开关设备所检项目合格。	
51	GX-B1495/20-3-242424 ~ 242428	2024年6月7日	本次共检高压开关设备5台，5台高压开关设备所检项目合格。	
52	GX-B1495/20-3-242429 ~ 242440	2024年6月7日	本次共检高压开关设备12台，12台高压开关设备所检项目合格。	

53	GX-B1495/20-3-242441 ~ 242454	2024年6月7日	本次共检高压开关设备14台，14台高压开关设备所检项目合格。	 <p>2024.4.27</p>
54	GX-B1495/20-3-242455 ~ 242463	2024年6月7日	本次共检高压开关设备9台，9台高压开关设备所检项目合格。	 <p>2024.5.1</p>
55	GX-B1495/20-3-242464 ~ 242468	2024年6月7日	本次共检高压开关设备5台，5台高压开关设备所检项目合格。	 <p>2024.5.2</p>

56	GX-B1495/20-3-242469 ~ 242480	2024年6月7日	本次共检高压开关设备12台，12台高压开关设备所检项目合格。	
57	GX-B1308/23-3-24017	2024. 6. 7	综合判定：合格。	
58	GX-B1308/23-3-24018	2024年6月11日	综合判定：合格。	

59	GX-B1308/23-3-24019	2024年6月11日	综合判定：合格。	
60	GX-B1322/21-3-24041~24051	2024年6月4日	本次共检电力电缆11条， 11条电力电缆所检项目合格。	
61	GX-B1309/21-3-24006	2024年6月9日	综合判定：合格。	

62	GX-B1500/21-3-24029	2024年6月9日	综合判定：合格。	
63	GX-B1500/21-3-24030	2024年6月9日	综合判定：合格。	
64	GX-B1500/21-3-24031	2024年6月9日	综合判定：合格。	




65	GX-B1500/21-3-24032	2024年6月9日	综合判定：合格。	 A worker in a red uniform and orange helmet is working on a large blue industrial component. The worker is leaning over the component, and there are various pipes and machinery in the background. A timestamp '2024.5.15' is visible in the bottom right corner of the image.
66	GX-B1500/21-3-24033	2024年6月9日	综合判定：合格。	 A worker in a red uniform and orange helmet is standing next to industrial machinery. The worker is looking towards the camera. There are various pipes and machinery in the background. A timestamp '2024.5.15' is visible in the bottom right corner of the image.
67	GX-B1500/21-3-24034	2024年6月9日	综合判定：合格。	 A worker in a red uniform and orange helmet is standing next to a large blue industrial component. The worker is looking towards the camera. There are various pipes and machinery in the background. A timestamp '2024.5.15' is visible in the bottom right corner of the image.

68	GX-B1309/21-3-24007	2024年6月9日	综合判定：合格。	
69	GX-B1500/21-3-24035	2024年6月9日	综合判定：合格。	
70	GX-B1500/21-3-24036	2024年6月9日	综合判定：合格。	

71	GX-B1500/21-3-24037	2024年6月9日	综合判定：合格。	
72	GX-B1500/21-3-24038	2024年6月9日	综合判定：合格。	
73	GX-B1309/21-3-24008	2024年6月9日	综合判定：合格。	

74	GX-B1500/21-3-24039	2024年6月9日	综合判定：合格。	
75	GX-B1500/21-3-24040	2024年6月9日	综合判定：合格。	
76	GX-B1500/21-3-24041	2024年6月9日	综合判定：合格。	

77	GX-B1500/21-3-24042	2024年6月9日	综合判定：合格。	
78	GX-B1303/21-3-24004	2024年6月11日	综合判定：合格。	
79	GX-B1303/21-3-24005	2024年6月11日	综合判定：合格。	

80	GX-B1308/23-3-24020	2024. 6. 11	综合判定：合格。	
81	GX-B1308/23-3-24021	2024. 6. 11	综合判定：合格。	
82	GX-B1499/23-3-24035	2024. 6. 12	所检项目合格	

83	GX-B1499/23-3-24036	2024. 6. 12	所检项目合格	
84	GX-B1310/21-3-24114	2024. 6. 12	符合标准要求。	
85	GX-B1310/21-3-24115	2024. 6. 12	符合标准要求。	

86	GX-B1310/21-3-24116	2024. 6. 12	符合标准要求。	 2024.04.17
87	GX-B1310/21-3-24117	2024. 6. 12	符合标准要求。	 2024.04.17
88	GX-B1310/21-3-24118	2024. 6. 12	符合标准要求。	 2024.04.17

89	GX-B1310/21-3-24119	2024. 6. 12	符合标准要求。	
90	GX-B1310/21-3-24120	2024. 6. 12	符合标准要求。	
91	GX-B1310/21-3-24121	2024. 6. 12	符合标准要求。	



92	GX-B1310/21-3-24122	2024. 6. 12	符合标准要求。	
93	GX-B1310/21-3-24123	2024. 6. 12	符合标准要求。	
94	GX-B1428/21-3-24027	2024. 6. 12	无缺陷迹痕显示。	

95	GX-B1310/21-3-24141	2024. 6. 12	符合标准要求。	
96	GX-B1310/21-3-24110	2024. 6. 12	未发现超过 $\Phi 2\text{mm}$ 当量直径的缺陷。	

97	GX-B1310/21-3-24111	2024. 6. 12	未发现超过 $\Phi 2\text{mm}$ 当量直径的缺陷。	 A photograph of a worker wearing a red hard hat and a pink long-sleeved uniform. The worker is looking towards the camera while operating machinery. A yellow timestamp '2024. 4. 29' is visible in the bottom right corner of the image.
98	GX-B1310/21-3-24112	2024. 6. 12	未发现超过 $\Phi 2\text{mm}$ 当量直径的缺陷。	 A photograph of a worker wearing a red hard hat and a pink long-sleeved uniform with a yellow stripe on the sleeve. The worker is operating machinery. A yellow timestamp '2024. 4. 29' is visible in the bottom right corner of the image.

99	GX-B1310/21-3-24113	2024. 6. 12	未发现超过 $\Phi 2\text{mm}$ 当量直径的缺陷。	 A photograph showing a worker in a red uniform and red helmet inspecting a large piece of machinery, possibly a crane or excavator. The worker is looking towards the camera. A yellow timestamp '2024. 4. 30' is visible in the bottom right corner of the photo.
100	GX-B1328/20-3-24107	45455	合格。	 A photograph showing a worker in a yellow safety vest and red helmet inspecting a storage area. The worker is looking towards the camera. A yellow timestamp '2024. 4. 15' is visible in the bottom right corner of the photo.

101	GX-B1328/20-3-24108	45455	合格。	
102	GX-B1328/20-3-24109	45455	本次共检验电器2支，2支 验电器合格。	

103	GX-B1321/20-3-241211~ 241216	45450	本次共检电力电缆6条，6 条电力电缆所检项目合格 。	
104	GX-B1321/20-3-241217~ 241223	45450	本次共检电力电缆7条，7 条电力电缆所检项目合格 。	


105	GX-B1321/20-3-241224~ 241229	45450	本次共检电力电缆6条，6 条电力电缆所检项目合格 。	
106	GX-B1321/20-3-241230~ 241238	45450	本次共检电力电缆9条，9 条电力电缆所检项目合格 。	

107	GX-B1321/20-3-241239~ 241247	45450	本次共检电力电缆9条，9 条电力电缆所检项目合格 。	
108	GX-B1321/20-3-241248~ 241255	45450	本次共检电力电缆8条，8 条电力电缆所检项目合格 。	

109	GX-B1321/20-3-241256~ 241263	45450	本次共检电力电缆8条，8 条电力电缆所检项目合格 。	
110	GX-B1321/20-3-241264~ 241277	45450	本次共检电力电缆14条， 14条电力电缆所检项目合 格。	

111	GX-B1321/20-3-241278~ 241287	45450	本次共检电力电缆10条， 10条电力电缆所检项目合格。	
112	GX-B1328/20-3-24093	45455	本次共检验电器50支，50 支验电器合格。	

113	GX-B1328/20-3-24094	45455	本次共检携带式接地和接地短路装置45套，45套携带式接地和接地短路装置合格。	
114	GX-B1328/20-3-24095	45455	本次共检绝缘杆4套，4套绝缘杆所检项目合格。	

115	GX-B1328/20-3-24096	45455	本次共检绝缘胶垫70件， 70件绝缘胶垫合格。	
116	GX-B1328/20-3-24099	45455	本次共检绝缘手套6只，6 只绝缘手套合格。	

117	GX-B1328/20-3-24100	45455	本次共检绝缘鞋6只，6只 绝缘鞋合格。	
118	GX-B1328/20-3-24101	45455	本次共检绝缘手套2只，2 只绝缘手套合格。	

119	GX-B1328/20-3-24102	45455	本次共检绝缘鞋2只，2只 绝缘鞋合格。	
120	GX-B1328/20-3-24103	45455	本次共检绝缘杆1套，1套 绝缘杆合格。	

121	GX-B1328/20-3-24104	45455	本次共检验电器1支，1支 验电器合格。	
122	GX-B1328/20-3-24105	45455	本次共检绝缘手套 44只, 44只绝缘手套合格 。	

123	GX-B1328/20-3-24106	45455	本次共检绝缘鞋44只，44只绝缘鞋合格。	
124	GX-B1539/22-3-24001	45455	所检项目合格。	



125	GX-B1539/22-3-24002	45455	所检项目合格。	
126	GX-B1309/21-3-24009	45456	综合判定：合格。	

127	GX-B1500/21-3-24043	45456	综合判定：合格。	 <p>2024.5.16</p>
128	GX-B1500/21-3-24044	45456	综合判定：合格。	 <p>2024.5.16</p>

129	GX-B1500/21-3-24045	45456	综合判定：合格。	
130	GX-B1500/21-3-24046	45456	综合判定：合格。	

131	GX-B1500/21-3-24047	45456	综合判定：合格。	 A worker in a red uniform and helmet is working on a large blue industrial pipe in a tunnel. The worker is standing on a concrete platform, and the pipe is part of a larger system of machinery. The date 2024.5.16 is visible in the bottom right corner of the image.
132	GX-B1500/21-3-24048	45456	综合判定：合格。	 A worker in a red uniform and helmet is working on a large blue industrial pipe in a tunnel. The worker is kneeling on the ground, and the pipe is part of a larger system of machinery. The date 2024.5.16 is visible in the bottom right corner of the image.

133	GX-B1309/21-3-24010	45456	综合判定：合格。	
134	GX-B1500/21-3-24049	45456	综合判定：合格。	

135	GX-B1500/21-3-24050	45456	综合判定：合格。	
136	GX-B1500/21-3-24051	45456	综合判定：合格。	

137	GX-B1500/21-3-24052	45456	综合判定：合格。	
138	GX-B1500/21-3-24053	45456	综合判定：合格。	

139	GX-B1500/21-3-24054	45456	综合判定：合格。	 A photograph showing a worker in a red protective suit and helmet operating machinery in an industrial setting. The worker is standing next to a blue machine, possibly a pump or motor. The background shows a dark, possibly underground or enclosed industrial environment. A timestamp '2024-5-16' is visible in the bottom right corner of the photo.
-----	---------------------	-------	----------	--