

序号	报告编号	发布日期	结论	影像资料
89	GX-B1548/20-1-24022	2024. 6. 11	所检项目合格	
90	GX-B1310/21-1-24098	2024. 6. 28	符合标准要求	

91	GX-B1310/21-1-24099	2024. 6. 28	符合标准要求	 <p>2024/4/17</p>
92	GX-B1534/20-1-24040	2024. 6. 28	所检项目合格	 <p>2024/6/28</p>

93	GX-B1534/20-1-24041	2024. 6. 28	所检项目合格	
94	GX-B1534/20-1-24042	2024. 6. 28	所检项目合格	

95	GX-B1534/20-1-24043	2024. 6. 28	所检项目合格	
96	GX-B1534/20-1-24044	2024. 6. 28	所检项目合格	

97	GX-B1534/20-1-24045	2024. 6. 28	所检项目合格	 <p>A photograph of a male worker wearing a red hard hat, safety glasses, and a light blue short-sleeved button-down shirt. He is standing outdoors next to a yellow truck. A silver metal toolbox is on the ground in front of him. A red date stamp '2024/6/28' is visible in the bottom right corner of the photo.</p>
98	GX-B1415/22-1-24007	2024. 6. 28	综合判定：合格	 <p>A photograph of a worker in a dark uniform and red hard hat, illuminated by a bright light source. The worker is looking at a tablet or clipboard. The background is dark and appears to be an industrial or underground setting. A yellow date stamp '2024/06/28' is visible in the bottom left corner of the photo.</p>

99	GX-B1415/22-1-24008	2024. 6. 28	综合判定：合格	 <p>A worker wearing a red hard hat and safety glasses is using a handheld device in a dark, industrial setting. The worker is illuminated by a bright light source, possibly a flashlight. The background shows some equipment and a wall. A yellow timestamp '2024/06/03' is visible in the bottom right corner of the image.</p>
100	GX-B1415/22-1-24009	2024. 6. 28	综合判定：合格	 <p>A worker wearing a red hard hat and safety glasses is working in a dark environment. A sign with the text '越位保护' (Over-position Protection) is visible in the foreground. The worker is illuminated by a bright light source, possibly a flashlight. The background shows some equipment and a wall. A yellow timestamp '2024/06/03' is visible in the bottom right corner of the image.</p>

101	GX-B1515/22-1-24003	2024/6/27	所检项目合格。	
-----	---------------------	-----------	---------	---