


序号	报告编号	发布日期	结论	影像资料
70	GX-B1515/22-Y-24009	2024. 7. 5	所检项目合格	
71	GX-B1515/22-Y-24010	2024. 7. 5	所检项目合格	

72	GX-B1310/21-Y- 24134	2024. 7. 5	符合标准要求。	
73	GX-B1427/21-Y-24134	2024. 7. 5	符合标准要求。	

74	GX-B1310/21-Y- 24128	2024. 7. 5	符合标准要求。	
75	GX-B1310/21-Y- 24129	2024. 7. 5	符合标准要求。	

76	GX-B1428/21-Y- 24129	2024. 7. 5	无缺陷迹痕显示。	
77	GX-B1310/21-Y- 24130	2024. 7. 5	符合标准要求。	

78	GX-B1428/21-Y- 24130	2024. 7. 5	无缺陷迹痕显示。	
79	GX-B1310/21-Y- 24131	2024. 7. 5	符合标准要求。	



80	GX-B1427/21-Y-24131	2024. 7. 5	符合标准要求。	
81	GX-B1310/21-Y- 24132	2024. 7. 5	符合标准要求。	

82	GX-B1427/21-Y-24132	2024. 7. 5	符合标准要求。	
83	GX-B1310/21-Y- 24133	2024. 7. 5	符合标准要求。	

84	GX-B1427/21-Y-24133	2024. 7. 5	符合标准要求。	
85	GX-B1310/21-Y- 24127	2024. 7. 5	符合标准要求。	

86	GX-B1427/21-Y-24127	2024. 7. 5	符合标准要求。	 <p>A photograph showing a worker in a red hard hat and safety harness working on a metal structure. The worker is positioned on a platform or scaffolding, and the structure appears to be part of a large industrial or construction project. The date 2024/5/22 is visible in the bottom right corner of the image.</p>
87	GX-B1310/21-Y- 24140	2024. 7. 5	符合标准要求。	 <p>A photograph showing a worker in a red hard hat and safety harness working on a metal structure. The worker is positioned on a platform or scaffolding, and the structure appears to be part of a large industrial or construction project. The date 2024/6/14 is visible in the bottom right corner of the image.</p>

88	GX-B1310/21-Y- 24139	2024. 7. 5	符合标准要求。	 A photograph showing a worker in a grey uniform and a dark helmet working on a blue metal structure, possibly a staircase or walkway. The worker is leaning over the structure. A yellow timestamp '2024/6/14' is visible in the bottom right corner of the image.
89	GX-B1310/21-Y- 24138	2024. 7. 5	符合标准要求。	 A photograph showing a worker in a red helmet and grey uniform working on a blue metal structure. The worker is crouching and appears to be working on a large, circular component of the structure. A yellow timestamp '2024/6/14' is visible in the bottom right corner of the image.

90	GX-B1310/21-Y- 24136	2024. 7. 5	符合标准要求。	
91	GX-B1428/21-Y- 24136	2024. 7. 5	无缺陷迹痕显示。	

92	GX-B1310/21-Y- 24137	2024. 7. 5	符合标准要求。	
93	GX-B1428/21-Y- 24137	2024. 7. 5	无缺陷迹痕显示。	

94	GX-B1539/22-Y-24257	2024. 7. 9	所检项目合格。	 A yellow wheel loader is parked on a dirt surface at a construction site. Two workers in safety gear are standing next to it. The background shows a large pile of rubble. A yellow date stamp '2024/7/29' is visible in the bottom right corner of the photo.
95	GX-B1539/22-Y-24258	2024. 7. 9	所检项目合格。	 A yellow wheel loader is parked on a dirt surface at a construction site. Two workers in safety gear are standing next to it. The background shows a clear sky and a distant hill. A yellow date stamp '2024/7/29' is visible in the bottom right corner of the photo.

96	GX-B1539/22-Y-24259	2024. 7. 9	所检项目合格。	 A photograph showing a worker in a white protective suit, red helmet, and white face mask. The worker is seated in the operator's seat of a piece of heavy machinery, possibly a forklift or a similar vehicle. The worker is looking down at a control panel or instrument cluster. A yellow timestamp '2024/6/28' is visible in the bottom left corner of the photo.
97	GX-B1539/22-Y-24260	2024. 7. 9	所检项目合格。	 A photograph showing a worker in a white protective suit, red helmet, and white face mask. The worker is seated in the operator's seat of a piece of heavy machinery, possibly a forklift or a similar vehicle. The worker is holding a tool or a component in their gloved hands. A yellow timestamp '2024/6/28' is visible in the bottom left corner of the photo.

98	GX-B1539/22-Y-24261	2024. 7. 9	所检项目合格。	
99	GX-B1539/22-Y-24262	2024. 7. 9	所检项目合格。	

100	GX-B1539/22-Y-24263	2024. 7. 9	所检项目合格。	
101	GX-B1539/22-Y-24264	2024. 7. 9	所检项目合格。	

102	GX-B1539/22-Y-24265	2024. 7. 9	所检项目合格。	
103	GX-B1539/22-Y-24266	2024. 7. 9	所检项目合格。	

104	GX-B1539/22-Y-24267	2024. 7. 9	所检项目合格。	
105	GX-B1539/22-Y-24268	2024. 7. 9	所检项目合格。	

106	GX-B1539/22-Y-24269	2024. 7. 9	所检项目合格。	
107	GX-B1539/22-Y-24270	2024. 7. 9	所检项目合格。	

108	GX-B1539/22-Y-24271	2024. 7. 9	所检项目合格。	
109	GX-B1539/22-Y-24272	2024. 7. 9	所检项目合格。	

110	GX-B1539/22-Y-24273	2024. 7. 9	所检项目合格。	 <p>A worker wearing a white protective suit, a red hard hat, and a white face mask is working inside the cab of a vehicle. The worker is leaning over a control panel or dashboard. A yellow date stamp '2024/6/29' is visible in the bottom left corner of the image.</p>
111	GX-B1539/22-Y-24274	2024. 7. 9	所检项目合格。	 <p>A yellow wheel loader is parked on a dirt surface. A worker in a white protective suit and red hard hat is standing next to the front of the loader. The loader has the number 'HF1020' on its side. A yellow date stamp '2024/6/29' is visible in the bottom right corner of the image.</p>

112	GX-B1539/22-Y-24275	2024. 7. 9	所检项目合格。	 A yellow wheel loader is parked on a dirt surface. Two workers wearing hard hats and safety vests are standing next to the front of the machine. The background shows a clear blue sky and a flat, open area. A yellow timestamp '2024/6/29' is visible in the bottom right corner of the photo.
113	GX-B1539/22-Y-24276	2024. 7. 9	所检项目合格。	 A yellow wheel loader is parked on a dirt surface. Two workers wearing hard hats and safety vests are standing next to the front of the machine. The background shows a clear blue sky and a flat, open area. A yellow timestamp '2024/6/29' is visible in the bottom right corner of the photo.

114	GX-B1310/21-Y-24135	2024年7月9日	符合标准要求。	
115	GX-B1427/21-Y-24135	2024年7月9日	符合标准要求。	

116	GX-B1557/22-Y-24041	2024年7月8日	所检项目合格。	
117	GX-B1557/22-Y-24042	2024年7月8日	所检项目合格。	

118	GX-B1557/22-Y-24043	2024年7月8日	所检项目合格。	
119	GX-B1557/22-Y-24044	2024年7月8日	所检项目合格。	

120	GX-B1556/22-Y-24019	2024年7月8日	所检项目合格。	
121	GX-B1556/22-Y-24020	2024年7月8日	所检项目合格。	

122	GX-B1557/22-Y-24045	2024年7月10日	所检项目合格。	 <p>A yellow Sany wheel loader is parked on a dirt surface. Two workers in high-visibility vests are standing in front of it. The loader has 'SANY' and 'SV485H' visible on its side. A yellow date stamp '2024/7/4' is in the bottom right corner.</p>
123	GX-B1521/20-Y-24463	2024年7月10日	所检项目合格。	 <p>A yellow Sany tracked excavator is parked in a quarry or construction site. Two workers in high-visibility vests are standing next to it. The excavator has 'SANY' and 'SV485H' visible on its side. A yellow date stamp '2024/7/4' is in the bottom right corner.</p>

124	GX-B1521/20-Y-24464	2024年7月10日	所检项目合格。	 <p>A yellow SANY SV485H tracked excavator is shown at a construction site. The excavator has the number '15' on its side and 'SANY' and 'SV485H' on its arm. Two workers in safety gear are standing near the excavator. The background shows a large pile of earth and a clear blue sky. A yellow timestamp '2024/7/4' is visible in the bottom right corner of the photo.</p>
125	GX-B1521/20-Y-24465	2024年7月10日	所检项目合格。	 <p>A worker wearing a red hard hat and a light-colored safety jacket is operating a tracked excavator. The worker is holding a tool or device near the excavator's controls. The background is slightly hazy. A yellow timestamp '2024/7/4' is visible in the bottom right corner of the photo.</p>

126	GX-B1521/20-Y-24466	2024年7月10日	所检项目合格。	
127	GX-B1521/20-Y-24467	2024年7月10日	所检项目合格。	

128	GX-B1521/20-Y-24468	2024年7月10日	所检项目合格。	 A photograph showing a person wearing a red hard hat and a light-colored work jacket, sitting inside the operator's cab of a tracked excavator. The person is holding a yellow handheld device, possibly a tablet or a specialized tool. The background shows the interior of the cab with windows and control panels. A yellow date stamp '2024/7/4' is visible in the bottom right corner of the image.
129	GX-B1521/20-Y-24469	2024年7月10日	所检项目合格。	 A photograph of a yellow SANY tracked excavator, model Y160H, operating in a mining or construction site. The excavator is positioned on a dirt surface, and its arm is extended. In the background, there are snow-capped mountains under a clear blue sky. Two people are standing near the excavator. A yellow date stamp '2024/7/4' is visible in the bottom right corner of the image.

130	GX-B1521/20-Y-24470	2024年7月10日	所检项目合格。	
131	GX-B1521/20-Y-24471	2024年7月10日	所检项目合格。	

132	GX-B1521/20-Y-24472	2024年7月10日	所检项目合格。	
133	GX-B1521/20-Y-24473	2024年7月10日	所检项目合格。	

134	GX-B1521/20-Y-24474	2024年7月10日	所检项目合格。	
135	GX-B1521/20-Y-24475	2024年7月10日	所检项目合格。	

136	GX-B1521/20-Y-24476	2024年7月10日	所检项目合格。	
137	GX-B1521/20-Y-24477	2024年7月10日	所检项目合格。	

138	GX-B1521/20-Y-24478	2024年7月10日	所检项目合格。	
139	GX-B1521/20-Y-24479	2024年7月10日	所检项目合格。	

140	GX-B1521/20-Y-24480	2024年7月10日	所检项目合格。	
141	GX-B1539/22-Y-24239	2024年7月10日	所检项目合格。	

142	GX-B1539/22-Y-24240	2024年7月10日	所检项目合格。	
143	GX-B1539/22-Y-24241	2024年7月10日	所检项目合格。	

144	GX-B1539/22-Y-24242	2024年7月10日	所检项目合格。	
145	GX-B1539/22-Y-24243	2024年7月10日	所检项目合格。	

146	GX-B1539/22-Y-24244	2024年7月10日	所检项目合格。	
147	GX-B1539/22-Y-24245	2024年7月10日	所检项目合格。	

148	GX-B1539/22-Y-24246	2024年7月10日	所检项目合格。	
149	GX-B1539/22-Y-24247	2024年7月10日	所检项目合格。	

150	GX-B1539/22-Y-24248	2024年7月10日	所检项目合格。	
151	GX-B1539/22-Y-24249	2024年7月10日	所检项目合格。	

152	GX-B1539/22-Y-24250	2024年7月10日	所检项目合格。		
153	GX-B1539/22-Y-24251	2024年7月10日	所检项目合格。		

154	GX-B1539/22-Y-24252	2024年7月10日	所检项目合格。	 A yellow wheel loader with the number 219 on its side is parked on a dirt surface. A person in a white shirt and red safety vest is standing next to it. The background shows a hilly landscape under a clear blue sky. A yellow timestamp '2024/6/30' is visible in the bottom right corner of the photo.
155	GX-B1539/22-Y-24253	2024年7月10日	所检项目合格。	 A yellow wheel loader with the number 220 on its side is parked on a dirt surface. Two people in safety vests are standing next to it. The background shows a hilly landscape under a clear blue sky. A yellow timestamp '2024/6/30' is visible in the bottom right corner of the photo.

156	GX-B1539/22-Y-24254	2024年7月10日	所检项目合格。	
157	GX-B1539/22-Y-24255	2024年7月10日	所检项目合格。	

158	GX-B1539/22-Y-24256	2024年7月10日	所检项目合格。	
-----	---------------------	------------	---------	---