

序号	报告编号	发布日期	结论	影像资料
16	GX-B1328/20-Y-24086	2024. 11. 15	所检项目合格。	
17	GX-B1328/20-Y-24084	2024年11月19日	本次共检验电器6支，6支验电器所检项目合格。	

18	GX-B1310/21-Y-24175	2024年11月18日	符合标准要求。	 <p>2024.11.7</p>
19	GX-B1310/21-Y-24176	2024年11月18日	符合标准要求。	 <p>2024.11.7</p>

20	GX-B1539/22-Y-24319	2024年11月20日	所检项目合格。	 A yellow wheel loader is parked on a dirt surface. Two workers wearing high-visibility vests and hard hats stand in front of the machine. The date '2024/11/5' is visible in the bottom right corner of the photo.
21	GX-B1539/22-Y-24320	2024年11月20日	所检项目合格。	 A yellow wheel loader is parked on a dirt surface. Two workers wearing high-visibility vests and hard hats stand in front of the machine. The date '2024/11/5' is visible in the bottom right corner of the photo.
22	GX-B1539/22-Y-24321	2024年11月20日	所检项目合格。	 A yellow wheel loader is parked on a dirt surface. Two workers wearing high-visibility vests and hard hats stand in front of the machine. The date '2024/11/5' is visible in the bottom right corner of the photo.

23	GX-B1539/22-Y-24322	2024年11月20日	所检项目合格。	
24	GX-B1539/22-Y-24323	2024年11月20日	所检项目合格。	

25	GX-B1539/22-Y-24324	2024年11月20日	所检项目合格。	
26	GX-B1539/22-Y-24325	2024年11月20日	所检项目合格。	
27	GX-B1539/22-Y-24326	2024年11月20日	所检项目合格。	

28	GX-B1539/22-Y-24327	2024年11月20日	所检项目合格。	
29	GX-B1539/22-Y-24328	2024年11月20日	所检项目合格。	
30	GX-B1539/22-Y-24329	2024年11月20日	所检项目合格。	

31	GX-B1539/22-Y-24330	2024年11月20日	所检项目合格。	
32	GX-B1539/22-Y-24331	2024年11月20日	所检项目合格。	
33	GX-B1557/22-Y-24056	2024年11月19日	所检项目合格。	

34	GX-B1557/22-Y-24057	2024年11月19日	所检项目合格。	
35	GX-B1557/22-Y-24058	2024年11月19日	所检项目合格。	
36	GX-B1521/20-Y-24610	2024年11月19日	所检项目合格。	

37	GX-B1521/20-Y-24611	2024年11月20日	所检项目合格。	
38	GX-B1563/24-Y-24052	2024年11月19日	所检项目合格。	
39	GX-B1539/22-Y-24332	2024年11月19日	所检项目合格。	

40	GX-B1423/20-Y-24013	2024年11月19日	综合判定：合格。	
41	GX-B1423/20-Y-24014	2024年11月19日	综合判定：合格。	
42	GX-B1423/20-Y-24015	2024年11月19日	综合判定：合格。	

43	GX-B1521/20-Y-24612	2024年11月21日	所检项目合格。	
44	GX-B1521/20-Y-24613	2024年11月21日	所检项目合格。	

45	GX-B1521/20-Y-24614	2024年11月21日	所检项目合格。	
46	GX-B1521/20-Y-24615	2024年11月21日	所检项目合格。	

47	GX-B1521/20-Y-24616	2024年11月21日	所检项目合格。	 A yellow tracked excavator is shown in a construction or mining site. The excavator is the primary focus, with its arm and bucket visible. A person in a high-visibility vest stands near the tracks for scale. The background shows a rocky hillside under a clear blue sky. A yellow timestamp '2024/11/10' is visible in the bottom right corner of the photo.
48	GX-B1521/20-Y-24617	2024年11月21日	所检项目合格。	 A yellow tracked excavator is shown in a construction or mining site. The excavator is the primary focus, with its arm and bucket visible. A person in a high-visibility vest stands near the tracks for scale. The background shows a rocky hillside under a clear blue sky. A yellow timestamp '2024/11/10' is visible in the bottom right corner of the photo.

49	GX-B1521/20-Y-24618	2024年11月21日	所检项目合格。	
50	GX-B1521/20-Y-24619	2024年11月21日	所检项目合格。	

51	GX-B1521/20-Y-24620	2024年11月21日	所检项目合格。	
52	GX-B1521/20-Y-24621	2024年11月21日	所检项目合格。	

53	GX-B1521/20-Y-24622	2024年11月21日	所检项目合格。	 A yellow excavator is shown in operation at a construction site. The excavator is positioned on a dirt mound, and its arm is extended. A worker in a high-visibility vest is visible in the background. The date stamp '2024/11/15' is visible in the bottom right corner of the image.
54	GX-B1521/20-Y-24623	2024年11月21日	所检项目合格。	 A yellow excavator is shown in operation at a construction site. The excavator is positioned on a dirt mound, and its arm is extended. A worker in a high-visibility vest is visible in the background. The date stamp '2024/11/16' is visible in the bottom right corner of the image.

55	GX-B1521/20-Y-24624	2024年11月21日	所检项目合格。	
56	GX-B1521/20-Y-24625	2024年11月21日	所检项目合格。	

57	GX-B1521/20-Y-24626	2024年11月21日	所检项目合格。	 A yellow excavator is shown at a construction site. Two workers in safety gear are standing near the machine. The date stamp '2024/11/16' is visible in the bottom right corner of the photo.
58	GX-B1521/20-Y-24627	2024年11月21日	所检项目合格。	 A yellow excavator is shown at a construction site. A worker in safety gear is standing near the machine. The date stamp '2024/11/16' is visible in the bottom right corner of the photo.

59	GX-B1521/20-Y-24628	2024年11月21日	所检项目合格。	 A yellow tracked excavator is shown at a construction site. The excavator is positioned on a dirt surface, and its bucket is raised. A person in a high-visibility vest is standing next to the excavator. The background shows a concrete wall and a clear sky. A yellow timestamp '2024/11/16' is visible in the bottom right corner of the image.
60	GX-B1521/20-Y-24629	2024年11月21日	所检项目合格。	 A yellow tracked excavator is shown working on a pile of rubble or debris. The excavator is positioned on the pile, and its bucket is raised. A person in a high-visibility vest is standing next to the excavator. The background shows a clear blue sky and some distant structures. A yellow timestamp '2024/11/16' is visible in the bottom right corner of the image.

61	GX-B1521/20-Y-24630	2024年11月21日	所检项目合格。	 A yellow excavator is shown at a construction site. A worker in a high-visibility vest stands nearby. The date stamp '2024/11/16' is visible in the bottom right corner of the photo.
62	GX-B1521/20-Y-24631	2024年11月21日	所检项目合格。	 A yellow excavator is shown at a construction site. A worker in a high-visibility vest stands nearby. The date stamp '2024/11/16' is visible in the bottom right corner of the photo.

63	GX-B1521/20-Y-24632	2024年11月21日	所检项目合格。	
64	GX-B1521/20-Y-24633	2024年11月21日	所检项目合格。	

65	GX-B1521/20-Y-24634	2024年11月21日	所检项目合格。	 A yellow excavator is shown working on a dirt slope. The excavator is positioned on the right side of the frame, with its arm extended towards the left. A person in a high-visibility vest is standing near the base of the slope. The background shows a large, eroded dirt bank under a clear blue sky. A yellow timestamp '2024/11/17' is visible in the bottom right corner of the image.
66	GX-B1521/20-Y-24635	2024年11月21日	所检项目合格。	 A yellow excavator is shown working on a rocky slope. The excavator is positioned on the right side of the frame, with its arm extended towards the left. A person in a high-visibility vest is standing near the base of the slope. The background shows a large, eroded dirt bank under a clear blue sky. A yellow timestamp '2024/11/17' is visible in the bottom right corner of the image.

67	GX-B1521/20-Y-24636	2024年11月21日	所检项目合格。	 A yellow tracked excavator is shown in a construction or mining site. The excavator is positioned on a dirt surface, and its bucket is raised. A person in a high-visibility vest is standing near the excavator. The date stamp '2024/11/17' is visible in the bottom right corner of the image.
68	GX-B1521/20-Y-24637	2024年11月21日	所检项目合格。	 A red tracked excavator is shown in a construction or mining site. The excavator is positioned on a dirt surface, and its bucket is raised. A person in a high-visibility vest is standing near the excavator. The date stamp '2024/11/17' is visible in the bottom right corner of the image.

69	GX-B1521/20-Y-24638	2024年11月21日	所检项目合格。	
70	GX-B1521/20-Y-24639	2024年11月21日	所检项目合格。	

71	GX-B1521/20-Y-24640	2024年11月21日	所检项目合格。	 A yellow LUGON excavator is shown at a construction site. The excavator's arm is extended, and its bucket is resting on the ground. Two workers in high-visibility vests and hard hats are standing near the machine. The background shows a clear blue sky and a dirt area. A yellow timestamp "2024-11-17" is visible in the bottom right corner of the photo.
72	GX-B1522/20-Y-24122	2024年11月20日	所检项目合格。	 A teal tracked drilling rig is shown at a construction site. The rig is mounted on a tracked chassis and has a long vertical mast. A worker in a high-visibility vest and hard hat is standing next to the rig. The background shows a clear blue sky and a dirt area. A yellow timestamp "2024-11-16" is visible in the bottom right corner of the photo.

73	GX-B1522/20-Y-24123	2024年11月20日	所检项目合格。	 A yellow drilling rig is shown in a desert environment. The rig is a large piece of machinery with a tall mast and various components. A person in a yellow safety vest is standing next to the rig. The background shows a clear blue sky and sandy terrain. A yellow timestamp "2024/11/5" is visible in the bottom right corner of the image.
74	GX-B1310/21-Y-24171	2024年11月25日	符合标准要求。	 A worker wearing a red hard hat and a grey jacket is inspecting a large, circular industrial component. The component has a blue base and a white upper section with several bolts. The worker is kneeling and looking into the component. A yellow timestamp "2024/11/25" is visible in the bottom right corner of the image.

75	GX-B1310/21-Y-24172	2024年11月25日	符合标准要求。	
76	GX-B1310/21-Y-24173	2024年11月25日	符合标准要求。	

77	GX-B1310/21-Y-24174	2024年11月25日	符合标准要求。	
78	GX-B1557/22-Y-24059	2024年11月25日	所检项目合格。	
79	GX-B1521/20-Y-24654	2024年11月25日	所检项目合格。	