

序号	报告编号	发布日期	结论	影像资料
15	GX-B1310/21-1-24271	2024. 12. 3	符合标准要求	
16	GX-B1418/23-1-24001	2024. 12. 10	综合判定：合格	



17	GX-B1328/20-1-24056	2024. 12. 10	本次共检验电器9支，9支验电器合格	
18	GX-B1328/20-1-24057	2024. 12. 10	本次共检便携式短路接地线6套，6套所检项目合格	

19	GX-B1328/20-1-24058	2024. 12. 10	本次共检绝缘杆6套，6套绝缘杆合格	
20	GX-B1598/24-1-24057	2024. 12. 10	实测钢丝绳有效截面积损失百分比最大为0.46%，小于5%为正常	

21	GX-B1598/24-1-24058	2024. 12. 10	实测钢丝绳有效截面积 损失百分比最大为 0.56%，小于5%为正常	
22	GX-B1598/24-1-24059	2024. 12. 10	实测钢丝绳有效截面积 损失百分比最大为 0.43%，小于5%为正常	

23	GX-B1598/24-1-24060	2024. 12. 10	实测钢丝绳有效截面积 损失百分比最大为 0.61%，小于5%为正常	
24	GX-B1598/24-1-24061	2024. 12. 10	实测钢丝绳有效截面积 损失百分比最大为 0.61%，小于5%为正常	

25	GX-B1598/24-1-24062	2024. 12. 10	实测钢丝绳有效截面积 损失百分比最大为 0.72%，小于5%为正常	 2024/11/13
26	GX-B1332/21-1-24067~24078	2024. 12. 12	本次共检电力电容器12 台，12台所检项目合格	 2024/11/26

27	GX-B1303/21-1-24012	2024. 12. 12	综合判定：合格	
28	GX-B1303/21-1-24013	2024. 12. 12	综合判定：合格	

29	GX-B1303/21-1-24014	2024. 12. 12	综合判定：合格	
----	---------------------	--------------	---------	---